

27/03/2002

ASS. REC. BY:

REF: CS/TM120002021/Fgfs

N2

Special Instruction:

Surveyor: Ram ASSIGNMENT (Office)From (Person): tiona Gan Bee Song of TM1 Date/Time: 20.2.2020 11:30AM

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 11260 Insured: GBD 4702Lat Workshop m/s Comfortdelgro Tel: 62148300of 59 luyang barePolicy No: MW009269 Claim No: M2001340

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 18.2.2020

(Client's Record)

CA / REV / REP. / REV 24 HRS mp1 H.O.D. Endorsement: \_\_\_\_\_Date/Time: 20.2.2020 12:04pm Person Contacted: Junan Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 11260 - NA / INC 090239251R Rep - 23/10/2009
	GBD 4702L - X
	21/02/20 @ 2.10pm revised to Fiona Gan via Meimian.

ASS. REC. BY: Ram

REF:

## ASSIGNMENT

Front: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: 3HC11260 Yr Regn: 05/01/2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius Hybrid (84) c.c. 1728Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 466014 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTDKB3FU003561364

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

DAWATI

Front

Rear

R/Bal. 8 mm R/Bal. 8 mmL/Bal. 8 mm L/Bal. 8 mmD.O.A. 18/02/2020 D.O.I. 20/2/2020Survey held at Confidential (Loyal)Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orN/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 10 MAR 2020

P/R \$4587.90/- with 2 repair days (Red to 664.50, 137.7)

confirmation 2/3/2020 with charges.

Date/Time, File Pass to?

1) 10/3/2020

Date/Time, File Return to?

2) \_\_\_\_\_

☐ : Prell. Report☐ : Final ReportDays Of Repair: 2Resurvey No. of Trip: 1Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Insp (\$)☐ Weekend (\$)

Survey Fee:

Transportation: 250

Photos

Others

TOTAL

1111261Report Format: MEP-TPLump Sum / L.B. (\$): 4587.90

**Note: This document has not been finalised.**

# **LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd  
20 McCallum Street  
#09-01 Tokio Marine Centre  
Singapore 069046

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Fiona Gan Bee Song

Date: 21 Feb 2020

## **Preliminary Advice**

Insured Vehicle No	: GBD4702L	Accident Date	: 18/02/2020
TP Vehicle No	: SHC1126D	Assignment Date	: 20/02/2020
Make	: TOYOTA PRIUS HYBRID	Est. Duration of Repair	: 2.00
Date of Inspection	: 20/02/2020		
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) 59 LOYANG DRIVE SINGAPORE 508969		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,252.40
Revised Amount	:S\$	4,587.90
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,587.90

Lump Sum Repair	:S\$
-----------------	------

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Feb 2020 <a href="#">Sendback Est</a>	19 Feb 2020 17:05 <b>S\$5,252.40</b>	20 Feb 2020 11:30 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

#### CLAIM SUBFOLDER DETAILS

Insured:	SANKRANTI HOTELS PTE LTD, Co. Reg. No.: 201113958R			
Main Claimant:	CTPL			
Vehicle Reg. No.:	SHC1126D	Date of Loss:	18/02/2020 17:00 - :59 [31 Months and 13 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / M2001340	Policy/Cover Note No.:	MW009269 (Comprehensive) Coverage: 01/11/2019 - 31/10/2020	
Vehicle Reg. No. (Insured):	GBD4702L	Policy No. (Claimant):		
		Excess:	S\$0.00	
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300			
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by <b>Fiona Gan Bee Song</b> - 65926378]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 02/03/2020]			

#### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	19/02/2020 13:10
Date Of Accident	18/02/2020 17:20
Exact Location Of Accident	PIE SLIP ROAD TO WHITLEY ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC1126D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	1XXXXX821R
Email Address	FLEETSAFETY@TAXICDGE.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS HYBRID 4G

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

### Driver

Name of Driver	TEH KOK MENG
NRIC No	SXXXX295F
Date Of Birth	01/12/1968
Occupation	OUTDOOR
Date Of Driving Pass	23/04/1993
Driving Experience	26 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97607316
Fax Number	
Contact Number	
Email Address	WETWET43@HOTMAIL.COM

Address	BLK 219 TAMPINES STREET 24 #09-30
Postcode	520219
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : - GENDER: : FEMALE
Passenger 2	NAME: : - GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD4702L
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

RH REAR

No. Of Passenger (Including Driver)

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE. LTD.  
CO. REG. NO. 199603821R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: **Loke Wei Yeng**  
NRIC/FIN No.:

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 18/2/2020 at about 17:20 hrs, I veh A was driving at above said location with 2 passenger onboard. Suddenly veh B swerved to right hand side without signalling came into collision with my taxi. Veh B lorry right rear hit & grazed onto the left front portion of my taxi. Veh B continue drive away. I able to stop him eventually. Scene photo is taken. No injury at the point of accident.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 196303821R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: Loke Wei Yeng  
NRIC/FIN No.:

YUARMC SketchPlanForm\_13

Team: ARC Repair TP(CLSO)

JOB CARD Sales Order:

305382425  
JC NO.:

CUSTOMER

COMFORT TRANSPORTATION PTE LTD  
MR/MS 7010045  
CUSTOMER 383 SIN MING DRIVE  
ADDRESS Singapore SINGAPORE 575717  
65508755

TEL. (R) (O)  
(P)

DISCOUNT CARD NO.:

REGN NO. SHC1126D

MILEAGE

MAKE: TOYOTA

FUEL

MODEL PRIUS HYBRID(G4) 18-02-2020 18:5

E 1/2  
DATE/TIME IN

YR OF MANU. 05-07-2017

TARGET DATE

CHASSIS CODE JTDKE3FU003561361


COMPLETION DATE/TIME

ent Date: 18.02.2020  
REF: 3P 18.02.2019

JOB DESCRIPTION

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Name:  
V/C No.: SHC1126D CHIANG  
vehicle No.:

Vehicle No.: SHC1126D

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

To be returned to Service Reception upon collection

To be kept by Security Guard

# ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300

**TP INSURER:** Tokio Marine Insurance Singapore Ltd (HQ)  
**CTPL**

Singapore

## PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	18/02/2020
Vehicle Reg. No.:	SHC1126D	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Vehicle Reg. Date:	05/07/2017
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	2ZRS056234	Chassis No:	JTDKB3FU003561361
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

## COST OF CLAIMS

	Amount
Parts	4,031.40
Miscellaneous Items	11.00
Labour	1,210.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (\$\$)</b>	<b>5,252.40</b>
<b>+ GST 7.00% (\$\$)</b>	<b>367.67</b>
<b>Nett Amount (\$\$)</b>	<b>5,620.07</b>

This claim is handled by: CHIANG LIAT CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**REPAIR DETAILS****Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 19 Feb 2020)**Parts:** 144 TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHC1126D/19/02/2020 17:05**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER COVER x (R)	25.00	0.00	*490.50 FL
2	1		*FRONT LH FENDER	25.00	0.00	*933.10 FL
3	1		*FRONT LH FENDER LINING	25.00	0.00	*198.50 FL
4	1		*FRONT LH FENDER HYBRID EMBLEM	25.00	0.00	*86.50 FL
5	1		*FRONT LH WHEEL COVER	25.00	0.00	*175.80 FL
6	1		*FRONT LH HEADLAMP ASSY	25.00	0.00	*3,413.80 FL
7	1		*FRONT LH BUMPER LH	25.00	0.00	*77.00 FL

F=Franchise part. L=ListItemDisc.

**Sub Total (S\$)** 5,375.20**- List Item Discount on L Items (S\$)** 1,343.80**Total Parts (S\$)** 4,031.40

ComfortDelGro Engineering Pte Ltd/SHC1126D/19/02/2020 17:05. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting.
- To display damaged part(s) during resurvey.
- Parts prices are subject to confirmation.
- Third party survey is on a "Without Prejudice" basis.
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer

Signature:

Date:

## Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	OD/TP Case (Insurer)	11.00
<b>Sub Total (\$\$)</b>			<b>11.00</b>

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	PANEL BEATING	New	640.00
2	SPRAY PAINTING	New	450.00
3	CHECK WIRING & LIGHTING	New	60.00
4	TUFF KOTE	New	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,210.00</b>

ComfortDelGro Engineering Pte Ltd/SHC1126D/19/02/2020 17:05. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*2/2/2020*  
*20/2/2020 13:30hrs*  
*Parasurama@lkk-auto.com*  
*88622778*  
*But print photo*  
*2 days*

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305382425  
 REGN NO : SHC1126D  
 MILEAGE : 0000000000  
 MAKE : TOYOTA  
 MODEL : PRIUS HYBRID(G4)  
 DATE OF REGN : 05.07.2017  
 DATE/TIME IN : 18.02.2020 18:50  
 ACCIDENT DATE : 18.02.2020

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001	04-01-0302-0574-A	PRIG4 FENDER SUB-ASSY FRO	1	933.10	25.00	699.82	Buc
0002	04-01-0302-2815-A	PRIG4 UNIT ASSY HEADLAMP	1	3,413.80	25.00	2,560.35	Scr
0003	03-01-0302-2057-G	PRIG4 CAP WHEEL	1	175.80	25.00	131.85	Scr
0004	04-01-0302-2297-G	PRIG4 EMBLEM SIDE PANEL (	1	86.50	25.00	64.87	na

SUB-TOTAL : 3,456.89

## JOB NATURE

0000	L	merimen	11.00
0001	PB	PANEL BEATING	640.00
0002	SP	SPRAYPAINT CHARGE	400.00
0003	17-01	CHECK ALL LIGHTING	50.00
0004	20-00	TUFF COAT ON AFFECTED PARTS.	30.00

SUB-TOTAL : 1,131.00

Our Job Ref No : 305382425

Date : 27/02/20

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK

Fax :

Attn : RAM

: SHC1126D

18/02/2020

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

Z The repair job shall bill to: TOKIO GBD4702L

2. The finalized amount shall be:

(a) Spare Parts after List discount

\$3,456.89<sup>90</sup>

(b) Labour Charges

\$1,131.00

**Total for Part-By-Part Repair Cost**

\$4,587.89<sup>90</sup>

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

**Final Lumpsum Repair cost**

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :

Name : CHIANG

Tel : 62148314

Fax : 65468156

Signature :

Name : Ram

Date : 2/3/2020

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TM20002921/FQF3N2  
Date: 12/03/2020

## REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MW009269  
Claimant Vehicle No: SHC1126D Insured Vehicle No: GBD4702L  
Date of Loss: 18/02/2020 Nature of Claim: TP Claim No: M2001340

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SHC1126D Engine No: 2ZRS056234  
Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A) Chassis No: JTDKB3FU003561361  
Reg. Date: 05/07/2017 (Man. Year: 2017) Odometer: 466014 km  
Colour: Blue  
Engine Capacity: 1798 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

## CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15  
Front Left Side: Davanti 8 mm Rear Left Side: Davanti 8 mm  
Front Right Side: Davanti 8 mm Rear Right Side: Davanti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,031.40	3,456.90	574.50	14.25
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,210.00	1,120.00	90.00	7.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,252.40</b>	<b>4,587.90</b>	<b>664.50</b>	<b>12.65</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>367.67</b>	<b>321.15</b>	<b>46.52</b>	<b>12.65</b>
<b>Nett Amount (S\$)</b>	<b>5,620.07</b>	<b>4,909.05</b>	<b>711.02</b>	<b>12.65</b>

## INSPECTION

Date of Assignment: 20/02/2020 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)  
Date Inspected: 20/02/2020 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)  
Estimated Period of Repair: 2.0 days 59 Loyang Drive  
Singapore 508969

Adjuster: PARASURAM SHANMUGAM

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Mar 2020)

Parts: 144 TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHC1126D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FRONT BUMPER COVER	Repair	490.50 FL	-	*- FL
2	1		*FRONT LH FENDER	Buckled	933.10 FL	-	*933.10 FL
3	1		*FRONT LH FENDER LINING	Not Necessary	198.50 FL	-	*- FL
4	1		*FRONT LH FENDER HYBIRD EMBLEM	Necessary	86.50 FL	-	*86.50 FL
5	1		*FRONT LH WHEEL COVER	Scratched	175.80 FL	-	*175.80 FL
6	1		*FRONT LH HEADLAMP ASSY	Scratched	3,413.80 FL	-	*3,413.80 FL
7	1		*FRONT LH BUMPER LH	Not Necessary	77.00 FL	-	*- FL

F=Franchise part, L=ListItemDisc.

Sub Total (S\$)	5,375.20	4,609.20
- List Item Discount on L Items 25.00/25.00% (S\$)	1,343.80	1,152.30
Total Parts (S\$)	4,031.40	3,456.90

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	11.00	11.00
<b>Sub Total (S\$)</b>			<b>11.00</b>	<b>11.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	640.00	640.00
2	SPRAY PAINTING	New	450.00	400.00
3	CHECK WIRING & LIGHTING	New	60.00	50.00
4	TUFF KOTE	New	60.00	30.00
<b>Gross Labour Cost (S\$)</b>			<b>1,210.00</b>	<b>1,120.00</b>

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;