



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 21/05/2020

User ID : CatherineLee

Section A - Accident Details

Registration Number	SMB1624D
Case Reference Number	BUS/02/20/5028
Registration Date	13/2/2015
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Dharsanakumar Ganesan
Type of Accident	Side Swipe
Accident Date and Time	17/2/2020 3:20 PM
Accident Reported Date and Time	17/2/2020 5:15 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24105802
Special Instruction to ARC, if any	SMB1624D-RIGHT SIDE VIEW MIRROR BROKEN GX2331Y (TP) INSURED WITH ERGO
Prepared Date and Time	19/2/2020 6:21 PM
Chassis Number	WMAA22ZZ8F7002609
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$530.00	\$265.00
Total Spray Cost	\$0.00	\$0.00
Total Spare Part Cost	\$896.33	\$896.33
Total Other Cost	\$200.00	\$200.00
TOTAL COST	\$1,626.33	\$1,361.33
Lump Sum Total	\$0.00	\$1,350.00
Number of Repair Days	1.0	0.5
Prepared / Adjusted By	Jeong Choon Hwee	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	19/02/2020 6:33 PM	22/02/2020 9:32 AM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 21/05/2020

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL FRONT VIEW MIRROR RH	\$530.00	\$265.00
Total Labour	\$530.00	\$265.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Spray Painting & Panel Beating		

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$200.00	\$200.00
Total Other Costs	\$200.00	\$200.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010161	BODY RH	4001M01-ACCE467	MIRROR,VIEW:FRONT,R H,FOR MAN	1.00	\$1,244.90	10.00	\$1,120.41	Replace	Replace
Total					\$1,244.90		\$1,120.41		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

$$\begin{array}{r} 1,120.41 \\ - 207.08 \\ \hline 896.33 \\ 265 \\ 200 \\ \hline 1,361.33 \end{array}$$

4S
\$1,350
0.5 days
half days