

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AXA INSURANCE PTE LTD			Ref : CC4/ASM20002963/R1pa3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:SAW THENG			Date: 16-07-2020 Code: ASM		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLZ 5822H	Veh. Inspected	FBD 7658L	
	Policy No.	GA530061	Coverage (\$)	0.00	
	Claim No.	S0M02FVY	Excess (\$)	0.00	
	Assign From		Assign Date	20/02/2020	
2. Vehicle Particulars & Condition					
	Make & Model	YAMAHA X-1R	c.c	135	
	Engine No.	HIDDEN	Year of Reg.	2009	
	Chassis No.	4S3303456	Colour	MULTI	
	Odometer	20876	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	80/90-17	MAXXIS	3 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	90/80-17	MAXXIS	3 mm	
	L/H Rear Tyre			mm	
4.					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S & N/S BODY.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	06/02/2020	Inspection Date	20/02/2020	
	Survey held at	•			
	BLOCK 1006 BUKIT MERAH LANE 2 #01-10 SINGAPORE 159762				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				