

ASS. REC. BY:

REF: CS31MSG 20002973/HFSJ⁹² Special Instruction:

Surveyor: Hock Ann

ASSIGNMENT (Office)

From (Person): Katharine Wong of MSIG Date/Time: 21.2.2020 9.57a.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLC 3201J Insured: SMJ 3570 U

at Workshop m/s Nuo Automotiva Tel: 9091 4853

of 53 Uls N11 105-44

Policy No: 29118576AVW Claim No: 62026

Sum Insured: Excess:

Make of Veh: D.O.A. 19.1.2020
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 21/2/20 10.16am Person Contacted: Mrs NEO Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SLC 3201J - NA LINC 19008848/13 REP - 12/05/2019
	SMJ 3570 U - X
21/2/20	→ surge take
21/2/20	→ range take
26/2/20	→ 4th part take

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Feb 2020		21 Feb 2020 09:57 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CAMLYN TAN , ID: S7231523E								
Main Claimant:	PRESTIGE LEASING P/L , Co. Reg. No.: 201723326H								
Vehicle Reg. No.:	SLC3201J	Date of Loss:	19/01/2020 10:00 - :59 [44 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 620216	Policy/Cover Note No.:	29118376AVW (Comprehensive) Coverage: 28/02/2019 - 27/02/2020						
Vehicle Reg. No. (Insured):	SMJ3570U	Policy No. (Claimant):							
		Excess:							
Repairer:	Neo Automotive Pte Ltd (HQ) 53 UBI AVE 1, #05-44 PAYA UBI INDUSTRIAL PARK, 408934 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 22/02/2020]								
Driver/Custodian (Insured):	SIM TONG BENG (/ Male), NRIC: S7032045B Email:								
Adj Asg. Remarks:	on WP. Liab: Clear. Car in as spoken with Mrs Neo Tks. WC.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/01/2020 17:49
Date Of Accident	19/01/2020 23:00
Exact Location Of Accident	323 CLEMENTI ARC 5 CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC3201J
Insured/Policyholder	
Name Of Registered Owner	PRESTIGE LEASING P/L
Co Reg No	2XXXXX326H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-91449265

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS-1.5 E GRADE (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	P2341220
Cover Note Number	

Driver

Name of Driver	LIM KUA AMM
NRIC No	SXXXX579Z
Date Of Birth	23/06/1967
Occupation	OUTDOOR
Date Of Driving Pass	21/04/1997
Driving Experience	22 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91441338
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address 53 UBI AVENUE 1
 #05-44 PAYA UBI INDUSTRIAL PARK
 Postcode 408934
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY KAREN - PROGRESSIVE CAR CARE PTE LTD TEL 6741 5336

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMJ3570U → (Vollkammer)
 Vehicle Make/Model/Colour Skoda 2.0
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	326H
Vehicle Details	
Vehicle No.:	SLC3201J
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Feb 2020
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E GRADE 1.5 A/T
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	1NZZ325275
Chassis No.:	MHFBT9F3X06068426
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$13,725.00
Original Registration Date:	10 May 2016
First Registration Date:	10 May 2016
Transfer Count:	2
Actual ARF Paid:	\$13,725.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 May 2026
PARF Rebate Amount:	\$10,293.00
Intended COE Rebate Details	
COE Expiry Date:	09 May 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,504.00
COE Rebate Amount:	\$28,246.00
Total Rebate Amount:	\$38,539.00

- 6862

The information contained herein is correct as at 24 Feb 2020

OK

Find your perfect drive and save up to \$22,500*



Find out more

*Terms and conditions apply.

Search filters: Toyota Vios, Price Range, Depreciation, 2016, Vehicle Type

Home » Used Cars » Car Design Motor » Toyota Vios 1.5A E

Toyota Vios 1.5A E

Overview Financial Insurance Accessories Similar Research Photos Map

Vehicle specifications table including Price (\$50,800), Depreciation (\$7,050/yr), Mileage (55,945 km), Road Tax (\$684/yr), Dereg Value (\$38,649), COE (\$45,504), Engine Cap (1,497 cc), Curb Weight (1,045 kg), Type of Vehicle (Mid-Sized Sedan), Reg Date (20-May-2016), Manufactured (2015), Transmission (Auto), OMV (\$13,699), ARF (\$13,699), Power (80.0 kW), No. of Owners (3).



Features

Fuel Saver, ABS Braking System, SRS Airbags, Reliable 1.5L DOHC 16 Valves VVT-I Engine, Smooth Auto Transmission. View specs of the Toyota Vios (2013-2017)

Accessories

Sports Rims, Factory Fitted Audio System, DVD Player, LCD Monitor, Solar Films.

Description

Reliable Workhorse. Super Fuel Economical Consumption. Interior And Exterior In Excellent Condition. Flexible Loan Available Up To 100%. Purchase With Us As A Case-Trust Accredited Company In Town For 22 Years. Call Us Now!

Category

PARF Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more




Car Valuation - Free

Find out the market value of your existing car for free. Get started

Posted on: Compare

ited on: 22-Feb-2020

Price Chart



Shortlist Compare Add to Report Error More Actions

Seller Information

Car Design Motor

17 vehicles for sale. 22 sold in past 3 mths

61 Ubi Avenue 2 #05-05

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Feb 2020		21 Feb 2020 09:57 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CAMLYN TAN , ID: S7231523E								
Main Claimant:	PRESTIGE LEASING P/L , Co. Reg. No.: 201723326H								
Vehicle Reg. No.:	SLC3201J	Date of Loss:	19/01/2020 10:00 - :59 [44 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 620216	Policy/Cover Note No.:	29118376AVW (Comprehensive) Coverage: 28/02/2019 - 27/02/2020						
Vehicle Reg. No. (Insured):	SMJ3570U	Policy No. (Claimant):							
		Excess:							
Repairer:	Neo Automotive Pte Ltd (HQ) 53 UBI AVE 1, #05-44 PAYA UBI INDUSTRIAL PARK, 408934 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Imm.Advice due 22/02/2020]								
Driver/Custodian (Insured):	SIM TONG BENG (/ Male) , NRIC: S7032045B Email:								
Adj Asg. Remarks:	on WP. Liab: Clear. Car in as spoken with Mrs Neo Tks. WC.								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLC3201J (620216)**
[SMJ3570U]
TP
PRESTIGE LEASING P/L
Jan 19 2020 10:00AM
[CAMLYN TAN]
Neo Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter			View	View in Browser ▾
Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	24/02/20 10:10	Chassis Number		Load JPG <input checked="" type="checkbox"/>
2	24/02/20 10:10	Odometer Reading		Load JPG <input checked="" type="checkbox"/>
3	24/02/20 10:11	General View		Load JPG <input checked="" type="checkbox"/>
4	24/02/20 10:11	General View		Load JPG <input checked="" type="checkbox"/>
5	24/02/20 10:11	General View		Load JPG <input checked="" type="checkbox"/>
6	24/02/20 10:11	General View		Load JPG <input checked="" type="checkbox"/>
7	24/02/20 10:11	General View		Load JPG <input checked="" type="checkbox"/>
8	24/02/20 10:11	General View		Load JPG <input checked="" type="checkbox"/>
9	24/02/20 10:11	General View		Load JPG <input checked="" type="checkbox"/>
10	24/02/20 10:11	General View		Load JPG <input checked="" type="checkbox"/>
11	24/02/20 10:11	General View		Load JPG <input checked="" type="checkbox"/>
12	24/02/20 10:11	General View		Load JPG <input checked="" type="checkbox"/>
13	24/02/20 10:11	General View		Load JPG <input checked="" type="checkbox"/>
14	24/02/20 10:11	General View		Load JPG <input checked="" type="checkbox"/>
15	24/02/20 10:11	General View		Load JPG <input checked="" type="checkbox"/>
16	24/02/20 10:11	General View		Load JPG <input checked="" type="checkbox"/>
17	24/02/20 10:11	General View		Load JPG <input checked="" type="checkbox"/>
18	24/02/20 10:11	General View		Load JPG <input checked="" type="checkbox"/>
19	24/02/20 10:11	General View		Load JPG <input checked="" type="checkbox"/>
20	24/02/20 10:11	General View		Load JPG <input checked="" type="checkbox"/>
21	24/02/20 10:11	General View		Load JPG <input checked="" type="checkbox"/>
22	24/02/20 10:11	General View		Load JPG <input checked="" type="checkbox"/>
23	24/02/20 10:11	General View		Load JPG <input checked="" type="checkbox"/>
24	24/02/20 10:11	General View		Load JPG <input checked="" type="checkbox"/>
25	24/02/20 10:11	General View		Load JPG <input checked="" type="checkbox"/>
26	24/02/20 10:11	General View		Load JPG <input checked="" type="checkbox"/>
27	24/02/20 10:11	General View		Load JPG <input checked="" type="checkbox"/>
28	24/02/20 10:11	General View		Load JPG <input checked="" type="checkbox"/>
29	24/02/20 10:11	General View		Load JPG <input checked="" type="checkbox"/>
30	24/02/20 10:11	General View		Load JPG <input checked="" type="checkbox"/>
31	24/02/20 10:11	General View		Load JPG <input checked="" type="checkbox"/>
32	24/02/20 10:11	General View		Load JPG <input checked="" type="checkbox"/>
33	24/02/20 10:11	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
34	24/02/20 10:11	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
35	24/02/20 10:11	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	24/02/20 10:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	24/02/20 10:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	24/02/20 10:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	24/02/20 10:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	24/02/20 10:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	24/02/20 10:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	24/02/20 10:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	24/02/20 10:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	24/02/20 10:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	24/02/20 10:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	24/02/20 10:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	24/02/20 10:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	24/02/20 10:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
49	24/02/20 10:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
50	24/02/20 10:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
51	24/02/20 10:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
52	24/02/20 10:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
53	24/02/20 10:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
54	24/02/20 10:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
55	24/02/20 10:12	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
56	24/02/20 10:12	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
57	24/02/20 10:12	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
58	24/02/20 10:12	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
59	24/02/20 10:12	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
60	24/02/20 10:12	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
61	24/02/20 10:12	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
62	24/02/20 10:12	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
63	24/02/20 10:12	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
64	24/02/20 10:12	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
65	24/02/20 10:12	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
66	24/02/20 10:12	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
67	24/02/20 10:12	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
68	27/02/20 08:47	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
69	27/02/20 08:47	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
70	27/02/20 08:47	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
71	27/02/20 08:47	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
72	27/02/20 08:47	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
73	27/02/20 08:47	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/02/20 17:17	OI Gia Report	Load PDF	
2	20/02/20 17:17	TP SLC3201J Gia Report	Load PDF	
3	20/02/20 17:18	PRI from C Yogarajah LLC	Load PDF	
4	20/02/20 17:22	Policy	Load PDF	
5	20/02/20 17:33	email from opts	Load PDF	
6	20/02/20 17:34	email to workshop	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG20002973/HTF3S2
Date: 02/03/2020

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29118376AVW
Claimant Vehicle No :	SLC3201J	Insured Vehicle No :	SMJ3570U
Date of Loss:	19/01/2020	Nature of Claim:	TP
		Claim No:	620216

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC3201J	Engine No:	1NZZ325275
Make & Model:	TOYOTA VIOS, 1.5 E GRADE (A)	Chassis No:	MHFBT9F3X06068426
Reg. Date:	10/05/2016 (Man. Year: 2015)	Odometer:	280682 km
Colour:	Silver		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/50 R15	Rear Tyre Size:	195/50 R15
Front Left Side:	Grenlander 5 mm	Rear Left Side:	Grenlander 5 mm
Front Right Side:	Grenlander 5 mm	Rear Right Side:	Grenlander 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	21/02/2020	
Date Inspected:	21/02/2020	Inspected At: Neo Automotive Pte Ltd (HQ) 53 UBI AVE 1, #05-44 PAYA UBI INDUSTRIAL PARK Singapore 408934
Estimated Period of Repair:	4.0 days	

Adjuster: LEE HOCK ANN

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500.00 - \$3,300.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Mar 2020)

Parts: 143 TOYOTA VIOS 1.5 E GRADE (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLC3201J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >