

ASS. REC. BY:

REF: CS/TM12002984/ Fvf302

Special instructions:

S. Vektor: $\begin{pmatrix} 1 \\ 0 \\ 0 \end{pmatrix}$ Ram

ASSIGNMENT (Office)

From (Person): Jeffrey Tan

of TMI

Date/Time: 21.10.20 12:24 PM

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHB 438E

Insured:

SLZ 4500T

at Workshop m/s

Comfront del 1990

Tel-

6214 9300

of 59 loyang, Dmvs

Policy No: MT 10075 6

Claim No.

M 200 1363

Sum Insured:

Excess:

Make of Veh:

D.O.A. 20.2.20

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time

21.7. 2020 1:40 P.M.

Person Contacted:

Vehicle ☒ IN ☐ OUT

| Date/Time | Action/Instruction (✓) Estimate |
|-----------|--|
| | SHB 4132 E - (C4) FCI 20001214/1143 Jan - 20 / 01 / 2000 |
| | SLZ 4500 T - X |
| | |
| 24/2/20 | Send preli revised via merimen |
| | |

Our Job Ref No : 305382728
Date : 28/02/20

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : RAM
: SHB4138E

Fax :


20/02/2020


The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO SLZ4500T
2. The finalized amount shall be:
- (a) Spare Parts after List discount _____
- (b) Labour Charges _____
- Total for Part-By-Part Repair Cost** _____
- (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: _____
Final Lumpsum Repair cost \$1,500.00

3. Estimated normal period for repairs: 3 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : CHIANG
Tel : 62148314
Fax : 65468156

Signature : 
Name : RAM
Date : 28/02/2020

For Official Use Only

| Item | Amount | Document Attached Yes or No | Confirm By (Signature) | Remarks |
|---|--------|--------------------------------|---------------------------|---------|
| 1. Rental Rate P/Day | | YES | | |
| 2. Loss of Income Paid | | N | | |
| 3. Survey Fees | | | | |
| 4. LTA Search Fee | 7.49 | | | |
| 5. Medical Fees (on behalf of driver, if applicable) | | | | |
| 6. Overrun | | | | |

Remarks:

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

| | 21 Feb 2020 | 21 Feb 2020 | 21 Feb 2020 | Policy No. | Policy Submitted | Not Authored | Status |
|------|-----------------------------|----------------------|-----------------|------------|------------------|--------------|--------------------------------------|
| Main | 21 Feb 2020 Sendback Est | 11:23 S\$2,356.78 | 12:22 Assign | | | | New Assignment Cancel Case |

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

| | | | |
|-----------------------------|--|------------------------|--|
| Insured: | WANG TING, ID: S8573620E | | |
| Main Claimant: | CTPL | | |
| Vehicle Reg. No.: | SHB4138E | Date of Loss: | 20/02/2020 17:00 - :59 [57 Months and 28 Days From LTA Reg Date (Man Yr)] |
| Claim Type: | TP / M2001363 | Policy/Cover Note No.: | MT100756 (Comprehensive) Coverage: 02/05/2019 - 01/05/2020 |
| Vehicle Reg. No. (Insured): | SLZ4500T | Policy No. (Claimant): | |
| | | Excess: | S\$0.00 |
| Repairer: | ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300 | | |
| Handling Insurer: | Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Jeffrey Tay - 65926413] | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/03/2020] | | |
| Adj Asg. Remarks: | OI HAS NOT RPT THE ACCDT | | |

ASSOCIATED MAIL RECEIVED

View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All Search Tasks Create New Task Complete

| ID | Task Name | Assigned By | Completed On | Created On | Done? |
|-------------|-----------|-------------|--------------|------------|-------|
| No results. | | | | | |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

| | | | |
|----------------------------------|--|-------|---|
| To: | Tokio Marine Insurance Singapore Ltd 20 McCallum Street #09-01 Tokio Marine Centre Singapore 069046 | From: | LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933 |
| Attn: | Jeffrey Tay | Date: | 24 Feb 2020 |
| <u>Preliminary Advice</u> | | | |

| | | | |
|--------------------|-------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SLZ4500T | Accident Date | : 20/02/2020 |
| TP Vehicle No | : SHB4138E | Assignment Date | : 21/02/2020 |
| Make | : HYUNDAI I40 | Est. Duration of Repair | : 3 |
| Date of Inspection | : 21/2/2020 | | |
| Inspection At | : COMFORTDELGRO ENGINEERING PTE LTD | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

| | | |
|---------------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 2,356.78 |
| Revised Amount | :S\$ | 1,877.10 |
| Check Items (Estimated) | :S\$ | 342.72 |
| Total | :S\$ | 2,219.82 |
| Lump Sum Repair | :S\$ | |
| Total Loss Consideration | | |
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | |
| COE / PARF Rebate | :S\$ | |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | |

Remarks

| | |
|-------------------------------------|---|
| <input type="checkbox"/> | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation. |
| <input type="checkbox"/> | The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck. |
| <input checked="" type="checkbox"/> | Other comments :The above survey was conducted on a 'Without Prejudice' basis. |

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|---|--------------------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Company |
| Owner ID: | 821R |
| Vehicle Details | |
| Vehicle No.: | SHB4138E |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 24 Feb 2020 |
| Vehicle Make: | HYUNDAI |
| Vehicle Model: | I40 1.7L CRDI AT ABS AIRBAG 4DR |
| Primary Colour: | Blue |
| Manufacturing Year: | 2015 |
| Engine No.: | D4FDEU410028 |
| Chassis No.: | KMHLB41UMFU068117 |
| Maximum Power Output: | 100.0 kW (134 bhp) |
| Open Market Value: | \$20,157.00 |
| Original Registration Date: | 23 Apr 2015 |
| First Registration Date: | 23 Apr 2015 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$12,720.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 22 Apr 2023 |
| PARF Rebate Amount: | \$9,540.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 22 Apr 2023 |
| COE Category: | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years): | 8 |
| PQP Paid: | \$50,177.00 |
| COE Rebate Amount: | \$19,840.00 |
| Total Rebate Amount: | \$29,380.00 |
| Message | |
| Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier. | |

The information contained herein is correct as at 24 Feb 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|--|
| Date Of Report | 21/02/2020 09:53 |
| Date Of Accident | 20/02/2020 17:50 |
| Exact Location Of Accident | T JUNCTION OF YIO CHU KANG RD TWDS HOUGANG AND B |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------|
| Vehicle Registration Number | SHB4138E |
|-----------------------------|----------|

Insured/Policyholder

| | |
|--------------------------|--------------------------------|
| Name Of Registered Owner | COMFORT TRANSPORTATION PTE LTD |
| Co Reg No | 1XXXXX821R |
| Email Address | FLEETSAFETY@CDGETAXI.COM.SG |
| Mobile Phone No | |
| Alternative Phone No | OFFICE-65508768 |

Vehicle Particulars

| | |
|--|-------------|
| Manufacturer | HYUNDAI |
| Model | I40 |
| Exact Purpose for which vehicle was being used at time of accident | |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | TAXI |

Insurance Company

| | |
|---------------------------|--------------------------------|
| Name of Insurance Company | MS FIRST CAPITAL INSURANCE LTD |
| Type Of Coverage | THIRD PARTY FIRE AND/OR THEFT |
| Fleet Policy | YES |
| Policy Number | D-18088936MFSH |
| Cover Note Number | |

Driver

| | |
|----------------------|------------------------|
| Name of Driver | ROHINI B AMIN |
| NRIC No | SXXXX119A |
| Date Of Birth | 28/09/1948 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 20/12/1982 |
| Driving Experience | 37 YEARS AND 2 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-97730155 |
| Fax Number | |
| Contact Number | |
| Email Address | ROHINIAMIN48@GMAIL.COM |

| | |
|---|---------------------------------------|
| Address | BLK 448B SENGKANG WEST WAY #08-321 |
| Postcode | 792448 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OTHER - TAXI DRIVER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|--------------------------|
| Type Of Accident | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 2 |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

REFER ATTACHED

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | YES |
| Remarks/ Reasons: | - |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|-------------|
| Vehicle Registration Number | SLZ4500T |
| Vehicle Make/Model/Colour | HONDA |
| Details Of Properties | |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | WANG TING |
| NRIC/Passport Number | |
| Contact Number | |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | FRONT |
| No. Of Passenger (Including Driver) | |

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRADING CORPORATION PTE LTD
CO. REG. NO. 110303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: **Loke Wei Tieng**
NRIC/FIN No:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 20/2/2020 at about 17:50 hrs, I Ven A was driving straight at above said location without passenger. I reduced my car speed to stop when traffic light change from amber to red. Suddenly I felt an impact from behind. Ven B came from behind front portion collided onto the rear portion of my car. Some photo taken. No injury reported at the point of accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMPANY NAME: [Signature]
CO. REG. NO. 110000021R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Loke Wei Yeng
NRIC/FIN No.:



Date/Time: 21.02.2020 10:14

Page: 1

Team: ARC Repair TP(CLSO)

JOB CARD

Sales Order:

JC NO: 305382/28


| | | |
|---|--|--|
| CUSTOMER COMFORT TRANSPORTATION PTE LTD MS 7010045 CUSTOMER NO 383 SIN MING DRIVE ADDRESS Singapore SINGAPORE 575717 65508755 (R) (P) | REGN NO: SHB4138E MAKE: HYUNDAI MODEL: I-40 YR OF MANU: 23.04.2015 CHASSIS CODE: KMHLB41UMPU068117 | MILEAGE FUEL DATE/TIME IN: 21.02.2020 08:35 TARGET DATE COMPLETION DATE/TIME |
|---|--|--|

Accident Date: 20.02.2020

JOB DESCRIPTION

NATURE: 3P.20.12.2019

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Wedge Slip

Exit Pass

Vehicle No: SHB4138E

CHIANG

Vehicle No: SHB4138E

Signature

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CTPL

Singapore

PARTICULARS OF CLAIM

| | | | |
|----------------------------------|--|--------------------|-------------------|
| Claim Type: | THIRD PARTY | Ref. No: | |
| Policy No: | | Date of Loss: | 20/02/2020 |
| Vehicle Reg. No.: | SHB4138E | Driveable? | YES |
| Party At Fault: | UNKNOWN | | |
| Make/Model: | HYUNDAI I40, 1.7 L CRDI AT ABS AIRBAG 4DR (A) | Vehicle Reg. Date: | 23/04/2015 |
| Vehicle Colour: | BLUE | Gen Condition: | GOOD |
| Engine No: | D4FDEU410028 | Chassis No: | KMHLB41UMFU068117 |
| Odometer: | 0 KM | | |
| Paint Type: | | | |
| List Item Discount: | 20.00 % | | |
| Total Loss? | NO | | |
| Est. Duration of Repair (day) | 3 | | |
| Present Location: | COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) | | |

| COST OF CLAIMS | Amount |
|--------------------------|-----------------|
| Parts | 1,285.78 |
| Miscellaneous Items | 11.00 |
| Labour | 1,060.00 |
| Paintwork Labour | 0.00 |
| Towing | 0.00 |
| Gross Total (S\$) | 2,356.78 |
| + GST 7.00% (S\$) | 164.97 |
| Nett Amount (S\$) | 2,521.75 |

This claim is handled by: CHIANG LIAT CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 21 Feb 2020)**Parts:** 143 HYUNDAI i40 1.7 L CRDI AT ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHB4138E/21/02/2020 11:23**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

| No. | Qty | Part No. | Particulars | %Disc | %Depr | Amount |
|-----|-----|----------|---|-------|-------|------------|
| 1 | 1 | | *REAR BUMPER COVER <i>Ev</i> | 20.00 | 0.00 | *553.00 FL |
| 2 | 2 | | *REAR BUMPER BRACKET SIDE LH/RH <i>xm</i> | 20.00 | 0.00 | *71.20 FL |
| 3 | 10 | | *REAR BUMPER CLIPS <i>rec</i> | 20.00 | 0.00 | *22.00 FL |
| 4 | 1 | | *REAR BUMPER REINFORCEMENT <i>xm</i> | 20.00 | 0.00 | *428.40 FL |
| 5 | 1 | | *REAR BUMPER UNDER COVER <i>scr</i> | 20.00 | 0.00 | *225.50 FL |
| 6 | 1 | | *REVERSE SENSOR <i>DM</i> | 0 | 0.00 | *135.70 FS |
| 7 | 1 | | *REAR BUMPER MAT <i>rec</i> | 0 | 0.00 | *50.00 FS |
| 8 | 1 | | *BOOTLID TEL NO. STICKER <i>rec</i> | 0 | 0.00 | *30.00 FS |
| 9 | 1 | | *BOOTLID COMFORT STICKER <i>rec</i> | 0 | 0.00 | *30.00 FS |

F=Franchise part, S=SpcNett, L=ListItemDisc.

| | |
|--|-----------------|
| Sub Total (S\$) | 1,545.80 |
| - List Item Discount on L Items (S\$) | 260.02 |
| Total Parts (S\$) | 1,285.78 |

ComfortDelGro Engineering Pte Ltd/SHB4138E/21/02/2020 11:23. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

| No | Qty | Particulars | Amount |
|----------------------------|-----|----------------------|--------------|
| Miscellaneous Items | | | |
| 1 | 1 | OD/TP Case (Insurer) | 11.00 |
| Sub Total (S\$) | | | 11.00 |

Estimates on Labour

| No | Particulars | Lab.Type | Amount |
|--------------------------------|-----------------------------|----------|-----------------------|
| Labour Items | | | |
| 1 | PANEL BEATING | New | 420 420.00 |
| 2 | SPRAY PAINTING | New | 400 400.00 |
| 3 | REMOVE/REFIX REVERSE SENSOR | New | 80 80.00 |
| 4 | TUFF KOTE | New | 80 80.00 |
| 5 | CHECK WIRING | New | 80 80.00 |
| Gross Labour Cost (S\$) | | | 1,060.00 |

ComfortDelGro Engineering Pte Ltd/SHB4138E/21/02/2020 11:23, Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Signature
25/2/2020

Ram/LKC
21/02/2020 1340
RamSuman@LCCauto.ren
88622728
L/C
AF+ Repair photo
3000000005

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

















| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-----------------------------|--|--------------------------------------|--------------------------------------|--------------------------------|------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
| Main | 21 Feb 2020 Sendback Est | 21 Feb 2020 11:23 S\$2,356.78 | 21 Feb 2020 12:22 Edit Adj Rpt | S\$1,500.00 Edit Estimates | S\$1,500.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|----------------------------------|---|------------------------|--|---|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS | | | | | | | | | |
| Insured: | WANG TING , ID: S8573620E | | | | | | | | |
| Main Claimant: | CTPL | | | | | | | | |
| Vehicle Reg. No.: | SHB4138E | Date of Loss: | 20/02/2020 17:00 - :59 [57 Months and 28 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / M2001363 | Policy/Cover Note No.: | MT100756 (Comprehensive) Coverage: 02/05/2019 - 01/05/2020 | | | | | | |
| Vehicle Reg. No. (Insured): | SLZ4500T | Policy No. (Claimant): | | | | | | | |
| | | Excess: | S\$0.00 | | | | | | |
| Repairer: | ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300 | | | | | | | | |
| Handling Insurer: | Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Jeffrey Tay - 65926413] | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 03/03/2020] | | | | | | | | |
| Adj Asg. Remarks: | OI HAS NOT RPT THE ACCDT | | | | | | | | |
| ASSOCIATED MAIL RECEIVED | | | View All | Compose Case Mail | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS | | | View All | Search Tasks Create New Task Complete | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

SHB4138E (M2001363)
[SLZ4500T]
TP
CTPL
Feb 20 2020 5:00PM
[WANG TING]
ComfortDelGro Engineering Pte Ltd

| | | | | | | | | | | |
|--------------------|-----------------|--|---------------|-----------|-------------------------------------|--|------------|--|-------------------------------------|--|
| Upload Documents | | | Upload Photos | | Compose New Letter | | View | | View in Browser | |
| Assessment Reports | | | | | | | 1 per page | | <input checked="" type="checkbox"/> | |
| No | Finalized On | ComfortDelGro Engineering Pte Ltd (Loyang) | | Thumbnail | Print | | | | | |
| 1 | 21/02/20 11:23 | Repairer Estimates | 1 | Load HTM | | | | | | |
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail | Print | | | | | |
| 1 | 24/02/20 11:43 | Adjuster Immediate Advice | 1 | Load HTM | | | | | | |
| | | | | | | | 3 per page | | <input checked="" type="checkbox"/> | |
| Photos/Images | | | | | | | 3 per page | | <input checked="" type="checkbox"/> | |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail | Print | | | | | |
| 1 | 28/02/20 10:49 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 2 | 28/02/20 10:49 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 3 | 28/02/20 10:49 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 4 | 28/02/20 10:49 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 5 | 28/02/20 10:49 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 6 | 28/02/20 10:49 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 7 | 28/02/20 10:49 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 8 | 28/02/20 10:49 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 9 | 28/02/20 10:49 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 10 | 28/02/20 10:49 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 11 | 28/02/20 10:49 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 12 | 28/02/20 10:50 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 13 | 28/02/20 10:50 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 14 | 28/02/20 10:50 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 15 | 28/02/20 10:50 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 16 | 28/02/20 10:50 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 17 | 28/02/20 10:50 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 18 | 28/02/20 10:50 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 19 | 28/02/20 10:50 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 20 | 28/02/20 10:50 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 21 | 28/02/20 10:50 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 22 | 28/02/20 10:50 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 23 | 28/02/20 10:50 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 24 | 28/02/20 10:50 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 25 | 28/02/20 10:50 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 26 | 28/02/20 10:50 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 27 | 28/02/20 10:50 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 28 | 28/02/20 10:50 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 29 | 28/02/20 10:50 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 30 | 28/02/20 10:50 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 31 | 28/02/20 10:50 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 32 | 28/02/20 10:50 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | | | | | |

| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|--|--|-------------------------------------|
| No | Finalized On | ComfortDelGro Engineering Pte Ltd (Loyang) | Thumbnail | Print |
| 33 | 28/02/20 10:50 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 34 | 28/02/20 10:50 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 35 | 28/02/20 10:50 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 36 | 28/02/20 10:50 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 37 | 28/02/20 10:50 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 38 | 28/02/20 10:50 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 39 | 28/02/20 10:50 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 40 | 28/02/20 10:50 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 41 | 28/02/20 10:50 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 42 | 28/02/20 10:50 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 43 | 28/02/20 10:50 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 44 | 28/02/20 10:50 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 45 | 28/02/20 10:50 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 46 | 28/02/20 10:50 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | ComfortDelGro Engineering Pte Ltd (Loyang) | Thumbnail | Print |
| 1 | 21/02/20 11:24 | E-filed GIA report |  Load PDF | |
| No | Finalized On | Tokio Marine Insurance Singapore Ltd (HQ) | Thumbnail | Print |
| 1 | 21/02/20 15:00 | TP - SHB4138E - Singapore Accident Statement |  Load PDF | |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> | | | |
| Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | | | |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI20002984/FVF3E2

Date: 28/02/2020

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MT100756

Claimant Vehicle No: SHB4138E

Insured Vehicle No: SLZ4500T

Date of Loss: 20/02/2020

Nature of Claim: TP

Claim No: M2001363

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB4138E

Make & Model: HYUNDAI I40, 1.7 L CRDI AT ABS AIRBAG 4DR (A) Engine No: D4FDEU410028

Reg. Date: 23/04/2015 (Man. Year: 2015)

Chassis No: KMHLB41UMFU068117

Colour: Blue

Odometer: 597980 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | | |
|--------------------------|------|-------------------------|-----|--------------------------|------|
| General Condition: | Good | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: | Good |

CONDITION OF TYRES

| | | | |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size: | 205/60 R16 | Rear Tyre Size: | 205/60 R16 |
| Front Left Side: | Hankook 6 mm | Rear Left Side: | Hankook 6 mm |
| Front Right Side: | Hankook 6 mm | Rear Right Side: | Hankook 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-----------------|-----------------|---------------|--------------|
| Parts | 1,285.78 | 886.10 | 399.68 | 31.08 |
| Miscellaneous Items | 11.00 | 11.00 | 0.00 | 0.00 |
| Labour | 1,060.00 | 980.00 | 80.00 | 7.55 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 2,356.78 | 1,877.10 | 479.68 | 20.35 |
| Approved Total (Overridden) (S\$) | | 1,500.00 | | |
| (S\$) | 2,356.78 | 1,500.00 | 856.78 | 36.35 |
| + GST 7.00/7.00% (S\$) | 164.97 | 105.00 | 59.97 | 36.35 |
| Nett Amount (S\$) | 2,521.75 | 1,605.00 | 916.75 | 36.35 |

INSPECTION

Date of Assignment: 21/02/2020 Present Location:

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 21/02/2020 Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: PARASURAM SHANMUGAM**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|--|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 28 Feb 2020) |
| Parts: | 143 | HYUNDAI I40 1.7 L CRDI AT ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SHB4138E) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Reference | Amount |
|-----|-----|----------|---------------------------------|---------------|------------|-----------|------------|
| 1 | 1 | | *REAR BUMPER COVER | Cracked | 553.00 FL | - | *553.00 FL |
| 2 | 2 | | *REAR BUMPER BRACKET SIDE LH/RH | Not Necessary | 71.20 FL | - | *- FL |
| 3 | 10 | | *REAR BUMPER CLIPS | Necessary | 22.00 FL | - | *22.00 FL |
| 4 | 1 | | *REAR BUMPER REINFORCEMENT | Not Necessary | 428.40 FL | - | *- FL |
| 5 | 1 | | *REAR BUMPER UNDER COVER | Scratched | 225.50 FL | - | *225.50 FL |
| 6 | 1 | | *REVERSE SENSOR | Damaged | 135.70 FS | - | *135.70 FS |
| 7 | 1 | | *REAR BUMPER MAT | Necessary | 50.00 FS | - | *50.00 FS |
| 8 | 1 | | *BOOTLID TEL NO. STICKER | Necessary | 30.00 FS | - | *30.00 FS |
| 9 | 1 | | *BOOTLID COMFORT STICKER | Necessary | 30.00 FS | - | *30.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$\$) | 1,545.80 | 1,046.20 |
| - List Item Discount on L Items 20.00/20.00% (\$\$) | 260.02 | 160.10 |
| Total Parts (\$\$) | 1,285.78 | 886.10 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

| No | Qty | Particulars | Repairer's | Amount |
|----------------------------|-----|----------------------|------------|--------|
| <u>Miscellaneous Items</u> | | | | |
| 1 | 1 | OD/TP Case (Insurer) | 11.00 | 11.00 |
| Sub Total (S\$) | | | 11.00 | 11.00 |

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------|-----------------------------|----------|------------|--------|
| <u>Labour Items</u> | | | | |
| 1 | PANEL BEATING | New | 420.00 | 420.00 |
| 2 | SPRAY PAINTING | New | 400.00 | 400.00 |
| 3 | REMOVE/REFIX REVERSE SENSOR | New | 80.00 | 60.00 |
| 4 | TUFF KOTE | New | 80.00 | 50.00 |
| 5 | CHECK WIRING | New | 80.00 | 50.00 |
| Gross Labour Cost (S\$) | | | 1,060.00 | 980.00 |

| |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >