

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	07/09/2019 08:40
Date Of Accident	11/08/2019 01:00
Exact Location Of Accident	BLK 105 JALAN RAJAH - C/PARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD6782X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E220

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken REPORTING ONLY

Vehicle Category TAXI

### Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

### Driver

Name of Driver	SEA WEI LIP (XU WEILI)
NRIC No	S7220890J
Date Of Birth	19/09/1972
Occupation	OUTDOOR
Date Of Driving Pass	05/12/1994
Driving Experience	24 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91450880
Fax Number	
Contact Number	
EMail Address	DERRICK_SEAWEILIP@YAHOO.COM

Address	BLK 87 TAMPINES AVE 1 #03-30
Postcode	528688
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	TAMPINES NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER POLICE REPORT NO: T-20190905/2044 \* TYPE OF ACCIDENT :- TAXI REVERSED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	UNKNOWN
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	NO DAMAGED
No. Of Passenger (Including Driver)	

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

GIA/RIAC SketchPlanForm\_V3

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer Police Report- T/20190905/2044

Note: I am willing to settle the claim if the amount is affordable.

DECLARATION

I/We declare the foregoing particulars are true in every respect.  
COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

CMR/AC SketchPlanForm\_V3



**SINGAPORE  
POLICE FORCE**



T/20190905/2044

Police Station Of Origin:  
Tampines N.P.C  
6 Tampines Avenue 4 SINGAPORE 529682  
Tel No: 1800-5871999

1 of 3

Report No. T/20190905/2044

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 05/09/2019 11:39		Vide Report No.:		Station Diary No.: 26
<b>Informant's Particulars</b>				
Name of Informant: SEA WEI LIP		Address: 87 TAMPINES AVENUE 1 #03-30 SINGAPORE 528688		
ID Type / ID No.: NRIC NO / S7220890J		Contact No.: Home/Office: Mobile: 91450880		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 47	Date of Birth: 19/06/1972	Type of Informant: Driver	
Race: Chinese		Language:	Institution / School Name:	
Occupation: Taxi driver		Driving Licence Information: Class: 3 Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 11/08/2019 13:00	Type of Location: Car Park
Location: Along Road 1 JALAN RAJAH B/105 JALAN RAJAH OPEN CARPARK				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No	

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHD6782X	Car				No Damage	0

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20190905/2044

Police Station Of Origin:  
Tampines N.P.C  
6 Tampines Avenue 4 SINGAPORE 529682  
Tel No: 1800-5871999

2 of 3

Report No. T/20190905/2044

**CONTINUATION OF REPORT**

Driver			
Name	SEA WEI LIP	ID No.	S7220890J
Related Vehicle	SHD6782X (Car)	Contact No.	91450880
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On the 11/08/2019 at about 1300hrs, I went to B/105 Jalan Rajah in my vehicle bearing the plate number SHD6782X to drop off my passenger. After alighting my passenger at the said location, I wanted to make a 3-point turn to exit the carpark.

While I was reversing, I suddenly felt an impact coming from the rear of my taxi. As such, I went down from my taxi and assessed my taxi and another parked vehicle behind my taxi. There were no damages or scratches on either vehicle. As such, I drove off from there.

I wished to state that my taxi do not have any rear-facing camera installed. I also did not take down the other vehicle details as there were no damages after I made a check.



**SINGAPORE  
POLICE FORCE**



T/20190905/2044

Police Station Of Origin:  
Tampines N.P.C  
6 Tampines Avenue 4 SINGAPORE 529682  
Tel No: 1800-5871999

3 of 3

Report No. T/20190905/2044

## CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

G /

Sgt 3 MOHAMAD IZWAN BIN MOHAMAD  
ISHAK

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

05/09/2019 11:39

Officer In Charge Of Case:

TP / GIA /

Staff Sgt WONG SIEU LUI

Contact No.: 65476151

Classification Of Case:



SINGAPORE  
POLICE FORCE

Authentication Stamp  
NP168

SIGNATURE



Accident Photo





Accident Photo



Accident Photo



Accident Photo



**Accident Photo**





**DRIVETHRU**

**VFM PTE LTD**

210 TURF CLUB ROAD A47 THE GRANDSTAND SINGAPORE 287995  
TEL: +65 6291 3113 FAX: +65 6286 9000 Website: www.drivethru.com.sg

SMJ 8651L  
C180

**TAX INVOICE**

**BILL TO:**

**GARAGE B PTE LTD**

NO.1 Bukit Batok Crescent #05-55 Wcega Plaza

SINGAPORE 658064

Invoice No. : HA201909 -000017

Date : 30/09/2019

Terms : 7 DAYS

Page No. : 1

Vehicle No.	Description	QTY	Rate	Amount
SKX3499T	Mazda 8 2.3L 18/09/2019 – 30/09/2019 ( 12 DAYS)	1	\$ 2160.00	\$ 2160.00
			Total Amount (Included G.S.T)	\$ 2160.00

Kindly cross & make cheque payable to: **VFM PTE LTD**

**Bank Current A/C No.:** 003-933818-0

**Bank Name:** DBS

For VFM PTE LTD

*Shuy*



Authorised Signature




**Victory Recovery** (Business Reg No.: 53096358B)  
65 Teban Gardens Rd #23-617, Singapore 600065.  
Mobile: 9618 0311 Fax: 6267 8996

CP-1908-0004E

CASH /  
W.O. No. 102319

**TOW JOB WORKS ORDER**

M cash Svc Date 13/8/19  
Car Make/Model \_\_\_\_\_ Vehicle No. SMJ 8651  
M'ship/NRIC No./Card No. \_\_\_\_\_ Contact No. \_\_\_\_\_  
Time - Rec'd \_\_\_\_\_ Arrived 1530 Completed 1630  
Amount Charge S\$ 200 Tow Truck No GR 33 75X  
Destination (from) 3 Ubi Ave 3 (to) 66 idc  
Remark (if any) cash  
Tow Driver's Signature \_\_\_\_\_ Member's Signature BY: PL1909/0018



- |                                                   |                                                     |                                                |
|---------------------------------------------------|-----------------------------------------------------|------------------------------------------------|
| <input type="checkbox"/> Change Tyres & Towing    | <input type="checkbox"/> Using King Dolly           | <input type="checkbox"/> Use Car Carrier       |
| <input type="checkbox"/> Basement / Multi Carpark | <input type="checkbox"/> Low Spoiler / Low Oil Sump | <input type="checkbox"/> Release Brake / Shaft |
| <input type="checkbox"/> Causeway / 2nd Link      | <input type="checkbox"/> Accident / Over-turn       | <input type="checkbox"/> Loaded                |

Note : The owner or his representative is required to follow along to the towing destination, failing which the tow operator shall not be liable for any alleged damages to the car nor missing items from the same. Vehicle is towed at owner's risk. The tow operator accepts no responsibility for any damages to the owner's vehicle whilst being towed.

CP-1909-0064F




**Victory Recovery** (Business Reg No.: 53096358B)  
65 Teban Gardens Rd #23-617, Singapore 600065.  
Mobile: 9618 0311 Fax: 6267 8996

CASH /  
W.O. No. 102722

**TOW JOB WORKS ORDER**

M cash Svc Date 13/9/19  
Car Make/Model \_\_\_\_\_ Vehicle No. SMJ 8651  
M'ship/NRIC No./Card No. \_\_\_\_\_ Contact No. \_\_\_\_\_  
Time - Rec'd \_\_\_\_\_ Arrived 1140 Completed 1225  
Amount Charge S\$ 170 Tow Truck No GR 33 75X  
Destination (from) 66 idc (to) 66 idc  
Remark (if any) cash  
Tow Driver's Signature \_\_\_\_\_ Member's Signature BY: PL1909/0018



- |                                                   |                                                     |                                                |
|---------------------------------------------------|-----------------------------------------------------|------------------------------------------------|
| <input type="checkbox"/> Change Tyres & Towing    | <input type="checkbox"/> Using King Dolly           | <input type="checkbox"/> Use Car Carrier       |
| <input type="checkbox"/> Basement / Multi Carpark | <input type="checkbox"/> Low Spoiler / Low Oil Sump | <input type="checkbox"/> Release Brake / Shaft |
| <input type="checkbox"/> Causeway / 2nd Link      | <input type="checkbox"/> Accident / Over-turn       | <input type="checkbox"/> Loaded                |

Note : The owner or his representative is required to follow along to the towing destination, failing which the tow operator shall not be liable for any alleged damages to the car nor missing items from the same. Vehicle is towed at owner's risk. The tow operator accepts no responsibility for any damages to the owner's vehicle whilst being towed.

**GARAGE B PTE LTD**

(REGISTRATION NO.: 201539366H)  
NO 1 BUKIT BATOK CRESCENT  
#05-55 WCEGA PLAZA  
SINGAPORE 658064  
TEL: 65-6262 3295 FAX: 65-6262 3293  
Email : emailgarageb@gmail.com

**GARAGE B**  
車のガレージ

---

**CASH SALE**

SMJ8651L MERCEDES BENZ C180

BLK 105 JALAN RAJAH  
#04-77 SINGAPORE 320105

INVOICE NC TP/SMJ8651L/0040

DATE : 15.01.2020

ATTENTION TAY TZU GIN, AUDWIN GERARD

MILLEAGE : NIL

TERM : C.O.D

ITEM	DESCRIPTION	TOTAL (\$)
1	COST OF REPAIR (TP-19-09-002)	36,300.00

---

SINGAPORE DOLLAR THIRTY SIX THOUSAND THREE HUNDRED ONLY

TOTAL \$ 36,300.00

## Note:

1. All cheques should be crossed and made payable to

GARAGE B PTE LTD

Banker : OCBC SINGAPORE

SGD A/C NO.: 617-876933-001



---

AUTHORISED SIGNATURE



# PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189

Tel: 6315 1239, Fax: 6315 3298, Mobile: 9061 0543

Tay Tzu Gin, Audwin Gerard  
Blk 105 Jalan Rajah  
#04-77  
Singapore 320105

Invoice no:	POS0417/19
Date:	14 January 2020
Report no:	417M0919.GB
Vehicle :	SMJ8651L

## INVOICE

No	Item Description	Qty	Unit Price	Total Amount(\$)
01	Being charges for the inspection of the accident vehicle, transport and photographs.			1,817.00
SGD(\$): One Thousand Eight Hundred and Seventeen only			Payable Amount:	1,817.00

"Cheque should be crossed and made payable to "Pro-Option Services"

PRO-OPTION SERVICES



Authorised Signature

# PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189

Tel: 6315 1239, Fax: 6315 3298, Mobile: 9061 0543

## ACCIDENT VEHICLE INSPECTION REPORT

Report no : 417M0919.GB  
Vehicle no : SMJ8651L

### **1 REFERENCE**

Date of inspection : 19 September 2019  
Requested by : Tay Tzu Gin, Audwin Gerard  
Blk 105 Jalan Rajah  
#04-77  
Singapore 320105  
Type of survey : Independent  
Repairer : Garage B Pte Ltd  
No 1 Bukit Batok Crescent, #05-55 WCEGA Plaza, Singapore 658064  
Date of accident : 11 August 2019

### **2 VEHICLE DATA**

Make/model : **MERCEDES BENZ C 180 BLUEEFFICIENCY**  
Chassis no : WDD2040312A841442  
Engine no : 27491030042762  
Date of registration : 19 June 2013  
Engine capacity : 1595 cc  
Odometer reading : 86171 km  
Colour : Black

### **3 STATIC CONDITION CHECK**

Steering : Affected  
Foot brakes : Serviceable  
Hand brakes : Serviceable  
Paintwork : Good  
General Condition : Good

### **4 TIRE CONDITION CHECK**

	<u>RH/MAKE</u>	<u>LH/MAKE</u>	<u>SIZE</u>
Front tread	: 6 mm/Continental	6 mm/Continental	225/45R17
Rear tread	: 6 mm/Continental	6 mm/Continental	225/45R17

### **5 BRIEF DESCRIPTION OF DAMAGE**

Front bumper cover cut/warped/distorted, headlamps casing broken, front bonnet bent, front support top panel bent, headlamp panels bent, front and rear undercarriage parts damaged, automatic gearbox – gears jammed, etc. Please see para. 8 of this report for more details.

### **6 REMARKS**

This inspection is carried out on a "WITHOUT PREJUDICE" basis and I have not authorized any repairs.

### **7 RECOMMENDATION**

Cost of repairs : \$36,300.00 (lump sum)  
No. of days taken : Eleven (11)

**8 ASSESSMENT OF DAMAGE AND COSTS**Report no: 417M0919.GBVehicle no: SMJ8651L**A SPARE PARTS**

<u>Description</u>	<u>Qty</u>	<u>Assessed Condition</u>	<u>Repairer's Amount</u>	<u>Revised Amount</u>
Front bumper cover	1	cut/warped/distorted	1,450.00	1,450.00
Front bumper reinforcement	1	bent	700.00	700.00
Front bumper side retainer L/R	2	necessary	70.00	70.00
Front bumper centre bottom mount	1	broken	80.00	80.00
Front bumper centre grille	1	broken	160.00	160.00
Front license plate moulding	1	squashed/deformed	150.00	150.00
Front bonnet	1	bent	2,033.00	2,033.00
Tow-eye cover	1	to reuse	68.00	0.00
Front grille assy	1	broken	750.00	750.00
LH headlamp assy	1	casing broken	980.00	980.00
RH headlamp assy	1	casing broken	980.00	980.00
Headlamp support frame L/R	2	bent/distorted	500.00	500.00
Front support top panel	1	bent	109.00	109.00
Front support top panel top cover	1	scraped/warped	100.00	100.00
Front support top panel top cover clip	6	necessary	36.00	36.00
Front shock absorber LH	1	bent	600.00	600.00
Front steering knuckle arm LH	1	bent	700.00	700.00
Front upper control arm LH	1	bent	480.00	480.00
Front lower control arm LH	1	bent	500.00	500.00
Front wheel bearing c/hub set - LH	1	bearing noisy/notchy	1,480.00	1,480.00
Front stabiliser bar	1	bent	480.00	480.00
Front stabiliser bar link L/R	2	bent	150.00	150.00
Front stabiliser bar bracket L/R	2	warped	70.00	70.00
Front shock absorber RH	1	bent	600.00	600.00
Frontsteering knuckle arm RH	1	bent	700.00	700.00
Front upper control arm RH	1	bent	480.00	480.00
Front lower control arm RH	1	bent	500.00	500.00
Front wheel bearing c/hub set - RH	1	bearing noisy/notchy	1,480.00	1,480.00
Front suspension subframe	1	bent/distorted	3,250.00	3,250.00
Front suspension subframe mounting	2	bush cracked	300.00	300.00
Front brake disc dust plate	1	bent	125.00	125.00
Steering rack & pinion assy	1	motor jammed	7,200.00	7,200.00
Rear suspension subframe	1	bent/distorted	2,150.00	2,150.00
Rear stabiliser bar	1	bent	350.00	350.00
Rear stabiliser bar bracket L/R	2	warped	70.00	70.00
Rear stabiliser bar link L/R	2	bent	140.00	140.00
Rear wheel carrier LH	1	bent/distorted	1,950.00	1,950.00
Rear lower control arm LH	1	bent	350.00	350.00
Rear lower control arm cover LH	1	bent	40.00	40.00
Rear camber strut LH	1	bent	350.00	350.00
Rear tie rod LH	1	bent	180.00	180.00
Rear tie rod cover LH	1	to reuse	35.00	0.00
Rear LH control arm - top	1	bent	360.00	360.00
Rear LH control arm - rear	1	bent	380.00	380.00
Rear wheel carrier RH	1	bent/distorted	1,950.00	1,950.00
Rear lower control arm RH	1	bent	350.00	350.00
Rear lower control arm cover RH	1	bent	40.00	40.00
Rear camber strut RH	1	bent	350.00	350.00

NN

NC

NN

Report no: 417M0919.GB  
 Vehicle no: SMJ8651L

Rear tie rod RH	1 bent	NM X	180.00	180.00
Rear tie rod cover RH	1 to reuse		35.00	0.00
Rear RH control arm – top	1 bent	NM	360.00	360.00
Rear RH control arm – rear	1 bent		380.00	380.00
Front RH sport rim	1 scraped	6065 NC X	980.00	980.00
	Subtotal of the above	5458.50	38,241.00	38,103.00
	Discount	10% / 10%	3,824.10	3,810.30
	Subtotal 1:		34,416.90	34,292.70
(Special nett)	1 broken		35.00	35.00
Front number plate	1 broken		35.00	35.00
Front number plate frame			70.00	70.00
	Subtotal 2:			70.00
	Total cost of parts:		34,486.90	34,362.70

## B LABOUR

Labour charges to dismantle and remove damaged parts, renew and install; to cut out damaged body panel, install and weld new part; to pull, knock, straighten and reshape affected areas.	1,200.00	600	900.00
Spray painting of the affected parts and areas – front bumper, front support top panel, front bonnet, headlamp panels, etc.	1,500.00	600	1,200.00
To check all affected wiring and electrical parts for condition and rectify where needed.	120.00	30	60.00
To align headlamps and refocus headlamp beams.	90.00	30	60.00
To reinstall front parking sensors and check for sensing functions.	80.00	30	60.00
To apply anti-rust undercoat for the affected areas.	150.00	30	60.00
To supply labour and materials to repair/rebuild automatic gearbox – gears jammed.	5,000.00	X NN	4,500.00
To hoist up engine to facilitate the necessary repairs, and to reinstall after the repairs.	1,000.00	X NN	800.00
To remove and replace damaged front suspension subframe and undercarriage parts.	1,500.00	X NN	1,200.00
To remove and replace damaged steering rack & pinion assy. To centralise steering wheel and computer reset steering angle.	800.00	X NN	600.00
To remove and replace rear suspension subframe and undercarriage parts.	1,500.00	X NN	1,200.00
To conduct computerised 4-wheel alignment to align wheels.	150.00	X NN	120.00
Towing services.	150.00		150.00
		1470	
Total cost of labour:	13,240.00		10,910.00
Total cost of repair:	47,726.90		45,272.70

Report no: 417M0919.GB  
Vehicle no: SMJ8651L

**9 CONCLUSION**

The revised or adjusted cost of repairs to restore the vehicle is

\$45,272.70

(a) The recommended cost of repair based on lump sum basis would be

**\$36,300.00**

(b) The estimated number of days taken by the repairs would be

**Eleven (11)**

(1<sup>st</sup> Reinspection conducted on 20<sup>th</sup> September 2019)

(2<sup>nd</sup> Reinspection (gearbox dismantled) conducted on 24<sup>th</sup> September 2019)


(Post-Repair Inspection conducted on 30<sup>th</sup> September 2019)

*The above recommendations in my view are fair and reasonable for the restoration of the vehicle to its pre-accident condition.*

**Note: Lump Sum Repair Basis**

*This means the repairer is allowed to replace the damaged parts with used, reconditioned or new parts, or repair it to a roadworthy condition.*

Yours faithfully



Liaw Leong San  
Licensed Automotive Appraiser

Dated: 14 January 2020

6973.50.  
4585600.  
06 days