

Shian Shian  
un-2-

CS3/III/1902/015/Hqd3-1<sup>er</sup>

and Information

Menmen

Demick Tan

ASSIGNMENT (Office)

III

Date/Time: 19/02/2020

0

SLL 7956R

Injured:

SHA 1871X

M.S. Panel Beating

Tel:

9739 1788

2 Kaki Bukit Ave 2 # 02-17 Autohub

MCOM0015

Claim No:

MCT 19110637

Excess:

D.O.A. 26/11/19

CASE REV / RES / DEV / MTR

R.O.D. Endorsement:

4:47pm @ 27/11/19

Present Charge(s):

Mr. Koh

Vehicle IN/OUT

DATE OF

X

Dismantle recovery - 29/11/19 01:33PM

After paint - 04/12/19 01:43PM


Submit PAS

20/12/19

28/1/20

Submit US \$3000, 4 days.

(Red \$3000, 50%).



27/2/2020

RECEIVED 26 FEB 2020

260+11=261

261-131=130

PRS

TH

28/11/19

ASSIGNMENT

WS / P / RES / C / RES / EVA / MV / MV

SLL 7956R

M.S. Panel Beating

2 Kaki Bukit Ave 2 #02-17

Autohub

After 10am  
Mr. Koh



The veh had commenced its repair at the time of inspection.

Consistent? Yes or No

Consistent? Yes or No

4 days Rep: Yes or No

Yes or No

CA / REV / REF / 24 HRS

Vehicle IN / OUT

Vehicle: SLL 7956R vs Regn 10/03/2019  
Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: M4 Forte CC: 1571

Salvage: A/C Insured / Std / NI / NA

Sp Reading: 779284 T/Radio: Insured / Std / NI / NA

Engine

C/Nr: KNAFJ411M45708213

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/65/R15

R: 175/65/R15

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 47mm R/Bal: 47mm

L/Bal: 47mm

D.O.A: 28/11/19 D.O.I: 28/11/19 12:15PM

Survey held at: M.S. Panel Beating

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

RECEIVED DEC 2019

PRB Report

PRB Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Other:

Other:

Other:

Other:

Other:

120

11

131

## Nivitha (LKK Auto)

---

**From:** Hsiao Tong (LKKAuto) <chewht@lkkauto.com>  
**Sent:** Wednesday, 19 February 2020 5:58 PM  
**To:** Derrick Tan; SUR; assignments  
**Cc:** Zuhaidah Samsuri; KKLau; Olivia Lau (LKKAuto)  
**Subject:** RE: PAPER SURVEY SLL7956R III REF: MCT19110637 //LKK REF: CS3/III19021015/Hqd3e2

Dear Sirs/Mdm,

Contents noted.

Hi SUR/Assign Team,

Kindly assist. CS3/III19021015/Hqd3e2

Best Regards,

**Hsiao Tong, Chew (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Derrick Tan <DerrickTan@iii.com.sg>  
**Sent:** Wednesday, 19 February 2020 4:49 PM  
**To:** KKLau <kklau@lkkauto.com>; Olivia Lau (LKKAuto) <olivialau@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>  
**Cc:** Zuhaidah Samsuri <aida@iii.com.sg>  
**Subject:** PAPER SURVEY SLL7956R III REF: MCT19110637

Dear Sir/Mdm,

Please conduct paper survey for the below TP vehicle and let us have your report urgently. LOD uploaded and rights granted to you in Merimen.

TP Veh No. : SLL7956R.

Thank you.

Derrick Tan  
Motor & Work Injury Claims Department

India International Insurance Pte Ltd  
64 Cecil Street, #04/#05 IOB Building, Singapore 049711  
Tel: 6347 6100, Ext – 264

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K



INDIA  
INTERNATIONAL  
INSURANCE  
SINGAPORE  
Serving the region since 1987

INDIA INTERNATIONAL INSURANCE PTE LTD

Co. Reg. No. 198703792K | GST Reg. No. M2-0078806-X  
1st Cash Street #04 & #05 10th Building Singapore 049711

Office (65) 63476100 Email insure@iil.com.sg  
Fax (65) 62244174 Website www.iil.com.sg

PRESERVE

MC 7/19/11 0637/01/25

UNINSURED LOSS

PRESERVE

5K ↑

SUBRO

PRESERVE

LPPN

P-S

INVESTIGATION FEE

SURVEY FEES

LEGAL FEES

1. KIC

fel

OTHERS

FRAUD CHECK


UPLOAD TO MERIMEN

GRANT RIGHTS

\*\*\*\*\*  
 \*\*\* TX REPORT \*\*\*  
 \*\*\*\*\*

TRANSMISSION OK

TX/RX NO 2674  
 RECIPIENT ADDRESS 65361860  
 DESTINATION ID  
 ST. TIME 13/01 09:50  
 TIME USE 01'16  
 PAGES SENT 2  
 RESULT OK



# ORACLE LAW CORPORATION

Advocates &amp; Solicitors

BRN:200904b/2L

Our Reference : SB/PO/Acc/2019-9203  
 Date : 9th January 2020



\*\* BY HAND ONLY \*\*

*M. S. Panel Betty Dorning*

**India International Insurance Pte Ltd**  
 64 Cecil Street #04-05  
 IOB Building  
 Singapore 049711  
Attention: Motor Claims Department

**Comfort Transportation Pte Ltd**  
 383 Sin Ming Drive  
 GAS Building  
 Singapore 575717

\*\* BY POST ONLY \*\*

**Mr Yeo Cheng Kiew**  
 Block 604 Ang Mo Kio Avenue 5  
 #02-2691  
 Singapore 560604

\*\* BY POST ONLY \*\*

Dear Sir,

**ACCIDENT INVOLVING SLL 7956R & SHA 1871X AT JUNCTION OF FRENCH ROAD AND HORNE ROAD ON 26.11.2019**

We act for Mr Quek Ting Chye Frankie, the owner of vehicle registration no. SLL 7956R which was involved in the above captioned accident.

We are instructed by our client to claim damages against the authorized driver of your Insured's taxi registration no. SHA 1871X, namely Mr Yeo Cheng Kiew, in connection with the above captioned accident.

We are instructed that the accident was caused by Mr Yeo Cheng Kiew's negligent driving and management of your Insured's said taxi registration no. SHA 1871X. As a result of the above captioned accident, our client's said vehicle was damaged and our client has been put to loss and expenses, particulars of which are as follows:-

## PARTICULARS

- | Description   | Amount       |
|---|--------------|
| 1. Cost of Repair   | S\$ 6,000.00 |
| 2. Loss of use (9 days @ S\$200.00 per day - PRI & weekend) | S\$ 1,800.00 |
| 3. Costs contribution                                       | S\$ 1,200.00 |

**Amount**  
 S\$ 6,000.00  
 S\$ 1,800.00  
 S\$ 1,200.00

# ORACLE LAW CORPORATION

Advocates & Solicitors

BRN-2009045722

Our Reference : SB/PO/Acc/2019-9203  
Date : 9th January 2020

**India International Insurance Pte Ltd**  
64 Cecil Street #04-05  
IOB Building  
Singapore 049711  
Attention: Motor Claims Department


**\*\* BY HAND ONLY \*\***



**Comfort Transportation Pte Ltd**  
383 Sin Ming Drive  
GAS Building  
Singapore 575717

**\*\* BY POST ONLY \*\***

**Mr Yeo Cheng Kiew**  
Block 604 Ang Mo Kio Avenue 5  
#02-2691  
Singapore 560604



**\*\* BY POST ONLY \*\***

13/1/2020

Dear Sirs

**ACCIDENT INVOLVING SLL 7956R & SHA 1871X AT JUNCTION OF FRENCH ROAD AND HORNE ROAD ON 26.11.2019**

We act for Mr Quek Ting Chye Frankie, the owner of vehicle registration no. SLL 7956R which was involved in the above captioned accident.

We are instructed by our client to claim damages against the authorized driver of your insured's taxi registration no. SHA 1871X, namely Mr Yeo Cheng Kiew, in connection with the above captioned accident.

We are instructed that the accident was caused by Mr Yeo Cheng Kiew's negligent driving and management of your insured's said taxi registration no. SHA 1871X. As a result of the above captioned accident, our client's said vehicle was damaged and our client has been put to loss and expenses, particulars of which are as follows:-

## PARTICULARS

<u>Description</u>	<u>Amount</u>
1. Cost of Repair	S\$ 6,000.00
2. Loss of use (9 days @ S\$200.00 per day - PRI & weekend)	S\$ 1,800.00
3. Costs contribution	S\$ 1,200.00
4. Disbursements:-	
a. Survey report fees	S\$518.00
b. Traffic police, GIA reports fees & LTA fees	S\$ 36.49
c. Xerox, transport & postage charges	S\$120.00
	<u>S\$ 674.49</u>
	<b><u>S\$ 9,674.49</u></b>

We enclose herewith a copy each of the following supporting documents for your kind attention:-

- Singapore Accident Statements of vehicle registrations no. SLL 7956R & SHA 1871X;
- LTA search result on taxi registration no. SHA 1871X;

.../2

**STANLEY BAY**  
LLB (Honours) Sheffield

**PAULINE ONG**  
LLB (Honours) Sheffield

**ALAN KOH**  
LLB (Honours) NUS

237 Alexandra Road  
#04-11 The Alexcior  
Singapore 159929

T (65) 6538 6250  
F (65) 6538 1860  
E mail@oraclelaw.sg

# Oracle Law Corporation

• Advocates & Solicitors • UEN/GST Reg No. 2009045722

Our Reference : SB/PO/Acc/2019-9203  
Date : 9<sup>th</sup> January 2020

Page 2

---

- c. M.S. Panel Beating Workshop's Invoice No. MS2019048 dated 18<sup>th</sup> December 2019 for the sum of S\$6,000.00;
- d. Auto Performance Appraisal's Tax Invoice No. APA19001947 dated 17<sup>th</sup> December 2019 for the sum of S\$518; and
- e. Original copy of Auto Performance Appraisal's Vehicle Survey Report No. 19/002049 dated 17<sup>th</sup> December 2019 together with photographs showing the damages sustained by our client's said vehicle.

We have on 27<sup>th</sup> November 2019 notified you of the above captioned accident and requested for a pre-repair inspection to be conducted.

Please note that if your insured has a counterclaim against our client arising out of the above captioned accident, you are also required to send to our firm a letter giving full particulars of the counterclaim together with all the relevant supporting documents within 8 weeks of your receipt of this letter.

Kindly note that you should send to our firm an acknowledgement of receipt of this letter within fourteen (14) days from the date hereof, failing which our client will have no alternative but to commence legal proceedings without further notice to you and/or your insured.

Yours faithfully



**Mr Stanley Bay / Miss Pauline Ong**

Encl (for India International Insurance Pte Ltd only)



# M.S. PANEL BEATING WORKSHOP

2 Kaki Bukit Ave 2 #02-17

AutoHub @ Kaki Bukit Singapore 417921

Hp. 91436036 Fax. 67478306 Email. Pauline.lim.lie.hwe@gmail.com

Quek Ting Chye Frankie  
C/O M.S. Panel Beating Workshop  
2 Kaki Bukit Ave 2  
#02-17 AutoHub @ Kaki Bukit  
Singapore 417921

**INVOICE NO : MS2019048**  
Date : 18/12/2019  
Vehicle number : SLL7956R  
Make/Model : Kia Fronte K3  
Accident Date : 26/11/2019

Total repair cost inclusive of spare parts  
and labour charges.

\$6,000.00

Singapore Dollars. Six Thousand Only

妙成嗎咭車廠  
M.S. PANEL BEATING WORKSHOP  
BLK 2 KAKI BUKIT AVE 2 #02-17  
AUTOHUB@KAKI BUKIT  
SINGAPORE 417921  
BRN 53182846M



---

M.S Panel Beating Workshop

## TAX INVOICE

Quek Ting Chye Frankie  
C/O M.S. Panel Beating Workshop  
2 Kaki Bukit Ave 2  
#02-17 AutoHub @ Kaki Bukit  
Singapore 417921

INVOICE NO : APA19001947

DATE : 17/12/2019

VEHICLE NO : SLL7956R

JOB REFERENCE NO : 19/002049

ACCIDENT DATE : 26/11/2019

SURVEY DATE : 29/11/2019

### DESCRIPTION

### AMOUNT

Survey Fees Inclusive Of Transportation	\$470.00
Photographs (\$1) Per Copies : 48	\$48.00

**TOTAL AMOUNT : \$518.00**

#### Notes :

All cheque payment should be "Crossed" and made payable to "Auto Performance Appraisal"

Auto Performance Appraisal



## VEHICLE SURVEY REPORTS

Quek Ting Chye Frankie  
C/O M.S. Panel Beating Workshop  
2 Kaki Bukit Ave 2  
#02-17 AutoHub @ Kaki Bukit  
Singapore 417921

### 1 Reference

Job Reference No : 19/002049  
Claim No : -  
Claim Type : Third Party  
Accident Date : 26/11/2019  
Survey Date : 29/11/2019  
Survey Report Date : 17/12/2019

### 2 Particulars Of Vehicle

Vehicle Registration No : SLL7956R  
Make & Model : Kia Forte K3  
Vehicle Registration Date : 10/03/2017  
Chassis No : KNAFJ411MH5708213  
Engine No : Blocked  
Colour : White

### 3 Condition Of Vehicle And Tyres

<u>Mileage (KM)</u>	<u>Brakes</u>	<u>Steering</u>	<u>Modification</u>
79908	Serviceable	Serviceable	None
<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Balance (MM)</u>
Front RHS	Continental	195/65R15	5
Front LHS	Continental	195/65R15	5
Rear RHS	Continental	195/65R15	6
Rear LHS	Continental	195/65R15	6

### 4 Description Of Damages

The vehicle sustained damages at frontal portion.  
(For information of damages please refer to Parts/Labour/Photographs attached)

### 5 Instruction

This survey was conducted entirely on a "WITHOUT PREJUDICE" basis, and we have not authorised any repair.

# AUTO PERFORMANCE APPRAISAL

Annex A

## Vehicle Assessment Reports

Ref No : 19/002049

### Damage And Repair Cost Adjustment

<u>S/No</u>	<u>Qty</u>	<u>Parts Description</u>	<u>Comments/condition</u>	<u>Workshop Estimate (\$)</u>	<u>Our Assessment (\$)</u>
<u>List Items</u>					
1	1	Front bumper ✓ CAA	Deformed	735.00	735.00 639.20 ✓
2	1	Front bumper RH tow cover ✓ SCR	Deformed	24.00	24.00 ✓
3	1	Front bumper lower air grille ✓ CAA	Deformed/cut	92.00	92.00 ✓
4	1	Front bumper side retainer ✓ H only ✓	Deformed/necessary	58.00	58.00 29 ✓
5	1 set	Front bumper clips ✓	Broken/necessary	30.00	30.00 25 ✓
6	1	Front bumper inner foam ✓ CAA	Broken	117.00	117.00 ✓
7	1	Front bumper inner reinforcement X (R)	Dented/bent	410.00	410.00
8	1	Front bumper inner lower beam ✓ BT	Bent	124.60	124.60 98.40 ✓
9	1	Front grille ✓ CAA	Deformed/broken	230.00	230.00 ✓
10	1	Front grille top cover X (R)	Dented	56.70	56.70
11	1	Front grille top cover centre "KIA" ✓	Grazed/cut	37.00	37.00 ✓
12	2	Headlamp ✓ CAA	RH - Broken/cut, LH - SC	3,690.00	3,690.00 1037.00 ✓
13	1	Front bonnet X (SC)	To repair		
14	1	Front support panel ✓ CAA	Broken	776.00	776.00 652.50 ✓
15	1	Air con condenser X (SC)	Serviceable/reuse	697.00	-
				7,077.30	6,380.30
Less discount 10%				707.73	638.03
Total :				6,369.57	5,742.27
<u>Special Nett Items</u>					
16	1	Front number plate ✓ BT	Broken/buckled	45.00	45.00 30 ✓
Total :				45.00	45.00
Total Spare Parts :				6,414.57	5,787.27

# AUTO PERFORMANCE APPRAISAL

## Vehicle Assessment Reports

Annex B

Ref No : 19/002049

### Damage And Repair Cost Adjustment

Items	Job Description	Workshop Estimate (\$)	Adjusted Costs (\$)
1	To remove, jack out, straighten, panel beating, align and renew replaced parts.	1,000.00	<del>700.00</del> 600 ✓
2	To putty and respray painting on affected areas.	1,100.00	<del>800.00</del> 300 ✓
3	To remove, refix aircon condenser, pipes, drier vacuum and recharge gas.	150.00	<del>120.00</del> 80 ✓
4	To check wirings and lightings.	50.00	30.00 ✓
5	To supplied and applied anti rust treatments.	100.00	<del>60.00</del>
Total Labour :		2,400.00	1,710.00
Total Spare Parts :		6,414.57	5,787.27
Total Labour :		2,400.00	1,710.00
Total Repair Costs :		8,814.57	7,497.27

### Assessor's Recommendation

Repairer Estimate : **8,814.57**  
Our Adjustment : **7,497.27**

### Remarks

The repairer has agreed to undertake the repair on a lump sum basis of \$6,000.00, with a repair period of 5 working days.

Surveyed By:

Lek Boon Hwee

Automobile Appraiser

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Prices are subject to confirmation
- Survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Parts 2983.30  
Parts less 10%  
2684.97  
Spc net 30  
Labour 1010  
3724.97  
2/5 less 20%  
2979.97  
↓  
\$3000

VEHICLE SURVEY REPORTS																																
<p>Quek Ting Chye Frankie  C/O M.S. Panel Beating Workshop  2 Kaki Bukit Ave 2  #02-17 AutoHub @ Kaki Bukit  Singapore 417921</p>																																
1	<b>Reference</b> Job Reference No : 19/002049 Claim No : - Claim Type : Third Party Accident Date : 26/11/2019 Survey Date : 29/11/2019 Survey Report Date : 17/12/2019																															
2	<b>Particulars Of Vehicle</b> Vehicle Registration No : SLL7956R Make & Model : Kia Forte K3 Vehicle Registration Date : 10/03/2017 Chassis No : KNAFJ411MH5708213 Engine No : Blocked Colour : White																															
3	<b>Condition Of Vehicle And Tyres</b> <table border="0"> <tr> <td><u>Mileage (KM)</u></td> <td><u>Brakes</u></td> <td><u>Steering</u></td> <td><u>Modification</u></td> </tr> <tr> <td>79908</td> <td>Serviceable</td> <td>Serviceable</td> <td>None</td> </tr> <tr> <td><u>Tyres</u></td> <td><u>Make</u></td> <td><u>Size</u></td> <td><u>Balance (MM)</u></td> </tr> <tr> <td>Front RHS</td> <td>Continental</td> <td>195/65R15</td> <td>5</td> </tr> <tr> <td>Front LHS</td> <td>Continental</td> <td>195/65R15</td> <td>5</td> </tr> <tr> <td>Rear RHS</td> <td>Continental</td> <td>195/65R15</td> <td>6</td> </tr> <tr> <td>Rear LHS</td> <td>Continental</td> <td>195/65R15</td> <td>6</td> </tr> </table>				<u>Mileage (KM)</u>	<u>Brakes</u>	<u>Steering</u>	<u>Modification</u>	79908	Serviceable	Serviceable	None	<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Balance (MM)</u>	Front RHS	Continental	195/65R15	5	Front LHS	Continental	195/65R15	5	Rear RHS	Continental	195/65R15	6	Rear LHS	Continental	195/65R15	6
<u>Mileage (KM)</u>	<u>Brakes</u>	<u>Steering</u>	<u>Modification</u>																													
79908	Serviceable	Serviceable	None																													
<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Balance (MM)</u>																													
Front RHS	Continental	195/65R15	5																													
Front LHS	Continental	195/65R15	5																													
Rear RHS	Continental	195/65R15	6																													
Rear LHS	Continental	195/65R15	6																													
4	<b>Description Of Damages</b> The vehicle sustained damages at frontal portion. (For information of damages please refer to Parts/Labour/Photographs attached)																															
5	<b>Instruction</b> This survey was conducted entirely on a "WITHOUT PREJUDICE" basis, and we have not authorised any repair.																															

# AUTO PERFORMANCE APPRAISAL

Annex A

## Vehicle Assessment Reports

Ref No : 19/002049

### Damage And Repair Cost Adjustment

<u>S/No</u>	<u>Qty</u>	<u>Parts Description</u>	<u>Comments/condition</u>	<u>Workshop Estimate (\$)</u>	<u>Our Assessment (\$)</u>
			<u>List Items</u>		
1	1	Front bumper	Deformed	735.00	735.00
2	1	Front bumper RH tow cover	Deformed	24.00	24.00
3	1	Front bumper lower air grille	Deformed/cut	92.00	92.00
4	2	Front bumper side retainer	Deformed/necessary	58.00	58.00
5	1 set	Front bumper clips	Broken/necessary	30.00	30.00
6	1	Front bumper inner foam	Broken	117.00	117.00
7	1	Front bumper inner reinforcement	Dented/bent	410.00	410.00
8	1	Front bumper inner lower beam	Bent	124.60	124.60
9	1	Front grille	Deformed/broken	230.00	230.00
10	1	Front grille top cover	Dented	56.70	56.70
11	1	Front grille top cover centre "KIA" logo	Grazed/cut	37.00	37.00
12	2	Headlamp	Broken/cut	3,690.00	3,690.00
13	1	Front bonnet	To repair		-
14	1	Front support panel	Broken	776.00	776.00
15	1	Air con condenser	Serviceable/reuse	697.00	-
				7,077.30	6,380.30
Less discount 10%				707.73	638.03
Total :				6,369.57	5,742.27
			<u>Special Nett Items</u>		
16	1	Front number plate	Broken/buckled	45.00	45.00
Total :				45.00	45.00
Total Spare Parts :				6,414.57	5,787.27

# AUTO PERFORMANCE APPRAISAL

## Vehicle Assessment Reports

Annex B

Ref No : 19/002049

### Damage And Repair Cost Adjustment

<u>Items</u>	<u>Job Description</u>	<u>Workshop Estimate (\$)</u>	<u>Adjusted Costs (\$)</u>
1	To remove, jack out, straighten, panel beating, align and renew replaced parts.	1,000.00	700.00
2	To putty and respray painting on affected areas.	1,100.00	800.00
3	To remove, refix aircon condenser, pipes, drier vacuum and recharge gas.	150.00	120.00
4	To check wirings and lightings.	50.00	30.00
5	To supplied and applied anti rust treatments.	100.00	60.00
Total Labour :		2,400.00	1,710.00
Total Spare Parts :		6,414.57	5,787.27
Total Labour :		2,400.00	1,710.00
Total Repair Costs :		8,814.57	7,497.27

### Assessor's Recommendation

Repairer Estimate : 8,814.57  
Our Adjustment : 7,497.27

### Remarks

The repairer has agreed to undertake the repair on a lump sum basis of \$6,000.00, with a repair period of 5 working days.

Surveyed By:



Lek Boon Hwee  
Automobile Appraiser



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	26/11/2019 17:23
Date Of Accident	26/11/2019 09:30
Exact Location Of Accident	FRENCH RD JUNC WITH HORNE RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL7956R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	QUEK TING CHYE FRANKIE
NRIC No	S1432773H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-87230233
Alternative Phone No	OFFICE-87230233

### Vehicle Particulars

Manufacturer	KIA
Model	FORTE K3
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5107294329
Cover Note Number	

### Driver

Name of Driver	QUEK TING CHYE FRANKIE
NRIC No	S1432773H
Date Of Birth	25/09/1960
Occupation	OUTDOOR
Date Of Driving Pass	28/06/1979
Driving Experience	40 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87230233
Fax Number	
Contact Number	OFFICE-87230233
EMail Address	NOEMAIL


## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and no copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that:
  - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the **"Personal Information"**) and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the **"Insurers"**), the insurers, lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purpose(s) of:
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the **"Purposes"**);
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers, lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the **above Purposes**; and
  - (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms); which may be sited outside of Singapore, for one or more of the **above Purposes**;
  - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
  - (e) the information so collected under (d) **above** may be shared / disclosed:
    - (i) to all insurers and/or any other third parties that assist in **evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated**; or
    - (ii) for complying with requirements under any regulations, laws or court orders;

  
Policyholder's Signature  
Date & Time

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time

  
Reporting Centre Personnel's Signature  
Name  
NRIC/IN No.

Accident Photo



Accident Photo



Accident Photo



Accident Photo



기아자동차(주)				KIA MOTORS CORPORATION	
기	차축	도장	외장		
SM	AXLE	PAINT	TRIM		
	SWP		WK		
형식	승인	번호			
APPD	MODEL	NO			
인년월일					
APPD DATE					
				kg	
				kg	
1-				kg	
2-				kg	



## SEARCH RESULTS

Our Ref No: GR-20-002967

Date of Request: 07/01/2020

Your Ref No: SB/PO/ACC/2019-9203

ORACLE LAW CORPORATION  
237 Alexandra Road #04-11  
The Alexcier  
Singapore 159929

Dear Sir/Madam,

**Your Search Criteria:**

Date of Accident: 26/11/2019

Place of Accident: JUNC OF FRENCH RD/HORNE RD

Client Vehicle No: SLL7956R

With reference to your search criteria for the accident report, the following documents were found to closely match your search criteria:

REQ. VEHICLE	ACCIDENT LOCATION	ACCIDENT DATE
SHA1871X	HORNE ROAD X FRENCH ROAD	26/11/2019 09:30

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.





RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

 6 Raffles Quay #18-00, Singapore 048580  
 Phone: +65 6224 0010 Fax: +65 6224 0030  
 Operating Hours: Monday to Friday 9am to 5pm  
 GST Registration No: M400017735
**TAX INVOICE**
 Our Ref No: GR-20-002969  
 Date of Request: 07/01/2020

Your Ref No: SB/PO/ACC/2019-9203

 ORACLE LAW CORPORATION  
 237 Alexandra Road #04-11  
 The Alexcier  
 Singapore 159929

Dear Sir/Madam,

 Date of Accident: 26/11/2019  
 Vehicle No: SLL7956R  
 Place of Accident: FRENCH RD JUNC WITH HORNE RD  
 Involving Vehicle No: SHA1871X

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SHA1871X	FRENCH RD JUNC WITH HORNE RD	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	26/11/2019 13:41
Date Of Accident	26/11/2019 09:30
Exact Location Of Accident	HORNE ROAD X FRENCH ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA1871X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
<b>Vehicle Particulars</b>	
Manufacturer	HYUNDAI
Model	I40
Vehicle Category	TAXI
<b>Insurance Company</b>	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	
<b>Driver</b>	
Name of Driver	YEO CHENG KIEW
NRIC No	S1113058E
Address	BLK 604 ANG MO KIO AVENUE 5 #02-2691

### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR

### Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
Number of Passengers (Including Driver)	1

### Circumstances of Accident

REFER POLICE REPORT NO: T/20191126/2130 \* TYPE OF ACCIDENT :- HEAD TO SIDE

### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

**SKETCH PLAN**

**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:


  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 26.11.2019@12:30hrs

**Lisa**  
Reporting Centre Personnel's Signature  
Name: -  
NRIC/FIN No.: -



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Ang Mo Kio South N.P.C  
81 Ang Mo Kio Avenue 3 SINGAPORE  
569929  
Tel No: 1800-4519999



T/20191126/2130

1 of 3

Report No. T/20191126/2130

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made:  
26/11/2019 16:39

Vide Report No.:

Station Diary No.:  
96

**Informant's Particulars**

Name of Informant:  
YEO CHENG KIEW

Address:  
APT BLK 604 ANG MO KIO AVENUE 5 #02-2691  
SINGAPORE 560604

ID Type / ID No.:  
NRIC NO / S1113058E

Contact No.:  
Home/Office: Mobile: 91995038

Nationality:  
SINGAPORE CITIZEN

Email:

Sex: Age: Date of Birth:  
Male 64 12/04/1955

Type of Informant:  
Driver

Race:  
Chinese

Language:  
English

Institution / School Name:

Occupation:  
Taxi driver

Driving Licence Information:  
Class: 2B,2A,2,3,4,5

Date of Expiry:

**General Information of the Accident**

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 26/11/2019 09:30	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 HORNE ROAD FRENCH ROAD Junction				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SHA1871X	Car	HYUNDAI	i40	Blue	Seriously Damaged	0
SLL7956R	Car			White	Slightly Damaged	0

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20191126/2130

Police Station Of Origin:  
Ang Mo Kio South N.P.C  
81 Ang Mo Kio Avenue 3 SINGAPORE  
569929  
Tel No: 1800-4519999

3 of 3




Report No. T/20191126/2130

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Sr Staff Sgt MOHAMMAD HAARIFAN BIN MOHAMMAD NASIR	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 26/11/2019 16:39
Officer In Charge Of Case: TP / AEIT / SI MOHAMAD ZULFAZDLI BIN ABDULLAH Contact No.: 65476204	Classification Of Case: 
Authentication Stamp NP168 	

Accident Photo



Accident Photo



Accident Photo





SCENE



SCENE



SCENE



SCENE





GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE  
6 Raffles Quay #18-00 Singapore 048580  
Tel (65) 6224 0010 Fax (65) 6224 0030  
Operating Hours : Monday to Friday, 09:00 – 17:00  
UEN: S665500200 / GST Reg. No.: M400017735

**IMPORTANT NOTE:** Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

### ADDENDUM

**(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:**

Original Report No : MCD619156073-01 Vehicle Registration No: SHA1871X  
Name (as shown in NRIC) : Yeo Cheng Kiew NRIC/FIN/Passport No : S xxxxx058E  
( Vehicle Driver / Vehicle Owner ) (\*) Please delete as appropriate  
Address : Blk 604 Ang Mo Kio Avenue 5 # 02-2691 Singapore (560604 )  
Contact (Tel) : - Mobile No. : 9199 5038  
Email Address : richardyck@gmail.com  
Date of Accident : 26.11.2019 Time of Accident : 09:30hrs  
Place of Accident : Horne Road x French Road  
Insurance Company : India International Insurance Pte Ltd

**(B) ADDITIONAL INFORMATION / AMENDMENTS:**

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Submit Police Report No: T/20191126/2130 and 3 days MC given by doctor.

 3/12/2019  
Policyholder / Driver's Signature  
Date:

Reporting Centre Personnel's Signature  
Name: Janet Lim  
NRIC/FIN No.:  
Date:

**Enquire Vehicle & Owner Information ( Vehicle No. SHA1871X As At 26 Nov 2019 / 09:30:00 )****Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: SB/PO/ACC/2019-9203

**Current Owner Details**

Owner ID Type: Company

Owner ID: 199303821R

Owner Name: COMFORT TRANSPORTATION PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.:383

Registered Street Name: SIN MING DRIVE

Registered Unit No.: -

Registered Building Name: GAS BUILDING

Registered Postal Code: 575717

**Current Vehicle Details**

Vehicle No.: SHA1871X

Make Description/Model: HYUNDAI / I40 1.7 CRDI F/L AT ABS AIRBAG 4DR

Insurance Company Name: INDIA INT'L INS PTE LTD

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	26/11/2019 13:41
Date Of Accident	26/11/2019 09:30
Exact Location Of Accident	HORNE ROAD X FRENCH ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA1871X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

### Driver

Name of Driver	YEO CHENG KIEW
NRIC No	S1113058E
Date Of Birth	12/04/1955
Occupation	OUTDOOR
Date Of Driving Pass	13/02/1975
Driving Experience	44 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91995038
Fax Number	
Contact Number	
EMail Address	RICHARDYCK@GMAIL.COM

Address	BLK 604 ANG MO KIO AVENUE 5 #02-2691
Postcode	560604
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER ATTACHED \* TYPE OF ACCIDENT :- HEAD TO SIDE

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL7956R
Vehicle Make/Model/Colour	KIA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	QUEK TING CHYE FRANKIE
NRIC/Passport Number	
Contact Number	87230233
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRONT
No. Of Passenger (Including Driver)	



**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 26.11.2019@12:30hrs

Lisa  
Reporting Centre Personnel's Signature  
Name: -  
NRIC/FIN No.:-

### SKETCH PLAN



A-SHA 1871X

B-SLL 7956R

**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

[illegible]

## DECLARATION

I/We declare the foregoing particulars are true in every respect.  
COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

Driver's Signature \_\_\_\_\_  
(If driver is not the policyholder)  
Date & Time: 26.11.2019@12:30hrs

**Lisa**  
Reporting Centre Personnel's Signature  
Name: ~  
NRIC/FIN No.: ~

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





SCENE



SCENE



SCENE



SCENE



SCENE



SCENE



SCENE



SCENE





SCENE





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL		Ref : CS3/III19021015/Hqd3e2-1	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 02-03-2020	
		Code : III2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHA 1871X	Veh. Inspected	SLL 7956R
Policy No.	MCOM0015	Coverage (\$)	0.00
Claim No.	MCT19110637	Excess (\$)	0.00
Assign From	DERRICK TAN	Assign Date	19/02/2020
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	KIA FORTE	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KNAFJ411MH5708213	Colour	WHITE
Odometer	79728	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	CONTINENTAL	4 mm
L/H Front Tyre	195/65 R15	CONTINENTAL	4 mm
R/H Rear Tyre	195/65 R15	CONTINENTAL	4 mm
L/H Rear Tyre	195/65 R15	CONTINENTAL	4 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	26/11/2019	Inspection Date	28/11/2019
Survey held at	M.S. PANEL BEATING WORKSHOP 2 KAKI BUKIT AVENUE 2 #02-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 7956R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	CRUMPLED	735.00	639.20
1	FRONT BUMPER RH TOW COVER	SCRATCHED	24.00	24.00
1	FRONT BUMPER LOWER AIR GRILLE	CRACKED	92.00	92.00
2	FRONT BUMPER SIDE RETAINER	N/S NECESSARY	58.00	29.00
1	SET FRONT BUMPER CLIPS	NECESSARY	30.00	25.00
1	FRONT BUMPER INNER FOAM	CRACKED	117.00	117.00
1	FRONT BUMPER INNER REINFORCEMENT	TO REPAIR SEE LABOUR	410.00	-
1	FRONT BUMPER INNER LOWER BEAM	BENT	124.60	98.40
1	FRONT GRILLE	CRACKED	230.00	230.00
1	FRONT GRILLE TOP COVER	TO REPAIR SEE LABOUR	56.70	-
1	FRONT GRILLE TOP COVER CENTRE "KIA" LOGO	NECESSARY	37.00	37.00
2	HEADLAMP	O/S BROKEN / CUT / N/S SERVICEABLE	3,690.00	1,039.20
1	FRONT BONNET (NPA)	SERVICEABLE	-	-
1	FRONT SUPPORT PANEL	CRACKED	776.00	652.50
1	AIR CON CONDENSER	SERVICEABLE	697.00	-
	LESS 10% DISCOUNT		-707.73	-298.33
			6,369.57	2,684.97
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT NUMBER PLATE (SN)	BENT	45.00	30.00
			45.00	30.00
<b><u>LABOUR</u></b>				
	TO REMOVE, JACK OUT, STRAIGHTEN, PANEL BEATING, ALIGN AND RENEW REPLACED PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER INNER REINFORCEMENT AND FRONT GRILLE TOP COVER.		1,000.00	600.00
	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS.		1,100.00	300.00
	TO REMOVE, REFIX AIRCON CONDENSER, PIPES, DRIER VACUUM AND RECHARGE GAS.		150.00	80.00

Report Ref No. CS3/III19021015/Hqd3e2-1



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRINGS AND LIGHTINGS.	NOT NECESSARY	50.00	30.00
	TO SUPPLIED AND APPLIED ANTI RUST TREATMENTS.		100.00	-
			2,400.00	1,010.00
GRAND TOTAL			8,814.57	3,724.97
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,000.00

Report Ref No. CS3/III19021015/Hqd3e2-1

LEE HOCK ANN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.