

City Auto PTE LTD
01-58/60/62 Sector C, Blk 8 Sin Ming
Industrial Estate
575643

Insurer Reference: GBE3835M TP
Repairer Reference: 029959
Date calculated: 20/02/2020 3:27 PM

Full Report
Registration: GBE3835M
Printed: 20/02/2020 3:27 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	India International Insurance
Printed by:	JASON QUAK	Currency:	SGD
Claim Reference:	GBE3835M TP	Date of Incident:	17/02/20
Estimated Repair Time:	4	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	PEUGEOT
Model:	PARTNER (7)
Sub Model:	BASE MODEL
Model Sheet Number:	11 68 01
Registration:	GBE3835M
VIN number:	VF37F9HF8FJ777111
Odometer:	

Model Specs

VAN	TWO PACK STRT COLOUR	PREPARE OFF VEHICLE
-----	----------------------	---------------------


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
74.004A	R + R REAR BUMPER		5.0	✓ 25.00
74.005A)	RENEW REAR BUMPER		2.0	✓ 10.00
74.004C	R + R BOTH REAR BUMPER CORNERS		2.0	✓ 10.00
74.004D	R + R REAR LOWER BUMPER MOULDING		2.0	✓ 10.00
NO NUMBER	R + R REAR BUMPER CROSSMEMBER		2.0	X 10.00
87.210L	R + R L/R UPPER WING DOOR HINGE		1.0	X 5.00
87.210L	R + R L/R LOWER WING DOOR HINGE		1.0	X 5.00
3079	L/R LOADING DOOR REPAIR		X 16.0*	80.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		3.10	31.0	155.00
Total of Labour				155.00

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description - TWO PACK STRT COLOUR		WU	Price SGD
	L/R LOADING DOOR REPAIR PAINTING <50%		19.0	✓

Paint Material Per Part

Code	Description	Price SGD
3079	L/R LOADING DOOR REPAIR PAINTING <50%	✓ 31.75

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor			
Time Paint		19.0	
Preparation Main Work Metal	1.90	19.0	95.00
Total	10 WU/h	3.80	38.0

Material Cost - Paint

	Price SGD
Repair Painting	31.75
Material-constant Metal Preparation	28.60
Total	60.35

Spare Parts

				prices as at 2001-01-01
Code	Description	Part Number	Supplier	Price SGD
2591	L/R BUMPER X <i>de</i>	7410 FN		170.00
3051	L/R LOWER HINGE X <i>de</i>	8717 C1		80.00
3049	L/R UPPER HINGE X <i>de</i>	8717 C0		80.00
2581	REAR BUMPER <i>de</i>	7410 GE		✓ 300.00
2640	REAR BUMPER C-MEMBER X <i>nn</i>	7414 ZF		230.00

Code	Description	Part Number	Supplier	Price SGD
2615	RR BUMPER BRKT SET	7416 J0		78.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			938.00
u: Used parts	Addition(+10.00%)			93.80
	Total			1,031.80

Extras

Code	Description	Price SGD
1000	70km/h sticker - <i>dec</i>	✓ 5.00*
1001	company sticker - <i>✓</i>	✓ 80- 180.00*
1002	reverse sensor - <i>X NN</i>	250.00*
	Total Extras	435.00

Final Calculation

	SGD	SGD
Parts		
Addition(+10.00%)	938.00	
Total Parts	93.80	1,031.80
Labour Time Base 10 WU/h		
Total 31.0 WU X 50.00 SGD/h	155.00	55.00
Total of Labour		155.00
Total Of Extras		85.00 435.00
Paint Work Time Base 10 WU/h		
Labour Cost 38.0 WU X 50.00 SGD/h	190.00	
Material Cost	60.35	
Total Paint Including Material		250.35
Repair Cost Excludes GST		1,872.15
GST (+7.0%)		131.05
Repair Cost Included GST		2,003.20

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

2 Days.
Unsur repair.
After repair photos.
GuoQiang - 82880282
25/2/2020.