

22/03/2002

ASS. REC. BY:

REF: CS/CTI 20003033/ksf3n2

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Tan Kah Loong

of CTI

Date/Time: 24.2.2002 9.50a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: Gx 6763H

Insured: GB13 178L

at Workshop m/s Eng Hung Automobi

Tel: 64835662

of BIK 10 H01-01 AMC Park 2 A Autopark

Policy No: DMCR5/A 1763619022

Claim No: SNM 2012 200913102

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 19.2.2002

CA / REV / REP. / REV 24 HRS

Date/Time: 24.2.2002 10.05a.m

Person Contacted: Judy

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (v) Estimate
	Gx 6763H - X
	GBB 178L - NSI/MC 110189601 4700 DOA - 24/2/2002
12/3	L/Sy @ 530d email & confirm (\$ 5,784.15 Red - 52%)

ASS. REC. BY:

REF:

C121

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: M / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 12 MAR 2020

Date/Time, File Pass to?

12/03/20

1)

Typist

Date/Time, File Return to?

2)



: Prell. Report



: Final Report

Days Of Repair:

12

Resurvey No. of Trip:

1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

220

Report Format:

Lump Sum / I.B.I. (\$

5,300/- L/S

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Feb 2020		24 Feb 2020 09:50 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: Main Claimant: JOINTECH ELECTRICAL & TRADING, Co. Reg. No.: 45104000K									
Vehicle Reg. No.: GX6763H		Date of Loss: 19/02/2020 07:00 - :59							
Claim Type: TP / SNM20D200913C02		Policy/Cover Note No.: DMCVSN17653619022							
Vehicle Reg. No. (Insured): GBB178L		Policy No. (Claimant): 5019503037-13							
		Excess: S\$350.00							
Repairer: Eng Heng Automobil Trading Co (HQ) Blk 10 #01-01 Ang Mo Kio Part 2A AutoPoint, 568047 Ang Mo Kio - Tel: 6483 5662									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/03/2020]									
				View All Compose Case Mail					
ASSOCIATED MAIL RECEIVED									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Monday, 24 February 2020 9:47 AM
To: Judy Goh; 'assignments'
Subject: Re: OUR REF: SNM20D200913/GBB178L/TKL - Notification and request for pre survey of an accident involving GX6763H and your insured GBB178L on 19 Feb 2020 at 7.55 am at KPE / MCE tunnel entrance near Sims Ave exit

WITHOUT PREJUDICE

Dear Judy,

We refer to your email below.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Judy Goh <engheng1981@yahoo.com>
Sent: Friday, February 21, 2020 11:42 AM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Subject: Re: OUR REF: SNM20D200913/GBB178L/TKL - Notification and request for pre survey of an accident involving GX6763H and your insured GBB178L on 19 Feb 2020 at 7.55 am at KPE / MCE tunnel entrance near Sims Ave exit

Dear Mr Tan,

I would like to appoint Mr. Kenneth Kong to conduct the pre repair survey.

Thank You.

Best Regards,
Judy

On Thursday, February 20, 2020, 03:08:14 PM GMT+8, Tan Kah Leong <kahleong.tan@sg.cntaiping.com> wrote:

Without Prejudice

Dear Judy,

We refer to your email below.

Please see attached and let us know if you agree with SJE.

Thank you.

Regards

Tan Kah Leong

Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Sent: Thursday, February 20, 2020 2:45 PM

To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; engheng1981@yahoo.com <engheng1981@yahoo.com>

Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: OUR REF: SNM20D200913/GBB178L/TKL - Notification and request for pre survey of an accident involving GX6763H and your insured GBB178L on 19 Feb 2020 at 7.55 am at KPE / MCE tunnel entrance near Sims Ave exit

Dear Kah Leong,

Please conduct PRS for GX6763H.

Note : officer in charge – Kah Leong 63896193.

*** Kindly quote our reference number when replying.

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Judy Goh <engheng1981@yahoo.com>

Sent: Thursday, February 20, 2020 9:58 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: Re: Notification and request for pre survey of an accident involving GX6763H and your insured GBB178L on 19 Feb 2020 at 7.55 am at KPE / MCE tunnel entrance near Sims Ave exit

Dear Sir/ Madam,

Please arrange for your surveyor to come to my workshop to survey the damaged vehicle, GX6763H.

Eng Heng Automobil Trading Co
10 Ang Mo Kio Industrial Park 2A
#01-01 AMK AUTOPOINT
Singapore 568047
Tel 64835662

Thank You.

Best Regards,
Mrs Judy Tan

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	000K
Vehicle Details	
Vehicle No.:	GX6763H
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Feb 2020
Vehicle Make:	TOYOTA
Vehicle Model:	LITEACE 5DR
Primary Colour:	Silver
Manufacturing Year:	2004
Engine No.:	3C3996658
Chassis No.:	CR425009754
Maximum Power Output:	-
Open Market Value:	\$18,689.00
Original Registration Date:	12 Aug 2004
First Registration Date:	12 Aug 2004
Transfer Count:	3
Actual ARF Paid:	\$935.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	11 Aug 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$13,055.00
COE Rebate Amount:	\$11,651.00
Total Rebate Amount:	\$11,651.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 25 Feb 2020

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	000K

Vehicle Details	
Vehicle No.:	GX6763H
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Feb 2020
Vehicle Make:	TOYOTA
Vehicle Model:	LITEACE 5DR
Primary Colour:	Silver
Manufacturing Year:	2004
Engine No.:	3C3996658
Chassis No.:	CR425009754
Maximum Power Output:	-
Open Market Value:	\$18,689.00
Original Registration Date:	12 Aug 2004
First Registration Date:	12 Aug 2004
Transfer Count:	3
Actual ARF Paid:	\$935.00

Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details	
COE Expiry Date:	11 Aug 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$13,055.00
COE Rebate Amount:	\$11,679.00
Total Rebate Amount:	\$11,679.00

Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 20 Feb 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/02/2020 14:36
Date Of Accident	19/02/2020 07:55
Exact Location Of Accident	ENTRANCE TO KPE (MCE) TUNNEL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GX6763H
Insured/Policyholder	
Name Of Registered Owner	JOINTECH ELECTRICAL & TRADING
Co Reg No	4XXXX000K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96387784

Vehicle Particulars

Manufacturer	TOYOTA
Model	LITEACE 5DR 2.2
Exact Purpose for which vehicle was being used at time of accident	REPORTING TO WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5019503037-13
Cover Note Number	12/02/2020 - 11/02/2021

Driver

Name of Driver	WONG WEI LIAT RAYMOND
NRIC No	SXXXX336D
Date Of Birth	19/03/1994
Occupation	INDOOR
Date Of Driving Pass	28/09/2016
Driving Experience	3 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96587343
Fax Number	
Contact Number	
EMail Address	WONGWI94@GMAIL.COM

Address	BLK 48 LORONG 5 TOA PAYOH #20-107
Postcode	310048
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : BEH XUN QUAN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ANG MO KIO NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 51 ANG MO KIO AVE 9 , POSTCODE: 569784 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4849999 - FAX NO: 62181399
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT NO: F/20200219/2031.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Details of Witness 1

Name	BEH XUN QUAN
Phone Number	90275216
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB178L
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE

Name of Driver	KONG KAH CHEN
NRIC/Passport Number	SXXXX167C
Contact Number	90709015
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	BEH XUN QUAN
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	GX6763H
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

Sketch Plan

SKETCH PLAN

VEHICLE NO.: 6X 67634
INSURER : NIC
DATE & TIME: 19/02/2020 (17:55)

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 19/02/20

Reporting Centre Personnel's Signature
Name: Dudyn Ann
NRIC/FIN NO.: 19/02/2020

Sketch Plan #2

SKETCH PLAN *SWS AVE EXT*

A: 6X6763H
(w/ 1 passenger)
Bm Xun Quan-M.
B: 6BB 178L

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Vehicle No: 6X6763H (NTUC)
Date & Time: 19/02/2020 @ 0755 (clear dry)
Refer to police report no: F/20200219/2031.

Note: Please note that your insurer may have 14 days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 19/02/20

Reporting Centre Personnel's Signature
Name: (AMK)
NRIC/FIN No.:

GIA/RC Sketch Plan Form V3 () Claim Own Policy () Claim Third Party () Reporting Only
() Claim OD/TP at other workshop ()



**SINGAPORE
POLICE FORCE**



F/20200219/2031

1 of 2

POLICE REPORT (NP299)

Report No. F/20200219/2031

Police Station Of Origin
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999

Date/Time Report Made 19/02/2020 11:25	Vide Report No.	Station Diary No. 32
Name Of Informant WONG WEI LIAT RAYMUND	Address APT BLK 48 LORONG 5 TOA PAYOH #20-107 SINGAPORE 310048	
ID Type / ID No. NRIC NO / S9412336D	Contact No. Home/Office Mobile 96587343	
Nationality SINGAPORE CITIZEN	Email Address	
Occupation TECHICAL OFFICER	Sex Male	Age 25
Institution/School Name	Date of Birth 19/03/1994	Race Chinese
	Language	
Date/Time Of Incident 19/02/2020 07:50 - 19/02/2020 07:55	Location Of Incident PAN-ISLAND EXPRESSWAY SINGAPORE	

Brief details.

On 19/02/2020 at about 7.53 am along KPE towards of direction of MCE near to Sims Ave exit, I was driving my company registered van (GX6763H) and one van (GBB178L) hit onto my rear causing the rear windscreen of my van to be shattered. My passenger namely Beh Xun Quan, NRIC: S9403108G which was sitting on the left passenger seat sustained one small cut at the back of his neck. I suspected that the cut might be caused by the shattered glass shard. I exchanged particular with another driver. On 19/02/2020, I sent my passenger to Raffles Hospital for medical attention. On the same day, my passenger told me that he was given two days MC due to his cut.

Signature Of Officer Recording The Report: F / SI QUEK CHAW YUEN	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 19/02/2020 11:25
Officer In-Charge Of Case: F / Ang Mo Kio North N.P.C / Staff Sgt SHAHRIL RASHIDI BIN SADLI Contact No.: 64849999	Classification Of Case:
Authentication Stamp SM 095	

Singapore Police Force

Sketch Plan #4



**SINGAPORE
POLICE FORCE**



F/20200219/2031

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. F/20200219/2031

I am lodging this report for my insurance's company record.

Signature Of Officer Recording The Report:

F / SI QUEK CHAW YUEN

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:
F / Ang Mo Kio North N.P.C /
Staff Sgt SHAHRIL RASHIDI BIN SADLI
Contact No.: 64849999

Authentication Stamp

Signature Of Informant:

Date/Time:
19/02/2020 11:25

Classification Of Case:

SN 045

Signature

20th FEB 2020

258

ENG HENG AUTOMOBIL TRADING CO

GX6763H Toyota Liteace CR42

20th FEB 2020

SN	QTY	DESCRIPTION	AMOUNT
		Balance b/f	\$ 6,314.15
31		Workmanship to remove and install rear windscreen and moulding	\$ 220.00
32		To panel beat and change rear boot lid, rear bumper, rear end panel, (inner and outer), straighten spare tyre compartment, change rear right and left fender, straight rear chasis and frame	\$ 2,200.00
33		To change rear absorbers, exhaust pipe and rear axle	\$ <i>nn</i> 550.00
34		To remove electrical wiring, accessories and refit change wiper motor, refit locks, check all lights	\$ 480.00
35		Wheel Alignment	\$ <i>nn</i> 120.00
36		To repray rear boot lid, rear end panel, rear spare tyre compartment, rear right and left fenders, rear bumper	\$ 1,200.00
			\$ 11,084.15

12cl
2000cl
X
8cl
X
1000cl

Dollars: Eleven Thousand Eighty Four and cents Fifteen Only

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20003033/KSF3N2
Date: 17/03/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN17653619022
Claimant Vehicle No :	GX6763H	Insured Vehicle No :	GBB178L
Date of Loss:	19/02/2020	Nature of Claim:	TP
		Claim No:	SNM20D200913C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GX6763H	Engine No:	3C3996658
Make & Model:	TOYOTA LITEACE, 2.2 5 DR (A)	Chassis No:	CR425009754
Reg. Date:	12/08/2004 (Man. Year: 2004)	Odometer:	207180 km
Colour:	Silver		
Engine Capacity:	2184 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	165R13X8	Rear Tyre Size:	165R13X8
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,314.15	3,500.86	2,813.29	44.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,770.00	3,200.00	1,570.00	32.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,084.15	6,700.86	4,383.29	39.55
Approved Total (Overridden) (S\$)		5,300.00		
Nett Amount (S\$)	11,084.15	5,300.00	5,784.15	52.18

INSPECTION

Date of Assignment:	24/02/2020	Eng Heng Automobil Trading Co (HQ)
Date Inspected:	24/02/2020 Inspected At:	Blk 10 #01-01 Ang Mo Kio Part 2A AutoPoint
Estimated Period of Repair:	12.0 days	Singapore 568047

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 Mar 2020)	
Parts:	N/A	TOYOTA LITEACE 2.2 5 DR (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GX6763H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT COVER	Bent	1,013.00 F	*1,013.00 FL
2	1		*REAR BOOT MIRROR	Missing	155.00 F	*155.00 FL
3	1		*REAR WINDSCREEN GLASS	Shattered	580.00 F	*580.00 FL
4	1		*REAR WINDSCREEN MOULDING	Necessary	180.00 F	*180.00 FL
5	1		*REAR WINDSCREEN WIPER NOZZLE	Serviceable	55.00 F	*- FL
6	1		*REAR WIPER MOTOR	Jammed	210.00 F	*210.00 FL
7	1		*REAR WIPER ARM	Dented	78.00 F	*78.00 FL
8	1		*REAR WIPER BLADE	Cut	28.00 F	*28.00 FL
9	1		*REAR BOOT COVER LOCK	Cracked	144.45 F	*144.45 FL
10	1		*REAR BOOT COVER HANDLE GARNISH	Warped	188.60 F	*188.60 FL
11	2		*REAR NUMBER PLATE BULB LAMP	Serviceable	110.00 F	*- FL
12	1		*REAR NUMBER PLATE	Serviceable	45.00 F	*- FL
13	1		*TOYOTA STICKER	Necessary	28.00 F	*28.00 FL
14	1		*LITEACE STICKER	Necessary	39.00 F	*39.00 FL
15	1		*70KM/H STICKER	Necessary	10.00 F	*10.00 FL
16	1		*5PAX STICKER	Necessary	10.00 F	*10.00 FL
17	1		*REAR LEFT FENDER	Buckled	265.00 F	*265.00 FL
18	1		*RIGHT FENDER	Bent	265.00 F	*265.00 FL
19	1		*REAR BUMPER	Bent	299.60 F	*299.60 FL
20	2		*REAR BUMPER REFLECTOR	Serviceable	76.00 F	*- FL
21	1		*REAR BUMPER BRACKET-RIGHT	Repair	38.50 F	*- FL
22	1		*REAR BUMPER BRACKET-LEFT	Repair	38.50 F	*- FL
23	2		*REAR BOOT LID ABSORBER	Serviceable	360.00 F	*- FL
24	1		*REAR END PANEL-INNER	Bent	365.00 F	*365.00 FL
25	1		*REAR END PANEL-OUTER	Bent	247.50 F	*247.50 FL
26	1		*REAR EXHAUST	Repair	200.00 F	*- FL
27	1		*REAR AXLE	Serviceable	550.00 F	*- FL
28	2		*REAR ABSORBERS	Serviceable	220.00 F	*- FL
29	1		*SPARE TYRE BRACKET/HOLDER	Buckled/Distorted	295.00 F	*295.00 FL
30	1		*SET REVERSE SENSOR	Missing	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,314.15	4,601.15
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,100.29
Total Parts (\$\$)	6,314.15	3,500.86

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WORKMANSHIP TO REMOVE AND INSTALL REAR WINDSCREEN AND MOULDING	New	220.00	120.00
2	TO PANEL BEAT AND CHANGE REAR BOOT LID, REAR BUMPER, REAR END PANEL (INNER AND OUTER), STRAIGHTEN SPARE TYRE COMPARTMENT, CHANGE REAR RIGHT AND LEFT FENDER, STRAIGHT REAR CHASIS AND FRAME	New	2,200.00	2,000.00
3	TO CHANGE REAR ABSORBERS, EXHAUST PIPE AND REAR AXLE	New	550.00	0.00
4	TO REMOVE ELECTRICAL WIRING, ACCESSORIES AND REFIT CHANGE WIPER MOTOR, REFIT LOCKS, CHECK ALL LIGHTS	New	480.00	80.00
5	WHEEL ALIGNMENT	New	120.00	0.00
6	TO RESPRAY REAR BOOT LID, REAR END PANEL, REAR SPARE TYRE COMPARTMENT, REAR RIGHT AND LEFT FENDERS, REAR BUMPER	New	1,200.00	1,000.00
Gross Labour Cost (S\$)			4,770.00	3,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >