

(08/11/13) wef

ASS. REC. BY: *Marius*

REF:

U31M34 20003051 / UV43N2

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date / Time

Action / Instruction

Date / Time

Action / Instruction

Date / Time

Action / Instruction

Date / Time

Action / Instruction

Date / Time

Action / Instruction

Date / Time

Action / Instruction

Date / Time

Action / Instruction

Date / Time

Action / Instruction

Date / Time

Action / Instruction

Date / Time

Action / Instruction

Date / Time

Action / Instruction

Date / Time

Action / Instruction

Date / Time

Action / Instruction

Date / Time

Action / Instruction

Date / Time

Action / Instruction

Date / Time

Action / Instruction

Date / Time

Action / Instruction

Date / Time

Action / Instruction

Date / Time

Action / Instruction

Date / Time

Action / Instruction

Date / Time

Action / Instruction

Date / Time

Action / Instruction

Date / Time

Action / Instruction

Date / Time

Action / Instruction

Date / Time

Action / Instruction

Date / Time

Action / Instruction

RECEIVED 13 MAR 2020

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

12/3 - typist

Report Format:

Merimen

Lump Sum / I.B.I. (\$

12,700k)

Days Of Repair:

7

Resurvey No. of Trip:

2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

) TOTAL

250

11

261

12/3/2020

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	NG CHEN HOW	Date:	12 Mar 2020

Preliminary Advice

Insured Vehicle No	: SLV2168D		
TP Vehicle No	: SMP7469Y	Accident Date	: 23/02/2020
Make	: AUDI A6	Assignment Date	: 27/02/2020
Date of Inspection	: 24/02/2020	Est. Duration of Repair	: 7.00
Inspection At	FASTECH AUTO PTE LTD (HQ) 1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear portion. The undercarriage affected due to collision and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	39,334.00
Revised Amount	:S\$	15,932.90
Check Items (Estimated)	:S\$	0.00
Total	:S\$	15,932.90
Lump Sum Repair (estimated)	:S\$	12,700.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Feb 2020		27 Feb 2020 10:44 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	GRAB RENTALS PTE LTD , Co. Reg. No.: 201617200G								
Main Claimant:	MUHAMMED SHABEER MOHIDEEN BIN MOHAMMED RASHID , ID: S9229470F								
Vehicle Reg. No.:	SMP7469Y	Date of Loss:	23/02/2020 01:00 - :59 [58 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 620545	Policy/Cover Note No.:	29141713 (Comprehensive) Coverage: 01/02/2020 - 31/12/2020						
Vehicle Reg. No. (Insured):	SLV2168D	Policy No. (Claimant):							
		Excess:							
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by NG CHEN HOW - 6643 1391]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Imm.Advice due 28/02/2020]								
Driver/Custodian (Insured):	LIM YUEN CHONG DAVID (), NRIC: S1539361J, Tel: +6590480219 Email:								
Adj Asg. Remarks:	Direct Survey by LKK Auto Consultants on 24/02/2020.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 25 February 2020 10:13 AM
To: motorsurvey@sg.msig-asia.com; SUR
Cc: Accounts (LKKAuto); KKLau
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 23/12/2020, SMP 7469Y (TP VEHICLE), SLV 2168D (OI VEHICLE)
Attachments: GIA.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SMP 7469Y at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 24/2/2020

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Singapore Dollar Tumbles - After This Big Announcement

Many Singaporean Still Don't Know But Singapore Is Facing Big Trouble Ahead [alumnza.com](#)

OPEN

Price Range

Depreciation

2015

Vehicle Type

Home > Used Cars > Auto Galleria Pte Ltd > Audi A6 2.0A TFSI MU

Audi A6 2.0A TFSI MU

- Overview
- Financial
- Insurance
- Accessories
- Similar
- Research
- Photos
- Map

PREMIUM AD

Price	\$88,000		
Depreciation	\$12,850 /yr View models with similar depre	Reg Date	27-May-2015 (5yrs 3mths 2days COE left)
Mileage	62,000 km (13.1k /yr)	Manufactured	2014
Road Tax	\$1,194 /yr	Transmission	Auto
Dereg Value	\$70,092 as of today <i>(change)</i>	OMV	\$38,504
COE	\$75,002	ARF	\$40,906
Engine Cap	1,984 cc	Power	132.0 kW (177 bhp)
Curb Weight	1,565 kg	No. of Owners	1
Type of Vehicle	Luxury Sedan		

Features

2.0L 4-Cylinder Turbocharged TFSI Engine Mated To An 8-speed Automatic Multitronic Transmission! Cruise Ctrl, Multi Function Steering, Paddle Shifters View specs of the Audi A6 (2011-2018)

Accessories

Audi MMI Nav Plus, Audi Drive Select, Electric/Memory Leather Seats, Comfort Key, 18" Rims, Dual Zone Auto Climate Control Aircon, LED/DRL Headlights

Description

Agent Unit From Premium Automobiles Singapore! Comprehensive Loan/High Trade In Available! Original Stock Condition, Guaranteed Accident-Free. STA Evaluation Available! Low Fuel Consumption Of 15.6Km/Litre Yet Pushing 177Bhp! Call Us Now For An Non Obligatory Viewing! Strictly By Appointment Only.

Category

PARF Car, Premium Ad Car

Status

Available

Resources



Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. [Find out more](#)



Car Valuation - Free
Find out the market value of your existing car for free. [Get started](#)



Price Chart

Summary

Click on the point to view the vehicle

- Shortlist

Report Error
- Compare

More Actions
- Add note

Seller Information

Auto Galleria Pte Ltd

9 vehicles for sale, 13 sold in past 3 mths

9 Tagore Lane #01-12

9@Tagore

[Search cars nearby](#)

Posted on: 13-Feb-2020 | Last Updated on: 14-Feb-2020

[Compare](#)

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 470F

Vehicle Details

Vehicle No.: SMP7469Y

Vehicle to be Exported: No

Intended Deregistration Date: 25 Feb 2020

Vehicle Make: AUDI

Vehicle Model: A6 2.0 TFSI MU

Primary Colour: Grey

Manufacturing Year: 2014

Engine No.: CDN410969

Chassis No.: WAUZZZ4G6EN163736

Maximum Power Output: 132.0 kW (177 bhp)

Open Market Value: \$38,516.00

Original Registration Date: 27 Mar 2015

First Registration Date: 27 Mar 2015

Transfer Count: 1

Actual ARF Paid: \$40,923.00 20461

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 26 Mar 2025

PARF Rebate Amount: \$30,692.00

Intended COE Rebate Details

COE Expiry Date: 26 Mar 2025

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$71,889.00

COE Rebate Amount: \$36,562.00

Total Rebate Amount: \$67,254.00

The information contained herein is correct as at 24 Feb 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/02/2020 16:28
Date Of Accident	23/02/2020 01:00
Exact Location Of Accident	BEDOK RESERVOIR ROAD BET B/115 / 116
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMP7469Y
Insured/Policyholder	
Name Of Registered Owner	MUHAMMED SHABEER MOHIDEEN BIN MOHAMMED RASHID
NRIC No	SXXXX470F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98346121
Alternative Phone No	OTHERS-98346121

Vehicle Particulars

Manufacturer	AUDI
Model	A6 2.0 TFSI MU
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5114484637
Cover Note Number	

Driver

Name of Driver	MUHAMMED SHABEER MOHIDEEN BIN MOHAMMED RASHID
NRIC No	SXXXX470F
Date Of Birth	14/08/1992
Occupation	INDOOR
Date Of Driving Pass	12/01/2011
Driving Experience	9 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98346121
Fax Number	
Contact Number	OTHERS-98346121
Email Address	NOEMAIL

Address	33 JALAN SELAMAT
Postcode	418563
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED;

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLV2168D
Vehicle Make/Model/Colour	HONDA / VEZEL HYBRID 1.5X AUTO
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Date of Accident : 23-02-2020 Accident Time: 1 am (24-HR-Format)
 Accident Place : Bedok Reservoir Rd Between Blk 115 and 116
 Vehicle No. (Car Plate No.) : SMP 74694 Make/Model: Audi A6 2.0
 Insurance Company : NTUC Policy No: 5114484637
 Owner or Company Name /IC No. : Muhammed Shabeer Mohideen Bin Mohammed Rashid (9229470F)
 Owner or Company Contact No. : _____ Owner's Hp 98346121 Company Tel _____
 DRIVER'S Name / IC No. : as above
 DRIVER'S Date Of Birth : 14-01-1992 DRIVER'S License Pass Date 12-01-2011
 Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: Owner
 DRIVER'S Address : 33 Jalan Selamat Singapore 418563
 DRIVER'S Contact No./ Alt No. : 1) _____ 2) _____
 DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)
 Email Address : _____
 Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET
 Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance
 Number of Passengers (Including Driver): 1 Driver
 Was there any video Captured by car camera: YES \ NO
 Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose
 Any Injury (If YES, Pls state): NO

Other Party Driver's Particular (if any)

Vehicle No: <u>SLY 2168D</u>	Vehicle No: _____
Vehicle Make/Model: _____	Vehicle Make/Model: _____
Name Driver: _____	Name Driver: _____
IC No. Driver/Contact: _____	IC No. Driver/Contact: _____

* NEW - Passenger's name & gender:


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


On 23.02.2020 at about 1am . I was travelling along
 Badok Reservoir Road Between B1K 115 and B1K 116 . I was travelling straight.
 Suddenly Vehicle B hit on my vehicle .

* Please Note : The Driver of Vehicle B did not stopped at the stop line to
 check incoming Vehicle .

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

COMPUTERISED 4 WHEEL ALIGNMENT HUNTER DSP700

Company: FASTECH AUTO PTE LTD
SMP 7469 Y
Date: 24.2.20 11:14



SMP 7469 Y

AUDI A6

Front : Left

Actual	Before	Specified Range
-1°18'	-1°18'	-1°00' 1°00'
2°59'	2°59'	2°20' 4°20'
-0°20'	-0°21'	-0°09' 0°09'
19°16'	19°16'	11°00' 13°00'
17°58'	17°58'	10°00' 14°00'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°06'	-0°06'	-1°00' 1°00'
3°25'	3°25'	2°20' 4°20'
-0°21'	-0°21'	-0°09' 0°09'
13°01'	13°01'	11°00' 13°00'
12°54'	12°54'	10°00' 14°00'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-1°11'	-1°12'	-0°45' 0°45'
-0°25'	-0°25'	
6°15'	6°15'	
-0°41'	-0°41'	-0°17' 0°17'

Rear : Left

Actual	Before	Specified Range
-2°05'	-2°05'	-2°00' 0°00'
-0°08'	-0°08'	0°00' 0°17'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-0°41'	-0°41'	-2°00' 0°00'
0°02'	0°02'	0°00' 0°17'

Rear

Cross Camber
Total Toe
Thrust Angle
Axle Offset

Actual	Before	Specified Range
-1°25'	-1°25'	
-0°07'	-0°06'	0°00' 0°34'
-0°05'	-0°05'	
0mm	0mm	

COMPUTERISED 4 WHEEL ALIGNMENT HUNTER DSP700

Company:
N:
ite

FASTECH AUTO PTE LTD
SMP 7469 Y
25.2.20 11:27



SMP 7469 Y

AUDI A6

Front : Left

Actual	Before	Specified Range
-0°09'	-0°09'	-1°00' 1°00'
2°58'	2°58'	2°20' 4°20'
-0°02'	-0°02'	-0°09' 0°09'
19°26'	19°26'	11°00' 13°00'
19°17'	19°17'	10°00' 14°00'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
0°04'	0°04'	-1°00' 1°00'
3°20'	3°20'	2°20' 4°20'
-0°01'	-0°01'	-0°09' 0°09'
9°57'	9°56'	11°00' 13°00'
10°01'	10°01'	10°00' 14°00'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-0°14'	-0°14'	-0°45' 0°45'
-0°22'	-0°22'	
9°30'	9°30'	
-0°03'	-0°03'	-0°17' 0°17'

Rear : Left

Actual	Before	Specified Range
-0°51'	-0°51'	-2°00' 0°00'
0°06'	0°05'	0°00' 0°17'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-0°42'	-0°42'	-2°00' 0°00'
0°05'	0°05'	0°00' 0°17'

Rear

Cross Camber
Total Toe
Thrust Angle
Axle Offset

Actual	Before	Specified Range
-0°09'	-0°09'	
0°11'	0°10'	0°00' 0°34'
0°00'	0°00'	
0mm	0mm	

not Admitted
date
24/2/20
2/s \$12,700
7 days.

Body	DD	\$2,880.00	—
	11	\$395.00	X
	11	\$288.00	—
Surf Len		\$855.00	X
Ben		\$295.00	—
Sheld		\$650.00	—
De/Torn		\$1,680.00	—
	11	\$410.00	X
	11	\$185.00	X
Body/Polu		\$3,995.00	—
De/Torn		\$488.00	—
	100	\$850.00	—
	100	\$210.00	—
D.J		\$1,800.00	—
	11	\$1,950.00	X
Cur/Torn		\$2,445.00	—
	11	\$95.00	X
	100	\$60.00	—
	11	\$315.00	X
Daye		\$899.00	—
Sur		\$1,500.00	X
Sit		\$2,115.00	—
	11	\$3,065.00	X
	11	\$1,099.00	X
Cur/Sit		\$1,800.00	650 S
	100	\$50.00	40 S
	100	\$50.00	30 S
	11	\$2,650.00	X
	11	\$1,050.00	—
		\$34,124.00	—

Body	DD	\$2,880.00	—
	11	\$395.00	X
	11	\$288.00	—
Surf Len		\$855.00	X
Ben		\$295.00	—
Sheld		\$650.00	—
De/Torn		\$1,680.00	—
	11	\$410.00	X
	11	\$185.00	X
Body/Polu		\$3,995.00	—
De/Torn		\$488.00	—
	100	\$850.00	—
	100	\$210.00	—
D.J		\$1,800.00	—
	11	\$1,950.00	X
Cur/Torn		\$2,445.00	—
	11	\$95.00	X
	100	\$60.00	—
	11	\$315.00	X
Daye		\$899.00	—
Sur		\$1,500.00	X
Sit		\$2,115.00	—
	11	\$3,065.00	X
	11	\$1,099.00	X
Cur/Sit		\$1,800.00	650 S
	100	\$50.00	40 S
	100	\$50.00	30 S
	11	\$2,650.00	X
	11	\$1,050.00	—
		\$34,124.00	—

\$80.00	20
\$80.00	50
\$120.00	80
\$150.00	100
\$100.00	60
\$180.00	80
\$380.00	150
\$150.00	120
\$150.00	60
11 \$120.00	X
\$2,200.00	1000
\$1,500.00	1000
\$39,334.00	

1. I/We Auto Consultants hence notify
 the Registrar of the following:
 a. To remove a license for spray painting
 b. To remove a license for driving a heavy
 truck
 c. To suspend a license for conviction
 d. To suspend a license for a "Written Prejudicial" test
 e. To suspend a license for alcohol
 f. To suspend a license for not being licensed and
 driving a motor vehicle from Insurance Company
 2. **TOTAL**
 3. **P-14661**
 4. **14661**
 5. **14661**
 6. **14661**
 7. **14661**
 8. **14661**
 9. **14661**
 10. **14661**
 11. **14661**
 12. **14661**
 13. **14661**
 14. **14661**
 15. **14661**
 16. **14661**
 17. **14661**
 18. **14661**
 19. **14661**
 20. **14661**
 21. **14661**
 22. **14661**
 23. **14661**
 24. **14661**
 25. **14661**
 26. **14661**
 27. **14661**
 28. **14661**
 29. **14661**
 30. **14661**
 31. **14661**
 32. **14661**
 33. **14661**
 34. **14661**
 35. **14661**
 36. **14661**
 37. **14661**
 38. **14661**
 39. **14661**
 40. **14661**
 41. **14661**
 42. **14661**
 43. **14661**
 44. **14661**
 45. **14661**
 46. **14661**
 47. **14661**
 48. **14661**
 49. **14661**
 50. **14661**
 51. **14661**
 52. **14661**
 53. **14661**
 54. **14661**
 55. **14661**
 56. **14661**
 57. **14661**
 58. **14661**
 59. **14661**
 60. **14661**
 61. **14661**
 62. **14661**
 63. **14661**
 64. **14661**
 65. **14661**
 66. **14661**
 67. **14661**
 68. **14661**
 69. **14661**
 70. **14661**
 71. **14661**
 72. **14661**
 73. **14661**
 74. **14661**
 75. **14661**
 76. **14661**
 77. **14661**
 78. **14661**
 79. **14661**
 80. **14661**
 81. **14661**
 82. **14661**
 83. **14661**
 84. **14661**
 85. **14661**
 86. **14661**
 87. **14661**
 88. **14661**
 89. **14661**
 90. **14661**
 91. **14661**
 92. **14661**
 93. **14661**
 94. **14661**
 95. **14661**
 96. **14661**
 97. **14661**
 98. **14661**
 99. **14661**
 100. **14661**
 101. **14661**
 102. **14661**
 103. **14661**
 104. **14661**
 105. **14661**
 106. **14661**
 107. **14661**
 108. **14661**
 109. **14661**
 110. **14661**
 111. **14661**
 112. **14661**
 113. **14661**
 114. **14661**
 115. **14661**
 116. **14661**
 117. **14661**
 118. **14661**
 119. **14661**
 120. **14661**
 121. **14661**
 122. **14661**
 123. **14661**
 124. **14661**
 125. **14661**
 126. **14661**
 127. **14661**
 128. **14661**
 129. **14661**
 130. **14661**
 131. **14661**
 132. **14661**
 133. **14661**
 134. **14661**
 135. **14661**
 136. **14661**
 137. **14661**
 138. **14661**
 139. **14661**
 140. **14661**
 141. **14661**
 142. **14661**
 143. **14661**
 144. **14661**
 145. **14661**
 146. **14661**
 147. **14661**
 148. **14661**
 149. **14661**
 150. **14661**
 151. **14661**
 152. **14661**
 153. **14661**
 154. **14661**
 155. **14661**
 156. **14661**
 157. **14661**
 158. **14661**
 159. **14661**
 160. **14661**
 161. **14661**
 162. **14661**
 163. **14661**
 164. **14661**
 165. **14661**
 166. **14661**
 167. **14661**
 168. **14661**
 169. **14661**
 170. **14661**
 171. **14661**
 172. **14661**
 173. **14661**
 174. **14661**
 175. **14661**
 176. **14661**
 177. **14661**
 178. **14661**
 179. **14661**
 180. **14661**
 181. **14661**
 182. **14661**
 183. **14661**
 184. **14661**
 185. **14661**
 186. **14661**
 187. **14661**
 188. **14661**
 189. **14661**
 190. **14661**
 191. **14661**
 192. **14661**
 193. **14661**
 194. **14661**
 195. **14661**
 196. **14661**
 197. **14661**
 198. **14661**
 199. **14661**
 200. **14661**
 201. **14661**
 202. **14661**
 203. **14661**
 204. **14661**
 205. **14661**<

MGIS Auto Consultants hence notify
the Repairer of the following:

1. To provide a free labor spray painting
2. To provide a damaged outlet during journey
3. To provide a subject to consultation
4. To provide a subject to "Waters Physical" tests
5. To provide a subject to "is allowed"
6. To provide a subject to "will be reviewed and
7. To provide a subject to "will be approved from Insurance Company"

TOTAL

P-122661

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG20003051/UVF3N2
Date: 17/03/2020

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29141713
Claimant Vehicle No :	SMP7469Y	Insured Vehicle No :	SLV2168D
Date of Loss:	23/02/2020	Nature of Claim:	TP
		Claim No:	620545

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP7469Y	Engine No:	CDN410969
Make & Model:	AUDI A6, 2.0 TFSI MU (A)	Chassis No:	WAUZZZ4G6EN163736
Reg. Date:	27/03/2015 (Man. Year: 2014)	Odometer:	68603 km
Colour:	Grey		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R17	Rear Tyre Size:	225/55R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Dayton 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Dayton 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	34,124.00	13,212.90	20,911.10	61.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,210.00	2,720.00	2,490.00	47.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	39,334.00	15,932.90	23,401.10	59.49
Approved Total (Overridden) (S\$)		12,700.00		
(S\$)	39,334.00	12,700.00	26,634.00	67.71
+ GST 7.00/7.00% (S\$)	2,753.38	889.00	1,864.38	67.71
Nett Amount (S\$)	42,087.38	13,589.00	28,498.38	67.71

INSPECTION

Date of Assignment:	27/02/2020	
Date Inspected:	24/02/2020	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	7.0 days	

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Mar 2020)
Parts:	143	AUDI A6 2.0 TFSI MU (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP7469Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR N/S	Badly Dented	2,880.00 F	*2,689.00 FL
2	1		*REAR DOOR OUTER HANDLE N/S	Not Necessary	395.00 F	*- FL
3	1		*REAR DOOR OUTER GLASS MOULDING N/S	Not Necessary	288.00 F	*- FL
4	1		*REAR DOOR GLASS REGULATOR & MOTOR N/S	Bent/Jammed	855.00 F	*455.00 FL
5	1		*REAR DOOR INNER RUBBER N/S	Torn	295.00 F	*162.00 FL
6	1		*REAR DOOR INNER LOCK N/S	Shorted	650.00 F	*631.00 FL
7	1		*REAR DOOR INNER TRIM BOARD N/S	Deformed/Torn	1,680.00 F	*1,200.00 FL
8	2		*REAR DOOR HINGES N/S	Not Necessary	410.00 F	*- FL
9	1		*REAR DOOR CHECKER N/S	Not Necessary	185.00 F	*- FL
10	1		*REAR FENDER N/S	Badly Dented/Cracked	3,995.00 F	*2,891.00 FL
11	1		*REAR FENDER UNDER TRIM COVER N/S	Deformed/Torn	488.00 F	*311.00 FL
12	1		*REAR FENDER QUARTER GLASS N/S	Necessary	850.00 F	*605.00 FL
13	1		*REAR WINDSCREEN MOULDING	Necessary	210.00 F	*162.00 FL
14	1		*ROCKER PANEL GARNISH N/S	Distorted	1,800.00 F	*850.00 FL
15	1		*ROCKER PANEL N/S	Repair	1,950.00 F	*- FL
16	1		*REAR BUMPER	Cut/Torn	2,445.00 F	*2,100.00 FL
17	1		*REAR BUMPER SIDE RETAINER N/S	Not Necessary	95.00 F	*- FL
18	1		*SET REAR BUMPER CLIPS	Necessary	60.00 F	*60.00 FL
19	1		*REAR SHOCK ABSORBER N/S	Not Necessary	315.00 F	*- FL
20	1		*REAR WHEEL HUB BEARING N/S	Damaged	899.00 F	*650.00 FL
21	1		*REAR LOWER ARM N/S	Serviceable	1,500.00 F	*- FL
22	1		*REAR KNUCKLE ARM N/S	Bent	2,115.00 F	*1,115.00 FL
23	1		*REAR CROSS MEMBER	Not Necessary	3,065.00 F	*- FL
24	1		*REAR WHEEL HOUSING PANEL N/S	Repair	1,099.00 F	*- FL
25	1		*FRONT DOOR N/S	Repair	2,650.00 F	*- FL
26	1		*CENTRE PILLAR N/S	Not Necessary	1,050.00 F	*- FL
27	1		*REAR SPORT RIM N/S	Cut/Bent	1,800.00 FS	*650.00 FS
28	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
29	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	34,124.00	14,601.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	1,388.10
Total Parts (\$\$)	34,124.00	13,212.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	20.00
2	TO DISMANTLE & REFIX REAR PDC SENSOR	New	80.00	50.00
3	TO DISMANTLE & REPLACING REAR FENDER QUARTER GLASS N/S	New	120.00	80.00
4	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY	New	150.00	100.00
5	TO TRANSFER REAR DOOR MECHANISM	New	100.00	60.00
6	TO CONDUCT WHEEL ALIGNMENT	New	180.00	80.00
7	TO DISMANTLE & REPLACING REAR UNDERCARRIAGE	New	380.00	150.00
8	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
9	TO SPRAY RUST PROOFING	New	150.00	60.00
10	TO DISMANTLE & REFIX PETROL TANK	New	120.00	0.00
11	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	2,200.00	1,000.00
12	TO PUTTY & SPRAY PAINTING	New	1,500.00	1,000.00
Gross Labour Cost (S\$)			5,210.00	2,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >