



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM20003101/Uga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 29-09-2020



ATTN:WINNIE

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJS 8675G	Veh. Inspected	SLC 1331E
Policy No.	GA500087	Coverage (\$)	0.00
Claim No.	S0M02H47	Excess (\$)	0.00
Assign From		Assign Date	24/02/2020

2. Vehicle Particulars & Condition

Make & Model	LEXUS GS250 (A)	c.c	2500
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	JTHBF1BL205006890	Colour	BLACK
Odometer	125312	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/45 R17	CONTINENTAL	6 mm
L/H Front Tyre	245/45 R17	CONTINENTAL	6 mm
R/H Rear Tyre	245/45 R17	CONTINENTAL	6 mm
L/H Rear Tyre	245/45 R17	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/02/2020	Inspection Date	24/02/2020
Survey held at	130 Bedok Reservoir Road #08-1339 Singapore 470130		
Repairer	ZOOM AUTOWERKS PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------