

ASS. REC. BY:

REF: CS 3 / ASM 20003022 / H4 f367 Special Instruction:

Surveyor: Huck AnASSIGNMENT (Office)From (Person): Jas Tan of ASM (AXA) Date/Time: 25/2/2022

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: YP 4367K Insured: SME 7200Mat Workshop m/s Teamwork Garage Tel: 6844 2475of Blk 53 Ubi Ave 1 #01-24Policy No: _____ Claim No: SOMU2601

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 16.2.2022
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 16/2/2022 11:09am Person Contacted: Shu Shan Vehicle- IN OUT

| Date/Time | Action/Instruction (X) Estimate |
|-----------|---|
| | YP 4367K - NA / AA118016536/24 RUA - 03/04/2023 |
| | SME 7200M - X |
| 3/3/20 | - survey taken |
| 3/3/20 | - Ranger taken |
| 1/1 | - policy workshop update |

ASS. REC. BY: H ANNREF: ASW (A/R)

PRS

ASSIGNMENT

From: _____

Date: 3/3/2020

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: YP 4367Kat Workshop m/s Teamworkof 53 Ubi Ave / 1101-3p

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 3 days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS 477

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: YP 4367KYr Regn: 14/10/2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: HINO XZU70Kc.c. 4009Colour: white

A/C: Insured / Std / NI / NA

Sp. Reading: 137264km

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHHTC53470K003/42

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modl: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 7.00-16R: 7.00-16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 5 mm

mm

R/Bal. 4x2 mm

mm

L/Bal. 5 mm

mm

L/Bal. 4x2 mm

mm

D.O.A. 16/2/20D.O.I. 3/3/20Survey held at Teamwork

11/4AM

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range → 3-4.5h
 hyper days → 3 day

PRS cap

RECEIVED 13 MAR 2020

mv - 39000

PV - 3582

NV - 35400

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

12/3/20 Typist

Rep. Format: PRS

Lump Sum / L.B.J: _____

Days Of Repair: 3Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$ _____)

☐

Interview (\$ _____)

☐

Tech. Invs (\$ _____)

☐

Weekend (\$ _____)

Survey Fee: 100

Transportation: _____

S + RS: _____

Photos _____

Others _____

TOTAL

100



Service Request Details

Claim

S0M02GO1

Reference

None 

Loss Date

February 16, 2020

Report Date

Feb 25, 2020 9:08:00 AM

Request Date

February 25, 2020

Due Date

March 3, 2020

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

YP4367K

Model

XZU710R-HKFMS3-4.0 D (M)

Service Address

...

Primary Contact/Insured

POH EE HAI

BLK 34 EUNOS CRESCENT, #06-260, 400034, Singapore

83185345

Claim Handler

TAN Jas

6568804844

jas.tan@axa.com.sg

Additional Instructions

7

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

Summer Lee (LKK Auto)

From: TEAMWORK <claims@teamworkgarage.com>
Sent: Tuesday, 25 February, 2020 9:08 AM
To: NIKAM Santosh Pandurang
Cc: TEAMWORK
Subject: [EXTERNAL] RE: OUR REF : 2002-43 // YOUR REF : SME7200M
ACCIDENTINVOLVING SME7200M AND YP4367K
Attachments: GIA REPORT.PDF

Dear Santosh Nikam,

Sorry we have attached the GIA report for vehicle YP4367K.

Thank you and have a nice day.

Regards,

Shu Shan

Teamwork Garage Pte Ltd
Blk 53 Ubi Avenue 1
#01-24
Paya Ubi Industrial Park
Singapore 408934
Tel: 6844 2475
Fax:6844 2474

From: NIKAM Santosh Pandurang
Sent: Tuesday, 25 February 2020 9:04 AM
To: TEAMWORK
Subject: FW: [EXTERNAL] OUR REF : 2002-43 // YOUR REF : SME7200M ACCIDENTINVOLVING SME7200M AND YP4367K

Hi Sir / Madam,

Kindly confirm the vehicle no. mention in the subject line is different and the attach GIA report is different.

Regards,
Santosh Nikam

From: TEAMWORK [mailto:claims@teamworkgarage.com]
Sent: Monday, February 24, 2020 4:54 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>
Cc: TEAMWORK <claims@teamworkgarage.com>
Subject: [EXTERNAL] OUR REF : 2002-43 // YOUR REF : SME7200M ACCIDENT INVOLVING SME7200M AND YP4367K

WITHOUT PREJUDICE

OUR REF : 2002-43
YOUR REF : SME7200M

Dear Sir / Madam,
PRE-REPAIR INSPECTION FOR YP4367K
ACCIDENT INVOLVING SME7200M AND YP4367K ON 16.02.2020.

We refer to the above matter and enclosed herewith our client's GIA report and notification of Pre-repair inspection for your attention.

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction-Amendment No. 1 of 2016 of 2016 of Pre-repair Inspection for your attention.

Thank you and have a nice day.

Regards,

Shu Shan
Teamwork Garage Pte Ltd
Blk 53 Ubi Avenue 1
#01-24
Paya Ubi Industrial Park
Singapore 408934
Tel: 6844 2475
Fax:6844 2474

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Singapore - Externals or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Singapore - Externals or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62563562

To : AXA Insurance Pte Ltd

12/3/2020

Survey details

| | |
|---------------------|-------------------------|
| Date of loss | 16-Feb-20 |
| Date of appointment | 25-Feb-20 |
| Date of survey | 3-Mar-20 |
| Location of survey | Teamwork Garage Pte Ltd |

Vehicle Details:

| | |
|----------------------|---------------------|
| Claim Type: | Third Party |
| Vehicle number | YP 4367K |
| Make and Model | HINO XZU700R-HKFMS3 |
| Date of registration | 14-Oct-16 |
| Excess | |
| Market Value | \$39,000 |
| Part Rebate | \$3,582 |
| Nett Loss | \$35,418 |

Repair details

| | |
|------------------|--|
| Initial Estimate | |
|------------------|--|

Proposed/Revised repair cost:

| | |
|-------------------------|--|
| Parts | |
| Check item | |
| Labour | |
| Total | |
| Lump Sum(if applicable) | |

| | |
|--------------------------|---|
| Number of days of repair | 3 |
|--------------------------|---|

Remarks:

The estimated repair cost of the damaged vehicle is in the region of \$3,000.00 - \$4,500.00

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | |
|-------------------------------|-------------------------|
| Owner ID Type: | Company |
| Owner ID: | 736C |
| Vehicle Details | |
| Vehicle No.: | YP4367K |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 03 Mar 2020 |
| Vehicle Make: | HINO |
| Vehicle Model: | HINO XZU700R-HKFM53 |
| Primary Colour: | White |
| Manufacturing Year: | 2016 |
| Engine No.: | N04CUS28549 |
| Chassis No.: | JHHTCS3H70K003142 |
| Maximum Power Output: | - |
| Open Market Value: | \$30,342.00 |
| Original Registration Date: | 14 Oct 2016 |
| First Registration Date: | 14 Oct 2016 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$1,518.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | No |
| PARF Eligibility Expiry Date: | - |
| PARF Rebate Amount: | \$0.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 13 Oct 2026 |
| COE Category: | C - Goods Vehicle & Bus |
| COE Period(Years): | 10 |
| PQP Paid: | \$5,419.00 |
| COE Rebate Amount: | \$3,582.00 |
| Total Rebate Amount: | \$3,582.00 |

The information contained herein is correct as at 03 Mar 2020

OK


[Connect with Facebook](#)

HOME

NEW CARS

USED CARS

COMMERCIAL VEH

RENTAL CARS

SELL CARS

MOTOR DIRECTORY

Home > Used Commercial Veh > Hino XZU710R

HINO XZU710R

OVERVIEW

GALLERY

Share



| | |
|-------------------|-------------------|
| Price | \$45,800 |
| Registration Date | 14-Oct-2015 |
| COE Remaining | 5yrs 7mths 10days |
| Manufactured | 2015 |
| Mileage | 100,000 km |
| No. of Owners | 1 |
| Transmission | Manual |
| Engine Capacity | 4,009 cc |
| Fuel Type | Diesel |
| COE | \$5,833 |
| Paper Value | \$3,276 |
| Depreciation | \$8,150 / year |
| Type | Truck |

Singles50 in Singapore

www.singles50.sg


USED VEHICLE SEARCH

hino xzu710r

| | |
|------------------|--------------|
| Category | Vehicle Type |
| Transmission | Engine Cap |
| Min Price | Max Price |
| Min Depreciation | Max Depre |
| From Reg Year | To Reg Year |

Hino 14Pt Truck With 2 Side Sliding Door, 7Pt Height Box. New Paint. Superb Condition Taken Care By Seller. No Other Repair Required. Call Us Now To Arrange For Viewing.

For full set of photos and payment break-down, <https://www.sgcarmart.com/550665&DL=3431>

Status: Available | Category: -

Date Posted: 06-Jan-2020 | Date Updated: 20-Feb-2020

SELLER INFORMATION

Bell Auto Pte Ltd

8 Tuas Avenue 18 (Level 5 & 7) (map)

67457076

RAYMOND

96792154

SP TAN

97686949

"SAY YOU SAW THIS AD ON STCARS.SG!"



VEHICLE TOOLS

| | |
|---------------|-----------|
| COE Results | Loan Calc |
| Post an Ad | Road Tax |
| Carpark Rates | Car Insur |

SIMILAR VEHICLES



Mitsubishi Fuso Canter
FEBX1
04-Feb-2015
\$45,800



Mitsubishi Fuso Canter
FEB71
04-Sep-2014
\$49,800



Isuzu NHR85A Tipper (COE
till 08/2028)
06-Aug-2008
\$49,800



Isuzu NNR85
12-Jan-2017
\$50,000

Meet your mature soul

www.singles50.sg

LIFESTYLE

| | |
|-----------------|-----------|
| Food & Beverage | Health Ci |
| Home Needs | IT Produ |
| Men's Fashion | Men's Ho |

Top Team Management Tool

Project & Task Management Tool that Grows w/ Your Team. Free Trial. Write

Hino XZU700R 2015 Transmission Truck [* Contact Ad *](#) [Available Used Services](#) [X](#)

Home » Used Cars » United Overseas Bank Limited » Hino XZU700R

Hino XZU700R

[Overview](#) [Accessories](#) [Similar](#) [Research](#) [Photos](#) [Map](#)

We do not warrant the accuracy of this info.
The bidder is expected to do his/her due diligence checks before bidding.

| | | | |
|-----------------|---------------------------|---------------|--------------------------------------|
| Price | N.A | Lifespan | 03-Aug-2037 |
| Depreciation | N.A | Reg Date | 04-Aug-2017 (7yrs 5mths COE left) |
| Auction closing | 27th Mar 2019 at 11:00 PM | | |
| Mileage | N.A | Manufactured | 2017 |
| Road Tax | N.A | Transmission | Manual |
| Dereg Value | N.A | OMV | \$38,267 |
| COE | \$16,938 | ARF | \$1,914 |
| Engine Cap | 4,009 cc | No. of Owners | 1 |
| Curb Weight | 2,460 kg | | |
| Type of Vehicle | Truck | | |

Features

SRS Airbags, ABS.

Accessories

CD Player, Fog Lamps.

Description

With Key, This Vehicle Is Non GST Chargeable, Kindly Download The Non GST Chargeable Tender Form At This Link: <https://goo.gl/F6n7T9>

Category

Auction Vehicle

Status

Expired

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started




Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posted on: 23-Mar-2019 | Last updated on: 25-May-2019

Tags: Hino XZU700R, 2017 Hino XZU700R, Hino XZU700R

Recommended for you



Increase for Cat A and B while Cat E falls



Gojek to introduce \$0.70 surcharge



Vehicle sales and transfers to go online



218i Gran Coupe: BMW's compact fighter



8 Top European Car specialists in East



10 Best aircon repair & servicing experts

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|-----------------------|
| Date Of Report | 17/02/2020 12:03 |
| Date Of Accident | 16/02/2020 19:45 |
| Exact Location Of Accident | ALONG PAYA LEBAR ROAD |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|---------------------------------|
| Vehicle Registration Number | YP4367K |
| Insured/Policyholder | |
| Name Of Registered Owner | UNI-TAT ICE & MARKETING PTE LTD |
| Co Reg No | 1XXXXX736C |
| Email Address | EARL@POLARMART.COM.SG |
| Mobile Phone No | |
| Alternative Phone No | OFFICE-67448484 |

Vehicle Particulars

| | |
|--|--------------------------|
| Manufacturer | HINO |
| Model | XZU710R-HKFMS3-4.0 D (M) |
| Exact Purpose for which vehicle was being used at time of accident | |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | COMMERCIAL VEHICLE |

Insurance Company

| | |
|---------------------------|---|
| Name of Insurance Company | GREAT EASTERN GENERAL INSURANCE LIMITED |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | YES |
| Policy Number | 2019-V0105894-VCV-R001 |
| Cover Note Number | 14/10/2019 TO 13/10/2020 |

Driver

| | |
|----------------------|----------------------|
| Name of Driver | HE JINGZHI |
| NRIC No | GXXXX187X |
| Date Of Birth | 15/07/1989 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 29/11/2017 |
| Driving Experience | 2 YEARS AND 2 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-96657706 |
| Fax Number | |
| Contact Number | |
| Email Address | NOEMAIL |

Address 51 UBI AVENUE 1, #01-26, PAYA, UBI INDUSTRIAL PARK, SINGAPORE 408933

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

refer with attach.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SME7200M *Hyundai elantra 2015*

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- 1) Please report correctly on the details of the accident to speed up the claims process.
- 2) This form must be completed by the policy holder and/or the authorised driver.
- 3) Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4) The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5) Any false reporting may be referred to the police for investigation.
- 6) The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7) By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8) **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in the [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firm, the Monetary Authority of Singapore and any relevant government agency/authority (such as police), for the purpose(s) of :
 - (i) Processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigations the accident and/or my claims;
 - (iii) Carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) Administering my claims (including the mailing of correspondence, statement, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) Complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "purposes")
- (b) All insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyer/law firms, may/are permitted to collect, use, disclose and/or process my personal information for one or more of the above purposes; and
- (c) My personal information may/can be disclosed by any of the insurer and/or GIA to their third party service providers or agents (including their lawyer/law firms), which may be sited outside of Singapore, for one or more of the above purposes.
- (d) My personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) The information so collected under (d) above may be shared / disclosed:
 - (i) To all insurers and/or any other third parties that assist in evaluating, investigation, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposed stated, or
 - (ii) For complying with requirements under my regulations, laws or court orders.



Policyholder's Signature
Date & Time:

何#志

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



Vehicle B which was at the second lane suddenly cut into my lane and collided onto right side of my vehicle.

*****for company vehicle only*****
 I _____ is the _____ of
 company _____ and im using the vehicle
 _____ for work /private purpose .

I/We declare the foregoing particulars are true in every respect.



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9507198-R

Page No.: 1 of 1

| PRE-REPAIR INSPECTION REPORT | | | | |
|---|--|-----------------------------|---|---|
| AXA INSURANCE PTE LTD | | Ref: CS3/ASM20003122/Hyf3e2 | | |
| 8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811 | | Date: 19-03-2020 | |  |
| ATTN: JAS TAN | | Code: ASM | | |
| 1. Policy Particulars :- (THIRD PARTY CLAIM) | | | | |
| Insured Veh. | SME 7200M | Veh. Inspected | YP 4367K | |
| Policy No. | | Coverage (\$) | 0.00 | |
| Claim No. | S0M02GO1 | Excess (\$) | 0.00 | |
| Assign From | JAS TAN | Assign Date | 25/02/2020 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | HINO XZU700R | c.c | 4009 | |
| Engine No. | HIDDEN | Year of Reg. | 2016 | |
| Chassis No. | JHHTCS3H70K003142 | Colour | WHITE | |
| Odometer | 197254 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 7.00-16 | CASUMINA | 5 mm | |
| L/H Front Tyre | 7.00-16 | CASUMINA | 5 mm | |
| R/H Rear Tyre | 7.00-16 (D) | KENDA | 4/4 mm | |
| L/H Rear Tyre | 7.00-16 (D) | KENDA | 4/4 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. | | |  | |
| 5. General information | | | | |
| Accident Date | 16/02/2020 | Inspect Date / Time | 03/03/2020 (11:44 AM) | |
| Survey held at | TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934 | | | |
| 5a. Remarks | | | | |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,500 | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 3 Working Days | | |

Report Ref No. CS3/ASM20003122/Hyf3e2

Inspected By



LEE HOCK ANN

Asst. Automotive Assessor



K.K. LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MinstAE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.