

INS. CASE OWNER:

CC4 / A16 2000 3146 / D es3

LRR:
IDAC:

Surveyor:

ABT

DOI:

24/2/2020


Date / Time :

24/2/2020

Registered in Merimen:

25/2/2020

Pre-assign / CCU / FTE



Insured Vehicle No. : SGZ 7722J

Claim No. : _____

Name of Insured : _____

Policy No. : _____

Insured Tel No. : _____ HP: _____

Make / Model : _____

Excess Sec II : S\$ _____ D.O.A : 13/2/2020

Place of Accident : _____

Is driver the owner? (YES / NO) Nature of Accident : _____

If NO, Driver Name / Age : _____


OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : _____

(V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SH8443K



INSRS:

WSP: Bifrost

Tel : _____

Liability : _____

RMKS: _____



INSRS:

WSP: _____

Tel : _____

Liability : _____

RMKS: _____



INSRS:

WSP: _____

Tel : _____

Liability : _____

RMKS: _____



INSRS:

WSP: _____

Tel : _____

Liability : _____

RMKS: _____

Date/ Time	STAGE	DATE / PIC
SH8443K : CC3 / CA1 / 40 / 6423 / H1 / py 3w3; DOA: 26/8/14	Non-Reporting ltr (1st):	
SGZ 7722J : CV1 / 0CB / 5007479 / RKC; DOA: -	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☐ ☐
	After call ltr to OI:	☐ ☐
	Authorisation To Act:	☐ ☐
	Release Voucher:	☐ ☐
	Final Repair Bill:	☐ ☐
	Car Rental Invoice:	☐ ☐
	Towing Invoice	☐ ☐
	LTA / GIA :	☐ ☐
	Medical Bill:	☐ ☐
	PIR:	☐ ☐
	Mandate/Reject Instruction:	☐ ☐
	LOD	☐ ☐
	Payment Breakdown Form:	☐ ☐
PRELIMINARY ADVICE Date/Time: _____ Sent By: _____	Post-Repair Photos:	☐ ☐
	Others:	☐ ☐
FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____		
Repair Cost: S\$ _____ (_____ days) Reduction: _____ % Email ☐ Call ☐		
FINAL SETTLEMENT Date/Time: _____ Confirm with: _____ Email ☐ Call ☐		
Final Liability: % (Agreed / Assessed) BOLA S/N No. : _____ If NO or B 28, Ass. Lia : _____		
Repair Cost: S\$ _____		
Loss of Rental (LOR): S\$ _____ (_____ days)		
Loss of Use (LOU): S\$ _____ (\$ _____ x _____ days)		
Loss of Income (LOI): S\$ _____ (\$ _____ x _____ days)		
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]		
GIA/LTA Search S\$ _____		
Medical: S\$ _____		
Disbursement: S\$ _____ (e.g. Tow/ Independent)		
Legal Cost S\$ _____		
Total: S\$ _____ Global Sum S\$: _____		
FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email ☐ Call ☐		
Payee 1: S\$ _____ Name 1: _____		
Payee 2: (Strike if N.A.) S\$ _____ Name 2: _____		
Payee 3: (Strike if N.A.) S\$ _____ Name 3: _____		

ASSIGNMENT

06 June 2027

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SH 8443K Yr Regn: 2019, June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Ioniq C.C. 1580Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 84270 T/Radio: Insured / Std / NI / NAEng/No: G4LEKU295283C/No: KMHC851CVKU164256Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15R: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: Daewoo Rear: MichelinR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 13/02/2020 D.O.I. 24/02/2020Survey held at Bijrost Sin Ming

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Portion

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

AIG 8GZ7722JTP video show TP must kerb upon collision. Left side must kerb.

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / L&L: () _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. _____ SI

Photos

Others

TOTAL