

22/03/2002

ASS. REC. BY:

REF:

08/AGI 2003187/KSD3

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Ivy Ratilla

of

AGI

Date/Time: 24/2/2020 @ 4.51pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

JQQ 2293

Insured:

SKL 1247E

at Workshop m/s

AE Auto

Tel:

9382 5367

of

160 Sin Ming Drive #06-01

Policy No:

Claim No:

C10005674

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 23/02/2020

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 5:09pm @ 26/2/2020

Person Contacted:

Ryan

Vehicle

IN/OUT

Date/Time	Action/Instruction
	Johny (✓)
	JQQ 2293 - X
	SKL 1247E - X

ASS. REC. BY:

REF: AGZ/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

10 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐


Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$



Veh No:

JQQ 2293

Yr Regn:

02, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Tractor

c.c

1998

Colour

A. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

59161

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

PN111NV401864602

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

205/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

23/2/20

D.O.I.

25/2/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S body & UIC

The UIC / Chassis frame / Body Structure affected due to collision.

Nivitha (LKK Auto)

From: Ivy Ratilla <ivy.r@budgetdirect.com.sg>
Sent: Monday, 24 February 2020 4:51 PM
To: Admin-D (LKKAuto)
Cc: SUR; Julie Mangubat
Subject: FW: ARRANGE PRE REPAIR INSPECTION FOR OUR VEHICLE JQQ 2293 || C10005674

Hi Team,

We would like to arrange TP PRS for JQQ2293. We do not have a copy of our PH's report yet. They have chosen Mr. Kenneth Kong To survey their client's vehicle.

Workshop information:

Location : AE AUTO PTE LTD
160, Sin Ming Auto Drive
Sin Ming Auto City # 06-01
Singapore 575722.
Handphone : 93825367 / 90030857 .
DirectLine : 64535654
Fax : 64591698

Please confirm. Thank you.

Regards,

Ivy Ratilla
Executive, Claims Admin

T +65 6540 2185
F +65 6725 0853
E ivy.r@budgetdirect.com.sg

Customer Care +65 6221 2111
Claims +65 6221 2199
Claims (Int.) +65 6540 2199

190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore 239924
budgetdirect.com.sg

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as Budget Direct Insurance.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

-----Original Message-----

From: Autoexcel Engineering Pte Ltd <aeexcel@singnet.com.sg>
Sent: Monday, 24 February 2020 4:36 PM
To: Ivy Ratilla <ivy.r@budgetdirect.com.sg>; Claims <claims@budgetdirect.com.sg>
Cc: Julie Mangubat <julie.m@budgetdirect.com.sg>
Subject: RE: ARRANGE PRE REPAIR INSPECTION FOR OUR VEHICLE JQQ 2293 || C10005674

Dear Officer In Charge ,

We wish to select Kenneth Kong LKK Auto Consultants Pte Ltd

Thank you & Regards

Ryan Soh (Manager)
Handphone : 93825367 / 90030857 .
DirectLine : 64535654
Fax : 64591698

-----Original Message-----

From: Autoexcel Engineering <aeexcel@singnet.com.sg>
Sent: Monday, 24 February 2020 4:02 PM
To: Claims <claims@budgetdirect.com.sg>
Subject: ARRANGE PRE REPAIR INSPECTION FOR OUR VEHICLE JQQ 2293 .

Dear officer In Charge,

Our vehicle JQQ 2293
Your insure SKL 1247 E
Date accident 23/02/2020

Please give us the lists of surveyor for Pre Repair Surveyor

Location : AE AUTO PTE LTD
160, Sin Ming Auto Drive
Sin Ming Auto City # 06-01
Singapore 575722.

Thank you

Regards
Ryan Soh 93825367 /64535654

-----Original Message-----

From: ricohscan691@gmail.com <ricohscan691@gmail.com>
Sent: Monday, February 24, 2020 3:47 PM

AE AUTO PTE LTD
160, Sin Ming Drive
Sin Ming Auto City #06-01
Singapore 575722
Tel: 64535654, 64591630
Fax: 64591698

Not withstanding
11 Day 8?
Recovery After Paint
10 days

Date : 24/02/2020

QUOTATION -THIRD PARTY CLAIM

AUTO & GENERAL INSURANCE (SINGAPORE) PTE LTD

Attn: Motor Claim Department . Officer In Charge

Claim : Third Party Claim
Veh. No : JQQ 2293
Model : TOYOTA INNOVA
Insured Ins: KURNIA

Accident on : 23/02/2020

QTY	PARTICULARS	W/S	ESTIMATE	SURVEYOR
	Your insure : SKL 1247 E			
1	FRONT LH FENDER	\$ R	580.60	✓
1	FRONT LH FENDER UNDERSHIELD	\$	282.00	✓
10	FRONT LH FENDER UNDERSHIELD CLIPS	\$	35.00	✓
1	FRONT LH WHEELHUB	\$	420.00	?
1	FRONT LH WHEEL BEARING	\$	285.00	?
1	FRONT LH LOWER ARM	\$	448.00	?
1	FRONT LH KNUCKLE ARM	\$	469.00	?
1	FRONT LH SUSPENSION	\$	620.00	?
1	FRONT LH DOOR	\$ R	1,228.50	✓
1	FRONT LH DOOR OUTER HANDLE	\$ R	385.00	X
2	FRONT LH DOOR HINGES	\$ R	480.00	✓
1	FRONT LH DOOR CENTER HINGE	\$	225.00	?
1	FRONT LH DOOR TRIM BOARD	\$	680.00	?
1	FRONT LH DOOR LOCK	\$ R	450.00	X
1	FRONT LH DOOR INNER GARNISH/ FLAP	\$	282.00	?
1	FRONT LH DOOR OUTER MOULDING	\$ R	398.60	X
1	FRONT LH DOOR WEATHERSTRIP	\$ R	298.00	508.00
1	FRONT LH DOOR PILLAR RUBBER	\$	266.50	?
1	FRONT LH DOOR PILLAR LOWER GARNISH	\$ R	383.00	X
1	FRONT LH WINDOW GEAR	\$ R	520.60	✓
1	FRONT LH WINDOW GEAR MOTOR	\$ R	388.78	✓
1	LH SIDE ROCKER PANEL	\$	980.50	?
1	LH SIDE CENTER PILLAR INNER	REPAIR		
1	LH SIDE CENTER PILLAR OUTER	\$ R	744.50	✓
1	LH SIDE CENTER PILLAR GARNISH	\$ R	447.00	X
1	REAR LH DOOR	\$ R	1,220.30	✓
2	REAR LH DOOR HINGES	\$ R	480.00	X
1	REAR LH DOOR TRIM BOARD	\$ R	680.00	X
1	REAR LH DOOR LOCK	\$ R	450.00	X
1	REAR LH DOOR OUTER MOULDING	\$ R	398.00	X
1	REAR LH DOOR OUTER HANDLE	\$ R	385.00	X
1	REAR LH DOOR WINDOW GEAR	\$	520.60	?
1	REAR LH DOOR WINDOW GEAR MOTOR	\$	388.78	?
1	TAILAMP LH	\$	580.00	?
1	TAILAMP LH LOWER BRACKET	\$	180.00	?
1	TAILAMP LH SIDE CLIP	\$	20.00	?
1	REAR LH FENDER	\$ R	988.85	X
1	REAR LH FENDER UNDERSHIELD	\$ R	285.00	X
1	REAR LH MUDFLAP	\$ R	220.00	X

5QQ 2293

Page 2

AE AUTO PTE LTD
160, Sin Ming Drive
Sin Ming Auto City #06-01
Singapore 575722
Tel: 64535654, 64591630
Fax: 64591698

AE AUTO PTE LTD
160, Sin Ming Drive
Sin Ming Auto City #06-01
Singapore 575722
Tel: 64535654, 64591630
Fax: 64591698

500 2293

QTY	LABOUR	AMOUNT	SURVEYOR
	Balance b/f	\$ 23,667.08	
	LABOUR :		
	Labour charges to replace repair, cutting welding, align adjust on accident area	\$ 1,600.00	1100
	Remove refix, replace garnish, trim board car seat upholstery etc	\$ 300.00	1201
	Labour to replace undercarriage and rim	\$ 500.00	?
	To do computer wheel alignment	\$ 80.00	✓
	Anti rust	\$ 120.00	901
	Transfer doors parts to another door	\$ 200.00	1201
	Remove refix fuel tank	\$ 250.00	X
	Sealant seal gap, on cutting welding area, waterproofing	\$ 250.00	601
	To do chassis body alignment	\$ 350.00	X
	To do spray painting on accident area	\$ 1,400.00	12001
	Check wiring system, check door wiring etc	\$ 200.00	401
	LABOUR :	\$ 5,250.00	
	TOTAL PARTS & LABOUR :	\$ 28,917.08	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



REPORT

Pegawai Penyiasat : R130080
No. Repot Bersangkut : TRAFIK JOHOR
BAHRU(S)005058/20

Balai :
Daerah :
Kontinjen :
No. Repot :
Tarikh :
Waktu :
Bahasa Diterima :
TRAFIK JOHOR BAHRU(S)
JBAHRU SELATAN
JOHOR
TRAFIK JOHOR BAHRU(S)005069/20
23/02/2020
17:17 PM
B. Malaysia

Butir-butir Penerima Repot :

Nama : WONG SIEW HUONG

No. Badan : R190482

Pangkat : UKPL

Butir-butir Jurubahasa (Jika Ada) :

No. K/P (Baru) : ---

No. Polis/Tentera : ---

Nama : ---

Bahasa Asal : ---

No. Pasport : ---

Alamat : ---

Butir-butir Pengadu :

Nama : HAMED BIN SAHIL BAGUSHAIR

No. K/P (Baru) : ---

No. Polis/Tentera : ---

No. Pasport : E5695991J

No. Sijil Beranak : ---

Jantina : Lelaki

Tarikh Lahir : 11/01/1956

Umur : 64 Tahun 1 Bulan

Keturunan : ARAB

Warganegara : SINGAPORE

Pekerjaan : SWASTA

Alamat Tinggal : BLK 498H TAMPINES ST 45 #01-452, 526498 SINGAPORE

Alamat IbuBapa : ---

Alamat Pejabat : ---

No. Tel (Rumah) : ---

No. Tel (Pejabat) : ---

No. Tel (Bimbit) : 6582227603

Emel : ---

Pengadu Menyatakan :

PADA 23/02/2020 JAM LEBIH KURANG 14:45HRS,SAYA MEMANDU MOTOKAR NOMBOR SKL1247E DARI PLAZA PELANGI HENDAK KE KOTA RAYA.PADA KETIKA ITU,APABILA SAYA SAMPAI DI JALAN KUNING,SAYA HENDAK MEMBELOK KE KANAN.APABILA SAYA LIHAT KE KIRI DAN KANAN DAPATI TIADA KENDERAAN,SAYA PUN MEMBELOK SEMASA SAYA MEMBELOK,TIBA-TIBA SEBUAH MPV NOMBOR JQQ2293 DATANG DARI SEBELAH KANAN SAYA MENYEBABKAN SAYA TIDAK SEMPAT BREK DAN TIDAK ELAK LALU TERLANGGAR BAHAGIAN TERI KIRI MPV TERSEBUT.DALAM KEJADIAN ITU, SAYA TIDAK MENGALAMI APA-APA KECEDEPERAN KEROSAKAN MOTOKAR SAYA IALAH BUMPER HADAPAN DAN LAMPU HADAPAN KANAN.LAIN-LAIN KEROSAKAN DAN NILAI KERUGIAN TIDAK PASTI,SEKIAN LAPORAN SAYA.

Tandatangan Pengadu :


Tandatangan Jurubahasa(Jika ada):

Tandatangan Penerima Repot:

ID Pencetak | Tarikh @ Masa Cetak

R190482 | 23/02/2020 05:25:29 PM

23/2020



POLIS DIRAJA MALAYSIA

REPOT POLIS

Balai : TRAFIK JOHOR BAHRU(S)
Daerah : J/BAHRU SELATAN
Kontinjen : JOHOR
No. Repot : TRAFIK JOHOR BAHRU(S)/005058/20
Tarikh : 23/02/2020
Waktu : 1547 PM
Bahasa Diterima : B. Malaysia

Pegawai Penyiasat : R130080

Butir-butir Penerima Repot :
Nama : MOHAMMAD HARRIS BIN HARNAIN
No. Badan : R193183
Pangkat : KONST

Butir-butir Jurubahasa (Jika Ada) :
Nama : —
No. : —
Pasport : —
Alamat : —
No. K/P (Baru) : —
Bahasa Asal : —
No. Polis/Tentera : —

Butir-butir Pengadu :
Nama : CHING KEE CHAU
No. K/P (Baru) : 690512085177
No. Sijil Beranak : —
Umur : 50 Tahun 9 Bulan
Pekerjaan : SWASTA
Alamat Tinggal : NO 33 JALAN SURIA 46 BANDAR SERI ALAM, MASAI, 81750 JOHOR
Alamat IbuBapa : —
Alamat Pejabat : —
No. Tel (Rumah) : —
Emel : —
No. Polis/Tentera : A1278564
Jantina : Lelaki
Keturunan : Cina
No. Pasport : —
Tarikh Lahir : 12/05/1969
Warganegara : Malaysia
No. Tel (Pejabat) : —
No. Tel (Bimbit) : 0187698198

Pengadu Menyatakan :
PADA 23/02/2020 JAM LEBIH KURANG 1445HRS SAYA MEMANDU M/KAR NO JQQ2293 DARI TAMAN TUN AMINAH. APABILA SAMPAI DI JALAN KUNING, SAYA JALAN TERUS. TIBA-TIBA ADA SEBUAH M/KAR NO SKL1247E KELUAR DARI SIMPANG SEBELAH KIRI LALU MELANGGAR M/KAR SAYA DI BAHAGIAN TEPI KIRI. SAYA TIDAK CEDERA. KEROSAKAN M/KAR SAYA TEPI KIRI, PINTU DEPAN BELAKANG, MUDGUARD DEPAN BELAKANG, ARM RIM TAYAR DEPAN BELAKANG, SKIRT BAWAH, BUMPER DEPAN BELAKANG, CERMIN SISI, DAN LAIN-LAIN KEROSAKAN YANG BELUM PASTI. SEKIAN LAPORAN SAYA.

Tandatangan Pengadu : 
Tandatangan Jurubahasa (Jika ada):
Tandatangan Penerima Repot: 