

SIN 117

REF:

AXA

Rasu 1

ASSIGNMENT

From

Date

6/3/18

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

FS 9322R

at Workshop no:

Sg 98 Motor

of

Insured

Policy No

Claims No

Sum Insured:

Excess:

(Client's Record)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

1wp

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FS 9322R Reg 12 11

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make:

SYM Joyride

cc:

172

Colour:

Black

AC

Insured

Std / Nil / NA

Sp. Reading:

Not Available

Radio

Insured

Std / Nil / NA

Eng No:

C No:

Gen Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod:

NR / SRim / STD A/Rim or

Tyre Size

F 110/90-13

R 130/70-12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front:

Rear:

R.Bal:

3

mm

R.Bal:

3

mm

L.Bal:

mm

L.Bal:

mm

D.O.A:

D.O:

7/3/2018

Survey held at:

As Above

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roof top or

The U/C / Chassis/frame / Body Structure affected due to collision

Date / Time Action / Instruction

7/3/2018 Mileage Not Available - No Basic Supply

Steering Found Damaged During Survey

Repair: Estimate Workshop will send to LKK

C/No - 114444

REPAIR RANGE \$4-6K

Date/Time File Pass to:

☐

Prel. Report

Days Of Repair:

☐

Final Report

Resurvey No. of Trip

Date/Time File Return to:

Survey Fee

Transportation

Fuel

Food

Tools

Other

Total

Report Format

Lum Sum / (E) / (S)

Add Fee:

☐

Steiner

3

☐

Grease

3

☐

Tie Rod

3

☐

Bolt

3

☐

Wash

3