

NATIONAL Assessment Centre Services

[Part 1 Jan 09]

MNA 120025713

Date In: 27/12/20 11:53	Job description: SAS e-filing	Date & Time Completed:	Done by:
Ref No: NA/INC 2000 3233/44	E-mail (within 3hrs, AIC 2hrs)		
Veh No: SGS 7997U	I-Motor Claim Form	MT/1086123-031	28/12/20 09:51
ICCA: 27/12/20 08:50	I-Motor W/O (Within: OD 2hrs, TP 4hrs)		
	I-Photo Uploaded		
	Assessment/Survey Report		
	Ass't Report by Fax / Hand to Owner/Wksp		

Preferred Wksp / INC Assign Wksp / GW: ()	Tel: ()	Fax: ()
TP Particulars:	Veh No: SLJ 525PX	INC () / Non-INC ()
Owner / Driver: ()	Tel: ()	
Policy No: ()	Period: ()	Cover Type: ()
Confirmed by: ()	Date: ()	Time: ()
Insured/Driver Liability: () %	[Note-Est. Status (WO): N: 0-20%; P: 21-79% P: 80-100%]	
Year of Registration: ()	Warranty: YES () / NO ()	
Excess: (\$)	Loading: \$1,000 () / \$2,000 ()	

General Remarks:

() Walk-In Customer: Customer's Information strictly Confidential & Strictly NO refer of repaler.

() Total Loss Case: to e-mail Insurer URGENTLY.

Drive-In () / Towed-In () ; Invoice: YES () / NO () ; Towing Co: ()

Remarks: (INC Ref No: 6788 6616)	Date & Time Completed:	Done by:
1) Apply for Transport Allowance () / Courtesy Car ()		
2) QC Check / Post Repair Inspection ()		
3) Upload Resurvey Photo [Repair Cost > \$3000] ()		

Injury: ()

Date/Time	Actions

NA 2001842

Client's Particulars:	Invoice Ref: NA 2001842	Invoice (S): 30.00	Reserve (S): 30.00
Driver/Owner:	1) AR: Accident Reporting (\$30);		
Contact No:	2) DA: Damage Assessment (\$100); INC (\$30)		
Damaged Portion:	3) TP: Towing Fee 540/543		
	4) PT: Follow-Through Survey \$120		
	5) PT: Follow-Through Survey (Resurvey) \$30		
	For claimant's use only (w/c 10 Jan 2009)		
	6) TR: Re-inspection \$75		
	7) N1: Idao DA + SMRT Survey \$160		
	8) NTUC Additional Services:		
	ON:		
	*N5: Courtesy Car / Tpt Allowance 35		
	*N6: Repair Co-ordination 510	10.00	
	*N7: Post Repair Inspection 325		
	*N8: DV / Collect Excess Coordination 35		
	TP (N11): TP (INC) against INC 520		
	9) N12: Idao Mobile 30		
Auditor's Comments:	Invoice dated	Fee Charged	
	Invoice dated	Fee Charged	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/02/2020 11:53
Date Of Accident	27/02/2020 08:50
Exact Location Of Accident	67 UBI AVE 1 (STARHUB GREEN)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGS7997U
Insured/Policyholder	
Name Of Registered Owner	CHAY WEN LIANG (XIE WENLIANG)
NRIC No	SXXXX520E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98522312
Alternative Phone No	OFFICE-98522312

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5107600658
Cover Note Number	

Driver

Name of Driver	CHAY WEN LIANG (XIE WENLIANG)
NRIC No	SXXXX520E
Date Of Birth	12/09/1976
Occupation	INDOOR
Date Of Driving Pass	17/03/1997
Driving Experience	22 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98522312
Fax Number	
Contact Number	OFFICE-98522312
EMail Address	NOEMAIL

Address	121 SUNSET WAY #02-02
Postcode	597153
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	HAVENT RETRIEVE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLJ5258X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	SIN HING FONG
NRIC/Passport Number	SXXXX506I
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

Starhub Green

67 Vbi Ave 1

A

B

↑ ↓

A = SGS 7997U

B = SLJ 5258X

B = 52J 5258X

Turn into driveway to Starhub Green. On turning right, turned too early and driver B car inadvertently hit my A front right wheel area.

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.		Date of Accident	27/02/2020 11:46
Vehicle No. (For Motor)	SGS7997U	Certificate Number	
Search			

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☐	5107600658		CHAY WEN LIANG (XIE WENLIANG)	S7631520E	GPC	drivo CLASSIC	SGS7997U	SGS7997U	14/03/2019	13/03/2020

Claim Handling

Accident MT/1086123

Policy No.	5107600658	Vehicle No.	SGS7997U	GST Registration No.	
Certificate No.					
Policyholder Name	CHAY WEN LIANG (XIE WENLIANG)			Policyholder NRIC	S7631520E
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading	0
Contact No.(Mobile)	98522312	Contact No.(Office)		Contact No.(Home)	
Email Address		Special Remark		eCode	No
KFK	☒ No ☐ Yes	TCA	☒ No ☐ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	50	Private Hire	No
▼ Accident Details					
Report Date	28/02/2020 09:45	Accident Report Within 24 hrs	Yes	Accident Type	Side Swipe
Date of Accident	27/02/2020	Time of Accident hh:mm	08:50	Country of Accident	Singapore
Reporting Centre		Orange Force		ICM No.	
Accident Location	67 UBI AVE 1 (STARHUB GREEN)				
▼ Total Excess Applicable					
Excess Type	Per Accident	Windscreen Excess	100.00		
OD Standard Excess	600.00	TP Standard Excess	0.00		
YIED OD Excess	0.00	YIED TP Excess	0.00	Driver is Covered?	Covered
Additional Excess	0				
Total OD Excess Applicable	600.00	Total TP Excess Applicable	0.00		
▼ Benefits					
▼ GST Registered Information					
GST Registered	No	GST Registration Date			
GST Registration No.		GST Status Verified	Yes		
Modification History					
▼ Policyholder Mailing Address					
Address 1	121 SUNSET WAY	Address 2	#02-02 CLEMENTI PARK	Address 3	SINGAPORE 597153
Address 4		Address Type	Singapore address	Post Code	597153
Unit No.		Related Policy Number	5107600658		
▼ OI Driver Info					
Driver Name	CHAY WEN LIANG	Driver Type	Main Driver	Driver DOB	12/09/1976
Unnamed driver Name		Driver NRIC	S7631520E	Driving Experience	22
Register Date of Driver License	17/03/1997	Driver Age	43	Contact No.(Home)	
Contact No.(Mobile)	98522312	Contact No.(Office)		Address 3	SINGAPORE 597153
Address 1	121 SUNSET WAY	Address 2	#02-02 CLEMENTI PARK	Post Code	597153
Address 4		Address Type	Singapore address		
Unit No.					
Does he own a Singapore Registered car?	☐ Yes ☒ No	Driver Vehicle No.		Driver Insurer Company	
Declaration					
Breathalyser or Blood Test Reading?	0 mg	Any injury?	☐ Yes ☒ No		
Modification History					

Claim 001 New

Claim Type *	OD-MD	Insured Name	CHAY WEN LIANG (XIE WENLIANG)	Insured NRIC	S7631520E
Contact No.(Mobile)	98522312	Contact No.(Home)	64690292	Contact No.(Office)	682571
Email Address	JUSTCHAY@OUTLOOK.COM	OI Vehicle Number	SGS7997U	TP Vehicle Number	SLJ525
Claim Description	SGS7997U / SLJ525EX ON 27 Feb 2020				
Preferred Workshop	0	Insured Liability	Fully at Fault	Name of Preferred Workshop	0
Repair No. Finalisation	Yes	Preferred Repair Option	Income to assign workshop	GIA report	Received
Date Registered		Claim Close Date	28/02/2020 09:50	Date Received	28/02/2020
Report Taken By	LIEW SHAN HUI				
☒ Print AX letter					

Save Submit

Attachment

Accident No.	MT/1086123	Claim No.	001
Last Doc. Received	☒ Yes ☐ No	Upload Date	28/02/2020 09:51
Path *			
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Message Read		Clear	Please Select
▼ Attachment List			

Category *	Confidential	Urgency *	Descr
Please Select	NO	Normal	
Please Select	NO	Normal	
Please Select	NO	Normal	
Please Select	NO	Normal	
Please Select	NO	Normal	
Please Select	NO	Normal	
Please Select	NO	Normal	

2/2

ASS. REC. BY:

REF:

Assessor:

Mobile: YES / NO

ASSIGNMENT (IDAC)**By CSO- Nature of Accident:**

- 1) Vehicle hit Vehicle: 2) Vehicle hit ??
- a) Motorcar () a) Pedestrian ()
- b) Motorcycle () b) Animal ()
- c) Bicycle ()
- 3) Vehicle hit Road Side Objects:
- a) Govn. Property () b) Road Work Object ()
- (Eg: signboard, barrier, tree etc)
- c) Private Property ()
- 4) Vehicle drop into drain ()
- 5) Damage due to Act of God:
- a) Fallen Object () b) Flood ()
- c) Other, _____
- 6) Parked & Found Damaged:
- a) Vandalism () b) Hit by Moving Object ()
- 7) Theft Case
- a) Stolen () b) Damage found ()
- when recovered.
- 8) Fire
- a) Whilst driving () b) Parked ()
- 9) Accident date more than 24hrs ()

Remarks for internal information**Remarks to appear in Works Order & Assessment report**

- 1) Potential Total Loss ()
- 2) SRS Light on ()
- 3) ABS Light on ()

By Assessor- 1) Vehicle Information

Veh No: SGS 7997 U Yr Regn: 14 Mar 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / M/V

/ Truck / Trailer or

Make & Model: Honda Civic 1.6 VTI C.C. 1597

Colour: Silver Transmission Type: Auto / Manual

Eng/No: _____ Sp. Reading: 38823

C/No: MRHFC5650GT001020

Gen. Cond: Good / Fair / Poor / Burnt or

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/50 R17

R: _____

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front		Rear	
R/Bal.	<u>6</u> mm	R/Bal.	<u>7</u> mm
L/Bal.	<u>6</u> mm	L/Bal.	<u>7</u> mm

Parallel Import: Yes / No Towed-In: Yes / No

Repair Type: LS / I.B.I Towing Required: Yes / No

No of Repair Days: 10 Vehicle in Idac: Yes / No

D.O.I. 28/2/2020 Time: 9.10 am

By Assessor- 2) Comments

1) Damages not due to recent accident.

2) Damages do not seem hit onto:

- a. Vehicle () b. Motorcycle () c. Bicycle () d. Pedestrian ()
- e. Animal () f. Govn Object () g. Road Work Object ()
- h. Private Property () i. Drain () j. Road Kerb/Grass Verge ()

3) Vehicle does not seem damaged as a result of:

- a. Fallen Object () b. Flood () c. Vandalism () d. Fire ()
- e. Moving Object () f. Stolen () g. Stolen & Recovered ()

Time Started:

Time completed:

1) CSO

2) ASS

3) Entire Operation Completed Time:

(01) Dent (02) Dented (03) Distorted (04) Cracked (05) Cut (06) Scratched (07) Deformed
(08) Shifted (09) Buckled (10) Broken (11) Necessary (12) Missing (13) Torn
(14) Unusable (15) Not Working

MOTOR CAR (Frt)

ACT/REPL/AC

(1) Replace (✓) (2) Repair (C) (3) Check (✓)
(4) Not Consistent (N/C)

Aug 2008
1 JB4

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper			
1005	992341	Frt Bumper Clips			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

Vehicle No. 56879974

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			
		RH Headlamp Top Chrome			

No of Items:

Accessories:

Condition (COS)

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary (12) Missing
(13) Torn (14) Unconfirmed (15) Not Working

MOTOR CAR (RH)

ACBON (AC)

(1) Replace (✓) (2) Repair (X) (3) Check (7)
(4) Not Consistent (INC)

2 of 4

Right Portion

Vehicle No: SGS7997 Y

NAC	INC	Item	CON	AC	Qty
1316	995327	Frt RH Door	BUC		
1317	991654	Frt RH Door Protector			
1318	991601	Frt RH Door Hinge	?		
1319	991685	Frt RH Door Wing Mirror			
1320	991583	Frt RH Door Garnish			
1321	991639	Frt RH Door Glass Outer Moulding			
1322	991588	Frt RH Door Glass Inner Moulding			
1323	991584	Frt RH Door Glass			
1324	991595	Frt RH Door Glass Regulator	?		
1325	991596	Frt RH Door Glass Regulator Motor			
1326	991662	Frt RH Door Rubber	?		
1327	991636	Frt RH Door Outer Handle			
1328	991607	Frt RH Door Inner Handle			
1329	991625	Frt RH Door Lock w/Key			
1330	991624	Frt RH Door Lock			
1331	991562	Frt RH Door Central Lock			
1332	991675	Frt RH Door Switch			
1333	991617	Frt RH Door Inner Trim Board			
1334	991568	Frt RH Door Checker			
1335	991575	Frt RH Door Felt			
1336	991688	Frt RH Door Wire Harness			
1337	991683	Frt RH Door Window Glass Pillar			
1338	991640	Frt RH Door Outer Pillar			
1339	991613	Frt RH Door Inner Pillar			
1340	991646	Frt RH Door Pillar Inner Garnish			
1341	990554	Centre Pillar RH			
1342	990543	Centre Inner Pillar RH			
1343	990518	Centre Pillar Upper Garnish RH			
1344	990565	Centre Pillar Lower Garnish RH			
1345	991670	Frt RH Door Step Garnish			
1346	994058	Rocker Panel RH			
1347	994049	Rocker Panel Inner Panel RH			
1348	994047	Rocker Panel Garnish RH	CAT		
1349	994055	Rocker Panel Outer Side Skirt RH			
1004	991300	Frt Bumper			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1030	991821	Frt RH Headlamp Assy			
1032	995089	Frt RH Side Lamp			
1105	995071	Frt RH Fender			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			

NAC	INC	Item	CON	AC	Qty
1350	993201	Rear RH Door	BUC		
1351	993284	Rear RH Door Protector			
1352	995307	Rear RH Door Hinge	?		
1353	993228	Rear RH Door Garnish			
1354	993278	Rear RH Door Glass Outer Moulding			
1355	993231	Rear RH Door Glass Inner Moulding			
1356	993229	Rear RH Door Glass			
1357	993289	Rear RH Door Glass Regulator	?		
1358	993240	Rear RH Door Glass Regulator Motor			
1359	993294	Rear RH Door Rubber	?		
1360	993276	Rear RH Door Outer Handle			
1361	993251	Rear RH Door Inner Handle			
1362	993261	Rear RH Door Lock			
1363	993256	Rear RH Door Inner Trim Board			
1364	993218	Rear RH Door Checker			
1365	993230	Rear RH Door Glass Channel			
1366	993242	Rear RH Door Glass Triangle Garnish			
1367	993285	Rear RH Door 1/4 Glass			
1368	993288	Rear RH Door 1/4 Glass Rubber			
1369	993287	Rear RH Door 1/4 Glass Pillar			
1370	993306	Rear RH Door Step Garnish			
1371	993309	Rear RH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1141	992958	Rear Bumper			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1151	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1166	995116	Rear RH Taillamp			
1228	993456	Rear RH Fender	BUC		
1229	993450	Rear RH Fender Protector			
1136	990247	Sticker			

No of Items:

Assessor:

(01)Bent (2)Dented (3)Distorted (4)Cracked (5)Cut (6)Scratched
(07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary
(12)Missing (13)Torn (14)Unconfirmed (15)Not Working

MOTORCAR (Rear)

(1)Replace (✓) (2)Repair (✓) (3)Check
(4)Not Compliant (N/C)

314

Rear Portion

Vehicle No: SGS 799 TV

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	SCR	R	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

No of Items: _____

Assessor: _____

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

ACTION (AC)

(1) Replace (✓) (2) Repair (X) (3) Check (?)
(4) Not Consistent (NC)

Aug. 2005

(44)

Vehicle No: SG 57997 U

NAC	INC	Item	CON	AC	Qty
1372	995163	Frt LH Shock Absorber			
1373	991944	Frt LH Shock Absorber Mounting			
1374	990632	Frt LH Coil Spring			
1375	995198	Frt LH Knuckle Arm			
1376	995199	Frt LH Knuckle Arm Bearing			
1377	995178	Frt LH Lower Arm			
1378	995169	Frt LH Upper Arm			
1379	995183	Frt LH Tie Rod			
1380	995143	Frt LH Drive Shaft			
1381	990661	Frt LH Control Arm			
1382	992062	Frt LH Trailing Arm			
1383	991848	Frt LH Leaf Spring			
1384	991293	Frt LH Brake Disc Rotor			
1385	991281	Frt LH Brake Caliper			
1386	991292	Frt LH Brake Pipe			
1387	991287	Frt LH Brake Hose			
1388	991295	Frt LH Brake Sensor Wire			
1389	991989	Frt Stay Bar Bracket			
1390	994455	Steering Rack & Pinion		?	
1391	994435	Steering Cross Member		?	
1392	994519	Frt Sub Frame			
1393	992003	Frt Sub Frame Mounting			
1394	991217	Frt Anti Roll Bar			
1395	991219	Frt Anti Roll Bar Linkage RH		?	
1396	990887	Engine Block			
1397	990890	Engine Block Gasket			
1398	990972	Engine Oil Sump			
1399	990960	Engine Oil			
1400	992224	Gear Box Assy			
1401	992229	Gear Box Gasket			
1402	992241	Gear Box Oil Sump			
1403	992257	Gear Oil			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1404	991134	Floor Panel			
1405	993719	Rear LH Shock Absorber			
1406	993723	Rear LH Shock Absorber Mounting			
1407	993170	Rear LH Coil Spring			
1408	993550	Rear LH Knuckle Arm			
1409	993551	Rear LH Knuckle Arm Bearing			
1410	993597	Rear LH Lower Arm			
1411	993884	Rear LH Upper Arm			
1412	995161	Rear LH Drive Shaft			
1413	995216	Rear LH Control Arm			
1414	993881	Rear LH Trailing Arm			
1415	993573	Rear LH Leaf Spring			
1416	992941	Rear LH Brake Disc Rotor			
1417	992937	Rear LH Brake Caliper Assy			
1418	990434	Rear LH Brake Pipe			
1419	992946	Rear LH Brake Hose			
1420	993819	Rear Sub Frame			
1421	993820	Rear Sub Frame Mounting			
1422	992813	Rear Anti Roll Bar			
1423	990168	Rear Anti Roll Bar Linkage			
1424	990202	Axle Beam			
1425	990170	Rear Axle Panhard Rod			
1426	990810	Differential Assy			
1427	992706	Propeller Shaft			

[illegible]

No of Items: _____ Assessor: _____

Original copy

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:		Singapore NRIC
Owner ID:		520E
Vehicle Details		
Vehicle No.:		SGS7997U
Vehicle to be Exported:		No
Intended Deregistration Date:		28 Feb 2020
Vehicle Make:		HONDA
Vehicle Model:		CIVIC 1.6 VTI CVT
Primary Colour:		Silver
Manufacturing Year:		2016
Engine No.:		R16B21601308
Chassis No.:		MRHFC5650GT001020
Maximum Power Output:		92.0 kW (123 bhp)
Open Market Value:		\$20,992.00
Original Registration Date:		14 Mar 2017
First Registration Date:		14 Mar 2017
Transfer Count:		0
Actual ARF Paid:		\$21,389.00
Intended PARF Rebate Details		
PARF Eligibility:		Yes
PARF Eligibility Expiry Date:		13 Mar 2027
PARF Rebate Amount:		\$16,041.00
Intended COE Rebate Details		
COE Expiry Date:		13 Mar 2027
COE Category:		A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):		10
QP Paid:		\$49,430.00
COE Rebate Amount:		\$34,773.00
Total Rebate Amount:		\$50,814.00

The information contained herein is correct as at 27 Feb 2020

OK

Claim Handling

Task Transfer Exit

Accident MT/1086123

LOS SAL SUB

Policy No.	5107600658	Vehicle No.	SGS7997U	GST Registration No.	
Certificate No.					
Policyholder Name	CHAY WEN LIANG (XIE WENLIANG)			Policyholder NRIC	S7631520E
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading	0
Contact No.(Mobile)	98522312	Contact No.(Office)		Contact No.(Home)	
Email Address		Special Remark		eCode	No
KFK	☒ No ☐ Yes	TCA	☒ No ☐ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	50	Private Hire	No

Accident Details

Report Date	28/02/2020 09:45	Accident Report Within 24 hrs	Yes	Accident Type	Side Swipe
Date of Accident	27/02/2020	Time of Accident hh:mm	08:50	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	No	ICM No.	
Accident Location	67 UBI AVE 1 (STARHUB GREEN)				

Total Excess Applicable

Excess Type	Per Accident	Windscreen Excess	100.00		
OD Standard Excess	600.00	TP Standard Excess	0.00		
YIED OD Excess	0.00	YIED TP Excess	0.00	Driver is Covered?	Covered
Additional Excess	0.00				
Total OD Excess Applicable	600.00	Total TP Excess Applicable	0.00		

Benefits

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

Policyholder Mailing Address

Address 1	121 SUNSET WAY	Address 2	#02-02 CLEMENTI PARK	Address 3	SINGAPORE 597153
Address 4		Address Type	Singapore address	Post Code	597153
Unit No.		Related Policy Number	5107600658		

OI Driver Info

Driver Name	CHAY WEN LIANG	Driver Type	Main Driver		
Unnamed driver Name		Driver NRIC	S7631520E	Driver DOB	12/09/1976
Register Date of Driver License	17/03/1997	Driver Age	43	Driving Experience	22
Contact No.(Mobile)	98522312	Contact No.(Office)		Contact No.(Home)	
Address 1	121 SUNSET WAY	Address 2	#02-02 CLEMENTI PARK	Address 3	SINGAPORE 597153
Address 4		Address Type	Singapore address	Post Code	597153
Unit No.					
Does he own a Singapore Registered car?	☐ Yes ☒ No	Driver Vehicle No.		Driver Insurer Company	

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	☐ Yes ☒ No
-------------------------------------	------	-------------	---

Modification History

Investigation

Claim 001 OD-MD

Claim Case Officer Tan Siew Choo

LOS SAL SUB

Claim Type	OD-MD	Insured Name	CHAY WEN LIANG (XIE WENLIAI	Insured NRIC	S7631520E
Contact No.(Mobile)	98522312	Contact No. (Home)	64690292	Contact No. (Office)	68257560
Email Address	JUSTCHAY@OUTLOOK.COM	OI Vehicle Number	SGS7997U	TP Vehicle Number	SLJ5258X
Claim Description	SGS7997U / SLJ5258X ON 27 Feb 2020				Name of Preferred Workshop
Preferred Workshop Contact	☐ No ☒ Yes	Preferred Repair Option	income to assign workshop	Insured Mobility report	Fully at Resolved
Date Registered	28/02/2020 09:52	Claim Close Date		Date Received	28/02/2020 00:00
Report Taken By	LIEW SHAN HUI	Workshop Repairer		Total Loss but Repaired	
☒ Print AK letter				OD Excess Collected by Workshop	

Modification History

Special Claim Creation Approval

Approval	Reason
----------	--------

Remarks

damage assessment Attachment

Vehicle Info

Vehicle Make	HONDA	Vehicle Model	CIVIC	Engine Capacity	
Date of Registration	14/03/2017	Classis No.	MRHFC5650GT001020		

2/28/2020

Claim Handling (damage assessment Claim Task MT/1086123 / Claim 001 OD-MD)

Towing Required * ☒ Yes ☐ NoVehicle in IDAC * ☒ Yes ☐ NoParallel Import * ☐ Yes ☒ No

Type of Tender * Own Damage

Assessor Name * SIMON

Survey Current Status

IDAC/Workshop Name NATIONAL ASSESSMENT CENTR

IDAC/Workshop Location 51 UBI AVENUE 1 #01-25 PAYA

Windscreen Parts & Labour Cost

Total Loss * ☐ Yes ☒ No

Market Value(\$)

Scrape Value(\$)

Economical Repair Value(\$)

Remark

REMARK: NO OF REPAIR DAYS: 10 DAYS 1X FRT RH WHEEL RIM - REPLACE 1X RH HEAD LAMP TOP CHROME - UNCONFIRM 1X REAR RH WHEEL RIM - REPLACE 1X REAR RH FENDER 1/4 GLASS - UNCONFIRM 1X REAR RH FENDER 1/4 GLASS SEALANT - REPLACE 1X REAR WINDSCREEN MOULDING - REPLACE 1X REAR WINDSCREEN SEALANT - REPLACE 1X FRT RH ANTI ROLL BAR LINKAGE - UNCONFIRM 1X FRT RH TIE ROD - REPLACE.

Remark for Supplementary

▼ Damage Listing

Find a Part	No.	Part No.	Description	Qty *	Repair Code *	
root						
Not Applicable	1	35500902	ROCKER PANEL GARNISH (RIGHT)	1	Replace	X
ABS	2	23300204	DOOR (REAR RIGHT)	1	Replace	X
ABSORBER	3	23303004	DOOR HINGE (BOTTOM) (REAR RIGHT)	1	Unconfirm	X
ACCELERATOR	4	23303104	DOOR HINGE (UPPER) (REAR RIGHT)	1	Unconfirm	X
ACTUATOR	5	23302404	DOOR GLASS REGULATOR (REAR RIGHT)	1	Unconfirm	X
ADVERTISEMENT STICKER	6	23306104	DOOR RUBBER (REAR RIGHT)	1	Unconfirm	X
AIR BAG	7	25400106	FENDER (REAR RIGHT)	1	Replace	X
AIR BLOWER	8	16000101	BUMPER (FRONT)	1	Replace	X
AIR BOX	9	16002401	BUMPER CLIPS (FRONT)	6	Replace	X
AIR CHAMBER BOX	10	16005102	BUMPER RETAINER (FRONT RIGHT)	1	Unconfirm	X
AIR CLEANER	11	16005001	BUMPER REINFORCEMENT (FRONT)	1	Unconfirm	X
AIR COMPRESSOR	12	16002902	BUMPER FOG LAMP COVER (FRONT RIGHT)	1	Unconfirm	X
AIR CON	13	27700102	HEAD LAMP (RIGHT)	1	Replace	X
AIR CON (VAN)	14	25400103	FENDER (FRONT RIGHT)	1	Replace	X
AIR COOLER	15	25400802	FENDER INNER PANEL (FRONT RIGHT)	1	Repair	X
AIR DISTRIBUTOR	16	25401202	FENDER LAMP (FRONT RIGHT)	1	Replace	X
AIR FILTER	17	25400902	FENDER INNER SHIELD (FRONT RIGHT)	1	Replace	X
AIR FLOW	18	43600102	TYRE (FRONT RIGHT)	1	Unconfirm	X
AIR GRILLE	19	23300202	DOOR (FRONT RIGHT)	1	Replace	X
AIR HORN	20	23303002	DOOR HINGE (BOTTOM) (FRONT RIGHT)	1	Unconfirm	X
AIR INTAKE	21	23303102	DOOR HINGE (UPPER) (FRONT RIGHT)	1	Unconfirm	X
AIR RESONATOR BOX	22	23302402	DOOR GLASS REGULATOR (FRONT RIGHT)	1	Unconfirm	X
AIR THROTTLE BODY AND SENSOR	23	23306102	DOOR RUBBER (FRONT RIGHT)	1	Unconfirm	X
ALARM	24	16000102	BUMPER (REAR)	1	Repair	X
ALTERNATOR	25	42000102	TAIL LAMP (RIGHT)	1	Unconfirm	X
ALUMINIUM PANEL - SIDE	26	25400904	FENDER INNER SHIELD (REAR RIGHT)	1	Replace	X
AMPLIFIER	27	43600104	TYRE (REAR RIGHT)	1	Unconfirm	X
ANTENNA	28	25401502	FENDER QUARTER GLASS RUBBER (REAR RIGHT)	1	Unconfirm	X
ANTI ROLL	29	401028	STEERING RACK & PINION	1	Unconfirm	X
APRON	30	401021	STEERING CROSS MEMBER	1	Unconfirm	X
ARCH	31	36600102	SHOCK ABSORBER (FRONT RIGHT)	1	Unconfirm	X
ARM REST	32	36600602	SHOCK ABSORBER MOUNTING (FRONT RIGHT)	1	Unconfirm	X
ASH TRAY	33	30000102	KNUCKLE ARM (FRONT RIGHT)	1	Unconfirm	X
AUTO CLUTCH	34	30000202	KNUCKLE ARM BEARING (FRONT RIGHT)	1	Unconfirm	X
AUTO COOLER PIPE	35	30500102	LOWER ARM (FRONT RIGHT)	1	Replace	X
AUTO CRUISE MOTOR	36	23600102	DRIVE SHAFT (FRONT RIGHT)	1	Unconfirm	X
AUTO TRANSMISSION						
AXLE						
BACK REST (M/C)						
BACK SEAT						
BALANCER						
BATTERY						
BEADING (M/C)						
BELT COVER (M/C)						
BELT TENSIONER						
BODY						

Save Submit



NATIONAL ASSESSMENT CENTRE SERVICES
(LKK GROUP)

51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park,
Singapore 408933, TEL: 6841 0055 FAX: 6841 6315

NAC
NATIONAL
ASSESSMENT
CENTRE

Vehicle Movement Form

Vehicle Check-In

Vehicle No: SGS 7999 Date In: _____ Time In: _____ with Keys: Yes / No

For Office use

Attended by: _____

Workshop Collection of Vehicle

Workshop: City Auto

Collection Date: 29-2-20 Time: 11:45 with Keys: Yes / No

Tow Truck No: YMS0970 Tow Man: Wong Lie Yao NRIC: S891682C#

Signature: [Signature]

For office use

Attended by: Rosli

Approved by: _____

Workshop Return of Vehicle

Workshop: _____

Returned Date: _____ Time: _____ with Key: Yes / No

* Tow In / Drive In
Tow Man / Workshop Representative: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Owner Collection of Vehicle

Collection Date: _____ Time: _____ with Key: Yes / No

Owner: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Approved by: _____

LKK Paya Ubi

From: Tan Siew Choo <siewchoo.tan@income.com.sg>
Sent: Friday, 28 February 2020 4:07 PM
To: NAC ; 'City Auto'
Subject: SGS7997U, OD claim no : MT/1086123

Importance: High

Dear IDAC and City Auto,

Learnt that veh is in IDAC (IDAC – pls confirm), do assist with the necessary arrangement asap.

Dear City Auto,

OD excess of \$600/- is applicable, pls assist to liaise with owner Mr Chay at tel : 98522312.

Survey required and you have to arrange personally at mtsurvey@income.com.sg

FOR PAYMENT: Please forward the Invoice & Discharge Voucher after the repairs has been done/ finalized with Surveyor to my email.

Regards.

Tan Siew Choo
Senior Executive
Operations, Motor and Personal Lines (PL)
T +65 6430 7882
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. Find out more at income.com.sg/careers



Our Ref: MT/CA/OD/051/1086123-001/TSC

28 Feb 2020

CITY AUTO PTE LTD

BLK 8 #01-58TO66

SIN MING INDUSTRIAL EST SECTOR C

SINGAPORE 575643

Dear Sir

CLAIM NUMBER: MT/1086123-001

REPAIR OF VEHICLE NUMBER: SGS7997U

We are pleased to inform you that you are successful in your tender to repair the vehicle. The details are as follows:

Award Date: 28 Feb 2020

Make: HONDA

Model: CIVIC

Estimated Repair Days: 8

Location: NATIONAL ASSESSMENT CENTRE SERVICES

Address: 51 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933

Benefits Applicable: N/A

Excess Applicable: 600.00

Please note that supplementary items will not be allowed.

If you have any queries, please contact Tan Siew Choo at 64307882 or email us at motor@income.com.sg.

Yours sincerely

Jenny Pe

Deputy Vice President

Motor Insurance

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.