

Tel No.: 6679 1146 / 91478545

Email: ben@allswellmotor.com.sg

account5@allswellmotor.com.sg

Not Withheld
 11 Long @ 2500k. Max
 Recovery After Pain
 lmotor.com.sg
 lswellmotor.com.sg
 4 days

(3rd Party Claim Against ^{***} III Insured 54A7022R)

DOA: 23.02.2020

Repair Estimate

Vehicle No. : SKK3149Y
Make & Model : Nissan Sylphy 1.5

Submitted by : Ben
COE Expiry : 31-05-2021

S/No	Part Description	Qty	Price	Unit Price	Disposition by
01	Front bumper 636.20 Bt	01	\$1,510.00		✓
02	LH headlamp 638 mg cm	01	\$900.00		✓
03	LH returner / RH returner cm	01	\$51 / \$151		✓
04	Support panel 637 Forde Bt	01	\$720.00		X 672.70
05	Lower arm 017 For	01	\$400.00		X
06	Linkage 12	01	\$180.00		X
07	LH wheel knuckle 2 12	01	\$395.00		X
08	LH headlamp lower bracket 117	01	\$45.00		✓
	10%				
	Special nett				
01	Clips / returner studs 122	01	\$40.00		✓
	\$40 / pkt				
	Labour Description				
01	Dismantle / Assembly of all affected parts	01	\$600.00		4801
02	Panel knocking of support panel 1201	01	\$200.00		X
03	Spray painting of all affected parts	01	\$400.00		✓

Note: If any the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.

kennethkong@kkauto.com

Griff x log 1000

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: