

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
AUT	O & GENERAL IN	SURANCE (S) PL	Ref : CS/AGI20003331/	: CS/AGI20003331/Atf3n2	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Date: 01-04-2020		
			Code: AGI		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SDU 7244J	Veh. Inspected	SJD 7001L	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10005747	Excess (\$)	0.00	
	Assign From	IVY RATILLA	Assign Date	28/02/2020	
2. Vehicle Particulars & Condition					
	Make & Model	MAZDA CX-3	c.c	1998	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	JM6DK2W7AH0125514	Colour	GREY	
	Odometer	82834	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	225/50 R18	YOKOHAMA	6 mm	
	L/H Front Tyre	225/50 R18	YOKOHAMA	6 mm	
	R/H Rear Tyre	225/50 R18	YOKOHAMA	6 mm	
	L/H Rear Tyre	225/50 R18	YOKOHAMA	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	5. General Information				
	Accident Date	27/02/2020	Inspection Date	02/03/2020	
	Survey held at	VISION AUTOWORK PTE LTD			
		8 KAKI BUKIT AVE 4, #08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a.					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

14 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: