

S9 MOTOR TRADING PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 2 March 2020
To : LKK

By Fax: 6256-4315

Attn : Mr Rasul

VEHICLE NO : FBM 6866L
ACCIDENT DATE: 26 February 2020

Honda CBF 190X

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1 Handle Bar <i>distand</i>	1	145.00 ✓
2 Brake Lever <i>clutch cut</i>	1	75.00 ✓
3 Fork Tube <i>distand</i>	1 set	480.00 ✓
4 Balancer <i>n/s cut o/s NW</i>	1 set	195.00 97.50
5 Mirror <i>n/s cut o/s NW</i>	1 set	145.00 72.50
6 Front Mudguard <i>broken</i>	1	215.00 ✓
7 Head Lamp Guard <i>broken</i>	1	185.00 ✓
8 Front RH Footrest <i>NW</i>	1	135.00 X
9 Front RH Footrest Rubber <i>NW</i>	1	85.00 X
10 Front RH Fairing <i>vaper</i>	1	135.00 X
11 RH Tank Cover <i>NW</i>	1	255.00 X
12 Front LH Left Rest <i>broken</i>	1	135.00 ✓
13 Exhaust Pipe <i>NW</i>	1	550.00 X
14 Exhaust Guard <i>NW</i>	1	185.00 X
15 Rear Tail Side Cover Fairing <i>cut</i>	2 1	195.00 ✓
16 Swing Arm <i>NW</i>	1	450.00 X
17 Brake Pedal <i>NW</i>	1	65.00 X
18 RH Centre Body Cover <i>NW</i>	1	45.00 X
Sub-Total		3,675.00
Less 10%		367.50
Sub-Total		3,307.50

1600.00
1440.00

VEHICLE NO : FBM 6866L

Honda CBF 190X

Nett Items

1	1 set side box <i>broken</i>	800.00	700/-
2	Side box rack <i>broken</i>	135.00	✓
3	Rear carrier box <i>NH</i>	450.00	X
4	Towing fee <i>NH</i>	40.00	X
5	Remove & replace necessary parts, align & etc	280.00	180/-
6	Remove & replace fork tube	120.00	80/-
7	Putty & respray paint	250.00	120/-

1215.00

Sub-Total 2,075.00

Nett Total 5,382.50

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

2655.00

L/S 2100/-

Kindly revert upon completion. Thank you.

S9 MOTOR TRADING PTE LTD

LG

02/03/2020 @ 1700hrs

Not Authorised

L/S now 4 days

[Signature]

LKK Auto

[Signature]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

22/03/2002

ASS. REC. BY:

REF:

08/SMO 20003332/Dq d3

Special Instruction:

Surveyor: BryanASSIGNMENT (Office)From (Person): Ye Yong kang Melvin SMODate/Time: 28/2/2020 @ 1:50pm

Estimated Cost: _____

Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: _____

FBM 6866L

Insured: SKH 4575J

at Workshop m/s _____

SG 98 Motor

Tel: 6452

of _____

BK 4001 # 01-21 AMK Ind. park 1

Policy No: _____

Claim No: _____

CMTD2000910/RUC

Sum Insured: _____

Excess: _____

Make of Veh: _____

(Client's Record)

D.O.A 26/22/2020

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 2:01pm @ 28/2/2020

Person Contacted: _____

Rose

Vehicle IN/OUT

Date/Time	Action/Instruction
	<u>FBM 6866L-X</u>
	<u>SKH 4575J- & CA/ASM 1802 0594/TI 16342 DOA: 11/11/2018</u>
<u>4/3/20-</u>	<u>Revised premi advise via email</u>
	<u>Bryan finalised LS \$2100, 4 days. (Red \$3282.50, 61%)</u>

ASS. REC. BY:

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: FBM 6866L Yr Regn: Jan, 2018Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda CBF 190X c.c. 184Colour: Red A/C: Insured / Std / NI / NASp. Reading: 90717 T/Radio: Insured / Std / NI / NAEng/No: SDH161FMKH3207580C/No: LALP5L704H3248333Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 110/70 R17R: 140/70 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Pirelli Rear MetzelerR/Bal. 3 mm R/Bal. 3 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 26/02/2020 D.O.I. 02/03/2020Survey held at SG 98 Motu AMK

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S Portion of O/S Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Sompo SKH 4575JMV 8.2KLIA 4.7KNL 3.5K

Date/Time, File Pass to?

☐ : Preli. Report

1) 24/04 Typist

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Rep. Format:

TP

Lump Sum / Fee: 2100

From: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Sent: Friday, 28 February 2020 1:50 PM
To: Sg Motor; Sg Motor; assignments; sur@lkkauto.com
Cc: Chua, Gek Tiang Ruth; Henry, Irene James
Subject: RE: REF: CMTD2000910/RUC RE: Plse arrange PRI on bike FBM 6866L as per attached.

Without Prejudice

Dear Leena,

We will appoint LKK Auto, Mr Mohd Rasul, to conduct the survey on a without Prejudice Basis.

Dear LKK Auto,

Please make the arrangement to survey for FBM6866L by Mr Mohd Rasul, on a without Prejudice Basis and revert with your preliminary report upon completion of survey to my colleague, Ruth.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @ Download on the App Store or GET IT ON Google Play

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Sg Motor <sgmotor2000@yahoo.com.sg>

Sent: Friday, 28 February, 2020 1:24 PM

To: Sg Motor <sg_motor_enterprise@yahoo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Sg Motor <sgmotor2000@yahoo.com.sg>
Sent: Friday, 28 February, 2020 11:18 AM
To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>; Sg Motor <sg_motor_enterprise@yahoo.com.sg>
Subject: Plse arrange PRI on bike FBM 6866L as per attached.

Attn: Motor Claims Dept

Plse arrange PRI on bike FBM 6866L as per attached.

Thank You

Regards

Leena

SG 98 Motor Pte Ltd

Blk 4001 #01-21

Ang Mo Kio Industrial Park I

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 4 March 2020 2:29 PM
To: Admin-D (LKKAUTO); 'Ye, Yong Kang Melvin'; assignments
Cc: 'Chua, Gek Tiang Ruth'; 'Henry, Irene James'; SUR
Subject: RE: REF: CMTD2000910/RUC RE: Plse arrange PRI on bike FBM 6866L as per attached.
Attachments: PRELI ADVISED FBM 6866L.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **FBM 6866L**
Number of days (estimated) : 4 days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Friday, 28 February 2020 2:06 PM
To: 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Chua, Gek Tiang Ruth' <ruth.chua@sompo.com.sg>; 'Henry, Irene James' <irene.henry@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: REF: CMTD2000910/RUC RE: Plse arrange PRI on bike FBM 6866L as per attached.

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ye, Yong Kang Melvin [<mailto:melvin.ye@sompo.com.sg>]
Sent: Friday, 28 February 2020 1:50 PM
To: Sg Motor; Sg Motor; assignments; sur@lkkauto.com
Cc: Chua, Gek Tiang Ruth; Henry, Irene James
Subject: RE: REF: CMTD2000910/RUC RE: Plse arrange PRI on bike FBM 6866L as per attached.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD2000920/RUC

Date: 04/03/2020

Our Ref: CS/SMO20003333/Dqd3

The Motor Claims Department
SOMPO INSURANCE SINGAPORE P

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. FBM 6866L .

Please be informed that we had conducted the inspection of the above-mentioned vehicle on 02/03/2020 at the premises of M/s SG 98 MOTOR and have the following to report: -

Workshop Estimate Amount	: S\$ 5,032.50
Revised Estimate Amount	: S\$ 2,439.00
"Check" Items Amount	: S\$ 0.00
Market Value	: S\$
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:

The vehicle sustained damages at the n/s portion and o/s rear.



Repair days: 4

Comments/ Present Status:

Damages Consistent.

Yours faithfully

Bryan Ang

Automotive Assessor / Investigator



Police Station Of Origin:
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

Report No. T/20200226/2159

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 26/02/2020 22:05	Vide Report No.:	Station Diary No.: 153
--	------------------	---------------------------

Informant's Particulars

Name of Informant: THANA RAJ S/O KHARILAH			Address: APT BLK 277 BANGKIT ROAD #03-112 SINGAPORE 670277		
ID Type / ID No.: NRIC NO / S8117680I			Contact No.: Home/Office: Mobile: 91456399		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 38	Date of Birth: 07/06/1981	Type of Informant: Rider		
Race: Indian			Language: English		Institution / School Name:
Occupation: Marine surveyor (ship and nautical)			Driving Licence Information: Class: 2B,2A,2,3,4,5 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 26/02/2020 15:45	Type of Location: Car Park
Location: Along Road 1 BUKIT PANJANG RING ROAD				
Blk 537A Bukit Panjang Ring Road MSCP, Deck 3				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: No Traffic
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBM6866L	Motorcycle	HONDA	CBF190X MANUAL	Red	Slightly Damaged	0
SKH4575J	Car					0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBM6866L	NTUC Income Insurance Co-Operative Limited	5097878857-02	10/02/2020	09/02/2021



**SINGAPORE
POLICE FORCE**



T/20200226/2159

2 of 3

Police Station Of Origin:
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

Report No. T/20200226/2159

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	THANA RAJ S/O KHARILAH	ID No.	S8117680I
Related Vehicle	FBM6866L (Motorcycle)	Contact No.	91456399
Hospital/Clinic	NATIONAL UNIVERSITY HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3,4,5 Date of Expiry: NIL
Date Treatment	26/02/2020	Date Discharge	26/02/2020
No. of Days granted Medical Leave	05	Degree of Injury	Slight
Driver			
Name	LOO GUAT HOON	ID No.	NIL
Related Vehicle	SKH4575J (Car)	Contact No.	90283308
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 26th February 2020 at about 1545hrs, I was riding my motorbike FBM6866L, along Blk 537A Bukit Panjang Ring Road MSCP, Deck 3. I was moving straight when out of a sudden, one motorcar bearing SKH4575J, who was going up the ramp dashed out and hit onto me causing me to fly out of my motorbike for about one meter.

I lost consciousness for a while, however, managed to wake up on my own. When I woke up, the car was in front of me and that was when I realized I was knocked down by the motorcar. I felt pain at that point, however, managed to exchange particulars with the driver. There was one male subject who I believed to be the other driver's son, helped to push my bike into a parking lot and I called for towing assistance. I then called my wife to assist to book for me a Grab and send me to NUH Emergency Department.

I was given 5 days MC, from 26th February 2020 till 1st March 2020, reference NUH20053343.



**SINGAPORE
POLICE FORCE**



T/20200226/2159

3 of 3

Police Station Of Origin:
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

Report No. T/20200226/2159

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

J /

Sgt 3 NUR SABRINA BINTE ABU HUSSAIN

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

26/02/2020 22:05

Officer In Charge Of Case:

TP / AEIT /

Sr Staff Sgt ONG YONG HOCK

Contact No.: 65476436

Classification Of Case:

Authentication Stamp

NP168

