

DATE: 25/10/2021 9021451/G3/j3-6r

ASSIGNMENT (Office)

28/21.2020

OD / TP / FW'S / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: YF 6745R

at Workshop mit Omega Auto P2

160 S. M. Drive #06-06 Yonkers, N.Y.

Police No. 191019/VC05/022728

Location:	CHEROKEE CO.,
Stream Name:	EL...

DATE: 2011-2012

Make of Veh. _____ D.O.A. 27. 11. 2011
(Client's Record) AKD 01

CA / REV / RID / DELETED

DATE/TIME: 10/27/98 4:30 PM

Case # 04-111 Parties Complaint Volume IN/OUT

Date/Time	Action/Instruction	By	U	U
-----------	--------------------	----	---	---

$$y = 2452 - x$$
$$x_1^2 + x_2^2 + x_3^2 + x_4^2 = k$$

\$6900, 14 Days

(\$ 8,000/- Red - 54%)

18/3/2020

120

621 - 142

ASSIGNMENT

09/12/19

UD / IF / WS / TP RES / GO RES / EVA / INV / MV

Vehicle No. YP 6245R

Workshop No. Omega Auto

160 v/m drive # 06-06 on my battery

Excess

Make of Veh. 10.30am owner waiting

(Policy Condition) PRS

Remark: The veh had commenced its repair at the time of inspection.

But. or Market Value

IDAC Accident Report Consistent? Yes or No

GIA / PR Seen Consistent? Yes or No

Est. Repairs days Rep. Yes or No

Est. Sum. % 3 Val. Yes or No

CA / REV / REP. / 24 HRS

Date Person Contacted Vehicle IN / OUT

Vehicle YP6245R 02 Jun 2017

Type: M. Car / M. Cycle / Bus / Van / Motor / Taxi / Prime Mover /

Truck / Trailer or

Make: Mit Canter CC 2898

Colour: white AC Insured / Std / NI / NA

Registration: U6604 T/Rates: Insured / Std / NI / NA

Eng/No

ChNo: FEB 21 EA 213 75

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: 01 / S/Rim / STD A/Rim or

Tyre Size F: 195/85 R 15

R: //

BSY DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal 8 mm

L/Bal 5 mm

D.O.A. w/s

Rear

R/Bal 5/5 mm

L/Bal 5/5 mm

D.O.A. 09-12-19 1923.

Survey held at

Des. of Damages: Front, Rear, O/S / N/S / U/C / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$ 18k - \$ 20k

RECEIVED 2019

11/12/19

4034

PR5

Days Of Repair:

Resurvey No. of Trip:

120

120

Summer Lee (LKK Auto)


From: ONG LI LI <llong@lonpac.com>
Sent: Friday, 28 February, 2020 3:58 PM
To: Nivitha (LKK Auto)
Cc: 'LKK (PRI)'
Subject: RE: Our Ref: L19.1476.AT//Your Ref: XD 3336G//PRS Our Ref: 19/19/19/VC05/022728 [External General]
Attachments: 22728 TP SR1.pdf

Lonpac External - General

Dear Nivitha

Please see attached for the TP survey report (part 1) and arrange paper survey.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse
Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 4 December 2019 5:56 PM
To: ONG LI LI <llong@lonpac.com>
Cc: 'LKK (PRI)' <assignments@lkkauto.com>
Subject: RE: Our Ref: L19.1476.AT//Your Ref: XD 3336G//PRS Our Ref: 19/19/19/VC05/022728 [External General]

Dear Ms Ong,

Noted with thanks.

Best Regards

Shiau Chan on behalf of G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [mailto:llong@lonpac.com]
Sent: Wednesday, 4 December 2019 5:15 PM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>

Cc: LKK (PRI) <assignments@lkkauto.com>


Subject: RE: Our Ref: L.19.1476.AT//Your Ref: XD 3336G//PRS Our Ref: 19/19/19/VC05/022728 [External General]

Lonpac External - General

Dear Nivitha

FYA

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse
Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]

Sent: Wednesday, 4 December 2019 4:11 PM

To: ONG LI LI

Cc: LKK (PRI)

Subject: Re: Our Ref: L.19.1476.AT//Your Ref: XD 3336G//PRS Our Ref: 19/19/19/VC05/022728 [External General]

Hi Li Li

We confirm that you have objected to our client's list of surveyors. Our client's vehicle is at the following address:

OMEGA AUTO PTE LTD

160 Sin Ming Drive

#06-06 Sin Ming Autocity

Singapore (575722)

Tel: Terence Lau (9271 8287)

Please inform your surveyor to conduct the pre-repair survey within 2 working days, failing which our client will have no alternative but to proceed with the repair of his vehicle.

Best regards

Anne

Kuru & Co

150 South Bridge Road

#04-06 Fook Hai Building

Singapore 058727

Tel: 6532 2009

Fax: 6532 2007

On Wednesday, 4 December 2019, 3:38:24 pm SGT, ONG LI LI <llong@lonpac.com> wrote:

Lonpac External - General

Without Prejudice

Save as to Costs

Dear Anne

Under the NIMA protocol, if you object to our list of surveyors, you must provide at least 10 surveyors but there are only 3 in your list.

Therefore, we are not agreeable with your proposed surveyor and we urge you to agree to appointing LKK Auto Consultants Pte Ltd as a Single Joint Expert. Please provide the details of the workshop.

Dear Nivitha

Please arrange survey.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse

Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]

Sent: Wednesday, 4 December 2019 3:30 PM

To: ONG LI LI

Subject: Re: Our Ref: L.19.1476.AT//Your Ref: XD 3336G//PRS Our Ref: 19/19/19/VC05/022728 [External General]

Hi Li Li

Our client is objecting to your list of surveyors. Attached is our client's list of proposed surveyors for your consideration.

Please state the surveyor you will be appointing to be the single joint expert or that you are objecting to our client's proposed list of surveyors.

If we do not hear from you within 2 working days, it shall be deemed that you have agreed to the appointment of any of the surveyors listed by our client.

Best regards

Anne

Kuru & Co

150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

ax: 6532 2007



This email has been checked for viruses by AVG antivirus software.
www.avg.com

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 02/12/2019 16:50
 Date Of Accident 29/11/2019 17:50
 Exact Location Of Accident PIE TOWARDS TUAS
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number YP6245R
Insured/Policyholder
 Name Of Registered Owner SWEE BEE CONTRACTOR PTE LTD
 Co Reg No 198800966Z
 Email Address NOEMAIL
 Mobile Phone No
 Alternative Phone No OFFICE-62971937

Vehicle Particulars

Manufacturer MITSUBISHI
 Model CANTER - FUSO
 Exact Purpose for which vehicle was being used at time of accident WORK PURPOSE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY
 Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number 5091580205-02
 Cover Note Number

Driver

Name of Driver RAJENDRAN THANABALAN
 NRIC No G6254432K
 Date Of Birth 02/05/1982
 Occupation OUTDOOR
 Date Of Driving Pass 18/02/2013
 Driving Experience 6 YEARS AND 9 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-81246911
 Fax Number
 Contact Number
 Email Address NOEMAIL

Address BLK 70 TANAH MERAH COAST
#03-99 SINGAPORE

Postcode 498751

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions AFTER-RAIN

Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 4

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 13

Passenger 1

NAME GOVINDARAJ JEGANATHAN

GENDER MALE

Passenger 2

NAME KARUPPAIAH NAVANEETHA KRISHNAN

GENDER MALE

Passenger 3

NAME KALIMUTHU SELVAKUMAR

GENDER MALE

Passenger 4

NAME NA

GENDER MALE

Passenger 5

NAME NA

GENDER MALE

Passenger 6

NAME NA

GENDER MALE

Passenger 7

NAME NA

GENDER MALE

Passenger 8

NAME NA

GENDER MALE

Passenger 9

NAME NA

GENDER MALE

Passenger 10

NAME NA

GENDER MALE

Passenger 11	NAME	NA
	GENDER	MALE
Passenger 12	NAME	NA
	GENDER	MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ANG MO KIO NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 51 ANG MO KIO AVE 9 , POSTCODE: 569784 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4849999 - FAX NO: 62181399
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER POLICE REPORT AND ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD3336G
Vehicle Make/Model/Colour	
Details Of Properties	REFER POLICE REPORT AND ATTACHED
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLM1378T (Wish)
Vehicle Make/Model/Colour	
Details Of Properties	REFER POLICE REPORT AND ATTACHED
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SJT7667G
Vehicle Make/Model/Colour	

Details Of Properties	REFER POLICE REPORT AND ATTACHED
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	RAJENDRAN THANABALAN
Approximate Age	
Injuries Sustain	REFER POLICE REPORT AND ATTACHED
Injured person in which vehicle?	YP6245R
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

DETAILS OF INJURED PERSON 2

Name	GOVINDARAJ JEGANATHAN
Approximate Age	
Injuries Sustain	REFER POLICE REPORT AND ATTACHED
Injured person in which vehicle?	YP6245R
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

DETAILS OF INJURED PERSON 3

Name	KARUPPAIAH NAVANEETHA
Approximate Age	
Injuries Sustain	REFER POLICE REPORT AND ATTACHED
Injured person in which vehicle?	YP6245R
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

DETAILS OF INJURED PERSON 4

Name	KALIMUTHU SELVAKUMAR
Approximate Age	
Injuries Sustain	REFER POLICE REPORT AND ATTACHED
Injured person in which vehicle?	YP6245R
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

E. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail package); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

PIE

A: YP6245R
B: XD3336G
C: SLM1378T
D: JYT7667G

A: YP6245R
B: XD3336G
C: SLM1378T
D: JYT7667G

As per POLICE REPORT

As per Police Report

I have declared the foregoing particulars and true in every respect.

Signature & Date

* Indicates a Significant Difference
 Date & Time

Driver's Signature
If driver is not the owner/lessee
Date & Time

Responsible Center Administrator's Signature
Name _____
Title/Date _____



**SINGAPORE
POLICE FORCE**



T/20191130/2037

1 of 5

Report No. T/20191130/2037

Police Station Of Origin:
Ang Mo Kio North N P C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No. 1800-4849999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 30/11/2019 09:48	Vide Report No.:	Station Diary No. 24
--	------------------	-------------------------

Informant's Particulars

Name of Informant: RAJENDRAN THANABALAN			Address: APT BLK 70 TANAH MERAH COAST ROAD #03-99 SINGAPORE 498751	
ID Type / ID No.: FIN NO / G6254432K			Contact No.: Home/Office: Mobile: 81246911	
Nationality: INDIAN			Email:	
Sex: Male	Age: 37	Date of Birth: 02/05/1982	Type of Informant: Driver	
Race: Indian			Language: English	Institution / School Name:
Occupation: DRIVER			Driving Licence Information: Class: 2B, 3, 4, 5 Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Others:	Drink Drive: No	Date/Time of Accident: 29/11/2019 17:50	Type of Location: Flyover
Location: Along Road 1 PAN ISLAND EXPRESSWAY				
PIE from Changi Airport towards Tuas. Lamp post 13 to 15. Lamp Post Number: 13				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJT7667G	Car					0
SLM1378T	Car					0
XD3336G	Lorry					0
YP8245R	Lorry				Seriously Damaged	13



**SINGAPORE
POLICE FORCE**



T/20191130/2037

Police Station Of Origin:
Ang Mo Kio North N.P.C.
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999

2 of 5
Report No. T/20191130/2037

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	NEILA KUMARAN S/O HUTHAYA KUMAR	ID No.	S9001278I
Related Vehicle	SJT7667G (Car)	Contact No.	97266667
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	YEO ENG NGHEE	ID No.	S0187650C
Related Vehicle	SLM1378T (Car)	Contact No.	94592197
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	MURUGESAN DINESH RAJA	ID No.	NIL
Related Vehicle	XD3336G (Lorry)	Contact No.	83282931
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL



**SINGAPORE
POLICE FORCE**



T/20191130/2037

3 of 5

Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999

Report No. T/20191130/2037

CONTINUATION OF REPORT

Passenger			
Name	GOVINDARAJ JEGANATHAN	ID No.	G8517171U
Related Vehicle	YP6245R (Lorry)	Contact No.	96106402
Hospital/Clinic	1 MEDICAL TECK GHEE	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	29/11/2019	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	NIL
Passenger			
Name	KARUPPAIAH NAVANEETHA KRISHNAN	ID No.	G2143982M
Related Vehicle	YP6245R (Lorry)	Contact No.	83161245
Hospital/Clinic	1 MEDICAL TECK GHEE	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	29/11/2019	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	NIL
Driver			
Name	RAJENDRAN THANABALAN	ID No.	G6254432K
Related Vehicle	YP6245R (Lorry)	Contact No.	81246911
Hospital/Clinic	1 MEDICAL TECK GHEE	Class of Driving Licence & Expiry Date	Class: 2B, 3, 4, 5 Date of Expiry: NIL
Date Treatment	29/11/2019	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	NIL
Passenger			
Name	KALIMUTHU SELVAKUMAR	ID No.	G2909694K
Related Vehicle	YP6245R (Lorry)	Contact No.	84259458
Hospital/Clinic	1 MEDICAL TECK GHEE	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	29/11/2019	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	NIL



SINGAPORE
POLICE FORCE



T/20191130/2037

4 of 5

Report No. T/20191130/2037

Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No. 1800-4849999

CONTINUATION OF REPORT

Brief Details.

On 29/11/2019 at about 1750hrs, I was driving my company lorry with 13 passengers at the back. I was driving along PIE from Changi Airport towards Tuas.

The traffic were very heavy and the roads were wet due to the rain.

Near to Lamp post 13 to 15 area, I felt a sudden impact from the rear which was caused by the driver of bearing plate number XD3336G. Due to the impact, my vehicle bearing plate number YP6245R had also moved forward and hit the other 2 vehicles in front of me. The first vehicle hit was SLM1378T and next was SJT7667G. Resulted in a chain collision accident.

All vehicles drivers came down from their vehicle to exchange particulars and take photograph of the accident

Subsequently on 29/11/2019 at about 1930hrs, me and my other colleagues namely Kalimuthu Selvakumar G2909694K, Karuppalan Navaneetha Krishnan G2143982M, Govindaraj Jeganathan G8517171U, went to 1 Medical Teck Ghee at Block 410 Ang Mo Kio Avenue 10 #01-837. We had all gotten 3 days of MC from 30/11/2019 to 02/12/2019.

that's all.



**SINGAPORE
POLICE FORCE**



T/20191130/2037

5 of 5

Report No. T/20191130/2037

Police Station Of Origin
Ang Mo Kio North N.P.C.
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No. 1800-4849999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Sgt 2 FOO CHUAN ZHEN 	Signature Of Informant 
Signature Of Interpreter: Not applicable	Date/Time 30/11/2019 09:48
Officer In Charge Of Case TP / AEIT / Sr Staff Sgt ONG YONG HOCK Contact No. 65476436	Classification Of Case
Authentication Stamp NP168 	



KM AUTO ASSESSORS PTE. LTD.

Insurance Loss Assessors / Adjusters

28 Casuarina Walk
Singapore 574086

T 6448 8208

F 6552 7277

E kmautoassessors@gmail.com

Regn. No. 200907340Z

INVOICE
NO. 9/TP1141/P

Messrs. SWEE BEE CONTRACTOR PTE LTD
140 PAYA LEBAR ROAD #09-08 AZ @ PAYA LEBAR S'PORE 409015
Date 13-Jan-20

9/12/TP005/R	Particulars	Amount
	<u>RE: YP 6245 R - MITSUBISHI CANTER FEB21ER4SDES (CBU) LORRY W/HYDRAULIC TAILGATE</u>	
	SURVEY FEE (INCL. PHOTOS & TRANSPORT CHARGES)	\$1,188.00
SGD: (ONE THOUSAND ONE HUNDRED AND EIGHTY-EIGHT ONLY)	TOTAL:	\$1,188.00

E & O. E.

for KM AUTO ASSESSORS PTE. LTD.

**KM AUTO ASSESSORS PTE. LTD.**

Insurance Loss Assessors / Adjusters

28 Casuarina Walk

Singapore 574086

T 6448 8208

F 6552 7277

E kmautoassessors@gmail.com

Regn. No. 200907340Z

**AUTOMOBILE
INSPECTION REPORT**

NO. 9/12/TP005/R

To: SWEE BEE CONTRACTOR PTE LTD	
140 PAYA LEBAR ROAD #09-08 AZ @ PAYA LEBAR S'PORE 409015	
General Condition: <u>Pass/Fair/Good/Excellent</u>	
Reg. No. YP 6245 R	Make/Model MITSUBISHI CANTER FEB21ER4SDEB (CBU) LORRY W/HYDRAULIC TAILGATE Year 2017
Engine No. 4P10C48555	Chassis No. FEB21EA21375 Colour White
Condition of Tyres	Speedometer Reading - Km 116604
Front N/S B/STONE 195/85R15 worn 40 %	Front O/S B/STONE 195/85R15 worn 40 %
Rear N/S (OUTER) B/STONE 195/85R15 worn 30 %	Rear O/S (OUTER) B/STONE 195/85R15 worn 30 %
Rear N/S (INNER) B/STONE 195/85R15 worn 30 %	Rear O/S (INNER) B/STONE 195/85R15 worn 30 %
As Requested By YOURSELF	On 9-Dec-20 The Above Vehicle
Was Inspected At (9-Dec-20) OMEGA AUTO PTE LTD BLK 21 SEC A SIN MING IND EST #01-42 S'PORE 575679	
And The Undermentioned Damage Was Noted:-	

Rear carriage assy. pushed forward and displaced, carriage tailgate assy. dented, bent and displaced, hydraulic cylinder pumps assy. bent, shifted and jammed, brackets bent, mounting crossbar assy. bent, no. plate bent and folded, n/s rear lamp assy. cracked and dislodged, bracket bent, o/s rear lamp assy. and bracket displaced, underrun bumper assy. bent and displaced, chassis frame assy. bent, carriage rear body crossmember bent, n/s body side member twisted, n/s sidegate assy. twisted and dislodged, rear hinges twisted, carriage floorboard bent.

Front cabin roof top panel rear portion dented and bent, rear body panel dented and bent, cabin rear windscreen glass assy. dislodged, rubber twisted, cabin rear reinforcement frame assy. bent.

Cabin front wiper garnish bent and dislodged, cab front panel dented and bent, both corner panels bent and shifted, front sides wing mirrors' displaced, brackets assy. bent, cabin front panel dented and bent, front grille assy. bent and dislodged, n/s signal lamp broken, n/s headlamp cracked, n/s sidelamp dislodged, o/s signal lamp, headlamp and sidelamp assy. dislodged, front bumper assy. twisted and flattened, n/s side guard dented, cut, bent and displaced, o/s side guard grazed, no. plate twisted and flattened, chassis frames and front crossmember bent.

Photographs:-	268 Copies	were taken at time of inspection and are attached.
The Repairers estimate was for a total amount of	\$	25,434.00
After adjustment the estimate was revised and agreed at	\$	18,626.50

SPECIAL REMARKS

The Repairers were **NOT AUTHORISED** to proceed with the repairs.
Survey was carried out without prejudice.

The above were due to impacts to the rear and frontal portions of the vehicle.

Alternatively, we recommend that repairs be carried out on a Lump Sum basis instead, @\$14,900/- Nett.


MICHAEL EE Dip.A.Eng., AMRTE, AMSAE, AMSCOE, AMRR, MSAAA

Date 13-Jan-20



KM AUTO ASSESSORS PTE. LTD.
Insurance Loss Assessors / Adjusters
28 Casuarina Walk
Singapore 574086
T 6448 8208
F 6552 7277
E kmautoassessors@gmail.com
Regn. No. 2009073402

APPENDIX 'A'
TO REPORT NO: 9/12/TP005/R
REGN. NO: YP 6245 R

Nature of Work and Materials	Repairers Estimate \$	Remarks	Amount Revised \$
1 pce cabin rear windscreen glass rubber	97.00	twisted, deformed - necessary	X 97.00 SVC
1 pce front windscreen glass rubber	190.00	necessary	/ 190.00
1 pce cab front panel assy.	1,300.00	dented & bent	/ 1,300.00
1 pce cab front panel "FUSO" plate	65.00	necessary	/ 65.00
1 pce front grille assy.	520.00	bent, cracked, dislodged	/ 520.00
1 pce front grille emblem	40.00	necessary	/ 40.00
2 pcs headlamps assy.	680.00	n/s cracked, both lamps' fasteners snapped	/ 680.00
2 pcs sidelamps assy.	240.00	not damaged	-
2 pcs front signal lamps assy.	532.00	n/s broken, o/s fastener snapped	/ 532.00
1 pce front bumper	550.00	twisted & flattened	/ 550.00
2 pcs front bumper brackets	220.00	1pce only - twisted	/ 110.00
2 pcs front bumper side guards	660.00	n/s dented, cut, o/s fastener snapped	/ 660.00
1 pce air con heater box assy.	1,750.00	housing dented, cracked	/ 1,750.00
			6,494.00
		less 25%	1,623.50
	6,844.00		4,870.50 6397
S.NETT			
1 pce cab front panel sealant	100.00	necessary	X 60.00 SVC
1 set front grille clips	30.00	necessary	X 21.00 SVC
1 pce front no. plate	60.00	twisted & flattened	/ 30.00 15
1 set tailgate graphic stickers	300.00	necessary	X 180.00 SVC
1 pce tailgate "60km/h" sticker	20.00	necessary	/ 10.00
1 pce tailgate "23 PAX" sticker	20.00	necessary	/ 10.00
1 pce tailgate mounting crossbar sticker	150.00	necessary	/ 80.00
1 set tailgate hydraulic cylinder pumps assy. - short	2,400.00	bent, stiffened, jammed	/ 2,400.00
1 set tailgate hydraulic cylinder pumps assy. - long	3,000.00	bent, stiffened, jammed	/ 3,000.00
2 pcs rear lamps assy.	360.00	n/s only - cracked, displaced	X 180.00
2 pcs rear lamp brackets	160.00	n/s only - bent	X 80.00 SVC
1 pce rear no. plate	50.00	bent & folded	/ 30.00 15
1 pce rear no. plate bracket	80.00	twisted	/ 45.00 30
1 pce rear underrun bumper assy.	600.00	bent & displaced	X 350.00 SVC
			910
LABOUR CHARGE - FRONT			
Remove necessary cabin interior upholsterys and fittings to enable necessary repairs, check and refit same.	280.00		120.00 60
Remove cabin rear windscreen glass to enable necessary repair, renew glass rubber and refit glass assy.	120.00		X 60.00
c/f	14,574.00		11,526.50
Total Amount Revised		\$	
Lump Sum Repairs Amount		\$	
It is estimated that the repairs will take		days to complete.	

APPENDIX 'A'**TO REPORT NO:****9/12/TP005/R****REGN. NO:****YP 6245 R****KM AUTO ASSESSORS PTE. LTD.**

Insurance Loss Assessors / Adjusters

28 Casuarina Walk

Singapore 574086

T 6448 8208

F 6552 7277

E kmautoassessors@gmail.com

Regn. No. 200907340Z

Nature of Work and Materials	Repairers Estimate \$	Remarks	Amount Revised \$
b/f	14,574.00		11,526.50
Remove front windscreen glass assy., to enable necessary repairs, check and refit glass assy.	200.00		100.00 ✓
Remove dashboard panel assy. and steering column assy. to enable necessary repairs, check and refit same.	300.00		180.00 ✓
Remove necessary air con. parts and fittings to enable necessary repairs, check, replace damaged parts, refit same, vacuum and recharge gas.	250.00		120.00 ✓
Remove lamps, necessary wirings and electrical fittings to enable necessary repairs, check, replace damaged parts, refit same, test electrical-circuit and refocus headlights.	60.00		30.00 ✓
Remove damaged parts, jack and cut out damaged body panels, jack out, straighten up damaged body panels and repair body parts and fittings, whichever possible and necessary, replace and weld necessary damaged parts, refit and align whichever parts necessary. (incl. alignment of cabin structure.)	1,200.00		800.00 ✓
Paint replacement parts and repaint damaged sections with welded portions in and outside.	1,200.00		800.00 ✓
Rustproof replacement parts and touch-up damaged sections.	150.00		70.00 ✓
c/f	17,934.00		13,626.50
Total Amount Revised	\$		
Lump Sum Repairs Amount	\$		
It is estimated that the repairs will take		days to complete.	

APPENDIX 'A'
TO REPORT NO: 9/12/TP005/R
REGN. NO: YP 6245 R



KM AUTO ASSESSORS PTE. LTD.

Insurance Loss Assessors / Adjusters

28 Casuarina Walk

Singapore 574086

T 6448 8208

F 6552 7277

E kmautoassessors@gmail.com

Regn. No. 2009073402

Nature of Work and Materials	Repairers Estimate \$	Remarks	Amount Revised \$
b/f	17,934.00		13,626.50
<u>LABOUR CHARGE - REAR</u>			
Dismantle and remove tailgate assy. and fittings, check, straighten up and repair tailgate assy., tailgate mounting crossbar assy., renew all hydraulic cylinders assy., refit, top up hydraulic fluid, reassemble, refit tailgate assy. and test hydraulic system. Lift out and remove rear carriages' aluminium canopy assy. to enable necessary repairs, check, lift up, refit and realign same, after necessary repairs.			
Disconnect, lift out rear carriage assy., repairs and rebuild carriage assy., including repairs to front reinforcement frame assy., n/s sidegate assy. and hinges, carriage rear body crossmember, n/s body side member and floorboard assy., lift up, refit, realign same on main chassis frame assy.			
Paint rear carriage assy.			
Remove lamps, necessary wirings and electrical fittings to enable necessary repairs, check, replace damaged parts, refit same, test electrical-circuit.	4,500.00		3,200.00 800
Jack out, straighten up and realign main chassis frame assy.	3,000.00		X 1,800.00
		2960	
TOTAL	25,434.00		18,626.50
		8667.75	
		20% = 8900	
Total Amount Revised	\$	18,626.50	
Lump Sum Repairs Amount	\$	14,900.00	
It is estimated that the repairs will take TWENTY-FOUR days to complete.			



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CS3/LPC19021451/Gsf3e2-1	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 20-03-2020	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 3336G	Veh. Inspected	YP 6245R	
Policy No.		Coverage (\$)	0.00	
Claim No.	19/19/19/VC05/022728	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	28/02/2020	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI CANTER	c.c	2998	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	FEB21EA21375	Colour	WHITE	
Odometer	116604	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/85 R15	BRIDGESTONE	5 mm	
L/H Front Tyre	195/85 R15	BRIDGESTONE	5 mm	
R/H Rear Tyre	195/85 R15 (D)	BRIDGESTONE	5/5 mm	
L/H Rear Tyre	195/85 R15 (D)	BRIDGESTONE	5/5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/11/2019	Inspection Date	09/12/2019	
Survey held at	160 SIN MING DRIVE #06-06			
Repairer	OMEGA AUTO PL			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 6245R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	CABIN REAR WINDSCREEN GLASS RUBBER	SERVICEABLE	97.00	-
1	FRONT WINDSCREEN GLASS RUBBER	NECESSARY	190.00	190.00
1	CAB FRONT PANEL ASSY	DENTED / BENT	1,300.00	1,300.00
1	CAB FRONT PANEL "FUSO" PLATE	NECESSARY	65.00	65.00
1	FRONT GRILLE ASSY	BENT / CRACKED / DISLODGED	520.00	520.00
1	FRONT GRILLE EMBLEM	NECESSARY	40.00	40.00
2	HEADLAMPS ASSY	N/S CRACKED, BOTH LAMPS' FASTENERS SNAPPED	680.00	680.00
2	SIDELAMPS ASSY	NOT DAMAGED	240.00	-
2	FRONT SIGNAL LAMPS ASSY	N/S BROKEN / O/S FASTENER SNAPPED	532.00	532.00
1	FRONT BUMPER	TWISTED / FLATTENED	550.00	550.00
2	FRONT BUMPER BRACKETS	TWISTED (1PC ONLY)	220.00	110.00
2	FRONT BUMPER SIDE GUARDS	N/S DENTED / CUT / O/S FASTENER SNAPPED	660.00	660.00
1	AIR CON HEATER BOX ASSY	HOUSING DENTED / CRACKED	1,750.00	1,750.00
	LESS 25% DISCOUNT		-	-1,599.25
			6,844.00	4,797.75
SPECIAL NETT ITEMS				
1	CAB FRONT PANEL SEALANT (SN)	SERVICEABLE	100.00	-
1	SET FRONT GRILLE CLIPS (SN)	SERVICEABLE	30.00	-
1	FRONT NO. PLATE (SN)	TWISTED / FLATTENED	60.00	15.00
1	SET TAILGATE GRAPHIC STICKERS (SN)	SERVICEABLE	300.00	-
1	TAILGATE "60KM/H" STICKER (SN)	NECESSARY	20.00	10.00
1	TAILGATE "23 PAX" STICKER(SN)	NECESSARY	20.00	10.00

Report Ref No. CS3/LPC19021451/Gsf3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILGATE MOUNTING CROSSBAR STICKER (SN)	NECESSARY	150.00	30.00
1	SET TAILGATE HYDRAULIC CYLINDER PUMPS ASSY. - SHORT (SN) (LOCAL REPAIR)	BENT / STIFFENED / JAMMED	2,400.00	400.00
1	SET TAILGATE HYDRAULIC CYLINDER PUMPS ASSY. - LONG (SN) (LOCAL REPAIR)	BENT / STIFFENED / JAMMED	3,000.00	400.00
2	REAR LAMPS ASSY (SN)	SERVICEABLE	360.00	-
2	REAR LAMP BRACKETS (SN)	SERVICEABLE	160.00	-
1	REAR NO. PLATE (SN)	BENT / FOLDED	50.00	15.00
1	REAR UNDERRUN BUMPER ASSY (SN)	SERVICEABLE	600.00	-
1	REAR NO. PLATE BRACKET (SN)	TWISTED	80.00	30.00
			7,330.00	910.00
	LABOUR			
	REMOVE NECESSARY CABIN INTERIOR UPHOLSTERY'S AND FITTINGS TO ENABLE NECESSARY REPAIRS, CHECK AND REFIT SAME.		280.00	60.00
	REMOVE CABIN REAR WINDSCREEN GLASS TO ENABLE NECESSARY REPAIR, RENEW GLASS RUBBER AND REFIT GLASS ASSY.	NOT NECESSARY	120.00	-
	REMOVE FRONT WINDSCREEN GLASS ASSY., TO ENABLE NECESSARY REPAIRS, CHECK AND REFIT GLASS ASSY.		200.00	100.00
	REMOVE DASHBOARD PANEL ASSY. AND STEERING COLUMN ASSY. TO ENABLE NECESSARY REPAIRS, CHECK AND REFIT SAME.		300.00	180.00
	REMOVE NECESSARY AIR CON. PARTS AND FITTINGS TO ENABLE NECESSARY REPAIRS, CHECK, REPLACE DAMAGED PARTS, REFIT SAME, VACUUM AND RECHARGE GAS.		250.00	120.00
	REMOVE LAMPS, NECESSARY WIRINGS AND ELECTRICAL FITTINGS TO ENABLE NECESSARY REPAIRS, CHECK, REPLACE DAMAGED PARTS, REFIT SAME, TEST ELECTRICAL-CIRCUIT AND REFOCUS HEADLIGHTS.		60.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE DAMAGED PARTS, JACK AND CUT OUT DAMAGED BODY PANELS, JACK OUT, STRAIGHTEN UP DAMAGED BODY PANELS AND REPAIR BODY PARTS AND FITTINGS, WHICHEVER POSSIBLE AND NECESSARY, REPLACE AND WELD NECESSARY DAMAGED PARTS, REFIT AND ALIGN WHICHEVER PARTS NECESSARY. (INCL. ALIGNMENT OF CABIN STRUCTURE.)		1,200.00	800.00
	PAINT REPLACEMENT PARTS AND REPAINT DAMAGED SECTIONS WITH WELDED PORTIONS IN AND OUTSIDE.		1,200.00	800.00
	RUSTPROOFING REPLACEMENT PARTS AND TOUCH-UP DAMAGED SECTIONS.		150.00	70.00
	DISMANTLE AND REMOVE TAILGATE ASSY. AND FITTINGS, CHECK, STRAIGHTEN UP AND REPAIR TAILGATE ASSY., TAILGATE MOUNTING CROSSBAR ASSY., RENEW ALL HYDRAULIC CYLINDERS ASSY., REFIT, TOP UP HYDRAULIC FLUID, REASSEMBLE, REFIT TAILGATE ASSY. AND TEST HYDRAULIC SYSTEM. LIFT OUT AND REMOVE REAR CARRIAGES' ALUMINIUM CANOPY ASSY. TO ENABLE NECESSARY REPAIRS, CHECK, LIFT UP, REFIT AND REALIGN SAME, AFTER NECESSARY REPAIRS. }		4,500.00	800.00
	DISCONNECT, LIFT OUT REAR CARRIAGE ASSY., REPAIRS AND REBUILD CARRIAGE ASSY., INCLUDING REPAIRS TO FRONT REINFORCEMENT FRAME ASSY., N/S SIDEGATE ASSY. AND HINGES, CARRIAGE REAR BODY CROSSMEMBER, N/S BODY SIDE MEMBER AND FLOORBOARD ASSY., LIFT UP, REFIT, REALIGN SAME ON MAIN CHASSIS FRAME ASSY. PAINT REAR CARRIAGE ASSY. REMOVE LAMPS, NECESSARY WIRINGS AND ELECTRICAL FITTINGS TO ENABLE NECESSARY REPAIRS, CHECK, REPLACE DAMAGED PARTS, REFIT SAME, TEST ELECTRICAL-CIRCUIT. }		-	-
	JACK OUT, STRAIGHTEN UP AND REALIGN MAIN CHASSIS FRAME ASSY.	NOT NECESSARY	3,000.00	-
			-	-
			-	-
			11,260.00	2,960.00
GRAND TOTAL			25,434.00	8,667.75
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,900.00

Report Ref No. CS3/LPC19021451/Gsf3e2-1



Report Ref No. CS3/LPC19021451/Gsf3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.