



m: 98448533  
t: 63855510  
w: www.detaillab.com.sg

PREMIER@Kaki Bukit, 8 Kaki Bukit Ave 4, #02-03/04 S41587

**MS FIRST CAPITAL INSURANCE LTD**

REQUEST FOR PRE-REPAIR SURVEY

CAR PLATE: SKV2390P

CAR: MERCEDES BENZ CLA180

OWNER: NG WEI LUN

We are authorised by the owner Mr Ng Wei Lun to assist him to claim Third Party against SHD6507A (Your Insured) to his vehicle as a result of an accident.

We append our estimates for the repairs upon appointed surveyor on-site at our workshop.

Please acknowledge and advise us on PRS date/time applicable under your insured policy.

Please also arrange for the survey to be arranged as soon as possible.

Vehicle number: SHD6507A (YOUR INSURED)

Policy Number: NA

Date & Time of Accident: 25/02/2020 17:00HRS

Location: ALONG ROAD 1 TRAVELING TOWARD ROAD 2 GEYLANG SERAI JOO CHIAT ROAD

DATE: 26-02-2020

DETAIL LAB

Ben Yap

Authorised Manager

mobile: 9844 8533

sg  
75