

22/03/2002

ASS. REC. BY:

REF: CS3/ASM 20003402/Hsf3016 Special Instruction:

PRS

Surveyor: Huck Arn

ASSIGNMENT (Office)

From (Person): Tan Jas

of Asm (AXA)

Date/Time: 2/3/2020

Estimated Cost: \_\_\_\_\_

Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SDU 8895Z

Insured: SKD 5236C

at Workshop m/s Triple - T Automobile

Tel: 63851171

of BK 3012 Bedok North Ave 4 #01-2066

Policy No: \_\_\_\_\_

Claim No: SOM02404

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_

(Client's Record)

D.O.A. 28.2.2020

CA / REV / REP. / REV 24 HRS

H.O.D Endorsement: \_\_\_\_\_

Date/Time: 1/3/2020 1.56 p.m

Person Contacted: Irene

Vehicle IN/OUT

Date/Time

Action/Instruction ( X ) Estimate.

SDU 8895Z-NS / INC 10025476 / DN D.O.A - 15/12/2010

SKD 5236C - X

03/03/20

@ 14:08 pm checked with Irene, no estimate.

\* 2/3/20 - survey

\* 3/3/20 - arrange to look

\* other notes

ASS. FDC BY: H-ANW

REF: AXA

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SD4 88952  
 at Workshop m/s: Blk 3012 Selek North  
 of: Ave 4 # 01-2066  
 Insured: Triple - T  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SD4 88952 Yr Regn: 28/11/2015  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: NISSAN SYLPHY cc 1598  
 Colour: white A/C: Insured / Std / NI / NA  
 Sp. Reading: 72759km T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: MNTBBAB1720025213  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 205/55/R16  
 R: 21  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 3 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 5 mm L/Bal. 5 mm  
 L/Bal. 5 mm D.O.A. 28/2/20 D.O.I. 2/3/20  
 Survey held at Triple - T (3/3/20)  
 Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Range → 2.5 - 2.5k</u> <u>repr Days → 3 day</u> <u>3K ✓</u>
	<u>MU - 51000</u> <u>PV - 44436</u> <u>NU - 6500 6564</u>
	<u>RECEIVED 04 MAR 2020</u> <u>PR5 case</u> <u>3/3/20</u> <u>monthly → 8282/100</u>

Date/Time, File Pass to? 04/03/20  
 1) Typist  
 : Preli. Report  
 : Final Report

Days Of Repair: 3  
 Resurvey No. of Trip: 1

2) \_\_\_\_\_  
 Report Format: PR5  
 Lump Sum / H.E. / ...

Add Fee:  
 : Site Insp (\$) \_\_\_\_\_  
 : Interview (\$) \_\_\_\_\_  
 : Tech. Invs (\$) \_\_\_\_\_  
 : ...

Survey Fee:	<u>100</u>
Transportation:	_____
Photos	_____
Others:	_____
TOTAL	<u>100</u>

## ◀ Service Request Details

Claim

SOM02HOY

Reference

None 

Loss Date

February 28, 2020

Report Date

Mar 2, 2020 10:15:18 AM

Request Date

March 2, 2020

Due Date

March 9, 2020

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

*P: Irene*

*T: 1.55pm 2/3/2020*

*v: ln*

*E:*

### Actions

Next Step

Agree to perform service

Decline Work	Accept Work
--------------	-------------

### Vehicle Information

Incident Vehicle Registration #

SDU8895Z

Model  
UNKNOWN

Service Address

---

...

Primary Contact/Insured

---

LEE TUCK LUN TERRENCE (LI DELUN TERRENCE)  
BLK 228 SERANGOON AVENUE 4, #02-67, 550228, Singapore

INSURANCE@DICKSON-AUTO.COM

Claim Handler

---

TAN Jas  
6568804844  
jas.tan@axa.com.sg

Additional Instructions

Messages   Invoices   History   Documents <sup>7</sup>   Assessment   Metrics   Notes

---

New Message

## VISHNU BATHAM Shekhar

---

**From:** Irene <motor@iaconsultingsg.com>  
**Sent:** Friday, February 28, 2020 5:40 PM  
**To:** SG AXA Insurance SM AXA SGP - Motor Survey  
**Cc:** candy@iaconsultingsg.com; sile@iaconsultingsg.com  
**Subject:** [EXTERNAL] ACCIDENT INVOLVING SDU8895Z AND SKD5236C ALONG SERANGOON AVE 3 ON 28.02.2020  
**Attachments:** doc00891720200228173112.pdf  
**Categories:** Shekhar

Dear Sir,

attached herewith the Notification Of Accident for your reference.

Kindly let us have a list of your ten surveyors as your nominated SJE for our consideration within the stipulated timeline under the NIMA Protocol.

Best Regards,  
Irene Tan  
Triple-T Automobile  
Tel: 6385 1171

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	799F
Vehicle Details	
Vehicle No.:	SDU8895Z
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Mar 2020
Vehicle Make:	NISSAN
Vehicle Model:	SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	HR16976906B
Chassis No.:	MNTBBAB17Z0025213
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$16,439.00
Original Registration Date:	28 Nov 2015
First Registration Date:	28 Nov 2015
Transfer Count:	0
Actual ARF Paid:	\$16,439.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Nov 2025
PARF Rebate Amount:	\$12,329.00
Intended COE Rebate Details	
COE Expiry Date:	27 Nov 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,001.00
COE Rebate Amount:	\$32,107.00
<b>Total Rebate Amount:</b>	<b>\$44,436.00</b>

- 8219.50

The information contained herein is correct as at 03 Mar 2020

OK

# NEW CAR DISCOUNTS & OFFERS

BEST DEAL DAILY!

EV 1 Year PROM

nissan sylphy Price Range Depreciation Year Reg Vehicle Type

Home » Used Cars » Ka-Hup Vehicles Trading » Nissan Sylphy 1.6A

## Nissan Sylphy 1.6A

Overview Financial Insurance Accessories Similar Research Photos



ESTABLISHED SINCE 1989



<b>Price</b>	\$54,800 <i>51</i>		
<b>Depreciation</b>	\$7,470 /yr <i>View models with similar depre.</i>	<b>Reg Date</b>	19-May-2016 <i>(6yrs 2mths 15days COE left)</i>
<b>Mileage</b>	55,700 km (14.7k /yr)	<b>Manufactured</b>	2016
<b>Road Tax</b>	\$742 /yr	<b>Transmission</b>	Auto
<b>Dereg Value</b>	\$42,349 as of today (change)	<b>OMV</b>	\$16,807
<b>COE</b>	\$47,889	<b>ARF</b>	\$16,807
<b>Engine Cap</b>	1,598 cc	<b>Power</b>	85.0 kW (113 bhp)
<b>Curb Weight</b>	1,205 kg	<b>No. of Owners</b>	1
<b>Type of Vehicle</b>	Mid-Sized Sedan		

### Features

Powerful 1.6L 4 Cylinder Inline DOHC Engine Producing 113Bhp Coupled With An Advanced X-Tronic CVT Auto Transmission. View specs of the Nissan Sylphy (2013-2016)

### Accessories

Sports Rims, Leather Seats, Keyless Entry/Start, Multi Function Steering.

### Description

1 Owner Only. 100% Loan Available. Low Price! Low Mileage 55000km Low Depreciation Only \$7469 Beautiful Condition. Agent Servicing From Day 1 Still Now. Must View To Believed. Smooth And Quiet Engine. Call Us Now.

### Category

PARF Car, Premium A/B/C/D

*DOA = 28/2/20*

*Balance 4 year 9 month.*

### Status

Available

*WV - 51000*

*NV - 44436*

### Resources

*bu 6500*



Car Valuation - Free

Get the market value of your existing car for free. Get started

Con... tion



Auto  
Consultants  
Pte Ltd

51 UBI AVE, L 001-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

04/03/2020

### Survey Details:

Date of loss	28-Feb-20
Date of appointment	2-Mar-20
Date of survey	2-Mar-20
Location of survey	TRIPLE-T AUTOMOBILE

### Vehicle Details:

Claim Type:	TP
Vehicle number	SDU 8895Z
Make and Model	NISSAN SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR
Date of registration	28-Nov-15
Excess	
Market Value	\$ 51,000.00
Part Rebate	\$ 44,436.00
Nett Loss	\$ 6,564.00

### Repair details:

Initial Estimate	
------------------	--

### Proposed/Revised repair cost:

Parts	
Check items (estimate)	
Labour	
<b>Total</b>	
<b>Lump Sum(if applicable)</b>	

Number of days for repair	<u>3</u>
---------------------------	----------

Remarks :

The estimated repair cost of the damaged vehicle is in the region of \$ 2,500.00 - \$ 3,000.00

**Remarks:**

--

**Mandate:**

<b>Liability(TP)</b>		<b>%</b>
Proposed repair cost		\$
Loss of use		\$ no. of days
Loss of rental		\$ no. of days
Loss of income		\$ no. of days
LTA search fees		\$
Others		\$
<b>Proposed Total</b>		<b>#VALUE!</b>

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	28/02/2020 15:20
Date Of Accident	28/02/2020 13:20
Exact Location Of Accident	SERANGOON AVE 3
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDU8895Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIM PENG HOON
NRIC No	SXXXX799F
Email Address	SUMLIM54@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-91298525
Alternative Phone No	OTHERS-91298525

### Vehicle Particulars

Manufacturer	NISSAN
Model	SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D19MTPV01013869
Cover Note Number	

### Driver

Name of Driver	SUM CHONG KEONG
NRIC No	SXXXX881A
Date Of Birth	13/11/1952
Occupation	INDOOR
Date Of Driving Pass	13/03/1984
Driving Experience	35 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90601654
Fax Number	
Contact Number	
E Mail Address	CHONGKEONG.SUM@GMAIL.COM

Address	BLK 329 SERANGOON AVE 3 #09-356
Postcode	550329
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : SUM MINYI
	GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO ATTACHED .

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKD5236C
Vehicle Make/Model/Colour	HYUNDAI
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LEE TUCK LUN
NRIC/Passport Number	SXXXX888F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have Insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) Investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

\_\_\_\_\_  
 Policyholder's Signature  
 Date & Time:

  
 \_\_\_\_\_  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

  
 \_\_\_\_\_  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
AXA INSURANCE PTE LTD		Ref: CS3/ASM20003402/Hsf3e2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date: 05-03-2020	
ATTN : TAN JAS		Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SKD 5236C	Veh. Inspected	SDU 8895Z
Policy No.		Coverage (\$)	0.00
Claim No.	S0M02HOY	Excess (\$)	0.00
Assign From	TAN JAS	Assign Date	02/03/2020
2. Vehicle Particulars & Condition			
Make & Model	NISSAN SYLPHY	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	MNTBBAB17Z0025213	Colour	WHITE
Odometer	72959 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	MICHELIN	5 mm
L/H Front Tyre	205/55 R16	MICHELIN	5 mm
R/H Rear Tyre	205/55 R16	MICHELIN	5 mm
L/H Rear Tyre	205/55 R16	MICHELIN	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5. General Information			
Accident Date	28/02/2020	Inspect Date / Time	02/03/2020 ( 03:25 PM )
Survey held at	BLK 3012 BEDOK NORTH AVE 4 #01-2066		
Repairer	TRIPLE-T AUTOMOBILE		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500-\$3,000			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	

Report Ref No. CS3/ASM20003402/Hsf3e2

Inspected By

LEE HOCK ANN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.