



Your Ref: MCT18120061

Date: 09th March 2020

Our Ref: CS1/III20003417/Bqf3s2

M/s India International Insurance Pte Ltd

64 Cecil Street
#05-02 IOB Building
Singapore 049711

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FBJ 7086E
INSURED VEHICLE: SH 6983G ACCIDENT DATE: 03/12/2018**

We thank you for your instruction on 28/02/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FBJ 7086E from M/s Pro-Option Services.
- b) Final Repair Bill of FBJ 7086E from M/s Dirt Wheel Motor Trading.
- c) Colour damaged vehicle photographs of FBJ 7086E.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : FBJ 7086E
Make & Model : K.T.M. 200 DUKE
Year of Registration : 2014
Chassis Number : VBKJUC404EC009986
Engine Capacity : 200 cc

2. We recommend that the repairs of the entire damage require about 3 (Three) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.