




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CC3/QBE20003485/Fea3q2		
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date : 28-04-2020		
		Code : QBE		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLA 3818R	Veh. Inspected	SH 9081P	
Policy No.	8-V0015314-MVA-R002	Coverage (\$)	0.00	
Claim No.	VC013528	Excess (\$)	0.00	
Assign From		Assign Date	02/03/2020	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI IONIQ	c.c	1580	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	KMHC851CVJU103347	Colour	BLUE	
Odometer	261046	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	DAVANTI	7 mm	
L/H Front Tyre	195/65 R15	DAVANTI	7 mm	
R/H Rear Tyre	195/65 R15	DAVANTI	8 mm	
L/H Rear Tyre	195/65 R15	DAVANTI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/03/2020	Inspection Date	02/03/2020	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		