

ASS. REC. BY:

REF: CS/MSG 2000 3493/ESF301

Special Instruction:

Surveilor: STIVA

ASSIGNMENT (Office)

From (Person): Crystal Le

of

MSG

Date/Time: 3.3.2020 9:16am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHB 2275E

Insured:

SLH 47905

at Workshop m/s

Ding Auto motive

Tel:

96891857

of 31 Corporation Road

Policy No:

1001179091

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A 2.3.2020

CA / REV / REP. / REV 24 HRS

Date/Time: 3/3/2020 1:08 p.m.

Person Contacted:

Mohan

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHB 2275E - CS/FCL 19/19 968/AYM D.O.A - 17/01/2019

SLH 47905 - X

Surveyor *Steve*

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP-RES / OD-RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? Yes or No
 GIA / PR Seen: _____ Consistent? Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *SHB 2775E* Yr Regn: *11/8/16*
 Type: *M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /*
Truck / Trailer or
 Make: *Hyundai 140* c.c. *1685*
 Colour: *Yellow* NC: Insured / Std / NI / NA
 Sp. Reading: *439911* T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: *KMH1B414M64092609*
 Gen. Cond: *Good / Fair / Poor / Burnt*
 Steering: *In order / Jammed / Leaked / Burnt or*
 Brakes: *In order / Jammed / Leaked / Burnt or*
 Mod: *Nil / S/Rim / STD / R/Rim or*
 Tyre Size: F: *205/60R16*
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or *Triangle*
 Front R/Bal. *5* mm Rear R/Bal. *5* mm
 L/Bal. *5* mm L/Bal. *5* mm
 D.O.A. *2/3/20* D.O.I. *3/3/20*
 Survey held at *Ding Automobile*
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear RH
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<i>9/3/20</i>	<i>Final \$1900, 4 dy1 (Guar) (\$ 3,602.18 Red: 66%)</i>

Signature
9/3/2020

RECEIVED 09 MAR 2020

Date/Time, File Pass to? *09/03/20*
☐ : Procl. Report
☒ : Final Report
 II Typist
 Date/Time, File Return to?

Days Of Repair: *4*
 Resurvey No. of Trip: *1*

Survey Fee:	<i>190</i>
Transportation:	
S + RS - SI	
Other	
TOTAL	<i>161</i>

Report Format:
 Lump Sum / I.B.I: (\$ *1,900/-* *US*)

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech Insp (\$)
☐ : Weekend (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj App	Adj Submitted	Ins Auth'd	Status
Main	02 Mar 2020		03 Mar 2020 12:01 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LIM YU KIAT, EUGENE, ID: S8215603H, Tel: +6590900544, Email: EUGENE_LYK@YAHOO.COM.SG		
Main Claimant:	CITYCAB PTE LTD, Co. Reg. No.: 199502839G		
Vehicle Reg. No.:	SHB2275E	Date of Loss:	02/03/2020 08:00 - :59 [42 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	1001179091 (Comprehensive) Coverage: 04/11/2019 - 03/11/2020
Vehicle Reg. No. (Insured):	SLH4790S	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Ding Automotive Pte Ltd (HQ) 31 CORPORATION ROAD, 649825 Boon Lay - Tel: 96992878		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 04/03/2020]		
Driver/Custodian (Insured):	LIM YU KIAT, EUGENE (37 / Male), NRIC: S8215603H, Tel: +6590900544 Email: EUGENE_LYK@YAHOO.COM.SG		
Adj Asp. Remarks:	on WP, Manual assigned to LKK via email on 03/03/2020, (Manual Assign). Liab: unclear, outsource as IHS Appt is full as per Winnie's email. Contact: Vadivelan Mohan @ 9689 1857 / 6265 7130.		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS View All

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Complete
----------	----------	------	------------	---------	---------	-------------	--------------	------------	----------

No results.

Summer Lee (LKK Auto)

From: Crystal Lee <crystal_lee@sg.msig-asia.com>
Sent: Tuesday, 3 March, 2020 9:16 AM
To: Admin-D (LKKAuto); assignments
Cc: Ong Zi Hui
Subject: Survey Request - Manual Assigned
Attachments: SAS2758139.PDF; Invoice.html

ACCIDENT INVOLVING SHB2275E AND SLH4790S (MSIG) ON 02/03/2020

Manual Assigned

Dear LKK,

Refer to the email below, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Thank you & Best regards,

Crystal Lee

Admin Officer, Claims Services (In-House Survey)

D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Winnie Chua <pingping_chua@sg.msig-asia.com>

Sent: Monday, 2 March 2020 5:50 PM

To: Crystal Lee <crystal_lee@sg.msig-asia.com>

Cc: Ong Zi Hui <zihui_ong@sg.msig-asia.com>; Taxis Customer Service <taxiscs@stengg.com>; Helene Phua <helene_phua@sg.msig-asia.com>

Subject: FW: ACCIDENT INVOLVING SHB2275E AND SLH4790S (MSIG) ON 02/03/2020 SURVEYOR ARRANGEMENT (Car in at 31 Corporation Rd, please outsource)

Dear Crystal,

Please outsource as car is in. IHS full.

Best Regards

Winnie Chua

Senior Admin Officer, Claims Services (In-House Survey)

Direct line +65 6594 2556 | Direct fax +65 6225 7402 | pingping_chua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Taxis Customer Service <taxiscs@stengg.com>

Sent: Monday, 2 March 2020 4:27 PM

To: Claims <claims@sg.msig-asia.com>

Cc: kelly.ding@dingauto.sg; dd.hashim@dingauto.sg; Claims@dingautomotive.com.sg

Subject: ACCIDENT INVOLVING SHB2275E AND SLH4790S ON 02/03/2020 SURVEYOR ARRAGEMENT

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Officer,

Kindly please arrange survey for vehicle **SHB2275E**. Vehicle already grounded inside workshop. Survey location will be at 31 Corporation Road.

Best Regards,
VADIVELAN MOHAN
Ding Automotive Pte Ltd
Hp : 96891857 / 62657130

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The forwarding of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attached to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disseminate contents.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	839G
Vehicle Details	
Vehicle No.:	SHB2275E
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Mar 2020
Vehicle Make:	HYUNDAI
Vehicle Model:	I40 1.7 CRDI F/L AT ABS AIRBAG 4DR
Primary Colour:	Yellow
Manufacturing Year:	2016
Engine No.:	D4FDGU662196
Chassis No.:	KMHLB41UMGU092609
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$18,769.00
Original Registration Date:	11 Aug 2016
First Registration Date:	11 Aug 2016
Transfer Count:	0
Actual ARF Paid:	\$18,769.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Aug 2024
PARF Rebate Amount:	\$14,076.00
Intended COE Rebate Details	
COE Expiry Date:	10 Aug 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$41,215.00
COE Rebate Amount:	\$22,851.00
Total Rebate Amount:	\$36,927.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 03 Mar 2020

OK

Shirley Hiew (LKK Auto)

From: Steve Chen (LKK Auto)
Sent: Monday, 9 March 2020 9:36 am
To: Taxis Customer Service
Cc: Claims@dingautomotive.com.sg; dd.hashim@dingauto.sg; kelly.ding@dingauto.sg; Asher Sng (LKKAuto); SUR
Subject: 50112491 / SHB2275E - Finalize Amount & After Repair Photo . (DOA:02/03/2020)

Dear Guang,

We confirm the finalize \$1900 (L/S, before4 GST). 4 repair days.

Thanks.

Best Regards,

Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Taxis Customer Service [mailto:taxiscs@stengg.com]
Sent: Saturday, March 07, 2020 2:08 PM
To: Steve Chen (LKK Auto)
Cc: Claims@dingautomotive.com.sg; dd.hashim@dingauto.sg; kelly.ding@dingauto.sg; Asher Sng (LKKAuto); SUR; CS A Team; Admin A
Subject: 50112491 / SHB2275E - Finalize Amount & After Repair Photo . (DOA:02/03/2020)

Dear Steve,

Please see below for the finalize according to our conversion to finalize for SHB2275E

Please refer attachment Estimate & After Paint for SHB2275E

Remark : Item No.2 in estimate price type change to special nets and discount to \$50 & Item No.6 in estimate price type change to special nets and discount to \$200 .

Lump Sum Repair

Total Repair – 04 Days

Labour = \$1310

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 04 Mar 2020

Preliminary Advice

Insured Vehicle No	: SLH4790S	Accident Date	: 02/03/2020
TP Vehicle No	: SHB2275E	Assignment Date	: 03/03/2020
Make	: HYUNDAI I40	Est. Duration of Repair	: 4 days
Date of Inspection	: 03/03/2020		
Inspection At	: Ding Automotive Pte Ltd (HQ) 31 CORPORATION ROAD Singapore 649825		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,102.08
Revised Amount	:S\$	1,758.49
Check Items (Estimated)	:S\$	565.96
Total	:S\$	2,324.45

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 02/03/2020 12:17
 Date Of Accident 02/03/2020 08:50
 Exact Location Of Accident ALONG CTE TOWARDS CANNING RISE
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHB2275E
Insured/Policyholder
 Name Of Registered Owner CITYCAB PTE LTD
 Co Reg No 1XXXXX839G
 Email Address NOEMAIL
 Mobile Phone No
 Alternative Phone No OFFICE-65508768

Vehicle Particulars

Manufacturer HYUNDAI
 Model I40-1.7 D CRDI (A)
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category TAXI

Insurance Company

Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
 Fleet Policy YES
 Policy Number D-18088937MFSH
 Cover Note Number

Driver

Name of Driver SUNNY CHIA POH CHUAN (SUNNY XIE BAOQUAN)
 NRIC No SXXXX516F
 Date Of Birth 11/08/1983
 Occupation OUTDOOR
 Date Of Driving Pass 27/10/2006
 Driving Experience 13 YEARS AND 4 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-94558002
 Fax Number
 Contact Number
 Email Address NOEMAIL

Address	APT BLK 801 KEAT HONG CLOSE #09-25 SINGAPORE
Postcode	682801
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : MALE
Passenger 3	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE NOT SUITABLE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLH4790S
Vehicle Make/Model/Colour	HONDA WHITE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIM YU KIAT , EUGENE

NRIC/Passport Number

SXXXX603H

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If Driver is not the policyholder)
Date & Time: 02/03/20

Reporting Centre Personnel's Signature
Name: WNL
NRIC/TIN No.:

12/5 PM

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 2/3/2020 ABOUT 08:50 HOURS I WAS DRIVING MY TAXI (SHB2275E) ALONG CTE TOWARDS CANNING RISE. AT TIME 3 PASSENGERS ON BOARD. AT TIME TRAFFIC WAS MODERATE. I WAS DRIVING AT 2ND LANE AT TIME. I WANTED CHANGE TO 3RD BUT DUE TO TRAFFIC I JUST MAINTAIN DRIVING ON 2ND LANE. SUDDENLY I FEEL BIG IMPACT FROM BEHIND. THEREAFTER I WENT DOWN CHECK. I REALIZED 1 VEHICLE HONDA COLLIDED ON MY VEHICLE REAR RHTS. HE CAME FROM 1ST LANE AND COLLIDED INTO MY VEHICLE. THE IMPACT VERY STRONG UNTIL MY PASSENGERS THINGS FLOW OVER. AFTER WHILE WE EXCHANGED PARTICULARS AND TOOK SOME PHOTOS FOR REPORTING PURPOSE. THE OTHER VEHICLE BEARING PLATE NUMBER (SLH4790S).

DECLARATION

(We declare the foregoing particulars are true in every respect.)

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time: 02/03/20

Reporting Centre Personnel's Signature
Name: VARDI
NRIC/ID No.:

QARAC Form 101-101-101-101

12:15pm

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

02/03/2020 21:34

OWNER'S PARTICULARS

JOB-NO: 50112491

NAME: CityCab PTE LTD (Fleet)
 ADDRESS: 383 SIN MING DRIVE
 SINGAPORE 575717 0

CONTACT: 65533880
 64739522

Page 1 of 2

VEHICLE DETAILS

LICENSE NO: SHB2275E TRANS: AUTO
 MAKE / MODEL: HYUNDAI / i40
 OWNER'S INSURER: MS First Capital Insurance Limited
 JOB-CODE: TP SA: Ding Auto User 2

CHASSIS: KMHLB41UMGU092609
 ENGINE: D4FDGU662196

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREAS	1.00	1,200.00	0.00	1,200.00	490	200	600
2 RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00	200		Y
3 RESPRAY REVERSE SENSOR	1.00	80.00	0.00	80.00	20		Y
4 RESPRAY END PANEL	1.00	250.00	0.00	250.00	200		Y
5 R&R REVERSE SENSOR AND CHECK WIRING CONNECTION	1.00	120.00	0.00	120.00	30		Y
6 CHECK WIRING AND LIGHTING SYSTEM WITH RE-POSITION TAIL LAMP	1.00	120.00	0.00	120.00	30		Y
7 RUST PROOFING	1.00	100.00	0.00	100.00	30		Y
TOTAL:		2,120.00	0.00	2,120.00			

MATERIALS

1 REAR BUMPER	1.00	599.80	119.92	479.88	L	Y	
2 REAR BUMPER PROTECTOR PAD	1.00	120.00	24.00	96.00	50 x 5	Y	
3 REAR BUMPER DIFFUSER	1.00	258.80	51.72	206.88	L	Y	
4 REAR BUMPER REINFORCEMENT	1.00	485.80	97.12	388.48	L	Y	
5 REAR BUMPER REINFORCEMENT SPONGE	1.00	98.80	19.72	78.88	L	Y	
6 REVERSE SENSOR SET	1.00	240.00	48.00	192.00	300 x 5	Y	
7 REAR BUMPER RETAINER RHS	1.00	48.62	9.72	38.90	L	Y	
8 REAR BUMPER REFLECTOR RHS	1.00	48.30	9.26	37.04	L	Y	
9 REAR END PANEL (REPAIR)	1.00	0.00	0.00	0.00	X L	Y	
10 REAR RHS EXHAUST MUFFLER ASSY	1.00	960.30	192.06	768.24	X L	Y	
11 REAR RHS BODY TAIL LAMP	1.00	565.80	113.12	452.48	X L	Y	
12 REAR BUMPER CLIPS	1.00	45.00	0.00	45.00	30/S	Y	
13 REAR BUMPER REINFORCEMENT BRACKET (RHS)	1.00	98.60	0.00	98.60	S	Y	
14 REAR END PANEL SEALANT	1.00	100.00	0.00	100.00	S	Y	
TOTAL:		3,665.82	684.64	2,982.18			

TOTAL PARTS & LABOUR :

5,788.82

684.64

5,102.18

EXCESS/LOADING: S\$ 0.00

No. Of Day:

4 (4)

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: S\$

DATE OF SURVEY:

3/13/20, 1.00pm

9934-12

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

SURVEYED BY: _____

CONTACT NO: _____

FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL: _____

FAX: _____

WKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

DING AUTOMOTIVE PTE LTD

Bik 10, #01-20

Sin Ming Industrial Est. Sec C

Singapore 575645

Tel: 6452 1208

Fax: 6452 0614

Vehicle: SHB2275E

Model: HYUNDAI I40

Chassis: KMHLB41UMGU092609

PARTS SUPPLEMENTARY & QUOTATION FORM

	LABOUR	PRICE	SURVEYOR MARKING
1	RESpray REAR FENDER RH	\$ 200.00	✓
2	RESpray REAR END PANEL	\$ 200.00	X Repaired
	TOTAL:	\$ 400.00	

Stew

5/3/20, 6.45pm



(Regn. No.: 1971X0263N)

TAXI REPAIR JOB SHEET - ACCIDENT

TAXI	JOB CARD CODE :	
CONTRACT / NON-BILLABLE		

TOWING / YES / NO	BODY WORK	PAINTING	ACCIDENT REPAIR
50112491		CREDIT LIMIT:	500,000.00

CityCab PTE LTD (Fleet)

383 SIN MING DRIVE
SINGAPORE 575717 0

CityCab

Date-Reg: 11/08/2016

Date-In: 02/03/2020 6:32 pm

TEL:

C# KMHLB41UMGU092609

E# D4FDGU662196

SHB2275E

		OF	
JOB NO:	BLOCK NO.		
		DATE & TIME	
VEHICLE IN ST LAND SYSTEMS	2/3	2020	9:40
VEHICLE INSIDE WORKSHOP	2/3	2020	9:40
VEHICLE OUT OF WORKSHOP			
VEHICLE OUT OF ST LAND SYSTEMS			

SERVICE ADVISOR	DEADLINE		VEHICLE NO.
	DATE	TIME	
VAN.			SH B2275E.

MODEL :	40			
MILEAGE :	439911			
FUEL TANK LEVEL :	E		1/2	F

S/NO	FAULTS INDICATED BY OWNER	DIAGNOSIS
	TP	

[illegible]

JOB CHECKED BY: _____ DATE/TIME: _____ SIGNATURE: _____

Remarks

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Mar 2020		03 Mar 2020 12:01 Edit Adj Rpt	S\$1,900.00 Edit Estimates	S\$1,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	LIM YU KIAT, EUGENE , ID: S8215603H, Tel: +6590900544, Email: EUGENE_LYK@YAHOO.COM.SG								
Main Claimant:	CITYCAB PTE LTD , Co. Reg. No.: 199502839G								
Vehicle Reg. No.:	SHB2275E	Date of Loss:	02/03/2020 09:00 - :59 [42 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 239853	Policy/Cover Note No.:	1001179091 (Comprehensive) Coverage: 04/11/2019 - 03/11/2020						
Vehicle Reg. No. (Insured):	SLH4790S	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Ding Automotive Pte Ltd (HQ) 31 CORPORATION ROAD, 649825 Boon Lay - Tel: 96992878								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 02/04/2020]								
Driver/Custodian (Insured):	LIM YU KIAT, EUGENE (37 / Male), NRIC: S8215603H, Tel: +6590900544 Email: EUGENE_LYK@YAHOO.COM.SG								
Adj Asg. Remarks:	on WP. Manual assigned to LKK via email on 03/03/2020. (Manual Assign). Liab: unclear. outsource as IHS Appt is full as per Winnie's email. Contact: Vadivelan Mohan @ 9689 1857 / 6265 7130.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHB2275E (239853)

[SLH4790S]

TP







































CITYCAB PTE LTD

Mar 2 2020 9:00AM

[LIM YU KIAT, EUGENE]

Ding Automotive Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View			View In Browser		
Video									1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail			Print			
1	13/03/20 16:25	Video - Accident(TP)						1 Load MP4						
Assessment Reports									1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail			Print			
1	04/03/20 16:54	Adjuster Immediate Advice						1 Load HTM						
Photos/Images									3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail			Print			
1	03/03/20 18:00	General View						1 Load JPG			<input checked="" type="checkbox"/>			
2	03/03/20 18:00	General View						1 Load JPG			<input checked="" type="checkbox"/>			
3	03/03/20 18:00	Odometer Reading						1 Load JPG			<input checked="" type="checkbox"/>			
4	03/03/20 18:00	Chassis Number						1 Load JPG			<input checked="" type="checkbox"/>			
5	03/03/20 18:00	General View						1 Load JPG			<input checked="" type="checkbox"/>			
6	03/03/20 18:00	General View						1 Load JPG			<input checked="" type="checkbox"/>			
7	03/03/20 18:00	General View						1 Load JPG			<input checked="" type="checkbox"/>			
8	03/03/20 18:00	General View						1 Load JPG			<input checked="" type="checkbox"/>			
9	03/03/20 18:00	General View						1 Load JPG			<input checked="" type="checkbox"/>			
10	03/03/20 18:00	General View						1 Load JPG			<input checked="" type="checkbox"/>			
11	03/03/20 18:00	General View						1 Load JPG			<input checked="" type="checkbox"/>			
12	03/03/20 18:00	General View						1 Load JPG			<input checked="" type="checkbox"/>			
13	03/03/20 18:00	General View						1 Load JPG			<input checked="" type="checkbox"/>			
14	03/03/20 18:00	General View						1 Load JPG			<input checked="" type="checkbox"/>			
15	03/03/20 18:00	General View						1 Load JPG			<input checked="" type="checkbox"/>			
16	03/03/20 18:00	General View						1 Load JPG			<input checked="" type="checkbox"/>			
17	03/03/20 18:00	General View						1 Load JPG			<input checked="" type="checkbox"/>			
18	03/03/20 18:00	General View						1 Load JPG			<input checked="" type="checkbox"/>			
19	03/03/20 18:00	General View						1 Load JPG			<input checked="" type="checkbox"/>			
20	03/03/20 18:00	General View						1 Load JPG			<input checked="" type="checkbox"/>			
21	03/03/20 18:00	General View						1 Load JPG			<input checked="" type="checkbox"/>			
22	03/03/20 18:00	General View						1 Load JPG			<input checked="" type="checkbox"/>			
23	03/03/20 18:00	General View						1 Load JPG			<input checked="" type="checkbox"/>			
24	03/03/20 18:00	General View						1 Load JPG			<input checked="" type="checkbox"/>			
25	03/03/20 18:00	General View						1 Load JPG			<input checked="" type="checkbox"/>			
26	03/03/20 18:00	General View						1 Load JPG			<input checked="" type="checkbox"/>			
27	03/03/20 18:00	General View						1 Load JPG			<input checked="" type="checkbox"/>			
28	03/03/20 18:00	General View						1 Load JPG			<input checked="" type="checkbox"/>			
29	09/03/20 09:37	Photographs of Damaged Parts						1 Load JPG			<input checked="" type="checkbox"/>			
30	09/03/20 09:37	Photographs of Damaged Parts						1 Load JPG			<input checked="" type="checkbox"/>			

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
31	09/03/20 09:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	09/03/20 09:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	09/03/20 09:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	09/03/20 09:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	09/03/20 09:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	09/03/20 09:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	09/03/20 09:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	09/03/20 09:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	09/03/20 09:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	09/03/20 09:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	09/03/20 09:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	09/03/20 09:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	09/03/20 09:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	09/03/20 09:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	09/03/20 09:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	09/03/20 09:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	09/03/20 09:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	09/03/20 09:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	09/03/20 09:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	09/03/20 09:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	09/03/20 09:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	09/03/20 09:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	09/03/20 09:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	09/03/20 09:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	09/03/20 18:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
56	09/03/20 18:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
57	09/03/20 18:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
58	09/03/20 18:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
59	09/03/20 18:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
60	09/03/20 18:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
61	09/03/20 18:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
62	09/03/20 18:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	03/03/20 10:50	OI SLH4790S GIA REPORT	 Load PDF	
2	03/03/20 10:50	TPD SHB2275E GIA REPORT	 Load PDF	
3	03/03/20 11:14	TPD SHB2275E - PRI	 Load PDF	
4	03/03/20 11:34	Email - to outsource as IHS appt is full	 Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	03/03/20 11:59	Survey Request - Manual Assigned	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/03/20 08:59	Supplementary	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^

v

Show Remarks To:

☐ Handling Insurer

Note:

Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20003493/ESF3E2

Date: 16/03/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001179091

Claimant Vehicle No : SHB2275E

Insured Vehicle No : SLH4790S

Date of Loss: 02/03/2020

Nature of Claim: TP

Claim No: 239853

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB2275E

Make & Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)

Engine No: D4FDGU662196

Reg. Date: 11/08/2016 (Man. Year: 2016)

Chassis No: KMHLB41UMGU092609

Colour: Yellow

Odometer: 439911 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Triangle 5 mm

Rear Left Side: Triangle 5 mm

Front Right Side: Triangle 5 mm

Rear Right Side: Triangle 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,054.18	1,042.50	2,011.68	65.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,520.00	1,310.00	1,210.00	48.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,574.18	2,352.50	3,221.68	57.80
Approved Total (Overridden) (S\$)		1,900.00		
(S\$)	5,574.18	1,900.00	3,674.18	65.91
+ GST 7.00/7.00% (S\$)	390.19	133.00	257.19	65.91
Nett Amount (S\$)	5,964.37	2,033.00	3,931.37	65.91

INSPECTION

Date of Assignment: 03/03/2020

Date Inspected: 03/03/2020 Inspected At:

Ding Automotive Pte Ltd (HQ)
31 CORPORATION ROAD
Singapore 649825

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Mar 2020)
Parts:	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB2275E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	599.60 FL	*599.60 FL
2	1		*REAR BUMPER PROTECTOR PAD	Necessary	120.00 FS	*50.00 FS
3	1		*REAR BUMPER DIFFUSER	Cut	258.60 FL	*258.60 FL
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	485.60 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT SPONGE	Not Necessary	98.60 FL	*- FL
6	1		*SET REVERSE SENSOR	Shorted	240.00 FS	*200.00 FS
7	1		*REAR BUMPER RETAINER RHS	Broken	48.62 FL	*48.62 FL
8	1		*REAR BUMPER REFLECTOR RHS	Broken	46.30 FL	*46.30 FL
9	1		*REAR END PANEL (NPA)	Repair	0.00 FL	*- FL
10	1		*REAR RHS EXHAUST MUFFLER ASSY	Not Necessary	960.30 FL	*- FL
11	1		*REAR RHS BODY TAIL LAMP	Not Necessary	565.60 FL	*- FL
12	1		*REAR BUMPER CLIPS	Necessary	45.00 FS	*30.00 FS
13	1		*REAR BUMPER REINFORCEMENT BRACKET (RHS)	Not Necessary	98.60 FS	*- FS
14	1		*REAR END PANEL SEALANT	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,666.82	1,233.12
- List Item Discount on L Items 20.00/20.00% (\$\$)	612.64	190.62
Total Parts (\$\$)	3,054.18	1,042.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREAS	New	1,200.00	600.00
2	RESPRAY REAR BUMPER	New	250.00	200.00
3	RESPRAY REVERSE SENSOR	New	80.00	20.00
4	RESPRAY END PANEL	New	250.00	200.00
5	R&R REVERSE SENSOR AND CHECK WIRING CONNECTION	New	120.00	30.00
6	CHECK WIRING AND LIGHTING SYSTEM WITH RE-POSITION TAIL LAMP	New	120.00	30.00
7	RUST PROOFING	New	100.00	30.00
8	RESPRAY REAR FENDER RH	New	200.00	200.00
9	RESPRAY REAR END PANEL (Repeated)	New	200.00	0.00
Gross Labour Cost (\$\$)			2,520.00	1,310.00


Report was unsubmitted during this print-out.

< END OF ESTIMATES >

INVENTORY CHECKLIST

S/No	Description of Item	Quantity	Check In	Check Out	Remarks
1.	Road Tax Disc				
2.	Spare Tyre				
3.	Stabdard Tool Set				
4.	Wheel Cap / Sport Rim				
5.	Radio / CD Player / Antenna				
6.	Headrest				
7.	Alarm System				
8.	Central Locking				
9.	MDT Antenna				
10.	Taxi Meter				

Condition of Vehicle



- Collision Damages

X - Malfunction

☐ - Inventory check cannot be performed due to major damages

Comments : _____

TERMS OF AGREEMENT

I, the registered owner of the above-described vehicle, hereby authorise the repairs and any essential works and supply of materials arising therefrom to proceed.

The vehicle may be driven on the road for testing purposes or otherwise in carrying out such repairs. Any claim for damages caused to the vehicle during the course of the road test or repair arising from any accident or otherwise is limited to the rectification free of cost. No claim for incidental or consequential losses is admissible.

The vehicle and its contents are left at this premises at my own risk whatever the cause of any damage thereto or theft or loss thereof.

Any claim for faulty workmanship is limited solely to the rectification free of cost of such faulty work, no claim for loss consequential or otherwise being admissible.

I also agree to pay the invoice at your customary rate and charges on strictly cash terms.

 Signature of Owner / Owner's Representative

 Service Advisor