

ASS. REC. BY:

REF:

CS3/CTI20003517/E6/307

Special Instructions:

Assigner: Steve

monmen

ASSIGNMENT (Office)

From (Person): Cecilia Low

of CTI

Date/Time: 3/3/2020

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SLB 9783L

Insured: GBK 8855R

at Workshop m/s Loh & Lee Motor

Tel: 62680909

of Blk 5 Pioneer Rd Nth #01-37

Policy No:

Claim No: SNM20D201097

Sum Insured:

Excess:

Make of Veh:

D.O.A 27/2/2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

Mr. Loh

H.O.D. Endorsement:

Date/Time: 3/3

Person Contacted:

Me

Vehicle IN/OUT

Date/Time

Action/Instruction Estimated (X)

SLB 9783L-X

GBK 8855R-X

05/03/20 @ 16:45 pm checked with Mr. Loh, not no estimate

Steve

REF:

CTI

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP-RES / OD-RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh. had continued its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLB9783L

Yr Regn:

28/4/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Tractor or

Make:

Nissan Note

c.c

1198

Colour

Red

A/C: Insured / Std / NI / NA

Sp. Reading

35439

T/Radio: Insured / Std / NI / NA

Eng/No:

Ch/No:

JN11TAAE 1229972249

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Locked / Burnt or

Brake: In order / Jammed / Locked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

27/2/20

D.O.A.

4/3/20

Survey held at

Loh & Lee Motor

Des. of Damages (Frt) / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV-47K

Repair range (2K-3K)
3 Repair days

[Signature]
5/3/2020

RECEIVED 03 MAR 2020

Date/Time, File Pass to?

06/03/20

☐

: Prelim. Report

☒

: Final Report

1) *[Signature]*
Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Insp (\$

☐

: Weekend (\$

Survey Fee:

190

Transportation:

) \$ + RS. \$

) Price

) Others

) ..

TOTAL

190

Report Format:

PRS

Lump Sum / I.B.I. (\$

Nivitha (LKK Auto)

From: Cecilia Low <cecilia.low@sg.cntaiping.com>
Sent: Tuesday, 3 March 2020 2:31 PM
To: bonnie kwok; sur@lkkauto.com; admin-a@lkkauto.com; assignments@lkkauto.com
Cc: Loh HAN SHENG
Subject: RE: OUR REF: SNM20D201097/SLB9783L/CECILIA - Pre-Repair Inspection: Your Vehicle: GBK8855R; Our Ref: Loh&Lee-SLB9783L; Accident Involving SLB 9783 L & GBK 8855 R on 27 February 2020

Without Prejudice

Dear Sirs

We regret to inform that we are not agreeable with your panel of surveyors.

Please note that we are appointing LKK to attend to the inspection.
Thank you.

Cecilia Low (Ms)
Senior Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6530 | F: (65) 6225 5879

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

From: bonnie kwok [mailto:litigation@bonniekwok.com]
Sent: Tuesday, 3 March 2020 10:05 AM
To: Cecilia Low <cecilia.low@sg.cntaiping.com>
Cc: Loh HAN SHENG <lohsheng@gmail.com>
Subject: Re: OUR REF: SNM20D201097/SLB9783L/CECILIA - Pre-Repair Inspection: Your Vehicle: GBK8855R; Our Ref: Loh&Lee-SLB9783L; Accident Involving SLB 9783 L & GBK 8855 R on 27 February 2020

Dear Sirs,

Our client rejects your list of surveyors.

We have been instructed to propose the following list of surveyors for the Single Joint Expert:-

1. Fong Kok Heng
2. Danny Yap
3. Willy Goh
4. Francis Ng
5. Dennis Yap
6. Louis Ng
7. Michael Yap
8. Lim Yong Tian
9. Patrick Ng
10. Philip Foo

Val Out

Kindly contact the repairers, M/s Loh & Lee Motor Workshop at 9837 3345 for pre-repair inspection arrangements.

Regards,

ST

BONNIE KWOK LLC

Advocates & Solicitors
101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358
TEL: 6536 6026
FAX: 6536 2279
email : litigation@bonniekwok.com
GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 8.45 a.m. to 5.45 p.m. and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

On Mon, 2 Mar 2020 at 15:31, Cecilia Low <cecilia.low@sg.cntaiping.com> wrote:

Without Prejudice

Dear Sirs

We refer to your email of even date.

We intend to conduct a Pre-Repair Survey of your client's vehicle jointly with your client/your motor workshop.

We propose to use one of the following motor surveyors to conduct the survey as a single joint expert.

LKK / LBS

Adrian Ling

Kelvin Ang

See Chew Seng
Mohd Fadhilah Bin Osman
Xing Quo Qiang
Kenneth Kong
Simon Ho
Chua Weijie
Marcus Chua
Henry Ng

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

If we do not hear from you within two days of this letter, you shall have deemed to have agreed that the surveyor appointed by us shall be Single Joint Expert for this matter.

Thank you.

Cecilia Low (Ms)

Senior Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6530 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Monday, 2 March 2020 2:58 PM
To: Cecilia Low <cecilia.low@sg.entaiping.com>; 'bonnie kwok' <litigation@bonniekwok.com>
Cc: Claims Dept of CTI <claimsdept@sg.entaiping.com>
Subject: OUR REF: SNM20D201097/SLB9783L/CECILIA - Pre-Repair Inspection: Your Vehicle: GBK8855R; Our Ref: Loh&Lee-SLB9783L; Accident Involving SLB 9783 L & GBK 8855 R on 27 February 2020

Dear Cecilia,

Please conduct PRS for SLB9783L.

Note : officer in charge – Cecilia 63896530.

*** Kindly quote our reference number when replying.

Thank you,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896116 | F: (65) 62247175

W: www.sg.entaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: bonnie kwok <litigation@bonniekwok.com>
Sent: Monday, March 2, 2020 11:12 AM

To: Claims Dept of CTI <claimsdept@sg.entaiping.com>

Subject: Urgent: Pre-Repair Inspection: Your Vehicle: GBK8855R; Our Ref: Loh&Lee-SLB9783L;
Accident Involving SLB 9783 L & GBK 8855 R on 27 February 2020

Urgent

Dear Sirs,

We refer to the above matter.

We hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle no. SLB 9783 L at M/s Loh & Lee Motor Workshop, Block 5 Pioneer Road North #01-37 Singapore 628458.

Regards,
ST

--

BONNIE KWOK LLC

Advocates & Solicitors

101A Upper Cross Street

#08-12 People's Park Centre

Singapore 058358

TEL: 6536 6026

FAX: 6536 2279

email : litigation@bonniekwok.com

GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 8.45 a.m. to 5.45 p.m. and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the

sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/02/2020 16:26
Date Of Accident	27/02/2020 15:05
Exact Location Of Accident	TAMAN JURONG SHOPPING CENTRE EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB9783L
Insured/Policyholder	
Name Of Registered Owner	LOH HOOI MING
NRIC No	SXXXX267Z
Email Address	FAYTHLOH@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90215770
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	NISSAN
Model	NOTE-1.2 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P1766409
Cover Note Number	

Driver

Name of Driver	YEO SOY TEE
NRIC No	SXXXX660I
Date Of Birth	16/11/1949
Occupation	INDOOR
Date Of Driving Pass	11/03/1969
Driving Experience	50 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96692431
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 39A WEST COAST PARK #03-01
Postcode	127712
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - FATHER IN LAW
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : CHAN SOW LIN
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBK8855R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	ZHI XIONG
NRIC/Passport Number	SXXXX274C
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time: 2020-02-27 16:35




Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

I AM AWARE THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

FORM 100 - SKETCH PLAN (2019-2020)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 27/02/2020 @ 15/0 hrs.

I was waiting at the Taman Jurong Shopping Centre gantry for the exit towards Yung An Rd. Vehicle B was in front of me. Suddenly Vehicle B start to reversing the vehicle. I horn to Vehicle B but he ignore my vehicle and collided onto my vehicle front portion, causing my vehicle damage. No one was injured.

- ☐ Claim own policy
☐ Claim third party
☒ Claim OD (TP) at other works hop Loh & Lee
☐ For record purpose

Policy No. P1766409

Insurer AXA Veh. No. SLB9783L

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

GAIRAC Sketch Plan Form V3

2020-02-27
1635hrs

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	267Z
Vehicle Details	
Vehicle No.:	SLB9783L
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Mar 2020
Vehicle Make:	NISSAN
Vehicle Model:	NOTE 1.2 CVT ABS D/AIRBAG 2WD 5DR
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	HR12184918B
Chassis No.:	JN1TAAE12Z0972249
Maximum Power Output:	58.0 kW (77 bhp)
Open Market Value:	\$13,026.00
Original Registration Date:	28 Apr 2016
First Registration Date:	28 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Apr 2026
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	27 Apr 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,504.00
COE Rebate Amount:	\$27,972.00
Total Rebate Amount:	\$31,722.00

The information contained herein is correct as at 04 Mar 2020

OK























...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Mar 2020		04 Mar 2020 14:35 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	Co. Reg. No.: -								
Main Claimant:	LOH HOOI MING, ID: S8077267Z								
Vehicle Reg. No.:	SLB9783L	Date of Loss:	27/02/2020 15:00 - :59 [45 Months and 30 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM20D201097	Policy/Cover Note No.:	DMCVSN19127819000						
Vehicle Reg. No. (Insured):	GBK8855R	Policy No. (Claimant):	P1766409						
		Excess:	S\$0.00						
Repairer:	Loh & Lee Motor Workshop (HQ) BLK 5 PIONEER ROAD NORTH #01-37, 628458 Pioneer - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Cecilia Low - 63896530]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 13/03/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLB9783L (SNM20D201097)
[GBK8855R]
TP
LOH HOOI MING
Feb 27 2020 3:00PM
[-]
Loh & Lee Motor Workshop

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Video									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)							Thumbnail	Print	
1	28/02/20 13:42	Video - Accident [Linked Accident Report Documents]							 Load MP4		
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	04/03/20 17:45	General View							 Load JPG	<input checked="" type="checkbox"/>	
2	04/03/20 17:45	General View							 Load JPG	<input checked="" type="checkbox"/>	
3	04/03/20 17:45	General View							 Load JPG	<input checked="" type="checkbox"/>	
4	04/03/20 17:45	General View							 Load JPG	<input checked="" type="checkbox"/>	
5	04/03/20 17:45	Odometer Reading							 Load JPG	<input checked="" type="checkbox"/>	
6	04/03/20 17:45	Chassis Number							 Load JPG	<input checked="" type="checkbox"/>	
7	04/03/20 17:45	General View							 Load JPG	<input checked="" type="checkbox"/>	
8	04/03/20 17:45	General View							 Load JPG	<input checked="" type="checkbox"/>	
9	04/03/20 17:45	General View							 Load JPG	<input checked="" type="checkbox"/>	
10	04/03/20 17:45	General View							 Load JPG	<input checked="" type="checkbox"/>	
11	04/03/20 17:45	General View							 Load JPG	<input checked="" type="checkbox"/>	
12	04/03/20 17:45	General View							 Load JPG	<input checked="" type="checkbox"/>	
13	04/03/20 17:45	General View							 Load JPG	<input checked="" type="checkbox"/>	
14	04/03/20 17:45	General View							 Load JPG	<input checked="" type="checkbox"/>	
15	04/03/20 17:45	General View							 Load JPG	<input checked="" type="checkbox"/>	
16	04/03/20 17:45	General View							 Load JPG	<input checked="" type="checkbox"/>	
17	04/03/20 17:45	General View							 Load JPG	<input checked="" type="checkbox"/>	
18	04/03/20 17:45	General View							 Load JPG	<input checked="" type="checkbox"/>	
19	04/03/20 17:45	General View							 Load JPG	<input checked="" type="checkbox"/>	
20	04/03/20 17:45	General View							 Load JPG	<input checked="" type="checkbox"/>	
21	04/03/20 17:45	General View							 Load JPG	<input checked="" type="checkbox"/>	
22	04/03/20 17:45	General View							Load JPG	<input checked="" type="checkbox"/>	
23	04/03/20 17:45	General View							Load JPG	<input checked="" type="checkbox"/>	
24	04/03/20 17:45	General View							Load JPG	<input checked="" type="checkbox"/>	
25	04/03/20 17:45	General View							Load JPG	<input checked="" type="checkbox"/>	
26	04/03/20 17:45	General View							Load JPG	<input checked="" type="checkbox"/>	

Linked Accident Report Documents

										View	<div>View in Browser</div>
Video										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)							Thumbnail	Print	
1	28/02/20 13:42	Video - Accident							<div>1</div> Load MP4		

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	28/02/20 13:43	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	28/02/20 13:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	28/02/20 13:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	28/02/20 13:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	28/02/20 13:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	28/02/20 13:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	28/02/20 13:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	28/02/20 13:42	Sketch Plan	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI20003517/ESF3E2

Date: 10/03/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN19127819000

Claimant Vehicle No: SLB9783L Insured Vehicle No: GBK8855R

Date of Loss: 27/02/2020 Nature of Claim: TP Claim No: SNM20D201097

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLB9783L

Make & Model: NISSAN NOTE, 1.2 (A) Engine No: HR12184918B

Reg. Date: 28/04/2016 (Man. Year: 2016) Chassis No: JN1TAAE12Z0972249

Colour: Red Odometer: 35439 km

Engine Capacity: 1198 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15

Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 04/03/2020

Date Inspected: 04/03/2020 Inspected At: Loh & Lee Motor Workshop (HQ)
BLK 5 PIONEER ROAD NORTH #01-37
Singapore 628458

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 10 Mar 2020)

Parts: 144 **NISSAN NOTE 1.2 (A) (Catalogue:Merimen Singapore 1.0)**

Labour: Repairer's **(Price-denominated Standard List)**

Print Code: (Unsubmitted, no print-code for SLB9783L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >