

ASSIGNMENT

Front:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: FZ 2330B

Policy No: 51022617(8-01 (12/11/2019-11/01/2020)

Claims No: MT 1089276-001

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Turn Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SHC4198B

Yr Regn: 01/11/2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius 4

c.c 1795

Colour:

Maroon

A/C: Insured / Std / NI / NA

Sp. Reading

298.334

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3F403573289

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195 / 65 R15

R: 195 / 65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Toyong

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

02/03/2020

D.O.I.

03/03/2020

Survey held at

SMRT.

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SHC 4198B - (C41) TP 20000618/8/MS D.O.A - 02/03/2020

FZ 2330B - X

TP.

TAX/03/20/2015

FZ 2330B

RECEIVED 24 MAR 2020

23/3/20

Confirm with Puh Sun

Finalize \$ 4,491.23 @ 3 days (P/P) (Red 7060.51, 6190)

Date/Time, File Page 107



: Prel. Report

Days Of Repair:

3

1)



: Final Report

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Date/Time, File Return 107

23/3/20 - typist

Rep. Form:

TP

Lump Sum / L.B.I. /

4491.23

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Veron Chen (LKKAUTO)

From: MTCL@income.com.sg
Sent: Monday, 23 March 2020 4:24 PM
To: Veron Chen (LKKAUTO)
Subject: RE: REQUEST FOR CLAIM NUMBER

Hi,

Please refer to attached for claim ref number.

Regards,

Ignatius Koh
Operations, Motor & Personal
Lines
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in with you

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Monday, 23 March 2020 11:21 AM
To: MTCL@income.com.sg
Subject: REQUEST FOR CLAIM NUMBER

Dear Sir/Madam,

Kindly provides claim number

S/NO	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle
1	MT/1089276-001	SMART TAXIS PTE LTD	SHC 4198B	FZ 2330B

D.O.A	Time of Accident	Estimate	Tentative repair cost
2/3/2020	18:00	\$11,751.74	\$4,491.23

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hello, NAC_PAYA_UBI_800601

Change Language

Change Password

Log Out

My Desktop

Notice of Loss

Policy Query

Policy No.		Date of Accident	02/03/2020 10:42
Vehicle No.(For Motor)	FZ2330B	Certificate Number	

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☐	5102261768-01		TITAN KANG KHA MENG	S9805022A	GMC	Third Party	FZ2330B	FZ2330B	12/11/2019	11/11/2020

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	369K
Vehicle Details	
Vehicle No.:	SHC4198B
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Mar 2020
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZR5099959
Chassis No.:	JTDKB3FU103573289
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	01 Nov 2017
First Registration Date:	01 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Oct 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	31 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$33,596.00
COE Rebate Amount:	\$23,752.00
Total Rebate Amount:	\$27,502.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 04 Mar 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/03/2020 12:12
Date Of Accident	02/03/2020 18:00
Exact Location Of Accident	JURONG POINT (BOON LAY WAY/ NEAR T/S)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4198B
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	1XXXXX369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-800000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	

Driver

Name of Driver	RATHA KRISHNAN S/O ARUMUGAM
NRIC No	SXXXX416Z
Date Of Birth	12/05/1947
Occupation	OUTDOOR
Date Of Driving Pass	21/05/1973
Driving Experience	46 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-800000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS MOVING FORWARD SLOWLY TO QUEUE AT THE TAXI STAND JURONG POINT (BOON LAY WAY), SUDDENLY I FELT AN IMPACT FROM MY RIGHT HAND FRONT SIDE OF MY TAXI. A MOTOR CYCLE FZ2330B HAD ENCROACHED INTO MY LANE AND HIT THE RIGHT HAND FRONT PORTION OF MY TAXI. I ALIGHTED AND CHECKED THE MOTOR CYCLIST RIDER AND HE HAD NO VISIBLE INJURY.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FZ2330B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	TITAN KANG KHA MENG
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information* and in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyer/s, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) conducting investigation, settling claims and/or disputes, and/or for other purposes as may be required by law;
- (ii) carrying out and/or dealing with my insurances or responding to any enquiries by me;
- (iii) disclosing my claim (including the making of a compensation, claim, award, payment, or part or whole or any other benefit) which could involve disclosure of certain personal data about me to bring about delivery of the sum as well as other related issues of work/employment/health;
- (iv) for the purpose of conducting investigation, settling claims and/or disputes, and/or for other purposes as may be required by law;
- (v) for the purpose of conducting investigation, settling claims and/or disputes, and/or for other purposes as may be required by law;
- (vi) for the purpose of conducting investigation, settling claims and/or disputes, and/or for other purposes as may be required by law;
- (vii) for the purpose of conducting investigation, settling claims and/or disputes, and/or for other purposes as may be required by law;
- (viii) for the purpose of conducting investigation, settling claims and/or disputes, and/or for other purposes as may be required by law;
- (ix) for the purpose of conducting investigation, settling claims and/or disputes, and/or for other purposes as may be required by law;
- (x) for the purpose of conducting investigation, settling claims and/or disputes, and/or for other purposes as may be required by law;



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Case Details

Case Reference Number :
TAX/03/20/2005

Type of Repair : Accident Repair

Vehicle Registration Number :
SHC4198B

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-10710-ID

Assigned By : Taxi Claims Manager
Team

Insurance Company Name : NTUC Income Insurance Co-operative
Ltd

Accident Date and Time : 02/03/2020 10:00 AM

Vehicle Age(In Months) : 28

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	371.63	Replace	• / cut
One Time Key In	Main			SUPPORT, FR BUMPER RH	1	76.90	76.90	25.00	57.68	Replace	1	57.68	Replace	• / BR
One Time Key In	Main			SUPPORT, FR BUMPER LH	1	82.30	82.30	25.00	61.72	Replace	0	0	Not Give	• X SVC
One Time Key In	Main			GRILLE, RADIATOR	1	165.00	165.00	25.00	123.75	Replace	0	0	Check	• X SVC
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace	• / NEC.
One Time Key In	Main			RETAINER, FR BUMPER, LH & RH	1	8.50	8.50	25.00	6.38	Replace	0	0	Not Give	• X SVC
One Time Key In	Main			COVER ASSY, ENGINE	1	180.10	180.10	25.00	135.07	Replace	0	0	Not Give	• X SVC
One Time Key In	Main			COVER ASSY, ENGINE UNDER CENTER SET	1	452.80	452.80	25.00	339.60	Replace	0	0	Not Give	• X SVC
One Time Key In	Main			COVER, ENGINE UNDER CENTER	1	94.50	94.50	25.00	70.88	Replace	0	0	Not Give	• X SVC

Total Spare Part Cost 7,788.51

Surveyor Total 2,932.04

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 7,622.20

Final Sur Total 2,932.04

SMRT Recommendation											Surveyor Approval			Remarks
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			GRILLE SUB-ASSY	1	335.60	335.60	25.00	251.70	Replace	0	0	Check	X SVC
One Time Key In	Main			UNIT, HEADLAMP, RH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	1	2,303.01	Replace	/ SOH
One Time Key In	Main			LAMP ASSY, FOG, RH	1	910.20	910.20	10.00	819.18	Replace	0	0	Not Give	X SVC
One Time Key In	Main			REINFORCEMENT FRONT UPPER	1	891.10	891.10	25.00	668.33	Replace	0	0	Not Give	X SVC
One Time Key In	Main			ABSORBER, FR BUMPER	1	70.30	70.30	25.00	52.72	Replace	0	0	Not Give	X SVC
One Time Key In	Main			EXTENSION SUB-ASSY, LH	1	116.30	116.30	25.00	87.22	Replace	0	0	Not Give	X SVC
One Time Key In	Main			EXTENSION SUB-ASSY, RH	1	116.30	116.30	25.00	87.22	Replace	0	0	Not Give	X SVC
One Time Key In	Main			REINFORCEMENT FRONT LOWER	1	238.50	238.50	25.00	178.88	Replace	0	0	Not Give	X SVC
One Time Key In	Main			ABSORBER, FR BUMPER LOWER	1	117.00	117.00	25.00	87.75	Replace	0	0	Not Give	X SVC
One Time Key In	Main			FENDER SUB-ASSY, FR, RH	1	933.10	933.10	25.00	699.83	Replace	1	0	Repair	X R
One Time Key In	Main			LINER, FR FENDER, RH	1	148.40	148.40	25.00	111.30	Replace	1	148.80	Replace	/ CRM
One Time Key In	Main			PAD, FR WHEEL RH	1	57.70	57.70	25.00	43.28	Replace	0	0	Not Give	X SVC
One Time Key In	Main			WHEEL, DISC FRONT	1	1,555.10	1,555.10	25.00	1,166.32	Replace	0	0	Not Give	X SVC
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	X SVC
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	1	39.67	Replace	/ Nec.
Total Spare Part Cost									7,788.61	Surveyor Total			2,932.04	
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)			0	
Final Spare Part Cost									7,622.20	Final Sur Total			2,932.04	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT RH PORTION	507.00	300	
Total:			507.00	300.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	0	
3	Main	TO RESPRAY FRONT FENDER RH	378.00	200	
4	Main	TO RESPRAY RIM	180.00	0	
Total:			1,116.00	400.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPLACE SUNDRY PARTS	100.00	20	
2	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0	
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
4	Main	TO CHECK WIRING AND SYSTEM FUNCTION	60.00	20	
5	Main	TO WASH AND VACUUM	60.00	0	
Total:			460.00	40.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	7,622.20	2,932.04
Total Labour Cost	507.00	300.00
Total Spray Painting	1,116.00	400.00
Other	460.00	40.00
Overall Total	9,725.20	3,672.04
Lump Sum Repair Option		

Estimator Assessment(\$)

Surveyor Assessment(\$)

Lump Sum Total

0.00

3,672.04

Surveyor Approved Amount

3,672.04

No of Repair Days*

3

3

Remarks

-

P/P Repair, before paint photo.

Surveyor Name

Sun Pin (LKK)

Signature

Save

Clear

Survey Date

03/03/2020

- KK Auto Consultants hence notify
the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Veron Chen (LKKAuto)

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) <YeoPohsuan@smrt.com.sg>
Sent: Monday, 23 March 2020 10:35 AM
To: Oi Sun Pin (LKK Auto)
Cc: SUR; CS A Team
Subject: RE: SHC4198B

Hi,

Amount confirmed as per your recommendation, thanks.

Regards
Poh Suan

-----Original Message-----

From: Oi Sun Pin (LKK Auto) [mailto:sunpin@lkkauto.com]
Sent: Monday, 23 March 2020 9:09 AM
To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)
Subject: RE: SHC4198B

Hi Poh Suan,

Confirm the finalize amount \$4,491.23. Repair day 3 days under part by part repair.

Thank you.

Best Regards,
Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Friday, 20 March, 2020 2:38 PM
To: Oi Sun Pin (LKK Auto)
Cc: SUR; CS A Team
Subject: SHC4198B

Hi Sun Pin,

Attached herewith the repair estimate of SHC 4198B having Case No: TAX/03/20/2005.

There is no change to the approved amount of \$4,491.23 @ 3 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Lim Wei Siong (Auto Svcs/Claims & IA/Claims & IA/Taxis)

Sent: Friday, 20 March 2020 2:06 PM

To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)

Subject: Emailing: Image_010.pdf

Your message is ready to be sent with the following file or link attachments:

Image_010.pdf

Note: To protect against computer viruses, e-mail programs may prevent sending or receiving certain types of file attachments. Check your e-mail security settings to determine how attachments are handled.

Oi Sun Pin (LKK Auto)

From: Oi Sun Pin (LKK Auto)
Sent: Monday, 23 March, 2020 9:09 AM
To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)
Subject: RE: SHC4198B

Hi Poh Suan,

Confirm the finalize amount \$4,491.23. Repair day 3 days under part by part repair.

Thank you.

Best Regards,
Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) [<mailto:YeoPohsuan@smrt.com.sg>]
Sent: Friday, 20 March, 2020 2:38 PM
To: Oi Sun Pin (LKK Auto)
Cc: SUR; CS A Team
Subject: SHC4198B

Hi Sun Pin,

Attached herewith the repair estimate of SHC 4198B having Case No: TAX/03/20/2005.

There is no change to the approved amount of \$4,491.23 @ 3 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Lim Wei Siong (Auto Svcs/Claims & IA/Claims & IA/Taxis)
Sent: Friday, 20 March 2020 2:06 PM
To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)
Subject: Emailing: Image_010.pdf

Your message is ready to be sent with the following file or link attachments:

Image_010.pdf

Shirley Hiew (LKK Auto)

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) <YeoPohsuan@smrt.com.sg>
Sent: Friday, 20 March 2020 2:38 pm
To: Oi Sun Pin (LKK Auto)
Cc: SUR; CS A Team
Subject: SHC4198B
Attachments: Image_010.pdf; CIMG8163.jpg; CIMG8162.jpg; CIMG8164.jpg

Hi Sun Pin,

Attached herewith the repair estimate of SHC 4198B having Case No: TAX/03/20/2005.

There is no change to the approved amount of \$4,491.23 @ 3 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Lim Wei Siong (Auto Svcs/Claims & IA/Claims & IA/Taxis)
Sent: Friday, 20 March 2020 2:06 PM
To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)
Subject: Emailing: Image_010.pdf

Your message is ready to be sent with the following file or link attachments:

Image_010.pdf

Note: To protect against computer viruses, e-mail programs may prevent sending or receiving certain types of file attachments. Check your e-mail security settings to determine how attachments are handled.

Section A - Accident Details

Registration Number	SHC4198B
Case Reference Number	TAX/03/20/2005
Registration Date	1/11/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	RATHA KRISHNAN S/O ARUMUGAM
Type of Accident	Side Swipe
Accident Date and Time	2/3/2020 6:00 PM
Accident Reported Date and Time	3/3/2020 11:44 AM
Is Surveyor Required?	Yes
Surveyed by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24105598
Special Instruction to ARC, if any	RIGHT HAND FRONT PORTION/ NTUC - LKK
Reported Date and Time	3/3/2020 2:22 PM
Quotation Number	
Mileage	
Repair Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$300.00
Total Spray Cost	\$1,116.00	\$400.00
Total Spare Part Cost	\$8,607.79	\$3,751.23
Total Other Cost	\$480.00	\$40.00
TOTAL COST	\$10,710.79	\$4,491.23 (P/P)
Uninsured Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	3.0
Reviewed / Adjusted By	Tuck Poo Kok	Sun Pin (LKK) / NTUC
Surveyor Sign Off Date	06/03/2020 9:04 AM	06/03/2020 3:01 PM
Signature		
Remarks	Total number of repair days = 3 days SUP = 0 day	
Notes	P/P Repair, before paint photo	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
50 Woodlands Avenue Park EA Singapore
Tax Number: S5555555
Estimator Telephone Number: 99662525
Accident Reporting Number: 99662525

Date Generated: 2019-02-20

User ID: PuhSuan

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2003-0274	Invoice Number	
Quotation Date	16.03.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT RH PORTION	\$507.00	\$300.00
Total Labour	\$507.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO RE SPRAY FRONT FENDER RH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,116.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO REMOVE AND RE-FIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$480.00	\$40.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		52119479/62	COVER, FR BUMPER	1.00	\$495.50	25.00	\$371.63	Replace	Replace	✓ C4T
		52115470/50	SUPPORT, FR BUMPER RH	1.00	\$78.90	25.00	\$59.18	Replace	Replace	✓ BR
		52115470/50	SUPPORT, FR BUMPER LH	0.00	\$82.30	0.00	\$0.00	Replace	Not Given	✓ SVC
		53112472/40	GRILLE, RADIATOR	0.00	\$165.00	0.00	\$0.00	Replace	Check	✓ SVC
		52161160/10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace	✓ RRC
		52535500/60	RETAINER, FR BUMPER, LH & RH	0.00	\$8.50	0.00	\$0.00	Replace	Not Given	✓ SVC
		51420470/30	COVER ASSY, ENGINE	0.00	\$180.10	0.00	\$0.00	Replace	Not Given	✓ SVC
		51410470/20	COVER ASSY, ENGINE UNDER CENTER SET	0.00	\$452.80	0.00	\$0.00	Replace	Not Given	✓ SVC
		51447470/30	COVER, ENGINE UNDER CENTER	0.00	\$94.50	0.00	\$0.00	Replace	Not Given	✓ SVC
		53101470/80	GRILLE SUB-ASSY	0.00	\$335.60	0.00	\$0.00	Replace	Check	✓ SVC
		51145476/91	UNIT, HEADLAMP RH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace	✓ SCR

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 10 Woodlands Industrial Park EA, Singapore
 Fax Number: 67955567
 Estimator Telephone Number: 68604023
 Accident Reporting Number: 68604072

Rate Generated: 30/03/2020
 User ID: PWD000

52021471 10	REINFORCEMENT FRONT UPPER	0.00	\$691.10	0.00	\$0.00	Replace	Not Given	✓	SVC
52611471 40	ABSORBER, FR BUMPER	0.00	\$70.30	0.00	\$0.00	Replace	Not Given	✓	SVC
52103470 10	EXTENSION SUB-ASSY, LH	0.00	\$116.30	0.00	\$0.00	Replace	Not Given	✓	SVC
52102470 20	EXTENSION SUB-ASSY, RH	0.00	\$116.30	0.00	\$0.00	Replace	Not Given	✓	SVC
52132470 10	REINFORCEMENT FRONT LOWER	0.00	\$238.50	0.00	\$0.00	Replace	Not Given	✓	SVC
52618470 90	ABSORBER, FR BUMPER LOWER	0.00	\$117.00	0.00	\$0.00	Replace	Not Given	✓	SVC
53801470 80	FENDER SUB-ASSY, FR, RH	1.00	\$933.10	100.00	\$0.00	Replace	Repair	✓	SVC
53875470 70	LINER, FR FENDER, RH	1.00	\$158.40	25.00	\$148.80	Replace	Replace	✓	CRA
53851470 81	PAD, FR WHEEL RH	0.00	\$57.70	0.00	\$0.00	Replace	Not Given	✓	SVC
42611-47450	WHEEL, DISC FRONT	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given	✓	SVC
	TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	✓	SVC
75374471 40	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.68	Replace	Replace	✓	REC
Total			\$9,635.24		\$2,932.05				

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		81210470 20	LAMP ASSY FOG RH	1.00	\$910.20	10.00	\$819.18	Replace	Replace
Total					910.20		819.18		

3751.23 /
 + 300.00 /
 + 440.00 /

4491.23 /

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	7AX / 03 / 20 / 2005	Date of Collection	4 / 3 / 20
Vehicle No	SHC 4198 B	Date of Request	5 / 3 / 20
Vehicle Model	TOYOTA PRIUS 4	Number of Days to Extend	

REQUEST FOR SUPPLYMENT PARTS

S/N	Number photos	Part Description	Quantity	Unit Price
1	8154, 160, 161	Lamp Assy Fog RH		\$ 910.20 / CRA
2				
3				
4				
5				
6				
7				
8				

<<<Please submit photographs for damaged parts>>>

I. (Name) CHIA

(Position) ADVISOR

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

CHIA

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC / Reservation / Number
Photo Submitted		Date of submission

For SMRT Staff