

AD-120 BY H-ANN
PRS

REF: III

ASSIGNMENT

From _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SJN 2261H
 at Workshop m/s A-Ten
 of P Public Unit 4 #04-20
 insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SJN 2261H yr Regn: 09/02/2009
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or 1339
 Make: Honda Fit cc 1296
 Colour: white A/C: Insured / Std / NI / NA
 Sp.Reading: 356188 T/Radio: Insured / Std / NI / NA

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

X	X
N/S	O/S

Eng/No: _____
 C/No: GE6130600
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/55/15
 R: 195/65/15
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

Front _____ Rear _____
 R/Bal: 6 mm pen/tp R/Bal: 5 mm Fall/m
 L/Bal: 6 mm L/Bal: 5 mm
 D.O.A: 2/3/20 D.O.I: 4/3/20
 Survey held at A-Ten 04/11/20

CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure allocated due to collision.

Date / Time	Action / Instruction
	<u>range → 2.5 - 3.5 hr</u> <u>repr days → 3 day</u>
	<u>mv - 23000</u> <u>pv - 10078</u> <u>inv - 12906</u>
	<u>6/3/2020</u>
	<u>PRS case</u>

RECEIVED 10 MAR 2020

Date/Time, File Pass (U) : Prel. Report
 : Final Report
 1) 1813 Typist
 Date/Time, File Return (C)
 3
 Report Format: PRS
 Long Form / LB:

Days Of Repair: 2
 Resurvey No. of Trip: 2
 Addl Fee: Site Insp (C) _____
 Interview (C) _____
 Tech. Inv (C) _____
 Wheel and (C) _____
 Survey Fee: 120
 Transportation: 3 + 10 = 13
 Other: _____
 Other: 11
171

SJN 5787J

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Wednesday, 4 March 2020 12:29 PM
To: Weng Kit; 'sur@lkkauto.com'; 'Admin-D (LKKAuto)'
Cc: 'Jerone'; Sundari Nagarajan - III
Subject: RE: Our Ref: SJN 2261H (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SJN 2261H & SHA 7773G ALONG 37 BEDOK SOUTH AVENUE 2 ON 2 MARCH 2020
Attachments: 20200303164813122.pdf; Surveyor Lis1.pdf

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO. : SJN2261H
III INSURED VEHICLE NO. : SHA7773G
DATE OF LOSS : 02.03.20

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by **Sundari**.

Please let us have your client's **accident report and repair estimate** for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

****Surveyor kindly upload this assignment to Merimen.**

We started using audatex since 1st dec 2019. Please do adjustments through Audatex and upload the report onto Merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street: #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Weng Kit [mailto:wengkit@chiaarul.com]

Sent: Wednesday, 4 March 2020 11:42 am

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: 'Jerone' <jerone@chiaarul.com>

Subject: RE: Our Ref: SJN 2261H (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SJN 2261H & SHA 7773G ALONG 37 BEDOK SOUTH AVENUE 2 ON 2 MARCH 2020

Dear Sirs,

We refer to your email below.

Our client is not agreeable to appoint your surveyor as the Single Joint Expert.

We are instructed by our client to propose the attached list of their surveyor as the mutual surveyor / single joint expert for your consideration.

Best Regards,

Weng Kit (Mr.)

Paralegal

M/s Chia S Arul LLC

151 Chin Swee Road

#03-09 Manhattan House

Singapore 169876

Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at info@chiaarul.com. Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

From: Motor Claim - III [mailto:motorclaim@iii.com.sg]

Sent: Wednesday, March 4, 2020 8:54 AM

To: Weng Kit

Cc: 'Jerone'

Subject: RE: Our Ref: SJN 2261H (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SJN 2261H & SHA 7773G ALONG 37 BEDOK SOUTH AVENUE 2 ON 2 MARCH 2020

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

We started using audatex since 1st dec 2019. Please submit your estimate/quotation through Audatex so that our surveyors can make the adjustments according.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Weng Kit [<mailto:wengkit@chiaarul.com>]
Sent: Tuesday, 3 March 2020 4:49 pm
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: 'Jerone' <jerone@chiaarul.com>
Subject: Our Ref: SJN 2261H (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SJN 2261H & SHA 7773G ALONG 37 BEDOK SOUTH AVENUE 2 ON 2 MARCH 2020

Dear Sirs,

We refer to the above matter.

Attached is a copy of our pre-repair survey notice dated 3 March 2020 for your attention.

Best Regards,

Weng Kit (Mr.)

Paralegal
M/s Chia S Arul LLC
151 Chin Swee Road
#03-09 Manhattan House
Singapore 169876
Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at info@chiaarul.com. Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.
It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

CHIA S ARUL LLC
ADVOCATES & SOLICITORS
UEN 201330709H

ARULCHELVAN S • DON TAN

Our Ref : SJN 2261H (wk)

Your Ref : To be advised

3 March 2020

India International Insurance Pte Ltd

BY EMAIL

Dear Sirs,

RE: PROPERTY DAMAGE CLAIM
CLAIMANT : FRESH CARS P/L
ACCIDENT INVOLVING SJN 2261H & SHA 7773G ALONG 37 BEDOK SOUTH
AVENUE 2 ON 2 MARCH 2020
PRE-REPAIR SURVEY NOTICE

1. We act for Fresh Cars P/L, the owner of motor vehicle no. SJN 2261H which was involved in the aforesaid accident.
2. We hereby in compliance with the Pre-Action Protocol for Non-Injury Motor Accident Claims, Appendix C of the State Courts Practice Directions Amendment No. 1 of 2016 ("the NIMA Protocol") give you **NOTICE** that we are claiming against your insured motor vehicle no. SHA 7773G for damages, costs and disbursements as a result of your insured driver's negligence.
3. Please let us know if you wish to conduct a pre-repair survey on our client's motor vehicle at:

Workshop	A-TEC Automotive Pte Ltd
Address	8 Kaki Bukit Avenue 4 #04 - 20 Premier Singapore 415875
Contact Person	Ms. Peggle (6384 5206)

4. Pursuant to paragraph 2.3 of the NIMA Protocol, in the event we do not receive your response within next two (2) working days (excluding any Saturday, Sunday or public holiday), our client will instruct the workshop to commence appraisal and repairs to the damaged motor vehicle without further reference to you.
5. Please advise the appointed surveyor to endorse on page 2 of this letter after the completion of each inspection.

Yours faithfully,

MR ARULCHELVAN S
cc: Client (By Email)

151 CHIN SWEE ROAD • #03-09
MANHATTAN HOUSE • SINGAPORE 169876
TEL : (65) 6733 4647 • FAX : (65) 6733 8183 (not for Service of Court documents)
EMAIL : info@chiaarul.com

M/s Chia S Arul LLC
Page 2

Our Ref : SJN 2261H (wk)

Your Ref : To be advised

PRE-REPAIR SURVEY (1)
WORKSHOP:

SURVEYOR:

Name:
Date/Time:

Name of Surveyor:
Contact Number:
Date/Time:

PRE-REPAIR SURVEY (2)
WORKSHOP:

SURVEYOR:

Name:
Date/Time:

Name of Surveyor:
Contact Number:
Date/Time:

POST-REPAIR SURVEY
WORKSHOP:

SURVEYOR:

Name:
Date/Time:

Name of Surveyor:
Contact Number:
Date/Time:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	540Z
Vehicle Details	
Vehicle No.:	SJN2261H
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Mar 2020
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G SKYROOF A
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	L13A4144529
Chassis No.:	GE61130600
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$15,500.00
Original Registration Date:	09 Feb 2009
First Registration Date:	09 Feb 2009
Transfer Count:	4
Actual ARF Paid:	\$15,500.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	08 Feb 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$12,864.00
COE Rebate Amount:	\$10,098.00
Total Rebate Amount:	\$10,098.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 05 Mar 2020

OK

NEW CAR DISCOUNTS & OFFERS

BEST DEAL DAILY!

VIEW ALL PROMOTIONS

Honda Fit 1.3A Price Range Depreciation Year Reg Vehicle Type

Home » Used Cars » V.I.P. Auto Nation Pte Ltd » Honda Fit 1.3A G Skyroof (COE till 12/2024)

Honda Fit 1.3A G Skyroof (COE till 12/2024)

Overview Financial Accessories Similar Research Photos Map

Price	\$30,800	Reg Date	15-Dec-2009 (4yrs 9mths 9days COE left)
Depreciation	\$6,440 /yr	Manufactured	2008
Mileage	107,000 km (10.5k /yr)	Transmission	Auto
Road Tax	\$649 /yr	OMV	\$15,390
Dereg Value	\$15,287 as of today (change)	ARF	\$15,390
COE	\$15,988	Power	73.0 kW (97 bhp)
Engine Cap	1,339 cc	No. of Owners	3
Curb Weight	1,070 kg		
Type of Vehicle	Hatchback		

Features

1.3L Fuel Efficient I-VTEC Engine, Smooth 5 Speed Auto Transmission, SRS Airbags, ABS, Key Immobilizer, Knockdown Rear Seats, Skyroof. View specs of the Honda Fit (2008-2013)

Description

Both Inhouse And Bank Loan Available, Interest For 3.18%. Rare Skyroof Model! High Trade In! Contact Us Now For A Non Obligatory Viewing!

Category

COE Car, Premium Ad Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more.



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Shortlist Report Error Compare More Actions Add no

DOA 2/3/20

18000 + 5500 = 23500

Return → 3 yrs 11mths

Reg → 6000

6000 + 500 = 6500

23500 - 6500 = 17000

23000

10098

12900

Seller Information

V.I.P. Auto Nation Pte Ltd

31 vehicles for sale. 32 sold in past 3 mths

60 Jalan Lam Huat #03-06/07

Carros Centre

Search cars nearby

Dennis	88701172
Jeff	92316935
Althan	92718770
Ray	90073753

Posted on: 03-Mar-2020 | Last Updated on: 03-Mar-2020

Upfront Payment

more Financial Info

Transfer Fee \$25

Doi \$9,240 (change) Maximum 70% Loan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/03/2020 16:02
Date Of Accident	02/03/2020 22:25
Exact Location Of Accident	37 BEDOK SOUTH AVE 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJN2261H
Insured/Policyholder	
Name Of Registered Owner	FRESH CARS PTE LTD
Co Reg No	2XXXXX540Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-89999999
Vehicle Particulars	
Manufacturer	HONDA
Model	FIT 1.3G SKYROOF A
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	999994039
Cover Note Number	
Driver	
Name of Driver	MAHATHIR BIN MOHAMMAD
NRIC No	SXXXX650F
Date Of Birth	05/11/1979
Occupation	OUTDOOR
Date Of Driving Pass	08/08/2017
Driving Experience	2 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81835475
Fax Number	
Contact Number	OFFICE-81835475
EMail Address	NOEMAIL

Address	BLK 226C SUMANG LANE #05-234
Postcode	823226
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA7773G
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	MAHATHIR BIN MOHAMMAD
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	SJN2261H
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Accident Sketch Plan

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, law or court orders.



Policyholder's Signature
Date & Time


Driver's Signature
(If driver is not the policyholder)
Date & Time


Reporting Centre (Insurers') Signature
Name
ABC/123456

Accident Sketch Plan

37 Bedok South Ave 2



- (A) SJN2261H
- (B) SHP77736

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I stopped my vehicle and stationary at 37 Bedok South Ave 2. When vehicle B reversing, vehicle B hit onto the front portion of my vehicle. Whole accident was captured by my vehicle built-in video recorder.

DECLARATION

(I/We declare that the above particulars are true in every respect)


 Police Officer's Signature
 Date: 1/1/18


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time


 Reporting Centre Personnel's Signature
 Name
 NRIC/IN No.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Mar 2020 11:32 Edit Reg		04 Mar 2020 00:00 Edit Adj Rpt	\$50.00 Edit Estimates	\$50.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	*, Co. Reg. No.: -								
Main Claimant:	-								
Vehicle Reg. No.:	SJN2261H	Date of Loss:	02/03/2020 00:00 - :59 [132 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	SHA7773G	Policy No. (Claimant):							
		Excess:							
Repairer:	A-tec Automotive Pte Ltd (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-11 AUTOBAY, 417883 Kaki Bukit - Tel: 90626929/97103383								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari NagaraJan - 6347 6071]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 13/03/2020]								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJN2261H
[SHA7773G]
TP

Mar 2 2020 12:00AM

[-]

A-tec Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter			View	View in Browser
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/03/20 18:00	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
2	05/03/20 18:00	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
3	05/03/20 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
4	05/03/20 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
5	05/03/20 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
6	05/03/20 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
7	05/03/20 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
8	05/03/20 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
9	05/03/20 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
10	05/03/20 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
11	05/03/20 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
12	05/03/20 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
13	05/03/20 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
14	05/03/20 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
15	05/03/20 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
16	05/03/20 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
17	05/03/20 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
18	05/03/20 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
19	05/03/20 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
20	05/03/20 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
21	05/03/20 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
22	05/03/20 18:00	General View	 Load JPG	<input checked="" type="checkbox"/>
23	05/03/20 18:01	General View	 Load JPG	<input checked="" type="checkbox"/>
24	05/03/20 18:01	General View	 Load JPG	<input checked="" type="checkbox"/>
25	05/03/20 18:01	General View	 Load JPG	<input checked="" type="checkbox"/>
26	05/03/20 18:01	General View	 Load JPG	<input checked="" type="checkbox"/>
27	05/03/20 18:01	General View	 Load JPG	<input checked="" type="checkbox"/>
28	05/03/20 18:01	General View	 Load JPG	<input checked="" type="checkbox"/>
29	05/03/20 18:01	General View	 Load JPG	<input checked="" type="checkbox"/>
30	05/03/20 18:01	General View	 Load JPG	<input checked="" type="checkbox"/>
31	05/03/20 18:01	General View	 Load JPG	<input checked="" type="checkbox"/>
32	05/03/20 18:01	General View	 Load JPG	<input checked="" type="checkbox"/>
33	05/03/20 18:01	General View	 Load JPG	<input checked="" type="checkbox"/>
34	05/03/20 18:01	General View	 Load JPG	<input checked="" type="checkbox"/>
35	05/03/20 18:01	General View	 Load JPG	<input checked="" type="checkbox"/>
36	05/03/20 18:01	General View	 Load JPG	<input checked="" type="checkbox"/>
37	05/03/20 18:01	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	05/03/20 18:01	General View		<input checked="" type="checkbox"/>
39	05/03/20 18:01	General View		<input checked="" type="checkbox"/>
40	05/03/20 18:01	General View		<input checked="" type="checkbox"/>
41	05/03/20 18:01	General View		<input checked="" type="checkbox"/>
42	05/03/20 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
43	05/03/20 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
44	05/03/20 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
45	05/03/20 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
46	05/03/20 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
47	05/03/20 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
48	05/03/20 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
49	05/03/20 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
50	05/03/20 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
51	05/03/20 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
52	05/03/20 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
53	05/03/20 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
54	05/03/20 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
55	05/03/20 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
56	05/03/20 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
57	05/03/20 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
58	05/03/20 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
59	05/03/20 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
60	05/03/20 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
61	05/03/20 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
62	05/03/20 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
63	05/03/20 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
64	05/03/20 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
65	05/03/20 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
66	05/03/20 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
67	05/03/20 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
68	05/03/20 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
69	05/03/20 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
70	05/03/20 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
71	05/03/20 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
72	05/03/20 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
73	05/03/20 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
74	05/03/20 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
75	05/03/20 18:02	Reinspection Photo		<input checked="" type="checkbox"/>
76	05/03/20 18:02	Reinspection Photo		<input checked="" type="checkbox"/>
77	05/03/20 18:02	Reinspection Photo		<input checked="" type="checkbox"/>
78	05/03/20 18:02	Reinspection Photo		<input checked="" type="checkbox"/>
79	05/03/20 18:02	Reinspection Photo		<input checked="" type="checkbox"/>
80	05/03/20 18:02	Reinspection Photo		<input checked="" type="checkbox"/>
81	10/03/20 08:57	After Repair Photo		<input checked="" type="checkbox"/>
82	10/03/20 08:57	After Repair Photo		<input checked="" type="checkbox"/>
83	10/03/20 08:57	After Repair Photo		<input checked="" type="checkbox"/>
84	10/03/20 08:57	After Repair Photo		<input checked="" type="checkbox"/>
85	10/03/20 08:57	After Repair Photo		<input checked="" type="checkbox"/>
86	10/03/20 08:57	After Repair Photo		<input checked="" type="checkbox"/>
87	10/03/20 08:57	After Repair Photo		<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	10/03/20 08:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
89	10/03/20 08:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
90	10/03/20 08:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
91	10/03/20 08:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	05/03/20 08:39	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III20003581/HTF3E2

Date: 19/03/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SJN2261H

Insured Vehicle No : SHA7773G

Date of Loss: 02/03/2020

Nature of Claim: TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJN2261H**

Make & Model: HONDA FIT, 1.3 G (A)

Engine No: L13A4144529

Reg. Date: 09/02/2009 (Man. Year: 2008)

Chassis No: GE61130600

Colour: White

Odometer: 356188 km

Engine Capacity: 1339 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Falken 5 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 04/03/2020

Date Inspected: 04/03/2020 Inspected At:

8 Kaki Bukit Ave 4 #04-20 Premier
Repairer : A-tec Automotive Pte Ltd

Estimated Period of Repair: 0.0 days

Adjuster: LEE HOCK ANN

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Mar 2020)

Parts: 144 HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJN2261H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >