

Sherwin Beh (LKK Auto)

From: Kamaliah KAMIS (SPF) <Kamaliah_KAMIS@spf.gov.sg>
Sent: Tuesday, 3 March, 2020 7:01 PM
To: Sherwin Beh (LKK Auto); Naz (LKKAuto)
Cc: Bryan Ang (LKKAuto)
Subject: Mechanical Inspection Report Request

Dear Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the **10 vehicles** below:

- a) **Case IAFP-IB-20200102 - Mechanical Inspection of Garbage Truck, XE4427R (TP/IP/78751/2019)**
- b) **Case IAFP-IB-20200102 - Mechanical Inspection of Motor Scooter, FBK9500H (TP/IP/78751/2019)**

On 20 December 2019 (Friday) at about 11.53 a.m., the Deceased (who was alone on his motor scooter) was travelling straight along Gambas Avenue towards the direction of Woodlands Avenue 8 in between lane 2 and lane 3 of the 3-lanes road and tried to squeeze in between two heavy vehicles that were travelling abreast to one another, on lane 2 and lane 3. While the Deceased was doing so, the Deceased lost control of his motor scooter and skidded to the left, into the path (right central opening) of the moving garbage truck driven by the Involved Party. As such, the Deceased's head was ran over by the right rear tyre of the Involved Party's garbage truck.

Vehicles to be inspected: **XE4427R** - Driver (Involved Party)
 FBG9070C - Rider (Deceased)

IO In-Charge: SIO Kamaliah

- c) **Case IAFP-IB-20200102 - Mechanical Inspection of Mini Bus, PA5844D (TP/IP/79655/2019)**

On 26 December 2019 (Thursday) at about 8.54 a.m., the Accused was exiting from Unit 78 Alps Avenue and made a right turn into Alps Avenue towards Changi Coast Road. In the midst of doing so, the frontal right portion of the Accused's mini bus collided into the right side of the Deceased while she was standing in the middle of the road, awaiting to cross the road. After the collision, the Accused came to a stop to render assistance to the Deceased.

Vehicles to be inspected: **PA5844D** - Driver (Accused)

IO In-Charge: SIO Kamaliah

- d) **Case IAFP-IB-20200102 - Mechanical Inspection of Motor Car, SLT2761B (TP/IP/79475/2019)**

On 29 December 2019 sometime before 4.58 p.m., the accused was driving his motor car along Nutmeg Road and was in the midst of making a u-turn when he claimed that the vehicle continued to surge forward despite him stepping onto the brakes, causing the motorcar to mount the road kerb and went on to collide onto the group of pedestrians who were at the pavement. Six pedestrians were conveyed to TTSH where two of the pedestrians succumbed to their injuries and were pronounced dead on the same day at 6.00 pm and 6.15pm respectively.

Vehicles to be inspected: **SLT2761B** - Driver (Accused)

IO In-Charge: SIO Adrian

- e) **Case IAFP-IB-20200102 - Mechanical Inspection of Motor Trailer, XD2600A (TP/IP/80209/2019)**
- f) **Case IAFP-IB-20200102 - Mechanical Inspection of Motorcycle, FBA3243S (TP/IP/80209/2019)**

On 30 December 2019 (Monday) at 8.49 a.m., the Deceased (who was alone on his motorcycle) was travelling along Boon Lay Avenue slip road into Jalan Boon Lay towards Jurong Pier Road. The Deceased subsequently travelled on lane 3 of 3 lanes road and sideswiped into the left portion of the Involved Party's trailer. The Deceased lost control of his motorcycle and skidded to the right, into the opening of the trailer driven by the Involved Party. As such, the Deceased was pinned under the left rear tyres and was dragged for about 2 motorcar lengths. As a result of the accident, the Deceased sustained head injury and was pronounced dead at the scene, at 8.54 a.m. by the attending paramedic.

Vehicles to be inspected: **XD2600A** - Driver (Involved Party)
 FBA3243S - Rider (Deceased)

IO In-Charge: SIO Raziz

- g) **Case IAFP-IB-20200102 - Mechanical Inspection of Motor Lorry, YP264A (TP/IP/69677/2019)**
- h) **Case IAFP-IB-20200102 - Mechanical Inspection of Bicycle (TP/IP/69677/2019)**

On 10 November 2019 (Friday) at about 7.39 am, the motor lorry YP 264 A was turning right from carpark into Nicoll Drive when bicycle travelling along Nicoll drive collided onto the right side of the motor lorry. The cyclist was sent to CGH where he succumbed to his injuries and was pronounced dead 3 days later.

Vehicles to be inspected: **YP264A** - Driver (Involved Party)
 Bicycle VR3460 - Pedal Cyclist (Deceased)

IO In-Charge: SIO Yazid

- i) **Case IAFP-IB-20200102 - Mechanical Inspection of Taxi, SHC4668L (TP/IP/61167/2019)**
- j) **Case IAFP-IB-20200102 - Mechanical Inspection of Motorcycle, FBH9390Z (TP/IP/61167/2019)**

On 29 September 2019 at about 0914 hrs, the motor taxi SHC 4668 L was travelling along CTE when the taxi changed lanes and side wiped onto the motorcycle. As a result the rider of the motorcycle was sent to TTSH where he was pronounced dead on 17 October 2019.

Vehicles to be inspected: **SHC4668L** - Driver (Accused)
 FBH9390Z - Rider (Deceased)

IO In-Charge: SIO Yazid

- 2. These request has been approved by my management.
- 3. Thank you Sirs.

cc: FAIT Team, fyip

Best regards,

Kamaliah Kamis (Miss)

Senior Investigation Officer | Fatal Accident Investigation Team
Traffic Police Department | Singapore Police Force
DID: (65) 6547 6435 | FAX: (65) 6547 6352



Singapore Police Force – *Commemorating 200 Years of Policing*

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance on information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."