

1/17/2010

ASS. REC. BY:

REF:

01TPD20003592/Pg

Special Instruction:

SURVEYOR:

ASSIGNMENT (Office)

From (Person): Kamalah Kamle

of SPF

Date/Time: 3/3/2020

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: YP264A

Insured:

at Workshop m/s

Tel:

of

Policy No: MHASPP06000030659/1

Claim No: TP/IP/69677/2019

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 10/11/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time


Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction () Estimate

YP264A-X.



Key-in

BY/20

IO In-Charge: SIO Adrian

- e) Case IAFP-IB-20200102 - Mechanical Inspection of Motor Trailer, XD2600A (TP/IP/80209/2019)
- f) Case IAFP-IB-20200102 - Mechanical Inspection of Motorcycle, FBA3243S (TP/IP/80209/2019)

On 30 December 2019 (Monday) at 8.49 a.m., the Deceased (who was alone on his motorcycle) was travelling along Boon Lay Avenue slip road into Jalan Boon Lay towards Jurong Pier Road. The Deceased subsequently travelled on lane 3 of 3 lanes road and sideswiped into the left portion of the Involved Party's trailer. The Deceased lost control of his motorcycle and skidded to the right, into the opening of the trailer driven by the Involved Party. As such, the Deceased was pinned under the left rear tyres and was dragged for about 2 motorcar lengths. As a result of the accident, the Deceased sustained head injury and was pronounced dead at the scene, at 8.54 a.m. by the attending paramedic.

Vehicles to be inspected: XD2600A - Driver (Involved Party)
FBA3243S - Rider (Deceased)

IO In-Charge: SIO Raziz

- g) Case IAFP-IB-20200102 - Mechanical Inspection of Motor Lorry, YP264A (TP/IP/69677/2019)
- h) Case IAFP-IB-20200102 - Mechanical Inspection of Bicycle (TP/IP/69677/2019)

On 10 November 2019 (Friday) at about 7.39 am, the motor lorry YP 264 A was turning right from carpark into Nicoll Drive when bicycle travelling along Nicoll drive collided onto the right side of the motor lorry. The cyclist was sent to CGH where he succumbed to his injuries and was pronounced dead 3 days later.

Vehicles to be inspected: YP264A - Driver (Involved Party)
Bicycle VR3460 - Pedal Cyclist (Deceased)

IO In-Charge: SIO Yazid

- i) Case IAFP-IB-20200102 - Mechanical Inspection of Taxi, SHC4668L (TP/IP/61167/2019)
- j) Case IAFP-IB-20200102 - Mechanical Inspection of Motorcycle, FBH9390Z (TP/IP/61167/2019)

On 29 September 2019 at about 0914 hrs, the motor taxi SHC 4668 L was travelling along CTE when the taxi changed lanes and side wiped onto the motorcycle. As a result the rider of the motorcycle was sent to TTSH where he was pronounced dead on 17 October 2019.

Vehicles to be inspected: SHC4668L - Driver (Accused)
FBH9390Z - Rider (Deceased)

IO In-Charge: SIO Yazid

- 2. These request has been approved by my management.
- 3. Thank you Sirs.

cc: FAIT Team, fyip

Best regards,

Kamaliah Kamis (Miss)