

ASS. REC. BY:

REF: CS/EG I 20003602/Gtf3

Special Instruction:

Surveyor: Sun Pin

ASSIGNMENT (Office)

From (Person): Pauline Soh

of Ergo

Date/Time: 5.3.2020 10.35a.m

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHB 2614

Insured: SMH 4239G

at Workshop m/s SMRT

Tel: 68662671

of 60 Woodland Industrial Park E4

Policy No:

Claim No: CDMPG 20000339

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 23/02/2020

CA / REV / REP. / REV 24 HRS

Date/Time: 5/3/2020 11.28a.m

Person Contacted:

Shanti

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHB 2614 - NA/FCI 19020186/24
	SMH 4239G - X
6/3	Submit 1A via menmen

REF: Ergo

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHB 261H Yr Regn: 04/07/2014
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Traller or

Make: Toyota Prius C.C. ~~1745~~
 Colour: Maroon A/C: Insured / Std / NI / NA
 Sp. Reading: 448.209 T/Radio: Insured / Std / NI / NA
 Eng/No: —
 C/No: JTPKN366205746829

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: 195/65 R15

R: 195/65 R15

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/
TOYO/YOKO or Achilles

Front	Rear
R/Bal. <u>5</u> mm	R/Bal. <u>5</u> mm
L/Bal. <u>5</u> mm	L/Bal. <u>5</u> mm
D.O.A. <u>03/02/2020</u>	D.O.I. <u>05/03/2020</u>

Survey held at SMART
Des. of Damages: Frt / Rear / O/S / (N/S) / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

[illegible]

Date/Time, File, Pass WZ. . . : Prel. Report

1) : Final Report

Date/Time, File Return to?

2)

Performed :

1. 4000 Euro / 1.6.1. / 12

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$ _____)

1: Interview (5

☐ : Tech. Invs (S)

Weekend 18

Survey Fee:

Transportation:

$$S \rightarrow RS, \quad SI$$

Phylos

1. Other

TOTAL

Nivitha (LKK Auto)

From: ERGO Insurance Pte. Ltd. (Claims Department) <claims@ergo.com.sg>
Sent: Thursday, 5 March 2020 10:35 AM
To: Shanti B Thaiyal Nayagi (Auto Svcs/Claims & IA/Claims & IA/Taxis); Admin-D (LKKAuto (admin-d@lkkauto.com)); Admin A (admin-a@lkkauto.com); Mei Kwan (LKKAuto (Meikwan@lkkauto.com))
Cc: Phoebe Xie; Zheng Hanyang
Subject: RE: Claims ref no. (P) CDMPG20000339 SHB261H - Survey (Ergo)

Date Classification : Confidential, C3

**** NOTE: Please create case, input our Claim ref no. and upload ALL survey related documents into Merimen. Payment invoices shall be ignored for cases that are not submitted via Merimen.**

Hi LKK,

Please conduct this survey request.

(Note: Survey vehicle only, LOD will be handled by Ergo)

Kindly inform us if you are not able to attend it.

Thank you.

Warmest Regards,
Pauline Soh
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five
Singapore 038985
DID.: +65 6829 9194
pauline.soh@ergo.com.sg

www.ergo.com.sg

ERGO

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: Shanti B Thaiyal Nayagi (Auto Svcs/Claims & IA/Claims & IA/Taxis) <BThaiyalN@smrt.com.sg>
Sent: Thursday, 5 March 2020 10:18 am
To: ERGO Insurance Pte. Ltd. (Claims Department) <claims@ergo.com.sg>
Cc: Phoebe Xie <phoebe.xie@ergo.com.sg>; Zheng Hanyang <hanyang.zheng@ergo.com.sg>
Subject: RE: Claims ref no. (P) CDMPG20000339 SHB261H - Survey (Ergo)

Dear Pauline,

Please refer to the preferred surveyors.

LKK	LKK Auto Consultants Pte Ltd
VAC	Vicom Ltd

Thank you & Regards

Shanti

SMRT Automotive Services PTE LTD

Accident Reporting Center (Claims Dept)

6866 2671/2 | bthaiyaln@smrt.com.sg



From: ERGO Insurance Pte. Ltd. (Claims Department) [<mailto:claims@ergo.com.sg>]

Sent: 05/03/2020 10:09

To: Shanti B Thaiyal Nayagi (Auto Svcs/Claims & IA/Claims & IA/Taxis)

Cc: Phoebe Xie; Zheng Hanyang

Subject: Claims ref no. (P) CDMPG20000339 SHB261H - Survey (Ergo)

Date Classification : Confidential, C3

Dear Shanti,

We would like to conduct a PRI survey, please refer to our list of surveyors :

1	AIS	Automobile Inspection Services Pte Ltd
2	FTA	FormTeam Consultancy Pte Ltd
3	IAS	Infiniti Appraisal Service
4	JPK	JP Knights Pte Ltd
5	LBS	L.B.S Auto Consultants Pte Ltd
6	LKK	LKK Auto Consultants Pte Ltd
7	PS	Priority Services
8	VAC	Vicom Ltd

9	AJAX	AJAX Inspection Services Pte Ltd
10	AA	Appraisal Associate

Warmest Regards,
Pauline Soh
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five
Singapore 038985
DID.: +65 6829 9194
pauline.soh@ergo.com.sg

www.ergo.com.sg

ERGO

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: Shanti B Thaiyal Nayagi (Auto Svcs/Claims & IA/Claims & IA/Taxis) <BThaiyalN@smrt.com.sg>
Sent: Wednesday, 4 March 2020 12:22 pm
To: ERGO Insurance Pte. Ltd. (Claims Department) <claims@ergo.com.sg>
Cc: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) <YeoPohsuan@smrt.com.sg>; Kok Tuck Foo (Auto Svcs/ARC/ARC/Taxis) <TuckFoo@smrt.com.sg>; Koo Yew Chung (Auto Svcs/ARC/ARC) <YewChung@smrt.com.sg>; Phua Zhi Yang (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR) <ZhiYang.Phua@smrt.com.sg>; Grace Ng Siu Ching (Auto Svcs/ARC/ARC/Taxis) <ngsiuching@smrt.com.sg>; Lim Wei Siong (Auto Svcs/Claims & IA/Claims & IA/Taxis) <weisiong@smrt.com.sg>; Chin Kim Ming (Auto Svcs/ARC/ARC/Taxis) <kimming.chin@smrt.com.sg>
Subject: RE: SHB261H - Survey (Ergo)

Dear Sir /Mdm,

Kindly arrange to survey the vehicle **SHB261H** within 48 hours according to GIA guide line, involving your insured **SMH4239G**

Insurance Company : **ERGO**
Vehicle in **Woodlands. SMRT Depot**

****Please arrange LKK / VICOM to survey our taxi***

Regards
Shanti
SMRT Automotive Services PTE LTD
Accident Reporting Center (Claims Dept)
6866 2671/2 | bthaiyaln@smrt.com.sg



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	369K
Vehicle Details	
Vehicle No.:	SHB261H
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Mar 2020
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2014
Engine No.:	2ZR1383967
Chassis No.:	JTDKN36U205746829
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$32,920.00
Original Registration Date:	09 Jul 2014
First Registration Date:	09 Jul 2014
Transfer Count:	0
Actual ARF Paid:	\$8,088.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Jul 2022
PARF Rebate Amount:	\$5,661.00
Intended COE Rebate Details	
COE Expiry Date:	08 Jul 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$53,269.00
COE Rebate Amount:	\$15,572.00
Total Rebate Amount:	\$21,233.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 06 Mar 2020

OK

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 06 Mar 2020

Preliminary Advice

Insured Vehicle No	: SMH4239G		
TP Vehicle No	: SHB261H	Accident Date	: 23/02/2020
Make	: HONDA ACCORD	Assignment Date	: 05/03/2020
Date of Inspection	: 05/03/2020	Est. Duration of Repair	: 3.00
Inspection At	: SMRT AUTOMOTIVE SERVICES PTE LTD (WOODLANDS) 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages N/S portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,394.17
Revised Amount	:S\$	1,161.47
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,161.47
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Survey on "WP"

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/02/2020 15:21
Date Of Accident	23/02/2020 13:25
Exact Location Of Accident	BALESTIER ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB261H
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	1XXXXX369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	
Driver	
Name of Driver	KARAM SINGH
NRIC No	SXXXX227C
Date Of Birth	11/03/1957
Occupation	OUTDOOR
Date Of Driving Pass	27/09/2011
Driving Experience	8 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 230
Postcode
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 3

Passenger 1
NAME: : MONIR
GENDER: : MALE
Passenger 2
NAME: : UNKNOWN
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT - THERE WAS AN ACCIDENT IN FRONT OF CEYLON SPORTS CLUB, BETWEEN A CAR AND MOTORCYCLE. AMBULANCE WAS ALSO PARKED NEXT TO THEM AS THEY WERE ATTENDING TO A MAN LYING ON THE ROAD. DUE TO THIS THE WHOLE BALESTIER ROAD WAS JAM WITH VEHICLES AND VERY SLOW MOVING. AS I WAS AT THE EXTREME RIGHT LANE, OUR LANE VEHICLES WERE MOVING SLOWLY AND OTHERS WERE NOT. AS WE WERE MOVING SLOWLY THIRD PARTY TRIED TO SWAY INTO MY LANE BUT HIT INTO MY CAR

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMH4239G
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver DARREN
NRIC/Passport Number
Contact Number

Address

Postcode


Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

Sketch Plan Pg. 1



DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

du 25/7/2020

Sketch Plan Pg. 2

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Ch 25/7/2022



Case Details

Case Reference Number : TAX/02/20/2078
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB261H

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-10726-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : ERGO Insurance Pte Ltd
 Accident Date and Time : 23/02/2020 05:25 AM
 Vehicle Age(In Months) : 67

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	0	Repair	X R
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	0	0	Not Give	X SVC
One Time Key In	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	0	0	Not Give	X SVC
One Time Key In	Main			BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	0	0	Check	X SVC
One Time Key In	Main			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	0	0	Not Give	X SVC
One Time Key In	Main			BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.80	Replace	0	0	Not Give	X SVC
One Time Key In	Main			ARM SUB-ASSY,FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Give	X SVC
One Time Key In	Main			ARM SUB-ASSY,FR BUMPER RH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Give	X SVC
One Time Key In	Main			BUMPER GRILLE SUB-ASSY,LOWER	1	311.10	311.10	25.00	233.33	Replace	0	0	Not Give	X SVC
One Time Key In	Main			LENS & BODY,FR TURN LH	1	511.80	511.80	10.00	460.62	Replace	0	0	Not Give	X SVC
Total Spare Part Cost									4,793.17	Surveyor Total 581.47				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									4,793.17	Final Sur Total 465.18				

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			LENS & BODY, FR TURN RH	1	511.80	511.80	10.00	460.62	Replace	0	0	Not Give	X SVC
One Time Key In	Main			BUMPER LIP FRT	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give	X SVC
One Time Key In	Main			BUMPER FRT ABSORBER LOWER	1	127.70	127.70	25.00	95.78	Replace	0	0	Not Give	X SVC
One Time Key In	Main			UNDER COVER CENTER	1	448.30	448.30	25.00	336.23	Replace	0	0	Not Give	X SVC
One Time Key In	Main			MIRROR ASSY,LH	1	1,224.90	1,224.90	25.00	918.68	Replace	0	0	Not Give	X SVC
One Time Key In	Main			MIRROR LAMP LH	1	65.30	65.30	10.00	58.77	Replace	0	0	Not Give	X SVC
One Time Key In	Main			COVER, OUTER MIRROR, LH	1	107.40	107.40	25.00	80.55	Replace	0	0	Not Give	X SVC
One Time Key In	Main			FENDER FRT/LH	1	723.40	723.40	25.00	542.55	Replace	1	542.55	Replace	/ PD
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	/ Nec
One Time Key In	Main			FENDER LINER FRT/LH	1	171.70	171.70	25.00	128.77	Replace	0	0	Not Give	X SVC
One Time Key In	Main			FENDER LINER PAD, FR WHEEL RH	1	49.30	49.30	25.00	36.97	Replace	0	0	Not Give	X SVC
Total Spare Part Cost									4,793.17	Surveyor Total 581.47				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									4,793.17	Final Sur Total 465.18				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT LH PORTION	507.00	300	/
Total:			507.00	300.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
-------	--------------	-----------	-------------------------	-------------------------	---------

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	✓
2	Main	TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	0	
3	Main	RESPRAY MIRROR COVER LH	378.00	0	
4	Main	TO RESPRAY FRONT FENDER LH	378.00	200	✓
5	Main	TO RESPRAY RIM	180.00	50	✓
Total:			1,494.00	450.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE AND REFIX WING MIRROR	120.00	0	
2	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	30	✓
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	50	✓
4	Main	TO REPLACE SUNDRY PARTS	100.00	20	✓
5	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30	✓
6	Main	TO WASH AND VACUUM	60.00	0	
Total:			600.00	130.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	4,793.17	465.18
Total Labour Cost	507.00	300.00
Total Spray Painting	1,494.00	450.00
Other	600.00	130.00
Overall Total	7,394.17	1,345.18
Lump Sum Repair Option		✓
Lump Sum Total	7,400.00	1,350.00
Surveyor Approved Amount		1,350.00

Estimator Assessment(\$)

Surveyor Assessment(\$)

No of Repair Days*

5

3

Remarks

Lump Sum Repair, After paint photo.

Surveyor Name

Sun Pin (LKK)

Signature

8381.00

Save

Clear

Survey Date

05/03/2020

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: