

Surveyor

REF: CS3/ASM19007174/R1vd3-1

Special Instruction:

ASSIGNMENT (Office)

HS: \$ 2,600.00

From (Person): Xinyi of Sea Hong Date/Time: 04/03/2020

Third Parties:

Estimated Cost Bill to:

Claimant:

OD/TP Re-inspection / Evaluation

Surveyor: C.L. Appraiser

To Inspect Vehicle No: JQN 1638 Insured: SKN 3512R

Workshop: Teamwork Garage

at Workshop m/s Teamwork Garage Tel: 68442475

of 53 Ubi Avenue 1 # 01-25

Policy No: SQM01L3G Claim No: 20-27688

Sum Insured: Excess:

Make of Veh: D.O.A. 22/04/2019

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig. days (Red \$ / %; Original 7 days)

Date/Time: 10/3/20 Submit Final Fig LS \$ 1150, 4 days (Red \$ 1450 / 56 %; Original days)

Date/Time	Action/Instruction
	JQN 1638 - CS3/ASM19007174/R1vd3e2 SKN 3512R - NA/II20001771/h7
	DOA: 22/4/2019 DOA: 4/2/2020
	RECEIVED 10 MAR 2020
	<i>[Signature]</i> 6/3/2020

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value :
Salvage Value :
Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add
Transport
Photos
Others
Total

Date:

190
190

- 1) Date/Time 10/3 - typist File Pass to
- 2) Date/Time File Return to
- 3) Date/Time File Pass to
- 4) Date/Time File Return to
- 5) Date/Time File Pass to
- 6) Date/Time File Return to

Nivitha (LKK Auto)

From: Xin Yi <xinyi@seahong.com.sg>
Sent: Wednesday, 4 March 2020 2:13 PM
To: 'Admin-D (LKKAuto)'; 'Admin A'
Cc: 'Chee Kiong'; samson@seahong.com.sg; amanda@seahong.com.sg; gideon@seahong.com.sg
Subject: SOP file ref: 20.27688 | MC 1614 / 2020 | Claim by Ter Poh Hock | JQN 1638

Dear Nivitha

MC / MC SUIT NO.	1614 OF 2020
CLAIMANT :	TER POH HOCK (OWNER & RIDER)
VEHICLE NUMBER :	JQN 1638
ALLEGED ACCIDENT DATE :	24.04.2019
AXA VEHICLE NUMBER :	SKN 3512R

- 1) Our client, AXA, informed us that you were engaged to do PRI for this claim.
- 2) The Plaintiff's LOD and other supporting documents can be downloaded via <https://1drv.ms/b/s!AtyQSG-oo66hlaB-RtLJMhOL579ZWA?e=4aspQk>.
- 3) Can we have the PRI report? Please also let us know if RI is required.
- 4) If you have conducted post repair inspection already, please let us have your survey report soonest. Thanks!

Thanks & Best Regards

Heng Xinyi

(Secretary to Mr Tan Chee Kiong)

Seah Ong & Partners LLP

36 Robinson Road

#12-03 City House

Singapore 068877

Tel: 6536 5369

Fax: 6536 5811

This message is intended for the recipient named above. It may contain confidential or privileged information. If you are not the intended recipient, please notify the sender immediately by replying to this message and then delete it from your system. Do not read, copy, use or circulate this communication. Thank you.

Disclaimer: Internet communications are not secure. While every reasonable effort has been made to ensure that this communication has not been tampered with, Seah Ong & Partners LLP cannot be responsible for alterations made to the contents of this message without its express consent. If you wish to receive a hard copy of this message for comparison or should you require any other form of confirmation of the contents of this message, please contact the sender. Opinions, conclusions and other information in this message that do not relate to the official business of the company shall be understood as neither given nor endorsed by Seah Ong & Partners LLP.

Assigned By: RAHUL
 From Person: Motorsunky
 Estimated Cost: _____
 Date/Time: 23/4/19 @ 11:15am

REF: CS3/ASM 19007(74) Rkd30P
 ASSIGNMENT (Office): ASM(AXA)

To Inspect Vehicle No: JON 1638
 at Workshop of: Teamwork
 of: 53 ubi Ave 1 # 01-25
 Insured: SKN 3512R
 Tel: 68492475

Policy No: _____
 Claim No: S9M01L3G
 Reason: _____
 Date of Acc: 22/04/19

CA / REV / REP. / REV 24 HRS
 Date/Time: 1:49pm @ 23/4/19 Person Contacted: Darren
 H.O.B. Endorsement: _____
 Vehicle: (N) OTT

Date/Time	Actual/Instructon (X) Estimate
	<u>JON 1638 - X</u>
	<u>SKN 3512R - COA/ASM 17018366/Cip934.2</u>
	<u>Dismantle: 30/4/2019</u>
	<u>DOA: 21/4/12</u>

Surveyor *Form*


REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: JQN 1638 Yr Regn: Dec / 14
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Yamaha 135LC C.C. 135
 Colour: MULTI A/C: Insured / Std / NI / NA
 Sp. Reading: 5663 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: _____
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Mod: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 70/90-17
 R: 80/90-17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or MAXXIS
 Front _____ Rear _____
 R/Bal. 3 mm R/Bal. 3 mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. 22/04/19 D.O.I. 23/04/19 0342pm
 Survey held at TEAMWORK
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lim Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Repair Range - (2k-25k) / 3 days
	JQN 1638 - X
	SCV 2012R - X
	<i>[Signature]</i> 21/5/2019

Date/Time, File Pass to? : Prel. Report
 : Final Report

Days Of Repair: 3
 Resurvey No. of Trip: 1

Date/Time, File Return to?
 2) _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee:	100
Transportation:	
\$ - RES. \$	
Photos	
Others	
TOTAL	100

Report Format: PRB
 Lump Sum / I.B.I: (\$ _____)

3019750968---

TOMMY CHOO, MARK GO LLC

60153349

Advocates & Solicitors
UEN NO : 201523418E
(a law corporation with limited liability)

151 CHIN SWEE ROAD #14-15/16
MANHATTAN HOUSE
SINGAPORE 169876
TEL : (65) 6532 2455
FAX : (65) 6538 9850 (Services of Court Documents By Fax Not Accepted)

EMAIL: lhling@tcmg.com.sg
Our Ref : LLH/ing/1251/0619/TWG

Your Ref : SKN 3512 R

12 JUN 2019

13 JUN 2019

LEE KOH SONG
13 Upper Boon Keng Road
#15-947
Singapore 380013

M/S AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way#27-01
AXA Tower
Singapore 068811

Attn: Motor Claims Department

Dear Sirs,

ACCIDENT INVOLVING JQN 1638 AND SKN 3512 R ON 22 APRIL 2019 ALONG BEDOK NORTH ROAD JUNCTION BEDOK RESRVOIR ROAD

We are instructed by **Ter Poh Hock**, to claim damages against you or your insured, the driver of motor vehicle no. **SKN 3512 R**, in connection with a road traffic accident on 22 of April 2019, at about 13:20 hours along Bedok North Road junction Bedok Reservoir Road, involving our client's motor vehicle no. **JQN 1638** and motor vehicle no. **SKN 3512 R** driven by your insured at the material time.

We are instructed that the accident was caused by your insured's negligence and/or management of his motor vehicle. As a result of the accident, our client's motor vehicle was damaged and our client had been put to loss and expenses, particulars of which are as follows:

1 Costs of Repair	\$ 2,782.00 (incl GST)
2 Loss of use (\$50 x 7 days)	\$ 350.00
3 Loss of Use (Pre-repair)(\$50 X 2 days)	\$ 100.00
4 LTA Search Fee	\$ 7.45
5 Survey Fee	\$ 451.00
6 Disbursement (at this stage)	\$ 93.00
7 Legal Cost (at this stage)	\$ 700.00



By Certificate of Posting
(For your attention:without enclosures)

BY PDX NO. 8176

PDX Intercompany Exchange Pte Ltd



010808716384

FROM TOMMY CHOO, MARK GO LLC
PDX Box No. 8141

TOMMY CHOO, MARK GO LLC

Advocates & Solicitors

UEN NO : 201523418E

(a law corporation with limited liability)

151 CHIN SWEE ROAD #14-15/16

MANHATTAN HOUSE

SINGAPORE 169876

TEL : (65) 6532 2455

FAX : (65) 6538 9850 (Services of Court Documents By Fax Not Accepted)

Email: lhling@tcmg.com.sg

\$ 4,483.45

A copy each of the following supporting documents is enclosed:

1. Copy of Traffic accident report and LTA search;
2. Copy of Certificate of Insurance;
3. Copy of survey report and invoice and repair bill;
4. Colour photographs pertaining to our client's motor vehicle for your perusal.

Our client had on 22 of April 2019 notified your insurer, M/s AXA Insurance (S) Pte Ltd about the accident and the pre-repair inspection was conducted.

Please note that if you are insured and you wish to claim from your insurance policy, you should immediately pass this letter to your insurer

Please note that you should send us an acknowledgment of receipt of this letter within fourteen (14) days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against your insured without further notice to you or your insured.

Please note that if you have a counterclaim against our client arising out of the accident, you are also required to send us a letter giving full particulars of the counterclaim together with the relevant documents within 8 weeks of your receipt of this letter.

Yours faithfully,



Encs.

cc. client

Enquire Vehicle & Owner Information (Vehicle No. SKN3512R As At 22 Apr 2019 / 13:20:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: LLHJQN1638.TWG

Current Owner Details

Owner ID Type: Singapore NRIC
Owner ID: S2076628Z
Owner Name: LEE KOH SONG
Registered Address Type: HDB / HUDC
Registered Block/House No.: 13
Registered Street Name: UPPER BOON KENG ROAD
Registered Unit No.: # 15 - 947
Registered Building Name: -
Registered Postal Code: 380013

Current Vehicle Details

Vehicle No.: SKN3512R
Make Description/Model: TOYOTA / LEXUS IS250 AUTO LUXURY
Insurance Company Name: AXA INSURANCE PTE LTD



Police Station Of Origin:
Kampong Ubi NPP
9 Eunos Crescent #01-2687 SINGAPORE
400009
Tel No: 1800-7479999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 22/04/2019 16:28	Vide Report No.: G/20190422/0084	Station Diary No.: 13
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: TER POH HOCK		Address:	
ID Type / ID No.: FIN NO / F8072690L		Contact No.: Home/Office: Mobile: 91403233	
Nationality: MALAYSIAN		Email:	
Sex: Male	Age: 40	Date of Birth: 05/10/1978	Type of Informant: Rider
Race: Chinese		Language:	Institution / School Name:
Occupation: Working proprietor (construction)		Driving Licence Information: Class: 2B,3C Date of Expiry: 13/03/2024	

General Information of the Accident

Type of Accident:	Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 22/04/2019 13:20	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 BEDOK NORTH ROAD BEDOK RESERVOIR ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JQN1638	Motorcycle				Slightly Damaged	0
SKN3512R	Car				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



Police Station Of Origin:
Kampong Ubi NPP
9 Eunos Crescent #01-2687 SINGAPORE
400009
Tel No: 1800-7479999

CONTINUATION OF REPORT

Rider			
Name	TER POH HOCK	ID No.	F8072690L
Related Vehicle	JQN1638 (Motorcycle)	Contact No.	91403233
Hospital/Clinic	Intemedical 24hrs clinic	Class of Driving Licence & Expiry Date	Class: 2B,3C Date of Expiry: 13/03/2024
Date Treatment	22/04/2019	Date Discharge	22/04/2019
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Brief Details.

On 22/04/2019 at around 1320hrs, I riding my motorbike and I made a stop on the most left lane at the traffic junction of Bedok North Road and Bedok Reservoir Road as the traffic light was red in colour. While waiting for the traffic light to turn green, suddenly a vehicle hit the rear side of my motorbike. The driver was still sleeping inside the vehicle.



Police Station Of Origin:
Kampong Ubi NPP
9 Eunos Crescent #01-2687 SINGAPORE
400009
Tel No: 1800-7479999

Report No. T/20190422/2108


CONTINUATION OF REPORT

Sketch Plan


Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 2 LING JUNXIAN
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / AEIT / SI ANG YI TING, STEPHANIE Contact No.: 65476414 ✓

Signature Of Informant: 
Date/Time: 22/04/2019 16:28
Classification Of Case:

Authentication Stamp
NP168





TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475 Fax : 6844 2474
 E-mail : claims@teamworkgarage.com
 GST registered number : 201015366H

PROFOMA INVOICE - PI-1694

TER POH HOCK
 C/O 53 Ubi Avenue 1 #01-24
 Paya Ubi Industrial Park
 Singapore 408934

Date : 11-Jun-19
 Vehicle number : JQN1638
 Make Model : YAMAHA 135LC
 Accident date : 22-Apr-19
 Reference number : 1904-54

Description		Amount SGD\$
Inclusive of supplying parts, labour, panel beating and spray painting		
Lump sum repair	:	2600.00
7% GST	:	182.00
Grand total	:	2782.00
Singdollars: TWO THOUSAND SEVEN HUNDRED AND EIGHTY TWO DOLLARS		



A handwritten signature in black ink, appearing to be 'Poh Hock'.

Teamwork Garage Pte Ltd



CONFIRMATION OF PURCHASE OF INSURANCE

E-Claim No: 002102-19020096
 Issue Date & Time: 05 JAN 2019 03:58:40pm
 Period of Cover: From 17 JAN 2019 To 16 JAN 2020
 Vehicle Registration No: JON103R
 Make of Vehicle: YAMAHA 135 LC
 Engine No: GYFE-2WR621 Chassis No: FMEYJ00410E02088021
 Capacity: 135.00 CC Year of Make: 2014
 Insured Name: TEE POH HOON
 Address: NO 23 JLN HULUBALANG 6 TMN LINGGI TUN AMINAH 81300 SKUDAI, JOHOR DAR
 NRIC/Business Reg No: 781005-01-5063
 Type of Cover: V-DO MOTOR COMPREHENSIVE
 Use of Vehicle: MOTORCYCLE - Z RIDER
 HP Owner:
 Sum Insured (RM): 4,000.00
 Transaction Type: Renewal
 All Claims Excess: RM 100.00
 Voluntary Excess: 0.00

Sum Insured (RM)	4,000.00	Premium (RM)	170.46
All Rider (YN)	Y	All Rider Amt (RM)	85.23
NCD %	25.000000 %	NCD Amt (RM)	63.92
		Basic Net (RM)	191.77
Tuition Load %	0 %	Tuition Load Amt (RM)	0.00
		Extra Coverage (RM)	0.00
GST	6.00 %	GST (RM)	11.51
		Stamp Duty (RM)	10.00
		Cycle P&C (RM)	15.78
Act Premium (RM)	47.98	Private Premium (RM)	227.06

Extra Benefits	Extra Summ (RM)	Extra Premium (RM)
ALL RIDERS	0.00	0.00
Cycle P&C (including premium for extra coverage when it is applicable) GST and stamp duty	5,503.00	13.78

Named Drivers
 ALL RIDERS

Agent: 002102-000 SENG HOE MOTOR ENTERPRISE
 Tel No: 07-5545653

THIS IS A COMPUTER GENERATED FORM. SIGNATURE IS NOT REQUIRED.

[> Back to OneMotoring](#)

Land Transport Authority
 10 Sin Ming Drive
 Singapore 575701
 GST Registration No. : M4-0006529-2

Print Date/Time : 22 Apr 2019 / 17:29:27

Receipt Date/Time : 22 Apr 2019 / 17:29:27

Tax Invoice/Receipt

Receipt No. : ITNET-00000-190422-002952

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SKN3512R As at 22 Apr 2019/13:20:00 Insurance Co: AXA INSURANCE PTE LTD				
1	Insurance Enquiry - SKN3512R Enquiry Fee 20190422172839582986	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	xxxxxxxxxxxx4633		Credit Card: Visa/MasterCard	7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

CL APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

INVOICE

Ter Poh Hock
C/o: Teamwork Garage Pte Ltd
53 Ubi Avenue 1 #01-24
Paya Ubi Industrial Park, Singapore 408934

Invoice No: CL/190578
Ref No: TWG/04/1908/TP
Date: 13 May 2019

DESCRIPTION

AMOUNT

OUR SERVICE FEE CHARGES:

- SURVEY INSPECTION FOR VEHICLE NO. JON 1638
- RESURVEY INSPECTION
- DIGITAL PHOTOGRAPHS SERVICES
(*INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS*)
- TRANSPORTATION

GRAND TOTAL S\$ 451.00

E & O. E

All cheque payment should be "Crossed" and made payable to " CL APPRAISER PTE LTD "

We shall be grateful if you could forward our payment at your early convenience.



CL Appraiser Pte Ltd

L APPRAISER PTE LTD

24 Penshurst Place, Singapore 556440
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Ter Poh Hock
C/o: Teamwork Garage Pte Ltd
53 Ubi Avenue 1 #01-24
Paya Ubi Industrial Park, Singapore 408934

Date : 13 May 2019
Our ref : TWG/04/1908/TP

Accident Date : 22 April 2019
Inspection Date : 24 April 2019
Repairer Name : Teamwork Garage Pte Ltd
53 Ubi Avenue 1 #01-24
Paya Ubi Industrial Park, Singapore 408934

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No : JQN 1638
Make / Model : Yamaha LC135
Chassis No : PMYUG041QE0268621
Engine No : 8399E-26S621

Year / Capacity : 2014 / 135 cc
Colour : Black
Mileage : 50663

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front	: Maxxis	70/90 -17	5 mm	Sport
Rear	: Maxxis	80/90 -17	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 51 copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis
and we have not given authorization and instruction to the repairer to proceed with the repair

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$ 2,600.00** on a contractual basis.

Under normal circumstances, the repair period would be about 7 (Seven) working days.

SLC L APPRAISER PTE LTD

Vehicle Registration No: JQN 1638

Our Ref No: TWG/04/1908/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Fairing assy (1 set)	Damage	\$ 495.00	\$ 495.00 385
1	Exhaust assy	Damage	\$ 525.00	\$ 525.00 420
1	Exhaust protector - Chrome	Damage	\$ 60.00	\$ 60.00 -
1	Rear taillamp	Damage	\$ 135.00	\$ 135.00 -
1	Rear wheel rim	Damage	\$ 320.00	\$ 320.00 XSC
1	Rear fender	Damage	\$ 120.00	\$ 120.00
1	Rear rim shaft	Necessary	\$ 45.00	\$ 45.00 XSC
1	Rear rim bearing	Necessary	\$ 38.00	\$ 38.00 XSC
1	Swing arm	Damage	\$ 425.00	\$ 425.00 Repair
			\$ 2,163.00	\$ 2,163.00
			Less 10%	\$ 216.30
Total Cost - List Items			\$ 1,946.70	\$ 1,946.70

SPECIAL NETT ITEMS

1	Rear number plate	Damage	\$ 18.00	\$ 18.00 15
1	Rear box	Damage	\$ 250.00	\$ 250.00 XSC
1	Rear box bracket	Intact	\$ 100.00	
1	Swing arm rubber	Necessary	\$ 75.00	\$ 75.00 XSC
1	Rear tyre (Depreciation)	Damage	\$ 120.00	\$ 60.00 XSC
1	Sticker (1 set)	Necessary	\$ 95.00	\$ 95.00 50
Total Cost - Special Nett items			\$ 658.00	\$ 498.00

Total cost of parts

\$ 2,604.70 \$ 2,444.70

SCL APPRAISER PTE LTD

Vehicle Registration No: JQN 1638

Our Ref No: TWG/04/1908/TP

S/No	Description	Repairer's Estimate	Revised Amount
	Total cost of parts c/f	\$ 2,604.70	\$ 2,444.70

LABOUR

1	To provide towing service.	\$ 50.00	\$ 50.00 X
2	To check electrical system, wire harness and focus headlamp.	\$ 80.00	\$ 50.00 30
3	To provide labour charges, workmanship to dismantle above damaged parts ; re-align body structure and damaged consistent to the accident.	\$ 380.00	\$ 320.00 200
4	To check , repair and straighten body frame to the original position.	\$ 350.00	\$ 350.00 150

380

GRAND TOTAL

	\$ 3,464.70	\$ 3,214.70
--	--------------------	--------------------

1008
 65
 380

 1453
 200
 1162.40
 41-1,150

 4 days

C L APPRAISER PTE LTD

Vehicle Registration No: JQN 1638

Our Ref No: TWG/04/1908/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 2,600.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD



Cheong K. H.
Automotive Appraiser

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/09/2019 15:46
Date Of Accident	22/04/2019 13:00
Exact Location Of Accident	ALONG BEDOK NORTH ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKN3512R
Insured/Policyholder	
Name Of Registered Owner	LEE KOH SONG
NRIC No	S2076628Z
Email Address	OPERATIONS@MDPL.COM.SG
Mobile Phone No	(LOCAL) +65-96222444
Alternative Phone No	OTHERS-96222444

Vehicle Particulars

Manufacturer	TOYOTA
Model	LEXUS IS250 AUTO LUXURY
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA201663
Cover Note Number	18/05/2018 - 17/05/2019

Driver

Name of Driver	LEE KOH SONG
NRIC No	S2076628Z
Date Of Birth	25/06/1949
Occupation	INDOOR
Date Of Driving Pass	18/06/2010
Driving Experience	8 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96222444
Fax Number	
Contact Number	OTHERS-96222444
EMail Address	OPERATIONS@MDPL.COM.SG

Address	BLK 13 UPPER BOON KENG ROAD #15-947
Postcode	380013
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO MOTORCYCLIST
Weather Conditions	CLEAR
Road Surface	DRY

Other information

Was any foreign vehicle involved in this accident?	YES
Foreign Vehicle Registration Number	JQN1638 (MOTORCYCLE)
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	KOLAM AYER NPP
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACHED SKETCH PLAN BY DRIVER.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	JQN1638
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	LEE KOH SONG
Approximate Age	
Injuries Sustain	FELT LIGHT HEAD & GIDDY THEN PASS OUT
Injured person in which vehicle?	SKN3512R
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

Sketch Plan Pg. 1

Date of accident: 22/4/19 Time: 13:00 Location: Bedok North Road
My Vehicle A: SKN3572R Vehicle B: 7QN1638 Vehicle C: -

SKETCH PLAN

No sketch plan
Not aware how the accident happened.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to the Police Report No.
7/20190912/2057

Claim OD/TP at Ah Lim Motor Claim OD/TP at other workshop Reporting Only

Remarks : Please forward a copy of my efile accident report to :

My workshop :
Email address :
& myself :
Email address :

Note : Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

AH LIM MOTOR COMPANY

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190912/2057

Police Station Of Origin:
Kolam Ayer NPP
72 Geylang Bahru #01-3038 SINGAPORE
330072
Tel No: 1800-2969999

1 of 3

Report No. T/20190912/2057

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 12/09/2019 12:38	Video Report No.:	Station Diary No.: 7
--	-------------------	-------------------------

Informant's Particulars

Name of Informant: LEE KOH SONG		Address: APT BLK 13 UPPER BOON KENG ROAD #15-947 SINGAPORE 380013	
ID Type / ID No.: NRIC NO / S2076628Z		Contact No.: Home/Office: Mobile: 96222444	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 70	Date of Birth: 25/06/1949	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: Company director		Driving Licence Information: Class: 3	Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 22/04/2019 13:00	Type of Location:
Location: Along Road 1 BEDOK NORTH ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision: Unknown				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
SKN3512R	Car	TOYOTA	LEXUS IS250 AUTO LUXURY	Black		0

Details of Vehicle Insurance

Vehicle No	Insurance Company	Insurance No	Effective	Expiry Date
SKN3512R	AXA INSURANCE SINGAPORE PTE LTD	GA201663	18/05/2019	17/05/2020



**SINGAPORE
POLICE FORCE**



T/20190912/2057

Police Station Of Origin:
Kolam Ayer NPP
72 Geylang Bahru #01-3038 SINGAPORE
330072
Tel No: 1800-2969999

2 of 3

Report No. T/20190912/2057

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	LEE KOH SONG	ID No.	S2076628Z
Related Vehicle	SKN3512R (Car)	Contact No.	96222444
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	22/04/2019	Date Discharge	22/04/2019
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 22/04/2019, at about 0800hrs, I left home without eating breakfast, and went to the office to work. I reach my office located at 3016 Bedok North Ave 4 #08-22.

I subsequently received a call from my daughter, informing me to proceed home, as there the contractor came to my house to repair the Air-Conditioner. I then drove home at about 0830hrs. While I was driving along Bedok North Road, I felt light head and giddy, and I subsequently pass out.

When I woke up, I was in Changi General Hospital. I could not recall what happened after I pass out, and I was informed by the Paramedics that I pass out somewhere, and I was sent to the hospital via an Ambulance.

I was unsure what happened on that day, and I received a claim from the insurance, thus, I am lodging this report.



**SINGAPORE
POLICE FORCE**



T/20190912/2057

Police Station Of Origin:
Kolam Ayer NPP
72 Geylang Bahru #01-3038 SINGAPORE
330072
Tel No: 1800-2969999

3 of 3


Report No. T/20190912/2057

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: A / Sgt 2 TAN ZHI KAI, BRANDAN	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 12/09/2019 12:36
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt NOR HIDAYU BINTE ABDUL SAMAD Contact No.: 65476423	Classification Of Case:
Authentication Stamp NP168 	



redefining / insurance

AXA Insurance Pte Ltd
 1800 880 4888 (Within Singapore)
 (65) 6880 4888 (International)
 (65) 6880 4740
 customer.care@axa.com.sg
 www.axa.com.sg

Certificate of Insurance

account number
04139

Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) - Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 - Road Transport Act, 1987 (Malaysia)
 Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Policy details

Policyholder name	LEE KOH SONG	Certificate number	GA201663 / 1
Cover	Comprehensive	Chassis number	JTHBK262202048190
Plan name	Peace	Engine number	4GR0334060
NCD applicable	0%		
Vehicle registration number	SKN3S12R		
Period of insurance	from 18/05/2019 to 17/05/2020 (both dates inclusive)		
Finance loan company	SPEEDO CAPITAL PTE LTD		

Persons or classes of persons entitled to drive*

- (a) The Policyholder
 (b) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS	Basic Own Damage Excess	SGD 2,200.00
	Windscreen Excess	SGD 100.00

An Additional Excess is applicable as follows:

1. S\$500 for unnamed Authorized Driver
2. S\$500 for declared Young and Inexperienced Driver
3. S\$5,000 for undeclared Young and Inexperienced Drivers. This additional excess is reduced to S\$2,500 if You have chosen AXA Premium Workshops.

Additional clauses & endorsements to your policy

Nil

(We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189).
 The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, endorsement etc.

AXA Insurance Pte Ltd (199903512M)
 8 Shenton Way, #24-01, AXA Tower,
 Singapore 068811
 Customer Centre, #B1-01

1 of 3

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





Your Ref: 20.27688

Date: 11th March 2020

Our Ref : CS3/ASM19007174/R1vd3e2-1

M/s AXA Insurance Pte Ltd
C/O: Seah Ong & Partners LLP
36 Robinson Road
#12-03 City House
Singapore 068877
(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: JQN 1638
INSURED VEHICLE: SKN 3512R
ACCIDENT DATE: 22/04/2019

We thank you for your instruction on 04/03/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of JQN 1638 from M/s C L Appraiser Pte Ltd.
- b) Singapore Accident Statement of Vehicles SKN 3512R.
- c) Police Report of Vehicles JQN 1638 and SKN 3512R.
- d) Final Repair Bill of JQN 1638 from M/s Teamwork Garage Pte Ltd.
- e) Colour damaged vehicle photographs of JQN 1638.

Pre-Repair Inspection Date : 23/04/2019 at M/s Teamwork Garage Pte Ltd, 53 Ubi Avenue 1 #01-24, Singapore 408934.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: JQN 1638
Make & Model	: Yamaha 135LC
Year of Registration	: 2014
Engine Capacity	: 135 cc
2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JQN 1638

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SET FAIRING ASSY	DAMAGED	495.00	385.00
1	EXHAUST ASSY	DAMAGED	525.00	420.00
1	EXHAUST PROTECTOR - CHROME	DAMAGED	60.00	60.00
1	REAR TAILLAMP	DAMAGED	135.00	135.00
1	REAR WHEEL RIM	SERVICEABLE	320.00	-
1	REAR FENDER	DAMAGED	120.00	120.00
1	REAR RIM SHAFT	SERVICEABLE	45.00	-
1	REAR RIM BEARING	SERVICEABLE	38.00	-
1	SWING ARM	TO REPAIR SEE LABOUR	425.00	-
	LESS 10% DISCOUNT		-216.30	-112.00
			1,946.70	1,008.00
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE (SN)	DAMAGED	18.00	15.00
1	REAR BOX (SN)	SERVICEABLE	250.00	-
1	REAR BOX BRACKET (SN)	INTACT	100.00	-
1	SWING ARM RUBBER (SN)	SERVICEABLE	75.00	-
1	REAR TYRE (SN)	SERVICEABLE	120.00	-
1	SET STICKER (SN)	NECESSARY	95.00	50.00
			658.00	65.00
LABOUR				
	TO PROVIDE TOWING SERVICE.	NOT NECESSARY	50.00	-
	TO CHECK ELECTRICAL SYSTEM, WIRE HARNESS AND FOCUS HEADLAMP.		80.00	30.00
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF SWING ARM.		380.00	200.00
	TO CHECK, REPAIR AND STRAIGHTEN BODY FRAME TO ORIGINAL POSITION.		350.00	150.00
			860.00	380.00
GRAND TOTAL			3,464.70	1,453.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,150.00



Report Ref No. CS3/ASM19007174/R1vd3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.