



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS4/MSG20003636/Dtf3e2

4 SHENTON WAY #21-01,SGX  
CENTRESINGAPORE 068807

Date : 04-06-2020



Code : MSG

### 1. Policy Particulars :- INVESTIGATION CASE

<b>Insured Veh.</b>	SKN 1352Z	<b>Veh. Inspected</b>	SMC 6250K
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	592258/IT	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	IRENE TAN	<b>Assign Date</b>	14/08/2019

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	B.M.W. 116D	<b>c.c</b>	1496
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2018
<b>Chassis No.</b>	WBA1V720505G87653	<b>Colour</b>	BLACK
<b>Odometer</b>	13390	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	205/55 R16	BRIDGESTONE	5 mm
<b>L/H Front Tyre</b>	205/55 R16	BRIDGESTONE	5 mm
<b>R/H Rear Tyre</b>	205/55 R16	BRIDGESTONE	5 mm
<b>L/H Rear Tyre</b>	205/55 R16	BRIDGESTONE	5 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

<b>Accident Date</b>	29/04/2019	<b>Inspection Date</b>	20/08/2019
<b>Survey held at</b>	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>3 Working Days</b>
-------------------------------------	-----------------------