

ASS. REC. BY:

REP: CS3/MSG/19015/03 / Gsf3-1

Special Instruction:

4/3/2020

27.2.19 11.08 a.m

Summary:

GQ

ASSIGNMENT (Office)

Date/Time:

From (Person):

(myal) Lee

of MS29

Bill to:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

XE 3025Z

Insured:

FBV 280 K

Tel:

96 910909

at Workshop m/s

Eng Soon Huat

of 1003 Eunice Ave 8 #01-55

Policy No:

72184560

Claim No:

MSC/V/19-001013

Sum Insured:

Excess:

D.O.A. 18.8.2019

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

mp

H.O.D. Endorsement:

Date/Time:

27.2.19 3.47 p.m

Person Contacted:

AL Long

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	FBV 280K X
	XE 3025Z X
	\$10900, 7 Days.
	8700

Annex A : Assesement / Adjustment on Spare Parts

XE 3025 Z

Item	Vehicle Parts Description	Condition	Qty	W/shop Est. (\$)	Disc (%)	Adjusted Cost (\$)
S/Nett Items						
Supply & install Scorpion Model:10,000						
Truck Mounted Attenuator for Truck						
XE 3025 Z (S/N: 10021)						
1	P/N: 10400A Module A Energy Absorber	Buckled/cut	1	\$9,500.00		\$9,500.00 ✓
2	Tail lamp with bracket (Left)	Bent/cracked	1	\$200.00		\$200.00 ✓
Total for Spare Parts :				\$9,700.00		\$9,700.00

Annex B : Adjustment on Labour and Spray Painting

XE 3025 Z

Item	Job Description	Workshop Est. (\$)	Adjusted Cost (\$)
1	Full Labour Cost, dismantling, removing, installation, repairing, re-alignment	\$1,200.00	\$1,200.00
TOTAL FOR LABOUR & SPRAY PAINTING :		\$1,200.00	\$1,200.00

Summary

	Workshop Est. (\$)	Adjusted Cost (\$)
TOTAL FOR SPARE PARTS :	\$9,700.00	\$9,700.00
TOTAL FOR LABOUR & SPRAY PAINTING :	\$1,200.00	\$1,200.00
TOTAL REPAIR COSTS :	\$10,900.00	\$10,900.00

7 Days

20%: 8700