



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 60 Woodlands Industrial Park E4, Singapore
 FAX Number 6385592
 Estimator Telephone Number 68662623
 Accident Reporting Number 68662672

Date Generated : 20/03/2020
 User ID PohSuan

Section A - Accident Details	
Registration Number	SHB1816B
Case Reference Number	TAX/03/20/2006
Registration Date	19/12/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	PUBHINDER SINGH S/O POORAN SINGH
Type of Accident	Head To Side
Accident Date and Time	2/3/2020 10:00 PM
Accident Reported Date and Time	3/3/2020 2:15 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	2/3/2020 11:40 PM
Replacement Vehicle issued?	No
Job Card Number	24106000
Special Instruction to ARC, if any	LEFT SIDE PORTION DAMAGE/ AIG - LKK
Repaired Date and Time	4/3/2020 9:19 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$500.00
Total Spray Cost	\$1,674.00	\$800.00
Total Spare Part Cost	\$8,949.19	\$5,001.28
Total Other Cost	\$516.00	\$180.00
TOTAL COST	\$11,815.19	\$6,481.28 (P/P)
Warranty Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / AIG
ARC / Surveyor Sign Off Date	10/03/2020 4:33 PM	10/03/2020 9:23 AM
Signature		
Remarks	Initial estimate = 6 days SUP = 0 day	P/P Repair, Before paint photo.



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number 63685592
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 20/03/2020
User ID PohSuan

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2003-0292	Invoice Number	
Quotation Date	16.03.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	\$676.00	\$500.00 ✓
Total Labour	\$676.00	\$500.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00 ✓
TO RESPRAY CENTER PILLAR LH	\$180.00	\$100.00 ✓
TO REPSRAY REAR DOOR LH	\$378.00	\$200.00 ✓
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00 ✓
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00 ✓
RESPRAY MIRROR COVER LH	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,674.00	\$800.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TRANSFER DOOR MECHANISM	\$120.00	\$120.00 ✓
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00 ✓
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00 ✓
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00 ✓
TO WASH AND VACUUM	\$60.00	\$0.00
TOWING CHARGE	\$56.00	\$0.00
Total Other Costs	\$516.00	\$180.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		67002471 62	PANEL SUB-ASSY, FRONT DOOR LH	1.00	\$1,249.60	25.00	\$937.20	Replace	Replace ✓
		85720471 40	DOOR FRONT MOTOR ASSY, POWER WINDOW	0.00	\$768.60	0.00	\$0.00	Replace	Check ✗
		68720121 51	HINGE ASSY, FRONT DOOR, UPPER LH	0.00	\$82.10	0.00	\$0.00	Replace	Check ✗
		68740121 20	HINGE ASSY, FRONT DOOR, LOWER LH	0.00	\$92.10	0.00	\$0.00	Replace	Check ✗
		69802210 10	DOOR FRONT WINDOW REGULATOR SUB-ASSY,	0.00	\$230.80	0.00	\$0.00	Replace	Check ✗
		68610470 40	CHECK ASSY, FRONT DOOR	0.00	\$153.50	0.00	\$0.00	Replace	Check ✗
		69040471 00	LOCK ASSY, FRONT DOOR LH	1.00	\$544.70	25.00	\$408.53	Replace	Replace ✓
		69410201 10	DOOR LOCK STRIKER	0.00	\$38.00	0.00	\$0.00	Replace	Check ✗
		67004472 10	PANEL SUB-ASSY, REAR DOOR, LH	1.00	\$1,243.90	25.00	\$932.93	Replace	Replace ✓

CRU
SVC
SVC
SVC
SVC
SVC
JAM
SVC
CRA



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number 63685592
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 20/03/2020
User ID PohSuan

Main repair estimate table with columns for Part Number, Portion, Stock Number, Part Name, Quantity, List Price, Discount, Final Price, ARC Check, and Surveyor Check. Includes a Total row at the bottom.

SVC
SVC
SVC
SVC
JAM
SVC
SVC
CUT
SVC
SVC
SVC
SVC
SVC
X
CRU
SVC
SVC
NEC
NEC
SVC

Added Spare Parts / Material Usage After Surveyor Signed off

Table for added spare parts with columns for Part Number, Portion, Stock Number, Part Name, Quantity, List Price, Discount, Final Price, ARC Check, and Surveyor Check. Includes a Total row.

short
bt
short
bt

Handwritten calculation: 5001.28 + 500.00 + 980.00 = 6481.28