

VOLKSWAGEN CENTRE SINGAPORE

17 Tuas Avenue 9
Singapore 639197
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 1/1

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Ms.
ONG
YEN NEE
6 LILAC DRIVE
Singapore 808196

Document no.
Document date 07-03-2020
Customer no. 5211043795
Customer GST-ID 201009404M
Dealer 39999
Job order number 2020000671/ 1
Job order date 07-03-2020
Service Advisor TIOU CHUAN CHEE

License plate	Model code	First registration	VIN	Model	Mileage
SMJ6060E	5G13HZ	05-04-2016	WVWZZZAUZGW059093	Golf 1.4 CLBM 92 TSI D7F	55,889

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
5G4833056AC	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
	Door RHR <i>Buc</i>	1	pcs.	1,987.16	#1	1,987.16	2,126.26
5G6839700D	Door Seal Outer RHR	1	pcs.	100.68	#1	100.68	107.73
D 378500A2	Sound Absorber Laminated	1	pcs.	41.40	#1	41.40	44.30
8K0831402D	Door Hinge RHR UPPER <i>X</i>	1	pcs.	129.72	#1	129.72	138.80
8K0831402D	Door Hinge RHR LOWER <i>X</i>	1	pcs.	129.72	#1	129.72	138.80
5G6839432J 5AP	Glass Channel Black LABOUR <i>X</i>	1	pcs.	234.10	#1	234.10	250.49
	Spray Painting	3	pcs.	840.00	#1 <i>840</i>	2,520.00	2,696.40
	TRANSFER DOOR MECHANISM	3	pcs.	800.00	#1 <i>800</i>	2,400.00	2,568.00
	AIG DIRECT SETTLEMENT	1	pcs.	840.00	#1 <i>420</i>	840.00	898.80
	DOA : 04/03/2020						
	TP VEH : SKN1955J						
	SURVEY BY "						

Quotation valid till 14-03-2020

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	8,382.78	7%	639.99	9,142.78	9,782.77
Total	760.00	8,382.78		639.99	9,142.78	9,782.77

3 Days.
before paint photos -
Gmo Qianf - 82880282
11/03/2020

Customer

---VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for online services, products and promotions).---

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification to original parts
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: