

PRS

2008/2009

ASS. REC. BY:

REF:

083/SM020003725/Hvd3m

Special Instruction:

Survey: Hock AnnASSIGNMENT (Office)From (Person): Grace Teo

of

SMO

Date/Time:

9/3/2020 10 am

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJX 74594

Insured:

SLG 33234

at Workshop m/s

The mechanic

Tel:

9119 3959

of

8 Kaki Bukit Ave 4 # 02-47

Policy No:

Claim No:

CMTD2001014/HAG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

5/3/2020

CA / REV / REP. / REV 24 HRS

Imp

H.O.D. Endorsement:

Date/Time: 10:15 am 9/3/2020

Person Contacted:

Ah XianVehicle ☒ IN / OUT

Date/Time

Action/Instruction

Island (X)SJX 74594 - XSLG 33234 - X12/3/20Submit PRS Est repair range \$3000 - \$4000

PRS

ASSIGNMENT

From: _____ Date: 9/3/2020
 Estimated Cost: _____
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SJX 74594
 at Workshop m/s The Mechanic
 of 25 Kaki Bukit Road 4 #05-85
 Insured: Synergy
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: 8 Suzuki Swift 4 #02-47

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJX 74594 Yr Regn: 26/11/2015
 Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover / ☐ Truck / ☐ Trailer or

Make: H-veon cc 1496
 Colour: white A/C: Insured / Std / NI / NA
 Sp. Reading: 118894 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: Ru 11/05067

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt
 Steering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or
 Brake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or
 Modi: Nil / ☒ S/Rim / ☐ STD A/Rim or
 Tyre Size: F: _____ R: 215/60/R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front 67 mm R/Bal. 57 mm
 L/Bal. 67 mm L/Bal. 57 mm
 D.O.A. 5/3/20 D.O.I. 9/3/20 0242PM
 Survey held at The mechanic
 Des. of Damages: ☒ Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Range 3-4 km</u> <u>upper Days - 4 day</u> <u>10/3/2020</u> <u>PRS case</u> <u>Dismantle part: 11/03/2020</u> <u>After repair: 13/03/2020</u>
	<u>MV - 53000</u> <u>PV - 38940</u> <u>NV - 14000</u>

RECEIVED 13 MAR 2020

9119 3759

Date/Time, File Pass to? ☐ : Prel. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) 12/3 - typist

Report Format: PRS

Lump Sum / L&J: ()

Days Of Repair: 4

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs ()

☐ : Weekend ()

Survey Fee:

Transportation:

S + PRS \$

Photos

Others

TOTAL

100
60
60
220

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Monday, 9 March 2020 10:00 AM
To: Wendy Jiang; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'; sur@lkkauto.com
Cc: Natalie Ng; Lua Siew Hui; Choo, Thelma
Subject: CMTD2001014/THE - PRI(LKK)/ SLG3323U & SJX7459U ACC ON 05.03.20 [2003-7612(MECH)(PD)]
Attachments: GIA report on SJX7459U.pdf

Our Reference : CMTD2001014/THE
Your Reference : RSS/ 2003-7612(MECH)(PD)

Without Prejudice
EMAIL ONLY

Date: 10.03.2020

OUR Email: motorsurvey@sompo.com.sg

Attention:
M/S R.S. SOLOMON LLC

Dear Wendy,

ACCIDENT INVOLVING SLG3323U & SJX7459U ON 05.03.2020

We refer to your email reply of 06.03.2020

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Aside to **LKK AUTO**,

Please make the arrangement to survey for **SJX7459U** on a without prejudice and any admission of liability basis.

Please be informed that **Ms. Thelma Choo** is the handler of this case who can be contacted at 63224 681/ thelma.choo@sompo.com.sg.

Please revert your report upon completion of survey to my colleague, **Ms. Thelma**.

Thank you.

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555

For motor claims survey request, please email to motorsurvey@sompo.com.sg



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Wendy Jiang <wendy_jiang@rssolomon.com>

Sent: Friday, March 6, 2020 5:42 PM

To: Henry, Irene James <irene.henry@sompo.com.sg>

Cc: Natalie Ng <natalie_ng@rssolomon.com>; Lua Siew Hui <lua_siewhui@rssolomon.com>; Teo, Grace <grace.teo@sompo.com.sg>; Choo, Thelma <thelma.choo@sompo.com.sg>

Subject: RE: SOMPO REF:CMTD2001014/THE/RE: PRE-REPAIR SURVEY ACCIDENT INVOLVING SJX7459U & SLG3323U [2003-7612(MECH)(PD)]

Dear Irene,

We refer to your email of even date.

We write to inform that our client will be appointing its own surveyor.

In this respect, please arrange your surveyors to contact Ms. Bao Bao of The Mechanic at mobile no. 9119 3959 for a pre-repair survey of our client's vehicle located at 25 Kaki Bukit Road 4 #05-85 SYNERGY @ KB, Singapore 417800.

Thank you and best regards,

Yours sincerely
Wendy Jiang | Legal Executive



R. S. SOLOMON LLC
ADVOCATES & SOLICITORS

R. S. Solomon LLC | 正氣律師事務所

300 Beach Road The Concourse #12-03/04 Singapore 199555

t +65 6817 7498 | f +65 6292 2665 | e wendy_jiang@rssolomon.com | w www.rssolomon.com

The contents of this email (including any attachment) are strictly confidential and may contain privileged information. If you are not the intended recipient, please notify us IMMEDIATELY and delete this email (including attachment) from your computer system. Thank you.

From: Henry, Irene James [<mailto:irene.henry@sompo.com.sg>]

Sent: Friday, 6 March 2020 5:33 pm

To: Wendy Jiang <wendy_jiang@rssolomon.com>

Cc: Natalie Ng <natalie_ng@rssolomon.com>; Lua Siew Hui <lua_siewhui@rssolomon.com>; Teo, Grace <grace.teo@sompo.com.sg>; Choo, Thelma <thelma.choo@sompo.com.sg>

Subject: SOMPO REF:CMTD2001014/THE/RE: PRE-REPAIR SURVEY ACCIDENT INVOLVING SJX7459U & SLG3323U [2003-7612(MECH)(PD)]

Our Reference : CMTD2001014/THE

Without Prejudice
EMAIL ONLY

Date: 06.03.2020

Attention:

M/S R. S. SOLOMON LLC

ACCIDENT INVOLVING SLG 3323U & SJX 7459U ON 05.03.2020

Dear Sirs,

We refer to your Notice of Accident dated 06.03.2020.

Please be informed that **Ms. Thelma Choo** the handler of this case who can be contacted at 6322 4681/thelma.choo@sompo.com.sg.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @



or



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Wendy Jiang <wendy_jiang@rssolomon.com>

Sent: Friday, 6 March, 2020 3:23 PM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Cc: Natalie Ng <natalie_ng@rssolomon.com>; Lua Siew Hui <lua_siewhui@rssolomon.com>

Subject: PRE-REPAIR SURVEY ACCIDENT INVOLVING SJX7459U & SLG3323U [2003-7612(MECH)(PD)]

Dear Sirs,

We act for the owner ('our Client') of vehicle no. SJX7459U.

Our Client's vehicle was involved in the aforesaid accident with your insured's vehicle no. SLG3323U at the material time. As a result, our Client's vehicle was damaged and before our Client proceeds to repair its vehicle, please let us know within 2 working days upon receipt of this notice whether you intend to conduct a pre-repair survey of our Client's vehicle within the stipulated timeline, our Client will proceed to repair its vehicle without further reference to you.

Please see below, the following documents for your necessary action:-

1. Our letter of even date; and
2. GIA & Police Reports lodged by our Client's driver.

Let us hear from you soonest.

Thank you and best regards,

Yours sincerely
Wendy Jiang | Legal Executive



R. S. SOLOMON LLC
ADVOCATES & SOLICITORS

R. S. Solomon LLC | 正氣律師事務所

300 Beach Road The Concourse #12-03/04 Singapore 199555

t +65 6817 7498 | f +65 6292 2665 | e wendy_jiang@rssolomon.com | w www.rssolomon.com

The contents of this email (including any attachment) are strictly confidential and may contain privileged information. If you are not the intended recipient, please notify us IMMEDIATELY and delete this email (including attachment) from your computer system. Thank you.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	025W
Vehicle Details	
Vehicle No.:	SJX7459U
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Mar 2020
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X A
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	L15B4025137
Chassis No.:	RU11105067
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,736.00
Original Registration Date:	26 Nov 2015
First Registration Date:	26 Nov 2015
Transfer Count:	①
Actual ARF Paid:	\$9,736.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Nov 2025
PARF Rebate Amount:	\$7,302.00
Intended COE Rebate Details	
COE Expiry Date:	25 Nov 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,399.00
COE Rebate Amount:	\$31,638.00
Total Rebate Amount:	\$38,940.00

The information contained herein is correct as at 09 Mar 2020

OK



9-Spoiler GZ
Racing Omnia
18" Rim With
Tyre



Small But
Powerful
Airge AG25
Air Purifier



Improve
Driving
Dynamics &
Performance



Buddy
Andro
Multi I

honda vezel

Price Range

Depreciation

Year Reg

Vehicle Type



Home » Used Cars » ValueCars Auto Traders » Honda Vezel 1.5A X

Honda Vezel 1.5A X

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price	\$56,500		
Depreciation ⓘ	\$8,930 /yr View models with similar depre	Reg Date	12-Jan-2016 (5yrs 10mths 2days COE left)
Mileage	52,649 km (12.7k /yr)	Manufactured ⓘ	2015
Road Tax ⓘ	\$682 /yr	Transmission	Auto
Dereg Value ⓘ	\$39,958 as of today (change)	OMV ⓘ	\$18,609
COE ⓘ	\$57,301	ARF ⓘ	\$8,609
Engine Cap	1,496 cc	Power	96.0 kW (128 bhp)
Curb Weight ⓘ	1,190 kg	No. of Owners ⓘ	1
Type of Vehicle	SUV		



Location Map

Features

1.5L 4 Cylinders Inline 16 Valves I-VTEC Engine, CVT Automatic Transmission, 130bhp, Traction Control, ABS, SRS Airbags, CTBA, Knockdown Rear Seats. View specs of the Honda Vezel (2014)

Accessories

Sports Rims, Leather Seats, Audio Player With USB/Bluetooth, Reverse Camera/Sensors, Solar Film, Retractable Side Mirrors, Fog Lights.

Description

Most Original 1 Owner Owned. Non Phv Unit With Proved. Genuine Mileage Clocked. Silver With Black Interior. High Paper Value. Most Sellable Honda Vezel In Showroom Now. Only Sent For Professional Grooming And Back In Showroom Condition. Flexible Loan And Installment Available. Thanks.

Category

PARF Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started




Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Price Chart

Summary



Shortlist

Report Error

Compare

More Actions

Add to

Seller Information

ValueCars Auto Traders

17 vehicles for sale. 42 sold in past 3 mths

61 Ubi Avenue 2 #02-06

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/03/2020 13:37
Date Of Accident	05/03/2020 14:55
Exact Location Of Accident	LORONG 06 TOA PAYOH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJX7459U
Insured/Policyholder	
Name Of Registered Owner	PEH2RENT PTE. LTD.
Co Reg No	2XXXXX025W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62712252

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL 1.5X A

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5109551694-01
Cover Note Number	

Driver

Name of Driver	POH AI LIN
NRIC No	SXXXX473J
Date Of Birth	07/09/1964
Occupation	OUTDOOR
Date Of Driving Pass	13/06/2003
Driving Experience	16 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97764367
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 20 BALAM ROAD #07-174
Postcode	370020
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	HEAVY RAIN
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : GOJEK PASSENGER
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	HOUGANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 60 HOUGANG AVE 9 , POSTCODE: 538775 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4890999 - FAX NO: 63126989
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER POLICE REPORT No.T/20200306/2043;

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLG3323U
Vehicle Make/Model/Colour	NISSAN / X-TRAIL 2.0 CVT ABS 4WD S/R 7-STR
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KOH EU JIN
NRIC/Passport Number	SXXXX323G
Contact Number	91829284
Address	

Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	POH AI LIN
Approximate Age	55
Injuries Sustain	-5DAYS MC-
Injured person in which vehicle?	SJX7459U
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	
Address	BLK 20 BALAM ROAD #07-174
Postcode	370020

Accident Sketch Plan

SKETCH PLAN



IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@vacom.com.sg

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

06 MAR 2020

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer
To Police Report

DECLARATION

I/We declare that the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: yackb@vics.com.sg
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

06 MAR 2020

Accident Sketch Plan



Accident Sketch Plan



**SINGAPORE
POLICE FORCE**



T/20200306/2043

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

1 of 3
Report No. T/20200306/2043

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 06/03/2020 11:24		Vide Report No.:		Station Diary No.: 50
Informant's Particulars				
Name of Informant: POH AI LIN		Address: APT BLK 20 BALAM ROAD #07-174 SINGAPORE 370020		
ID Type / ID No.: NRIC NO / S1642473J		Contact No.: Home/Office: Mobile: 97764367		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Female	Age: 55	Date of Birth: 07/09/1964	Type of Informant: Driver	
Race: Chinese		Language:	Institution / School Name:	
Occupation: GOJEK DRIVER		Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 05/03/2020 14:55	Type of Location: Straight Road
Location: Along Road 1 LORONG 6 TOA PAYOH LORONG 6 TOA PAYOH TURNING TO HDB HUB				
Weather: Heavy rain		Road Surface: Wet	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
SJX7459U	Car				Slightly Damaged	1
SLG3323U	Car					0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Accident Sketch Plan



**SINGAPORE
POLICE FORCE**



T/20200306/2043

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

2 of 3
Report No. T/20200306/2043

CONTINUATION OF REPORT

Driver			
Name	POH AI LIN	ID No.	S1642473J
Related Vehicle	SJX7459U (Car)	Contact No.	97764367
Hospital/Clinic	CARE MEDICAL PTE LTD	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	06/03/2020	Date Discharge	06/03/2020
No. of Days granted Medical Leave	05	Degree of Injury	Slight
Driver			
Name	KOH EU JIN	ID No.	S8223323G
Related Vehicle	SLG3323U (Car)	Contact No.	91829284
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 05/03/2020 at about 1455hrs, I was driving along Lorong 6 Toa Payoh and wanted to turn left into HDB Hub to alight one passenger. At that point of time, the traffic flow was quite congestive turning left into HDB Hub. As my vehicle was moving at a very slow speed, I felt an impact on the rear of my vehicle. Upon further check, one vehicle, SLG3323U had hit onto the rear of my vehicle.

At that point of time, there was one passenger on board of my vehicle. The passenger did not complain of any injury until the accident was over. As a result of the collision, the rear of my vehicle was damage and dented.

There was no police or ambulance at scene. After the incident, I felt discomfort on my neck and lower back area, and numbness on my limbs as such I went to seek treatment and was given 5 days of MC.

Accident Sketch Plan



SINGAPORE
POLICE FORCE



T/20200306/2043

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

3 of 3




Report No. T/20200306/2043

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Sgt 3 PHUA JIA JUN, MARK 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 06/03/2020 11:24
Officer In Charge Of Case: TP / GIA / Staff Sgt WONG SIEU LUI Contact No.: 65476151 	Classification Of Case:
Authentication Stamp NP158	



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

PRE-REPAIR INSPECTION REPORT				
SOMPO INSURANCE SINGAPORE PL		Ref: CS3/SMO20003725/Hvd3e2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date: 19-03-2020		
Code: SMO				
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SLG 3323U	Veh. Inspected	SJX 7459U	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2001014/THE	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	09/03/2020	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	RU11105067	Colour	WHITE	
Odometer	116894 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	CST	6 mm	
L/H Front Tyre	215/60 R16	CST	6 mm	
R/H Rear Tyre	215/60 R16	CONTINENTAL	5 mm	
L/H Rear Tyre	215/60 R16	CONTINENTAL	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5. General Information				
Accident Date	05/03/2020	Inspect Date / Time	09/03/2020 (02:42 PM)	
Survey held at	THE MECHANIC PTE LTD 8 KAKI BUKIT AVENUE 4 #02-46 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
AA) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	

Report Ref No. CS3/SMO20003725/Hvd3e2

Inspected By



LEE HOCK ANN

Asst. Automotive Assessor



K.K. LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MinetA&E, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever in contract or tort is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.