



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 06/03/2020

User ID : BoonChewTay

Section A - Accident Details

Registration Number	SMB1444G
Case Reference Number	BUS/03/20/1008
Registration Date	7/8/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Muhammad Imran Bin Zulkifli
Type of Accident	Side Swipe
Accident Date and Time	3/3/2020 2:30 PM
Accident Reported Date and Time	3/3/2020 5:45 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB1444G-LEFT FRONT PORTION GBH2762E (TP) INSURED
Prepared Date and Time	6/3/2020 1:21 PM
Chassis Number	WMAA22ZZ1E7002160
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$0.00
Total Spray Cost	\$708.00	\$0.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,503.00	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	06/03/2020 1:28 PM	
Signature		x
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 06/03/2020

User ID : BoonChewTay

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope		Quotation from AR				Adjusted by Surveyor, if applicable			
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		\$795.00				530			
Total Labour		\$795.00							
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS		\$708.00				616			
Total Spray Painting & Panel Beating		\$708.00							
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
Lump Sum Adjustment by Surveyor		\$0.00							
Total Other Costs		\$0.00							
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010153	Body	F01001-CW264	COVER, HEADLAMP: FRT LH, FOR MAN A22 BUS	1.00	\$974.70	100.00	\$0.00	Repair	X R
6010073	Body	F01001-CW262	DOVE: FRONT, FOR MAN A22 BUS	1.00	\$2,817.50	100.00	\$0.00	Repair	X R
Total							\$0.00		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Repair day - 2 days

La P/P

After paint

Sum Pn (444)

6/3/2020

TP with prjudice

530

+616

1,146

-20%

916.80

L/S= \$900

2 days