

27/03/2021

ASS. REC. BY:

REF: CS/ICS20003768/49 f3d Special Instruction:

Surveyor: MARCUS ASSIGNMENT (Office)From (Person): Elizabeth Chew Ming Lai of ECICS Date/Time: 9.3.2020 16.43 p.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SGU 1052A Insured: _____at Workshop in/s Falon - ASV Auto Tel: 67897997of BK 9006 #01-200 COMPANY ST 93Policy No: MPC19P00005900 Claim No: DMPC200005321/EC

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 7/3/2020(Client's Record) 10.3.2020

CA / REV / REP. / REV 24 HRS

Date/Time: 9.3.2020 5.09 p.m Person Contacted: Janet H.O.D. Endorsement: _____Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SGU 1052A - NA / VC 0902117417 D.O.A. - 13/04/2021</u>
<u>10/3/20 @ 11.16am</u>	<u>Verdict to Elizabeth Chew via Meimian.</u>
<u>16/3/20 @ 2.17pm</u>	<u>Nicholas Chew informed C/A via Meimian.</u>
<u>10/3/20 @ 4.14pm</u>	<u>informed Janet C/A & ex; to be by email.</u>

Wilmun

ASS. REC. BY: MAV

REF: ECICS CS/ICS20003768/149f3

ASSIGNMENT

From: _____ Date: 10.3.2020
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SGU 1052A
 at Workshop m/s Falcon - Air Auto
 of BK 9006 # 01-200 Tampinuse st 93
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SGU 1052A Yr Regn: 2/507
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CAI
 Make: Toyota WSH C.C. 1794
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 183.578 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: ZNE100363489
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Order / Jammed / Leaked / Burnt or
 Brake: Order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/65R15
 R: _____

N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 15/6
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS 982x
 Vehicle: IN / OUT
 Date: _____ Person Contacted: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Falcon
 Front R/Bal. 6 mm Rear R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 7/3/20 D.O.I. 10/3/20
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear & Rear window shattered
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Ad 2yrd</u>
	<u>LTA 10353 COE 3.3.2022</u>
	<u>net 4647</u>
<u>10/3/20</u>	<u>continued w/s \$2900 w-h Top (LTD \$1486.90, 34%)</u>

RECEIVED 13 MAR 2020

Date/Time, File Pass to? : Preli. Report
1/12/20 : Final Report
 Date/Time, File Return to?
1/
 Rep. Form: OVEROP
 Lump Sum / f.p.: 2900

Days Of Repair: 4
 Resurvey No. of Trip: 1
 Add Fee: : Site Insp (\$))
 : Interview (\$))
 : Tech. Invs (\$))
 : Weekend (\$))
 Survey Fee: 700
 Transportation: _____
 Photos: _____
 Others: 11
 TOTAL: 711

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Mar 2020 13:40 Sendback Est	09 Mar 2020 14:01 S\$4,386.90	09 Mar 2020 16:43 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	CHEW MONG HOCK, ID: S1167982Z, Tel: +6596362275, Email: NOEMAIL		
Vehicle Reg. No.:	SGU1052A	Date of Loss:	07/03/2020 22:00 - :59 [154 Months and 5 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / DMPC2000053H/EC	Policy/Cover Note No.:	MPC19P00005900 (Comprehensive)
		Excess:	S\$0.00
Repairer:	Falcon-Air Auto Services Pte Ltd (Tampines) Blk 9006 #01-200 Tampines St 93, Tampines - Tel: 67897997		
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Elizabeth Chew Ming Lai]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 18/03/2020]		
Driver/Custodian:	CHEW MONG HOCK (64 / Male) , NRIC: S1167982Z, Tel: +6596362275 Email: NOEMAIL		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 10 March 2020 4:14 PM
To: janet@falconair.com.sg
Cc: SUR
Subject: ECICS OD SGU 1052A (DOA: 07/03/2020)

Dear Janet,

As spoken with you.

As instructed by our client, please proceed to repair the insured vehicle **SGU 1052A (Excess \$ 0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	09 Mar 2020 13:37	Cim Veh Model Changed	(201172) TOYOTA WISH 1.8 (A).	[R] Janet Lim
2	09 Mar 2020 13:37	Cim Created	Reg No: SGU1052A, Policy No: MPC19P00005900, Acct Date: 2020/03/07, Claim Type: OD, Insurer: ECIC S Limited (HQ), Workshop: Falcon-Air Auto Services Pte Ltd (Tampines), Created from SAS:MFA320029917	[R] Janet Lim
3	09 Mar 2020 14:01	Cim Submitted	4386.90.	[R] Joel Ng
4	09 Mar 2020 16:40	Cim Registration Modified	Excess: -> 750.00.	[I] Nicholas Chua
5	09 Mar 2020 16:43	Cim Registration Modified	Excess: 750.00 -> 0.00, Excess Waived: -> 750.00.	[I] Nicholas Chua
6	09 Mar 2020 16:43	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):: RR Region: ECICS EXT ADJ - OD/TP, Suggested Adj. : LKK Auto Consultants Pte Ltd.	[I] Nicholas Chua
7	09 Mar 2020 16:43	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2020/03/18	[I] Nicholas Chua
8	09 Mar 2020 16:43	Adj Mandate Set	Approved:0.00,Reinsp:Adj decides.	[I] Nicholas Chua
9	09 Mar 2020 17:07	Assignment 1st Accessed		[A] LEE SU THING
10	09 Mar 2020 17:16	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] LEE SU THING
11	10 Mar 2020 11:13	Adj Rpt Initiated		[A] SHIAU CHAN
12	10 Mar 2020 11:15	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2020/03/18	[A] SHIAU CHAN
13	10 Mar 2020 11:16	Adj Mandate Request	Cur,Req:3650,30:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL, THE VEHICLE REPAIR ON LUMP SUM BASIS, WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
14	10 Mar 2020 14:17	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2020/03/18	[I] Nicholas Chua
15	10 Mar 2020 14:17	Adj Mandate Set	Approved:3650.30.	[I] Nicholas Chua

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Billing Ref No	Billing Date	Billing Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2462397	09 Mar 2020 13:37:56	OD/TP Case (Repairer)	Motor	Falcon-Air Auto Services Pte Ltd	Falcon-Air Auto Services Pte Ltd (Tampines)	SGU1052A		xx.xx
2463582	10 Mar 2020 11:13:57	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SGU1052A		11.77

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elizabeth Chew Ming Lai

Date: 10 Mar 2020

Preliminary Advice

Vehicle No	: SGU1052A	Accident Date	: 07/03/2020
Make	: TOYOTA WISH	Policy No.	: MPC19P00005900
Assignment Date	: 09/03/2020	Excess	: S\$0.00
Date of Inspection	: 10/03/2020	Est. Duration of Repair	: 4.00
Inspection At	: FALCON-AIR AUTO SERVICES PTE LTD (TAMPINES) BLK 9006 #01-200 TAMPINES ST 93 SINGAPORE		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion & rear windscreen shattered and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,386.90
Revised Amount	:S\$	3,650.30
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,650.30

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	15,000.00
COE / PARF Rebate	:S\$	10,353.00
Salvage Value	:S\$	
Margin for Repair	:S\$	4,647.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	982Z
Vehicle Details	
Vehicle No.:	SGU1052A
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Mar 2020
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 A
Primary Colour:	Grey
Manufacturing Year:	2007
Engine No.:	1ZZ2894913
Chassis No.:	ZNE100363489
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$16,791.00
Original Registration Date:	02 May 2007
First Registration Date:	02 May 2007
Transfer Count:	2
Actual ARF Paid:	\$18,471.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$25,174.00
COE Rebate Amount:	\$10,353.00
Total Rebate Amount:	\$10,353.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 10 Mar 2020

OK

2018 Nissan Serena e-... Gear knob differences Petrol Price

wish Price Range Depreciation > 10 year(s) Vehicle Type

Home » Used Cars » Coche Motors Pte Ltd » Toyota Wish 1.8A (COE till 01/2022)

Toyota Wish 1.8A (COE till 01/2022)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price \$16,888

Depreciation ⓘ \$9,120 /yr

Mileage N.A.

Road Tax ⓘ \$1,264 /yr

Dereg Value ⓘ \$9,753 as of today (change)

COE ⓘ \$26,330

Engine Cap 1,794 cc

Curb Weight ⓘ 1,300 kg

Type of Vehicle MPV

Reg Date 16-Jan-2007
(1yr 10mths 5days COE left)

Manufactured ⓘ 2006

Transmission Auto

OMV ⓘ \$16,538

ARF ⓘ \$18,192

Power 97.0 kW (130 bhp)

No. of Owners ⓘ 4



Shortlist

Compare

Report Error

More Action

Features

Reliable, Powerful And Fuel Efficient 16 Valves 1.8L VVT-i DOHC Engine, Automatic Transmission, Digital Climate Control Aircon, Airbags, ABS.

Accessories

Leather Seats, Sports Rims, Solar Films, Reverse Sensors, Retractable Side Mirrors, In-Car Camera, Floor Mat, Window Visors.

Description

Own This Car With 100% Loan. Flawless Interior And Exterior Condition. Regularly Serviced And Maintained. Guaranteed Accident Free. Best For Short Term Usage. Viewing By Appointment Only. Trade In Welcome. Feel Free To Call Us For A Friendly Discussion.

Category

COE Car, Premium Ad Car

Status

Available

Re: [Compare](#)

https://www.sgcarMart.com/used_cars/info.php?ID=887680&DL=3521

Seller Information

Coche Motors Pte Ltd

51 vehicles for sale. 45 sold in past 3

📍 10 Kaki Bukit Avenue 4 #03-64
Premier @ Kaki Bukit
[Search cars nearby](#)

👤 Vernon Liang 98%
Zac 97%

New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Foru



wish Price Range Depreciation > 10 year(s) Vehicle Type

Home » Used Cars » Prime Motor & Leasing » Toyota Wish 1.8A Sunroof (COE till 04/2022)

Toyota Wish 1.8A Sunroof (COE till 04/2022)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map



PRIME MOTOR & LEASING



(CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES)

PRIME CAR RENTAL & TAXI SERVICES PTE LTD • SECTION CREDIT & MOTOR LEASING PTE LTD • BEST PETROL AND DIESEL SUPPLY PTE LTD • BEST ELECTRICITY SUPPLY PTE LTD

Price \$18,900

Depreciation \$8,910 /yr

Mileage N.A.

Road Tax \$1,264 /yr

Dereg Value \$11,029 as of today (change)

COE \$26,004

Engine Cap 1,794 cc

Curb Weight 1,320 kg

Type of Vehicle MPV

Reg Date 24-Apr-2007
(2yrs 1mth 13days COE left)

Manufactured 2006

Transmission Auto

OMV \$18,816

ARF \$20,698

Power 97.0 kW (130 bhp)

No. of Owners 3



Shortlist

Compare

Report Error

More Action

Seller Information

Prime Motor & Leasing

126 vehicles for sale. 75 sold in past

31 West Coast Highway Lot 19/20

West Coast Car Mart

Tel: 67782233

Search cars nearby

Bobby

86%

Danny

83%

Features

Airbags, ABS, Reliable 1.8L VVTI Engine, Digital Climate Control Aircon, Sunroof. View specs of the Toyota Wish (2008-2009)

Accessories

Leather Seats, Sports Rims, Audio System.

Description

Elegant Silver MPV, With Sunroof, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In-House Loan Packages Available.

Category

COE Car

Sta

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/03/2020 13:06
Date Of Accident	07/03/2020 22:30
Exact Location Of Accident	BLK232 TAMPINES STREET 21 CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGU1052A
Insured/Policyholder	
Name Of Registered Owner	CHEW MONG HOCK
NRIC No	SXXXX982Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96362275
Alternative Phone No	OTHERS-96362275

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MPC19P00005900
Cover Note Number	

Driver

Name of Driver	CHEW MONG HOCK
NRIC No	SXXXX982Z
Date Of Birth	16/01/1956
Occupation	INDOOR
Date Of Driving Pass	23/11/1974
Driving Experience	45 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96362275
Fax Number	
Contact Number	OTHERS-96362275
EMail Address	NOEMAIL

Address	BLK232 TAMPINES STREET 21 #07-647
Postcode	521232
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : LIN XUE JING GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident


AS PER SKETCH PLAN ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Sketch Plan Pg. 2

SKETCH PLAN



A-SEU1052A

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was reversing into the lot at Tempins St 21
blk 232 open carpark. I did not realise that
the tree was into the lot & thus collided into
the tree causing serious damage to the rear of
my vehicle

claim OD / TP at Falcon-Air claim OD / TP Own W/shop Reporting Only

DECLARATION

(We declare the foregoing particulars are true in every respect.)

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NIC/ID No.:

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: 913/2020

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

ward purpose!

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO CHECK LIGHT AND WIRING	New	50.00 20
2	TO REMOVE/REFIT INNER TRIMS AND GARNISHES	New	150.00 80
3	INSTALL REVERSE SENSOR	New	11 60.00 x
4	TRANSFER TAILGATE PARTS	New	100.00 60
5	INSTALL TAILGATE GLASS	New	120.00 ✓
6	LABOUR/PANEL BEATING- REPAIR END PANEL	New	600.00 550
7	TO PUTTY AND RESPRAY	New	700.00 600
8	TRANSFER REAR VIEW CAMERA	New	11 120.00 x
Gross Labour Cost (\$)			1,900.00

Falcon-Air Auto Services Pte Ltd/SGU1052A/09/03/2020 14:01. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

FALCON-AIR AUTO SERVICES PTE LTD

(Incorporated in Singapore)

Head Office: Blk 178 Sin Ming Drive #01-02/03/13, #05-17 Sin Ming Avenue S(575721) Tel: 6452-0980 / 6458-0880 Fax: 6454-7638
Branches: Tompines S(63) Blk 5000 #31-02/3 S(628340) Tel: 6780-7007 Fax: 6780-7057 • No 8 Pandan Loop S(128220) Tel: 0779-5555 Fax: 0770-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



FALCON-AIR

FALCON - AIR AUTO SERVICES PTE LTD

CO. REG. No.: 1995-01140-D

INSURER: **ECICS Limited (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC19P00005900	Date of Loss:	07/03/2020
Vehicle Reg. No.:	SGU1052A	Driveable?	
Driver Age/Info:	64 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	NO
Insured/Claimant:	CHEW MONG HOCK	Contact No:	+6596362275
Driver:	CHEW MONG HOCK		

Make/Model:	TOYOTA WISH, 1.8 (A)	Vehicle Reg. Date:	02/05/2007
Vehicle Colour:	SILVER		
Engine No:	1ZZ2894913	Chassis No:	ZNE100363489
Odometer:	200000 KM		

Paint Type:
Total Loss? **NO**
Est. Duration of Repair (day) **6**

Description of Accident/Loss: **AS PER SKETCH PLAN ATTACH.**
Remarks: **VEHICLE IN WORKSHOP**

Present Location: **FALCON-AIR AUTO SERVICES PTE LTD (TAMPINES)**

Not Approved
2/5 @ 2900
4 days
Take photo after repair
Excess ?

COST OF CLAIMS

	Amount
Parts	2,486.90
Miscellaneous Items	0.00
Labour	1,900.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	4,386.90
+ GST 7.00% (\$\$)	307.08
Nett Amount (\$\$)	4,693.98

LINK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No alterations/modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

This claim is handled by: **JOEL NG**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Mar 2020)
 Parts: M1-MPV TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Falcon-Air Auto Services Pte Ltd/SGU1052A/09/03/2020 14:01
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER <i>2D</i>	0.00	0.00	*245.00F ✓
2	2		*REAR BUMPER SIDE RETAINER <i>17</i>	0.00	0.00	*56.00F X
3	1		*REAR BUMPER CLIPS <i>see</i> <i>SIN</i>	0	0.00	*25.00FS ✓
4	1		*TAILGATE <i>3-dg</i>	0.00	0.00	*480.00F ✓
5	1		*TAILGATE TRIM BOARD <i>winged for</i>	0.00	0.00	*250.00F ✓
6	1		*TAILGATE GLASS <i>slatted</i>	0.00	0.00	*550.00F ✓
7	1		*TAILGATE GLASS MOULDING <i>see</i>	0.00	0.00	*60.00F ✓
8	1		*TAILGATE GLASS SEALANT <i>see</i> <i>SIN</i>	0	0.00	*40.00FS ✓
9	1		*TAILGATE LOGO <i>see</i>	0.00	0.00	*28.00F ✓
10	1		*TAILGATE CHROME GARNISH <i>see/see</i>	0.00	0.00	*175.00F ✓
11	1		*REVERSE SENSOR <i>17</i>	0	0.00	*200.00FS X
12	1		*REAR NO PLATE <i>see/see</i>	0	0.00	*45.00FS <i>40</i>
13	1		*TAILGATE RUBBER <i>17</i>	0.00	0.00	*135.00F ✓

F=Franchise part. S=SpcNett.

Sub Total (S\$)	2,289.00
+ Margin on L,N Items 10.00% (S\$)	197.90
Total Parts (S\$)	2,486.90

Falcon-Air Auto Services Pte Ltd/SGU1052A/09/03/2020 14:01. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

P. 1923
10%
P-2115.30
S.N-105.00
L-140.00

3650.30
277

2820.

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO CHECK LIGHT AND WIRING	New	50.00 20
2	TO REMOVE/REFIT INNER TRIMS AND GARNISHES	New	150.00 80
3	INSTALL REVERSE SENSOR	New	1 1 60.00 x
4	TRANSFER TAILGATE PARTS	New	100.00 60
5	INSTALL TAILGATE GLASS	New	120.00 ✓
6	LABOUR/PANEL BEATING- REPAIR END PANEL	New	600.00 550
7	TO PUTTY AND RESPRAY	New	700.00 600
8	TRANSFER REAR VIEW CAMERA	New	1 1 120.00 x
Gross Labour Cost (S\$)			1,900.00

Falcon-Air Auto Services Pte Ltd/SGU1052A/09/03/2020 14:01. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7882
Branches : Tampines St 93 Blk 9006 #01-000 S(528840) Tel: 6783-7997 Fax: 6786-7997 • No 8 Pandan Loop S(128226) Tel: 6779-5655 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Mar 2020 13:40 Sendback Est	09 Mar 2020 14:01 S\$4,386.90	09 Mar 2020 16:43 Edit Adj Rpt	S\$2,900.00 Edit Estimates	S\$2,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	CHEW MONG HOCK , ID: S1167982Z, Tel: +6596362275, Email: NOEMAIL								
Vehicle Reg. No.:	SGU1052A	Date of Loss:	07/03/2020 22:00 - :59 [154 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / DMPC2000053H/EC	Policy/Cover Note No.:	MPC19P00005900 (Comprehensive)						
		Excess:	S\$0.00						
Repairer:	Falcon-Air Auto Services Pte Ltd (Tampines) Blk 9006 #01-200 Tampines St 93, Tampines - Tel: 67897997								
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Elizabeth Chew Ming Lai]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 18/03/2020]								
Driver/Custodian:	CHEW MONG HOCK (64 / Male) , NRIC: S1167982Z, Tel: +6596362275 Email: NOEMAIL								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• ECICS (10/03/2020): Alert - Adj Mandate Approved (S\$3650.30) - SGU1052A - Claim Handler: Elizabeth C...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SGU1052A (DMPC2000053H/EC)
 OD
 Mar 7 2020 10:00PM
 [CHEW MONG HOCK]
 Falcon-Air Auto Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View	View in Browser <input type="button" value="v"/>
Assessment Reports			1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Tampines)		Thumbnail Print
1	09/03/20 14:01	Repairer Estimates	1	Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	10/03/20 11:15	Adjuster Immediate Advice	1	Load HTM
Photos/Images			3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	10/03/20 15:32	Chassis Number	1	Load JPG <input checked="" type="checkbox"/>
2	10/03/20 15:32	Odometer Reading	1	Load JPG <input checked="" type="checkbox"/>
3	10/03/20 15:33	General View	1	Load JPG <input checked="" type="checkbox"/>
4	10/03/20 15:33	General View	1	Load JPG <input checked="" type="checkbox"/>
5	10/03/20 15:33	General View	1	Load JPG <input checked="" type="checkbox"/>
6	10/03/20 15:33	General View	1	Load JPG <input checked="" type="checkbox"/>
7	10/03/20 15:33	General View	1	Load JPG <input checked="" type="checkbox"/>
8	10/03/20 15:33	General View	1	Load JPG <input checked="" type="checkbox"/>
9	10/03/20 15:33	General View	1	Load JPG <input checked="" type="checkbox"/>
10	10/03/20 15:33	General View	1	Load JPG <input checked="" type="checkbox"/>
11	10/03/20 15:33	General View	1	Load JPG <input checked="" type="checkbox"/>
12	10/03/20 15:33	General View	1	Load JPG <input checked="" type="checkbox"/>
13	10/03/20 15:33	General View	1	Load JPG <input checked="" type="checkbox"/>
14	10/03/20 15:33	General View	1	Load JPG <input checked="" type="checkbox"/>
15	10/03/20 15:33	General View	1	Load JPG <input checked="" type="checkbox"/>
16	10/03/20 15:33	General View	1	Load JPG <input checked="" type="checkbox"/>
17	10/03/20 15:33	General View	1	Load JPG <input checked="" type="checkbox"/>
18	10/03/20 15:33	General View	1	Load JPG <input checked="" type="checkbox"/>
19	10/03/20 15:33	General View	1	Load JPG <input checked="" type="checkbox"/>
20	10/03/20 15:33	General View	1	Load JPG <input checked="" type="checkbox"/>
21	10/03/20 15:33	General View	1	Load JPG <input checked="" type="checkbox"/>
22	10/03/20 15:33	General View	1	Load JPG <input checked="" type="checkbox"/>
23	10/03/20 15:33	General View	1	Load JPG <input checked="" type="checkbox"/>
24	10/03/20 15:33	General View	1	Load JPG <input checked="" type="checkbox"/>
25	10/03/20 15:33	General View	1	Load JPG <input checked="" type="checkbox"/>
26	10/03/20 15:33	General View	1	Load JPG <input checked="" type="checkbox"/>
27	10/03/20 15:33	General View	1	Load JPG <input checked="" type="checkbox"/>
28	10/03/20 15:33	General View	1	Load JPG <input checked="" type="checkbox"/>
29	10/03/20 15:33	General View	1	Load JPG <input checked="" type="checkbox"/>
30	10/03/20 15:33	General View	1	Load JPG <input checked="" type="checkbox"/>
31	10/03/20 15:33	General View	1	Load JPG <input checked="" type="checkbox"/>
32	10/03/20 15:33	General View	1	Load JPG <input checked="" type="checkbox"/>
33	10/03/20 15:33	General View	1	Load JPG <input checked="" type="checkbox"/>
34	10/03/20 15:33	General View	1	Load JPG <input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Tampines)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	10/03/20 15:33	General View	Load JPG	<input checked="" type="checkbox"/>
36	10/03/20 15:33	General View	Load JPG	<input checked="" type="checkbox"/>
37	10/03/20 15:33	General View	Load JPG	<input checked="" type="checkbox"/>
38	10/03/20 15:33	General View	Load JPG	<input checked="" type="checkbox"/>
39	10/03/20 15:33	General View	Load JPG	<input checked="" type="checkbox"/>
40	10/03/20 15:33	General View	Load JPG	<input checked="" type="checkbox"/>
41	10/03/20 15:33	General View	Load JPG	<input checked="" type="checkbox"/>
42	10/03/20 15:33	General View	Load JPG	<input checked="" type="checkbox"/>
43	10/03/20 15:33	General View	Load JPG	<input checked="" type="checkbox"/>
44	10/03/20 15:33	General View	Load JPG	<input checked="" type="checkbox"/>
45	10/03/20 15:33	General View	Load JPG	<input checked="" type="checkbox"/>
46	10/03/20 15:33	General View	Load JPG	<input checked="" type="checkbox"/>
47	10/03/20 15:33	General View	Load JPG	<input checked="" type="checkbox"/>
48	10/03/20 15:33	General View	Load JPG	<input checked="" type="checkbox"/>
49	10/03/20 15:33	General View	Load JPG	<input checked="" type="checkbox"/>
50	10/03/20 15:33	General View	Load JPG	<input checked="" type="checkbox"/>
51	10/03/20 15:33	General View	Load JPG	<input checked="" type="checkbox"/>
52	10/03/20 15:33	General View	Load JPG	<input checked="" type="checkbox"/>
53	10/03/20 15:33	General View	Load JPG	<input checked="" type="checkbox"/>
54	13/03/20 08:06	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
55	13/03/20 08:06	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
56	13/03/20 08:06	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
57	13/03/20 08:06	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
58	13/03/20 08:06	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
59	13/03/20 08:06	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/03/20 11:10	ESTIMATE	Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Tampines)	Thumbnail	Print
1	09/03/20 13:12	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Tampines)	Thumbnail	Print
1	09/03/20 13:10	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	09/03/20 13:10	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	09/03/20 13:10	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	09/03/20 13:10	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	09/03/20 13:10	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	09/03/20 13:10	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	09/03/20 13:11	Identification Card	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Tampines)	Thumbnail	Print
1	09/03/20 13:12	Sketch Plan	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS20003768/UQF3E2

Date: 17/03/2020

REFERENCE

Insured/Claimant: CHEW MONG HOCK Policy No: MPC19P00005900
Date of Loss: 07/03/2020 Nature of Claim: OD Claim No: DMPC2000053H/EC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGU1052A**
Make & Model: TOYOTA WISH, 1.8 (A) Engine No: 1ZZ2894913
Reg. Date: 02/05/2007 (Man. Year: 2007) Chassis No: ZNE100363489
Colour: Grey Odometer: 183558 km
Engine Capacity: 1794 cc
Market Value/New Car Price: S\$15,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,486.90	2,220.30	266.60	10.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,900.00	1,430.00	470.00	24.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,386.90	3,650.30	736.60	16.79
Approved Total (Overridden) (S\$)		2,900.00		
(S\$)	4,386.90	2,900.00	1,486.90	33.89
+ GST 7.00/7.00% (S\$)	307.08	203.00	104.08	33.89
Nett Amount (S\$)	4,693.98	3,103.00	1,590.98	33.89

INSPECTION

Date of Assignment: 09/03/2020 Present Location: Falcon-Air Auto Services Pte Ltd (Tampines)
Date Inspected: 10/03/2020 Inspected At: Falcon-Air Auto Services Pte Ltd (Tampines)
Blk 9006 #01-200 Tampines St 93 Singapore 528840
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Mar 2020)
Parts: M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGU1052A)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	245.00 F	*245.00 F
2	2		*REAR BUMPER SIDE RETAINER	Not Necessary	56.00 F	*. F
3	1		*REAR BUMPER CLIPS	Necessary	25.00 FS	*25.00 FS
4	1		*TAILGATE	Badly Dented	480.00 F	*480.00 F
5	1		*TAILGATE TRIM BOARD	Warped / Deformed	250.00 F	*250.00 F
6	1		*TAILGATE GLASS	Shattered	550.00 F	*550.00 F
7	1		*TAILGATE GLASS MOULDING	Necessary	60.00 F	*60.00 F
8	1		*TAILGATE GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
9	1		*TAILGATE LOGO	Necessary	28.00 F	*28.00 F
10	1		*TAILGATE CHROME GARNISH	Bent / Smashed	175.00 F	*175.00 F
11	1		*REVERSE SENSOR	Not Necessary	200.00 FS	*. FS
12	1		*REAR NO PLATE	Scratched / Bent	45.00 FS	*40.00 FS
13	1		*TAILGATE RUBBER	Twisted	135.00 F	*135.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	2,289.00	2,028.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	197.90	192.30
Total Parts (\$\$)	2,486.90	2,220.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK LIGHT AND WIRING	New	50.00	20.00
2	TO REMOVE/REFIT INNER TRIMS AND GARNISHES	New	150.00	80.00
3	INSTALL REVERSE SENSOR	New	60.00	0.00
4	TRANSFER TAILGATE PARTS	New	100.00	60.00
5	INSTALL TAILGATE GLASS	New	120.00	120.00
6	LABOUR/PANEL BEATING- REPAIR END PANEL	New	600.00	550.00
7	TO PUTTY AND RESPRAY	New	700.00	600.00
8	TRANSFER REAR VIEW CAMERA	New	120.00	0.00
Gross Labour Cost (S\$)			1,900.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >