



Your Ref : C10005761

Date: 19<sup>th</sup> March 2020

Our Ref : CS/AGI20003769/R1qd3s2

**M/s Auto & General Insurance (Singapore) Pte Ltd**

(Budget Direct Insurance)  
190 Clemenceau Avenue #03-01  
Singapore Shopping Centre  
Singapore 239924  
(The Motor Claims Department)

Dear Sir / Madam,

**INSPECTION REPORT OF BICYCLE  
INSURED VEHICLE: SLU 1532Y  
ACCIDENT DATE: 01/03/2020**

(a)The bicycle sustained extensive damages, which had included its frame. (Details see photographs enclosed)

(b)We submit herewith our recommendation below:

<u>Qty</u>	<u>Description of Parts</u>	<u>Condition</u>	<u>Recommendation</u>
1	Shimano Dura – Ace 9000 c35 }	Cracked	\$3,000.00
2	Turbular Road Bike Wheelset }		
3	Assioma Duo (Power Meter Pedal)	Scratched	\$1,000.00
4	Carbon Handle Bar	Cracked	\$ 220.00
5	Giant propel Advanced 1 2017 Bicycle		\$2,600.00
		<b>Total:</b>	<u>\$6,820.00</u>



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

(c) Value of Bicycle \$6,820.00

Applying 15% depreciation as this is a used bicycle \$5,797.00

Our opinion on the reasonable value of the bicycle at the time of loss is \$5,800.00.

(SIN DOLLARS: Five Thousand Eight Hundred Only)

Vehicle Inspected By:

MRB

MOHD. RASUL BIN MOHD YUNUS

AMSOE, AMIRTE, AMSAE-A, M. MATAI

Automotive Assessor

K.K. LAU

MSd(Eng M), B Eng(Hons), Peng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),  
AM CATARI(CAN), M. MATA(USA), M. MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.