



Scope Of Work
Home Team Agency

SCOPE OF WORK

1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

CONTRACTOR :	SMRT	VEH TYPE :	UNMARKED	UNIT :	CNB SUP 'J'	Reference No.	1117/CNB/4W/20/02/01
VEH NO :	QX1117M / SLA2078R	REPAIR TYPE:	ACCIDENT				
VEH MAKE/MODEL:	CHEVROLET CRUZ	ODOMETER :	79331				
						iLMS No.	-

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)
1	Scope Of Repairs					
1.1	Rear Bumper	\$1,950.00	1	21%	2359.50	2359.50
1.2	Rear RH Bumper Retainer	\$55.00	1	21%	66.55	66.55
1.3	Rear RH Bumper Chrome Trim	\$75.00	1	21%	90.75	90.75
1.4	Rear Number Plate	\$50.00	1	21%	60.50	60.50
2	Additional Services					
2.1	NA	\$0.00	0	0%	0.00	0.00
Remarks:		Item 1.1 requires Overseas Indentment. ETA:- 8-10 weeks after confirmation of quotation			Parts Total:	\$ 2,577.30

S/N	LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour Qty	Total Man-Hour Cost (\$)
1	Scope Of Repairs			
1.1	Remove, Replace & Spray Paint for Rear Complete Bumper including replacing Rear RH Bumper Retainer, Rear RH Bumper Chrome Trim & Rear Number Plate	68.00	6	408.00
		SUB-TOTAL	6	408.00
2	Additional Services			
2.1	Towing Service From Station to Workshop (SOR 9)	176.80	1	176.80
2.2	Return Service From Workshop to Station (SOR 9)	61.20	1	61.20
		SUB-TOTAL	2	238.00
		Labour Total:	\$	646.00
		GRAND TOTAL :	\$	3,223.30
		Total sum billed under SOR only :	\$	238.00
		Total sum billed under CVR only :	\$	2,985.30
Contractor shall complete the entire repair within <u>85</u> working days upon approval date . (Include parts awaiting time)				

Verification of Scope of Work					
Contractor QC		Vetted By:		Approved By:	
Name:	KONG SEW KUI	Name:		Name:	
Date:	24.02.2020	Date:		Date:	
Sign:		Sign:		Sign:	

Verification of Completed Repairs					
Contractor QC		Home Team QC / Fleet Manager / Appointed Surveyor		Home Team Contract / Fleet Manager	
Name:		Name:		Name:	
Date:		Date:		Date:	
Sign:		Sign:		Sign:	

All completed repairs must be verified by Home Team Contract Manager / Fleet Manager before payment can be made

