

ASS. REC. BY:

REF: C1/TPO 20003783/Nq

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): Kamariah Kamis of SPF Date/Time: 06/03/2020

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBH 1556R Insured: _____

at Workshop m/s _____ Tel: _____

Policy No: MMHASP/06000034923/1 Claim No: TP/IP/66691/2019

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 27/10/19
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN/OUT _____

[illegible]

Sherwin Beh (LKK Auto)

From: Kamaliah KAMIS (SPF) <Kamaliah_KAMIS@spf.gov.sg>
Sent: Friday, 6 March, 2020 7:42 AM
To: Sherwin Beh (LKK Auto); Naz (LKKAUTO)
Cc: Bryan Ang (LKKAUTO)
Subject: Mechanical Inspection Report Request

Dear Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the 2 vehicles below on an urgent basis as the court mention will be in early April 2020:

- X a) **Case IAFP-IB-20200303 - Mechanical Inspection of Motorcycle, FBH1556R (TP/IP/66691/2019)** - *GC*
[DELAYED AS BOTH VEHICLES JUST RETURNED FROM HSA COMPOUND] - *WA*
b) **Case IAFP-IB-20200303 - Mechanical Inspection of Motor Car, SLP1145H (TP/IP/66691/2019)**

On 27 October 2019 (Sunday) at about 1.12 p.m., based on a video footage retrieved from the 2nd Involved Party's in-vehicle camera, the 2nd Involved Party was travelling straight along TPE (PIE) 9 km, on lane 1 of the 3-lanes road. Moments later, the 1st Involved Party was seen switching from lane 2 into lane 1, encroaching into the 2nd Involved Party's path. The 1st Involved Party was observed to be less than half a motor car's length away when he had switched lanes. The 2nd Involved Party was seen applying the brakes however, the front portion of the 2nd Involved Party's motor car collided onto the rear of the 1st Involved Party's motorcycle. As a result of the accident, the 1st Involved Party and the pillion (Deceased) were flung off from the motorcycle. The 1st Involved Party and the pillion (Deceased) were conveyed by ambulance to Changi General Hospital however, the Deceased succumbed to her injuries and was pronounced dead by Dr Lim Chung Thien Adrian in hospital, on the same day at 2.07 p.m.

Vehicles to be inspected: **FBH1556R** - Rider (Potential Defendant)
SLP1145H - Driver (Involved Party)

IO In-Charge: SIO Kamaliah

2. These request has been approved by my management.

3. Thank you Sirs.

- Help me open reference.

Best regards,

Kamaliah Kamis (Miss)
Senior Investigation Officer | Fatal Accident Investigation Team
Traffic Police Department | Singapore Police Force
DID: (65) 6547 6435 | FAX: (65) 6547 6352

- Naz



Singapore Police Force – Commemorating 200 Years of Policing

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."