

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____ **After-Paint:** _____
 Contacts : _____

Vehicle Nos : **SMF 539 C**
 Model : LEXUS ES250
 Year : _____
 Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	HEADLAMP RH	1	\$ 3,702.20	\$ 2550.00 3,702.20
2	HEADLAMP LOWER BRACKET RH	1	\$ 230.00	\$ 230.00
3	FRONT BUMPER	1	\$ 1,046.20	\$ 847.30 1,046.20
4	FRONT BUMPER RETAINER	2	\$ 86.30	\$ 127.26 172.60
5	FRONT BUMPER SIDE GARNISH RH	1	\$ 222.70	\$ ✓ 222.70
6	FRONT BUMPER FOG SIDE CHROME MOULDING RH	1	\$ 210.00	\$ ✓ 210.00
7	FRONT BUMPER SENSOR RH	1	\$ 488.00	\$ 300.00 488.00
8	FRONT FENDER RH	1	\$ 1,617.00	\$ 1,617.00
Parts Sub Total :				\$ 4257.26 7,688.70
Discount 10% :				\$ 425.73 768.87
PARTS TOTAL :				\$ 3831.53 6,919.83

CUTV ✓
 NSX
 CUTV ✓
 NECV
 CUTV ✓
 DLV ✓
 NDX

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	SUNDRIES	1	\$ 80.00	\$ 80.00
2	FRONT BUMPER CLIPS	1	\$ 60.00	\$ 30.00 60.00
3	FRONT FENDER SEALANT	1	\$ 100.00	\$ 100.00
4	FRONT FENDER INNER SHEILD CLIPS	1	\$ 60.00	\$ 60.00
SPECIAL NETT TOTAL :				\$ 30.00 300.00

NNX
 NEC ✓
 NNX
 NNX

Nos.	LABOUR	S\$
1	PANEL BEATING	\$ 400.00 800.00
2	R&R FRONT BUMPER SENSOR	\$ 60.00 150.00
3	SPRAY PAINTING	\$ 400.00 800.00
4	CHECK WIRING	\$ 30.00 80.00
5	TO RESET AND REPROGRAMME FAULT CODE	\$ 80.00 200.00
LABOUR TOTAL :		\$ 980.00 2,030.00

✓
 ✓
 ✓
 ✓
 ✓

Survey
 13/3/2020
 1500 hrs
 T. Lim
 Min

Resurvey
 23/3/2020
 1615 hrs
 T. Lim
 Min

Lump sum Repair
 Repair days 4
 4/3 3,850/2

PARTS TOTAL : \$3831.53 6,919.83
 SPECIAL NETT TOTAL : \$ 30.00 300.00
 LABOUR TOTAL : \$ 980.00 2,030.00
 GRAND TOTAL : \$ 4,841.53
 968.31
 3873.22

@ 20%

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: