

ASS. REC. BY:

REF: CS/U01 20003830/Atfs Special Instruction:

Surveyor: Adnan

ASSIGNMENT (Office)

From (Person): Josephine Wong of UOI Date/Time: 10.3.2020 4.06p.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBD 8130K Insured: _____at Workshop m/s Joo Hak Kee Tel: 67431913of B1 3007 Ubi road 1 #01-406Policy No: _____ Claim No: M11D09692003Sum Insured: _____ Excess: \$500.00Make of Veh: _____ D.O.A. 22.2.2020
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 10.3.2020 4.24p.m Person Contacted: Shimin H.O.D. Endorsement: _____Vehicle IN / OUT

Date/Time	Action/Instruction (V) Estimate
	GBD 8130K - M11D09692003/13 D.O.A - 22/02/2020
11/3/2020	offer lump sum \$9500/-
12/3/2020	Revert email, repairer willing under take \$10K
12/3/2020	2.10pm - inform by Josephine Wong authorise repair.
13/3/2020	inform repairer 2.16pm and authorise repair. excess \$500/-
	10K whichever lower

ASS. REC. BY:

REF: U01

ASSIGNMENT

From: _____ Date: 11-3-2020

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBD 8130K

at Workshop m/s Joo Hak Kee

of Bit 3007 ubi road 1 #01-406

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: \$500.00

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBD8130K Yr Regn: 2015, May
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Nissan NV200 c.c 1461

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 66213 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VSICYBAM2020100904

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185 R14C

R: 185 R14C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Giti

Front

R/Bal. 06 mm

L/Bal. 06 mm

D.O.A. _____

Survey held at JHK.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

OD U01

Lump Sum \$10,000/- (Ref: 6114 611: 33%)

Red: 9602.14; 48%

MV: 32k

PV: 21.4K

Net: 10.6K

Date/Time, File Pass to?

1) 15/4 Typist

Date/Time, File Return to?

2) _____

Rep. Format: OD

Lump Sum / B.I. / 10,000/-

Days Of Repair: 8

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL