

ASS. REC. BY:

REF: CS/TMI 2000 3846/Ref 302

Special Instruction:

Surveyor: ROMASSIGNMENT (Office)From (Person): Jeffrey Tay of TMI Date/Time: 11.5.2020 8.55 a.m.

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHA 1405J Insured: SMK 425Xat Workshop m/s Comforadelgro Tel: 62148300of 59 loyang drivePolicy No: MX 000848 Claim No: M 2001806

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 9-3-2020
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 11/3/2020 9.21 a.m. Person Contacted: Junani H.O.D. Endorsement: _____Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHA 1405J - (C4) 11/70087049/ UNW/3/1/2 DOC - 22/04/2021
	SMK 425X - X
11/03/20	@ 15:52 pm revised PA to Jeffrey via verimur

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Act Assigned	Act Wgt	Act Submitted	Ins Auth'd	Status
Main	10 Mar 2020 Sendback Est	10 Mar 2020 18:06 S\$1,948.02	11 Mar 2020 08:55 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	COMFORT LIMOUSINE SERVICES PTE LTD, Co. Reg. No.: 201508380W		
Main Claimant:	CTPL		
Vehicle Reg. No.:	SHA1405J	Date of Loss:	09/03/2020 14:00 - :59 [24 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M2001806	Policy/Cover Note No.:	MK000848 (Comprehensive) Coverage: 15/10/2019 - 14/10/2020
Vehicle Reg. No. (Insured):	SMK425X	Policy No. (Claimant):	
		Excess:	S\$1,800.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Jeffrey Tay - 65926413]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 20/03/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

821R

Vehicle Details

Vehicle No.:

SHA1405J

Vehicle to be Exported:

No

Intended Deregistration Date:

10 Mar 2020

Vehicle Make:

HYUNDAI

Vehicle Model:

AE IONIQ HEV 1.6 DCT

Primary Colour:

Blue

Manufacturing Year:

2018

Engine No.:

G4LEJU080166

Chassis No.:

KMHC851CVKU107336

Maximum Power Output:

103.6 kW (138 bhp)

Open Market Value:

\$24,785.00

Original Registration Date:

03 Sep 2018

First Registration Date:

03 Sep 2018

Transfer Count:

0

Actual ARF Paid:

\$11,699.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

02 Sep 2026

PARF Rebate Amount:

\$8,774.00

Intended COE Rebate Details

COE Expiry Date:

02 Sep 2026

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

8

PQP Paid:

\$25,872.00

COE Rebate Amount:

\$20,952.00

Total Rebate Amount:

\$29,726.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 10 Mar 2020

OK

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd
20 McCallum Street
#09-01 Tokio Marine Centre
Singapore 069046

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jeffrey Tay

Date: 11 Mar 2020

Preliminary Advice

Insured Vehicle No	: SMK425X		
TP Vehicle No	: SHA1405J	Accident Date	: 09/03/2020
Make	: HYUNDAI IONIQ HYBRID	Assignment Date	: 11/03/2020
Date of Inspection	: 10/03/2020	Est. Duration of Repair	: 2 days
Inspection At	: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,948.02
Revised Amount	:S\$	1,387.12
Check Items (Estimated)	:S\$	135.70
Total	:S\$	1,552.82

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP ; WP

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/03/2020 13:42
Date Of Accident	09/03/2020 14:45
Exact Location Of Accident	WOODLANDS SQUARE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA1405J
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	1XXXXX821R
Email Address	FLEETSAFETY@CDGETAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	IONIQ

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

Driver

Name of Driver	PHUA PUE HOE
NRIC No	SXXXX948G
Date Of Birth	25/03/1960
Occupation	OUTDOOR
Date Of Driving Pass	24/08/1983
Driving Experience	36 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94566633
Fax Number	
Contact Number	
Email Address	EDMUNDPHUA138@GMAIL.COM

Address	BLK 272B SENGKANG CENTRAL #08-319
Postcode	542272
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMK425X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MR YAP
NRIC/Passport Number	
Contact Number	97105763
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRONT
No. Of Passenger (Including Driver)	

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT INDUSTRIES INC. NEW YORK NY LTD
CO. REG. NO. 38679246

Policyholder's Signature
Date & Time:

Driver's Signature _____
 (If driver is not the policyholder)
 Date & Time: _____

Reporting Centre Personnel's Signature
Name:
NBIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 9 March 2020 @ 14:45 hrs I, VEH (A)

slow down at stop @ the Traffic Junction

few seconds later VEH (B) from the Rear

hit VEH (A) Rear @ the point of

accident - VEH (A) no pain.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMPACT 1117-1117-1117-1117-1117

1117-1117-1117-1117-1117

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.

Tyre Brand :

DAVANTI
15165219

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Tokro Wayne CP(P)
LKK - Ram

Date: 10.03.2020

Time: 14:24:31

Page: 1

12 IS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305386536
REGN NO : SHA1405J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 03.09.2018
DATE/TIME IN : 10.03.2020 13:00
ACCIDENT DATE : 09.03.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	REAR BUMPER	1	459.40	20.00	367.52	CRV DEF
0002	04-01-0104-2533-G	REAR BUMPER CENTRE-Black	1	451.25	20.00	361.00	DEF
0003	04-01-0104-2370-G	REAR BUMPER FOGLAMP	1	201.50	20.00	161.20	XUN
0004	04-01-0104-2545-G	REAR BUMPER LWR MOULDING	1	155.00	20.00	124.00	XUN
0005	04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60	NEC
0006	09-01-9999-0068-A	REVERSE SENSOR	1	135.70	200	135.70	XUN
0007	04-01-0104-1150-A	REAR BUMPER MAT	1	50.00	200	50.00	NEC

SUB-TOTAL : 1,217.02

JOB NATURE

0000	PB	PANEL BEATING	350.00	\$370
0001	SP	SPRAYPAINT CHARGE	250.00	\$260
0002	L	R/I REVERSE SENSOR	120.00	\$60
0003	20-05	TP MERIMEN	11.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

11/3/2020

Ram (LKK)
10/3/2020 1515
Parasuram@lkkauto.com
88622779
Ref paint photo
2 repair days

COMFORTDELGRO ENGINEERING PTE LTD

Date: 10.03.2020

REPAIR ESTIMATE

Tokio Marine (P/P)
LKK - Ram

Time: 14:24:31

Page: 2

JS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305386536
REGN NO : SHA1405J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 03.09.2018
DATE/TIME IN : 10.03.2020 13:0
ACCIDENT DATE : 09.03.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 731.00

TOTAL : 1,948.02

MVA NAME & SIGNATURE
DATE :

Long

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

COMFORTDELGRO ENGINEERING

Our Job Ref No 305386536

Date : 12/03/20

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : RAM

Vehicle Reg No. : SHA1405J

Date of Accident : 09-Mar-20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE --- SMK 425X

2. The finalized amount shall be:

(a) Spare Parts after List discount

\$796.12

(b) Labour Charges

\$590.00

Total for Part-By-Part Repair Cost

\$1,387.12

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

Final Lumpsum Repair cost

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Signature : 

Name : LIM T S

Name : RAM

Tel : 62148398

Date : 13/03/2020

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	-----			
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305386536
 REGN NO : SHA1405J
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 03.09.2018
 DATE/TIME IN : 10.03.2020 13:00
 ACCIDENT DATE : 09.03.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	REAR BUMPER	1	459.40	20.00	367.52	net
0002 04-01-0104-2533-G	REAR BUMPER CENTRE-Black	1	451.25	20.00	361.00	net
0003 04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60	net
0004 04-01-0104-1150-A	REAR BUMPER MAT	1	50.00		50.00	net

SUB-TOTAL : 796.12

JOB NATURE

0000 PB	PANEL BEATING	320.00
0001 SP	SPRAYPAINT CHARGE	200.00
0002 L	R/I REVERSE SENSOR	60.00
0003 20-05	TP MERIMEN	11.00

SUB-TOTAL : 591.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305386536
REGN NO : SHA1405J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 03.09.2018
DATE/TIME IN : 10.03.2020 13:0
ACCIDENT DATE : 09.03.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,387.12


MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :
AUTHORISED : YES / NO

...CLAIM SUBFOLDER...(Pending for Survey Report)















CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Mar 2020 Sendback Est	10 Mar 2020 18:06 S\$1,948.02	11 Mar 2020 08:55 Edit Adj Rpt	S\$1,387.12 Edit Estimates	S\$1,387.12 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	COMFORT LIMOUSINE SERVICES PTE LTD, Co. Reg. No.: 201508380W								
Main Claimant:	CTPL								
Vehicle Reg. No.:	SHA1405J	Date of Loss:	09/03/2020 14:00 - :59 [18 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / M2001806	Policy/Cover Note No.:	MK000848 (Comprehensive) Coverage: 15/10/2019 - 14/10/2020						
Vehicle Reg. No. (Insured):	SMK425X	Policy No. (Claimant):							
		Excess:	S\$1,800.00						
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Jeffrey Tay - 65926413]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 20/03/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SHA1405J (M2001806)
[SMK425X]
TP
CTPL
Mar 9 2020 2:00PM
[COMFORT LIMOUSINE SERVICES PTE LTD]
ComfortDelGro Engineering Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)							Thumbnail	Print	
1	10/03/20 18:06	Repairer Estimates								Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	11/03/20 15:56	Adjuster Immediate Advice								Load HTM	
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	13/03/20 09:58	General View								Load JPG	<input checked="" type="checkbox"/>
2	13/03/20 09:58	General View								Load JPG	<input checked="" type="checkbox"/>
3	13/03/20 09:58	General View								Load JPG	<input checked="" type="checkbox"/>
4	13/03/20 09:58	General View								Load JPG	<input checked="" type="checkbox"/>
5	13/03/20 09:58	General View								Load JPG	<input checked="" type="checkbox"/>
6	13/03/20 09:58	General View								Load JPG	<input checked="" type="checkbox"/>
7	13/03/20 09:58	General View								Load JPG	<input checked="" type="checkbox"/>
8	13/03/20 09:58	General View								Load JPG	<input checked="" type="checkbox"/>
9	13/03/20 09:58	General View								Load JPG	<input checked="" type="checkbox"/>
10	13/03/20 09:58	General View								Load JPG	<input checked="" type="checkbox"/>
11	13/03/20 09:58	General View								Load JPG	<input checked="" type="checkbox"/>
12	13/03/20 09:58	General View								Load JPG	<input checked="" type="checkbox"/>
13	13/03/20 09:58	General View								Load JPG	<input checked="" type="checkbox"/>
14	13/03/20 09:58	General View								Load JPG	<input checked="" type="checkbox"/>
15	13/03/20 09:58	General View								Load JPG	<input checked="" type="checkbox"/>
16	13/03/20 09:58	General View								Load JPG	<input checked="" type="checkbox"/>
17	13/03/20 09:58	General View								Load JPG	<input checked="" type="checkbox"/>
18	13/03/20 09:58	General View								Load JPG	<input checked="" type="checkbox"/>
19	13/03/20 09:58	General View								Load JPG	<input checked="" type="checkbox"/>
20	13/03/20 09:58	General View								Load JPG	<input checked="" type="checkbox"/>
21	13/03/20 09:58	General View								Load JPG	<input checked="" type="checkbox"/>
22	13/03/20 09:58	General View								Load JPG	<input checked="" type="checkbox"/>
23	13/03/20 09:58	General View								Load JPG	<input checked="" type="checkbox"/>
24	13/03/20 09:58	General View								Load JPG	<input checked="" type="checkbox"/>
25	13/03/20 09:58	General View								Load JPG	<input checked="" type="checkbox"/>
26	13/03/20 09:58	General View								Load JPG	<input checked="" type="checkbox"/>
27	13/03/20 09:58	General View								Load JPG	<input checked="" type="checkbox"/>
28	13/03/20 09:58	General View								Load JPG	<input checked="" type="checkbox"/>
29	13/03/20 09:58	General View								Load JPG	<input checked="" type="checkbox"/>
30	13/03/20 09:58	General View								Load JPG	<input checked="" type="checkbox"/>
31	13/03/20 09:58	General View								Load JPG	<input checked="" type="checkbox"/>
32	13/03/20 09:58	General View								Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
33	13/03/20 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
34	13/03/20 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
35	13/03/20 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
36	13/03/20 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
37	13/03/20 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
38	13/03/20 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
39	13/03/20 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
40	13/03/20 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
41	13/03/20 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
42	13/03/20 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
43	13/03/20 09:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	13/03/20 09:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	13/03/20 09:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	10/03/20 18:07	E-filed GIA report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI20003846/FSF3E2

Date: 18/03/2020

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MK000848

Claimant Vehicle No : SHA1405J

Insured Vehicle No : SMK425X

Date of Loss: 09/03/2020

Nature of Claim: TP Claim No: M2001806

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHA1405J

Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)

Engine No: G4LEJU080166

Reg. Date: 03/09/2018 (Man. Year: 2018)

Chassis No: KMHCH851CVKU107336

Colour: Blue

Odometer: 224730 km

Engine Capacity: 1580 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Davanti 6 mm	Rear Left Side:	Davanti 7 mm
Front Right Side:	Davanti 6 mm	Rear Right Side:	Davanti 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,217.02	796.12	420.90	34.58
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	720.00	580.00	140.00	19.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,948.02	1,387.12	560.90	28.79
+ GST 7.00/7.00% (S\$)	136.36	97.10	39.26	28.79
Nett Amount (S\$)	2,084.38	1,484.22	600.16	28.79

INSPECTION

Date of Assignment: 11/03/2020 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 10/03/2020 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Mar 2020)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA1405J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER	Cracked	459.40 FL	-	*459.40 FL
2	1		*REAR BUMPER CENTRE-BLACK	Deformed	451.25 FL	-	*451.25 FL
3	1		*REAR BUMPER FOGLAMP	Not Necessary	201.50 FL	-	*- FL
4	1		*REAR BUMPER LWR MOULDING	Not Necessary	155.00 FL	-	*- FL
5	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
6	1		*REVERSE SENSOR	Not Necessary	135.70 F	-	*- F
7	1		*REAR BUMPER MAT	Necessary	50.00 F	-	*50.00 F
					Sub Total (S\$)	1,474.85	982.65
					- List Item Discount on L Items 20.00/20.00% (S\$)	257.83	186.53
					Total Parts (S\$)	1,217.02	796.12

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	350.00	320.00
2	SPRAY PAINTING	New	250.00	200.00
3	R/I REVERSE SENSOR	New	120.00	60.00
Gross Labour Cost (\$\$)			720.00	580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >