22/03/2002 - ASS. REC. BY: REF: CS/C71 2	0003844/Tivf3  Special Instruction:
Surveyor: Taufixh ASSIGN	
From (Person): Chong Boon Sen of	
	Bill to:
OD HTP + WS+TP RES / OD RES / EVA / INV / MV To Inspect Vehicle No: SG 3 843 R	
at Workshop m/s Cycle & Conage	Tel: 91865300
of 186 Pandon Lavy	
Policy No: DmpcSN 30209019000	Claim No: SWM Donanos Co 1
Sum Insured:	Excess: \$ 950-00
Make of Veh: (Client's Record)	D.O.A. 8.3. 2000
CA REV REP. / REV 24 HRS  Date/Time: 10.3.70 9.50.50  Person Contacte	d:
Date/Time Action/Instruction ( ) Estimo	nto.
SGJ 848R- CS3/msg 130	DU+074/Tigbe2-1 201-19/02/2018
11/3/20 Revert via merimen	
	s from Alfred by merimen
11/3/20 Informed the Han CIA	
	by furned by email (Red 1732.25, 13/9)

1.00	T120003847/11vf3
	GNMENT  OF TRACK ON A No. 1
Date: 11 03 2020	Veh No: \$45898K Yr Regn: 2012, April
tisnated Cost:	Type: M.Ca / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
Inspect Vehicle No: SGJ 898R	Make: Mercelos GLC250 c.c 1991
Workshop m/s Cycle & Camage Industries	Colour A/C: Insured / Std / NI / NA
188 penden 100p	Sp.Reading 454 35 T/Radio: Insured / Std / NI / NA
	Eng/No:
sured:	C/No: WDC 2539462F206638
	Gen. Cond: Good / Fair / Poor / Burnt
laims No. Excess: \$ 950.00	Steering: Inorder / Jammed / Leaked / Burnt or
	Brake: Inorder / Jammed / Leaked / Burnt or
(Client's Record) lake of Veh:  Car In	
Goh chee Han 3	11 / 66/(1)
(Pallow Condition) 9181 7717 \$	Tyre Size: F:
(Policy Coridition)	R: BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR/ SUMI /
emark. The ventilad commenced its	41
repair at the time of inspection.	TOYO / YOKO or
Sal, or Market Value: 9150 K /	- Front Rear
DAC Accident Rport: Consistent? : Yes or No	R/Balmm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. L/Bal. mm
Est. Repairs: days Res.: Yes or No	D.O.A. D.O.I. 11/3/20 e/p
Lum Sum: % 3 Val.: Yes or No	Survey held at (FC Parolem lor)
CA (REV) REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS  Vehicle: IN / OU	
Date:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
8	
×	
	Dave Of Banaire &
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 6
i) : Final Report	Resurvey No. of Trip: Survey Fee:
1) : Final Report Date/Time, File Return to?	Resurvey No. of Trip: Survey Fee: Transportation:
i) : Final Report	Resurvey No. of Trip:
1) : Final Report  Date/Time, File Return to?  2)916 - typist Add F	Survey Fee:   Survey Fee:   Transportation:   See:   See:   Transportation:   See:   S
1) : Final Report Date/Time, File Return to?	Survey Fee:
1) : Final Report  Date/Time, File Return to?  2)916 - typist Add F	Survey Fee:   Survey Fee:   Transportation:   See:
1) : Final Report  Date/Time, File Return to?  2) 916 - typist Add F  Report Formal: Manney	Survey Fee:
1) : Final Report  Date/Time, File Return to?  2) 916 - typist Add F  Report Formal: Manney	Survey Fee:

## ...CLAIM SUBFOLDER...(New Assignment)

LAIM SUB	FOLDER TRA	CKING								
Case	Notified	Est Submitted	Adj Assigned	Adj Rije	Adj Sub	mitted	Ins Authred	Status		
Main	10 Mar 2020		10 Mar 2020 14:25 Assign					New Assignment Cancel Case		
	Main	Re	eference		Claim Details		Documents Show All			Show All
CLAIM SU	BFOLDER DE	TAILS				[Create	d by insurer]			
Insured:	GOH YEN	NEE, ID: SXXXX	(114A							
Vehicle Reg No.:	SG3898					08/03/20	08/03/2020 19:00 - :59			
Claim Type	Policy/Cover Note No.: DMPCSN30209019000 (Compre				nprehensi	orehensive)				
					Excess:	\$\$950.00	0			
Repairer:	Cycle & C	arriage Industri	es Pte Ltd (Par	idan Loop)	188 Pandan Loop	p, 128378	West Coast - Tel: 9	1865300	)	
Handling Insurer:							dled by <b>Chong Boo</b>	on Sen]		
Adjuster:	LKK Auto	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 [Final Rpt due 19/03/2020]								
Driver/Cust dian:	MOK LIP Y	ANG (MO LIYANG)	) (45 / Male) ,	NRIC: SXXX	X763F, Tel: +6	559099003	88 Email: NOEMAIL			
ASSOCIAT	ED MAIL RE	CEIVED					V	iew All	Compose	Case Mai
There are n	o mail for this	case.								
ALL ASSO	CIATED TAS	sks⊟				View All	Search Tasks	Create N	ew Task	Complet
Due Dat	e Priority	Type Task	Group Sub	ject Han	dler Assign	ned By	Completed On	Cre	ated On	Done
No results.										

change / Kenlyn ong / Cheory.

## Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Wednesday, 11 March 2020 5:31 PM

To:

Go Chee Han; SUR

Subject:

SGJ 898R-DOA: 8/3/2020 (CHINA TAIPING OD)

Dear Chee Han,

As instructed by our client, please proceed to repair the insured vehicle SGJ 898R, (Excess \$950.00).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

# View Received Message

This mail is associated with:

\*SGJ898R (SNM20D201203C01)

OD Mar 8 2020 7:00PM [GOH YEN NEE] Cycle & Carriage Industries Pte Ltd

Reply All | Mark as Unread | Print Message | Delete Message Reply China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA\_TAIPING), sent on 11/03/2020 17:01 PM. From LKK\_HQ Alert - Adj Mandate Approved (S\$11871.13) - SGJ898R - Claim Handler: Chong Boon Sen Subject Approved:11871.13:Please proceed to authorize repairs up to \$11,871.13 BEFORE Excess of \$950.00. RE-INSPECTION of vehicle required.

DOCUMENTS SUMMARY

There are no documents.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. From: LKK Auto Consultants Pte Ltd 3 Anson Road 51 Ubi Ave 1 #01-25 #16-00 Springleaf Tower Paya Ubi Industrial Park Singapore 079909 Singapore 408933 Attn: Chong Boon Sen Date: 11 Mar 2020 **Preliminary Advice** Vehicle No : SGJ898R Accident Date : 08/03/2020 Make : BENTLEY CONTINENTAL GT V8 Policy No. DMPCSN30209019000 Assignment Date : 10/03/2020 Excess : S\$950.00 Date of Inspection :11/3/2020 Est. Duration of Repair :6 Inspection At :CYCLE & CARRIAGE INDUSTRIES PTE LTD Point of Impact / General Description of Damages The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident. Repairer's Estimate (Gross) :S\$ 13,279.62 Revised Amount :S\$ 11,547.37 Check Items (Estimated) :S\$ 323.76 :S\$ 11,871.13 Lump Sum Repair :S\$ **Total Loss Consideration** New for Old Value :S\$ Pre-Accident Value :S\$ 150,000.00 COE / PARF Rebate :S\$ 78,669.00 Salvage Value :S\$ Margin for Repair :S\$ 71,331.00 Remarks ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation. The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck. Other comments:

## > Back to OneMotoring

# Enquire PARF/COE Rebate for Registered Vehicle

Singapore NRIC
114A
SGJ898R
No
11 Mar 2020
MERCEDES BENZ
GLC250 4MATIC (R18 LED)
Red
2016
27492030943079
WDC2539462F206638
155.0 kW (207 bhp)
\$44,644.00
24 Apr 2017
24 Apr 2017
1
\$54,502.00
Yes
23 Apr 2027
\$40,876.00
23 Apr 2027
B - Car above 1600cc or 97kW (130bhp)
10
\$53,106.00
\$37,793.00
\$78,669.00

The information contained herein is correct as at 11 Mar 2020

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

ACCIDENT	STATE	<b>JENT</b>
----------	-------	-------------

Date Of Report 10/03/2020 08:51

Date Of Accident 08/03/2020 19:40

LKK AutoFDNAMENIS hence notify Exact Location Of Accident

Country/State of Loss SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number SGJ898R

Insured/Policyholder

Name Of Registered Owner GOH YEN NEE Passport No/FIN SXXXX114A Email Address NOEMAIL

Mobile Phone No (LOCAL) +65-91160062 Alternative Phone No. OFFICE-90990038

Vehicle Particulars

Manufacturer MERCEDES-BENZ

Model GLC250

Exact Purpose for which vehicle was being used at

time of accident

PRIVATE USE

Are you claiming under your own insurance policy

for repair to your vehicle?

YES

If No, Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy

Policy Number DMPCSN30209019000

Cover Note Number

Driver

Name of Driver MOK LIP YANG (MO LIYANG)

Passport No/FIN SXXXX763F Date Of Birth 08/11/1974 Occupation INDOOR Date Of Driving Pass 03/01/2003

**Driving Experience** 17 YEARS AND 2 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-90990038

Fax Number

Contact Number

EMail Address NOEMAIL Address 1 ROBIN DRIVE #04-02

Postcode 258261

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured SPOUSE

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by NO

ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

Passenger 1 NAME: : NA

> GENDER: : FEMALE

2

NO

5

Passenger 2 NAME: : NA

> GENDER: : MALE

Passenger 3 NAME: : NA

> GENDER: : FEMALE

> > : FEMALE

Passenger 4 NAME: : NA

GENDER:

**Details of Police Action** 

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

**DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number SHD9785T

Vehicle Make/Model/Colour RENAULT

Details Of Properties

Vehicle Category TAXI

### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents/including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or Go Chee Han
    DID: 6771 4336 HP: 9181 7717
  - (ii) for complying with requirements under any regulations, laws or court orders.

(If driver is not the policyholder)

Date & Time


Reporting Centre Personnel's

Email: cheehan.go@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd Customer Service Centre - Pandan Loop

Policyholder's Signature Date & Time

Name:



I was driving along Collyer Quay towards Marina Boulevard. Was knocked on the left side by a taxi. This was along the left most lane of Finlayson Green towards Marina Boulevard at the Ylane split.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

Please note that you have 14 calendar days to revert and file the claim under your own policy. Failing to do so, your insurance company will not allow nor accept the claim.

(Please contact your insurance company for any further details)

Policyholder's Signature Date & Time

Driver's Signature

(If driver is not the policyholder)

Date & Time

Go Chee Han

DID: 6771 4336 HP: 9181 7717

Email: cheehan.go@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Reporting Centre Personnel's

Name:

the Repairer of the following . To resurvey before/after spray painting

- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

CHINA TAIPING INSURANCE (S) PTE

ATTN: MOTOR CLAIM DEPARTMENT

Acknowledged by Repairer

3 ANSON ROAD #16-00


SPRINGLEAF TOWER

SINGAPORE 079909

LTD

62222366

# **ESTIMATE FOR SGJ898R**



Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

Vehicle & Document Information

WIP No 42007

SGJ898R / 24/04/2017 Reg No/Reg Date

Date In/Mileage 35435

WDC2539462F206638 Chassis No

27492030943079 Engine No

MB/MB GLC 250 4MATIC SUV (X253) Make/Model 029 996 Hyacinth Re/ 041 101 ARTICO Blac Colour/Trim

Qty

1.00

1.00

1.00

1.00

1.00

1.00

1.00

1.00

Date/Time Printed CSE Operator Terms Account No

09/03/2020/ 19:30 CH 371 / Go Chee Han WC000668 Credit

Description of Goods / Services

Z REQUEST Customer Request M BPNSUN

POLICY NO/ACC DATE : DMPCSN3020901900

: 9-3-2020 // TBA DRIVE IN/EXCESS

DATE IN/DATE SURVEY: BY/AUTHRIZED ON

A BPILAB DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.

BPIRES RESPRAY FRONT BUMPER & LH/FRONT FENDER & HOOD

A BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT IDENTIFICATION STANDARD. NETT

A BPILAR TO REMOVE, REPLACE HEADLAMP WITH FOCUS

A BPILAB TO INSPECT & CONDUCT WHEEL ALIGNMENT NETT

S BPNSUB LABOUR TO REMOVE AND INSTALL FYRE FROM RIM, (RUN FLAT)

WHEEL BALANCE AND INSTALL NEW VALVE HEAD

LH/COVER BUMPER & FENDER AREA LEFT FRONT FENDER LH/INTERMEDIATE LAYER

FRONT BUMPER LH/BASIC MOUNTING FOR BUMPER

IMPACT ABSORBER

BOTTOM BASIC MOUNTING FOR BUMPER

LH/FRONT DISK WHEEL

LEFT HEADLAMP UNIT

Confirmed & accepted by

Go Chee Han DID: 6771 4336 HP: 9181 7717 1.00

Email: cheehan.go@cyclecarriage.com.sg Cycle & Carriage Industries Pte Ltd Customer Service Centre - Pandan Loop

97495749

Nett

13,279.62

Amount

1920.

/800· 2100.00

2880.00

380.00

120.00

540.00

60.00

224.96

895.61

nn 7 15.68

de 1343.58

nn × 148.49

nn 3 308.08

aut / 3414.32

New 69.46

Disc%

0.10

Unit Price

7% GST on 13279.62

929.57

Total Payable

224.96 00.00

15.68 00.00

69.46 00.00

148.49 00.00

779.44 00.00

3414.32 00.00

1343.58 00.00

895.61

308.08

00.00

00.00

14,209.19

16 commy Authorized signatory and company stamp ent, no signature is required.

Validity of this estimate is 14 days from date of quote. This is a computer generated docu Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

> Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg