

ASS. REC. BY:

REF:

CS3/AIG20003860/Htd302

Special Instruction:

Surveyor: Hock Ann

ASSIGNMENT (Office)

Main:

From (Person): Chin Icying

of AIG

Date/Time: 11/3/2020 @ 9:11am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBQ 6850K

Insured:

SMN 718K

at Workshop m/s:

ong Motor

Tel:

8380 2233

of

No. 464 Macpherson Road

Policy No:

1900133273

Claim No:

3819783497567

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 5/3/2020

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time: 1:39am @ 11/3/2020

Person Contacted:

Jueky

Vehicle IN / OUT

Date/Time	Action/Instruction
	Foliant (X)
	FBQ 6850K - X
	SMN 718K - X
11/3/20	- survey taken
12/3/20	- survey taken
1/1	- pending workshop update

17-ANN

A167

PRS

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FBQ 6850K

at Workshop n/s:

ONG motor

of

464 mapthum

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res:

Yes or No

Lam Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FBQ 6850K

or Regn:

22/11/2019

Type:

M.Car / M.Cycle

Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Kawasaki w175 cc

177

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading:

2363

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MH40J175 AJJP1682

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

80/100/17

R:

100/90/17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

5/3/20

D.O.I.

11/3/20

Survey held at

ONG motor

Des. of Damages

Frt

Rear

O/S

N/S

U/C

Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Submit DAR Report.

PRS cap

Date / Time

Action / Instruction

Don 10h
npr Days → 3 day

MV - 10000

PV - 3992

NV - 6000

RECEIVED 13 MAR 2020

Date/Time, File Pass (v)



Preli. Report



Final Report

11/3/20 Typist

Date/Time, File Pass (v)

Q

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:



Site Insp. (\$



Interview (\$



Tech. Insp. (\$



Training (\$

Survey Fee:

180

Transportation:

S + FS = \$

Parking:

Other:

TOTAL:

191

Report Form:

DAR-Tp

Emp. Code / U/C:

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE ...

From: Chin, Lee-Ying
To: 'assignments', Nivitha (LKK Auto)
Cc: Lim, Kok-Chong
Sent: 3/11/2020 9:11:30 AM
Attachments:  20200309163116867.pdf

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

CHIA S ARUL LLC
ADVOCATES & SOLICITORS
UEN 201330709H

ARULCHELVAN S • DON TAN

Our Ref: FBQ 6850K (wk)

Your Ref: To be advised

9 March 2020

AIG Asia Pacific Insurance Pte Ltd

BY EMAIL ONLY

Dear Sirs,

RE: PROPERTY DAMAGE CLAIM
CLAIMANT : SYAHRAIN BINTE MOHAMED RAMLAN
ACCIDENT INVOLVING FBQ 6850K & SMN 718K ALONG COLLEGE AVENUE
WEST ON 5 MARCH 2020
PRE-REPAIR SURVEY NOTICE

1. We act for Syahrain Binte Mohamed Ramlan, the owner of motor cycle no. FBQ 6850K which was involved in the aforesaid accident.
2. We hereby in compliance with the Pre-Action Protocol for Non-Injury Motor Accident Claims, Appendix C of the State Courts Practice Directions Amendment No. 1 of 2016 ("the NIMA Protocol") give you **NOTICE** that we are claiming against your insured motor vehicle no. SMN 718K for damages, costs and disbursements as a result of your insured driver's negligence.
3. Please let us know if you wish to conduct a pre-repair survey on our client's motor cycle at:

Address	464 Macpherson Road Singapore 368182
Contact Person	Mr. Jacky Siah (8380 2233)

4. Pursuant to paragraph 2.3 of the NIMA Protocol, in the event we do not receive your response within next two (2) working days (excluding any Saturday, Sunday or public holiday), our client will instruct the workshop to commence appraisal and repairs to the damaged motor vehicle without further reference to you.
5. Please advise the appointed surveyor to endorse on page 2 of this letter after the completion of each inspection.

Yours faithfully,

MR ARULCHELVAN S
cc: Client (By Email)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	494C
Vehicle Details	
Vehicle No.:	FBQ6850K
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Mar 2020
Vehicle Make:	KAWASAKI
Vehicle Model:	W175 SE MANUAL
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	BJ175AEP21258
Chassis No.:	MH4BJ175AJJP16805
Maximum Power Output:	-
Open Market Value:	\$2,692.00
Original Registration Date:	20 Nov 2019
First Registration Date:	20 Nov 2019
Transfer Count:	1
Actual ARF Paid:	\$404.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	19 Nov 2029
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$4,100.00
COE Rebate Amount:	\$3,972.00
Total Rebate Amount:	\$3,972.00

The information contained herein is correct as at 11 Mar 2020

OK



1/1

Bike model

Type Of Vehicle

Any

Price From

Any

Price To

Any

Class

Any

MORE SEARCH OPTIONS ▾

Q SEARCH

VIEW ALL (/listing/usedbikes/listing/)



REPORT ERROR (/listing/usedbike/brand/kawasaki/)

SHORTLIST

Share

SHARE (WHATSAPP) SEND TEXT (HTTP://WWW.SGBIKEMART.COM.SG/LISTING/USEDBIKE/KAWASAKI-KAWASAKI-W175/13767/)

Kawasaki W175

Listing Type

Paid Ad

Brand

Kawasaki (/listing/usedbike/brand/kawasaki/)

Model

Kawasaki W175 (/listing/usedbike/model/kawasaki-w175/)

Engine Capacity

177cc

Classification

Class 2B (/listing/usedbike/model/motorcycle-for-sale/class/class-2b/)

Registration Date

07/05/2019

COE Expiry Date

06/05/2029 (9 years 1 months left)

Mileage

2000km

No. of owners

2

Type of Vehicle

Classic Bikes (/listing/usedbike/model/motorcycle-for-sale/classic-bikes/)

LISTING EXPIRED

DETAILS

Kawasaki W175 With Aesthetic Mods. Great 2B Starter Bike. Easy To Maintain And Handle. Bulletproof Kawasaki Engine.

Accessories

Aftermarket Handle Bar. Aftermarket Handle Grips. Aftermarket Bar End Mirrors. Aftermarket Speedometer. Aftermarket Headlights & Signal Lights. Aftermarket Rear Breaklights. Aftermarket Front & Rear Fenders. Aftermarket Diamond Stitched Seat. Aftermarket Rear Shock To Increase The Height Of Bike. Sawtooth Tires For That Vintage Look. Exhaust Wrap. Pilot Jet And Carburetor Tweaking.

MSME20030680 / SME Motor Pte Ltd - Kaki Bukit
ENTRY DATE & TIME: 10/03/2020 15:21
SUBMITTED BY: Chia Pei Ying

Your NCD will be affected due to late reporting
Actual e-Filing Submission Date & Time: 10/03/2020 15:33

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/03/2020 15:21
Date Of Accident	05/03/2020 18:00
Exact Location Of Accident	NO.2 COLLEGE AVE WEST (STEPHEN RIADY CENTRE CARPAR
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBQ6850K
Insured/Policyholder	
Name Of Registered Owner	SYAHRAIN BINTE MOHAMED RAMLAN
NRIC No	SXXXX494C
Email Address	SYAHRAIN.RAMLAN@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97951025
Alternative Phone No	OFFICE-97951025
Vehicle Particulars	
Manufacturer	KAWASAKI
Model	175
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	D19MTMC01008471
Cover Note Number	
Driver	
Name of Driver	SYAHRAIN BINTE MOHAMED RAMLAN
NRIC No	SXXXX494C
Date Of Birth	20/11/1996
Occupation	INDOOR
Date Of Driving Pass	20/08/2015
Driving Experience	4 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97951025
Fax Number	
Contact Number	OFFICE-97951025
E-Mail Address	SYAHRAIN.RAMLAN@HOTMAIL.COM

Address BLK 513 BEDOK NORTH AVE 2 #04-263
 Postcode 460513
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON 05/03/2020 AT 1800HRS, I WAS RIDING MY BIKE (FBQ6850K) ALONG COLLEGE AVE WEST OPPOSITE OF STEPHEN RIADY CENTRE HEADING STRAIGHT. SUDDENLY, A CAR (SMN718K) COMING OUT FROM THE CARPARK WITHOUT STOPPING AND COLLIDED ONTO THE RIGHT SIDE OF MOTORCYCLE.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMN718K
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	SYAHRAIN BINTE MOHAMED RAMLAN
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FBQ6850K
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

2


Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

MOTOF 51

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 05/03/2020 at @ 1500hrs, I was riding my bike (FBQ 6850K) along College Ave west opposite of Stephen Ready Centre heading straight. Suddenly, a car (SMN 718K) coming out from the carpark without stopping and collided onto the right side of motorcycle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

2

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

FOR MOTORCYCLE

Check One Unit (R)

Vehicle No: **FBQ 6850/L**

Motorcycle

NAC	INC	Item	CON	AC	Qty
3001	991886	Front Number Plate			
3002	995065	Front Tyre			
3003	995095	Front Rim			
3004	994872	Front Tyre Rim Spoke			
3005	991771	Front Fender Wheel Guard	CRT		
3006	991283	Front Brake Disc			
3007	991281	Front Brake Caliper			
3008	991785	Front Fork Assy			
3009	991787	Front Fork Inner Tube			
3010	991789	Front Fork Outer Tube			
3011	991167	Front Fork Bracket			
3012	991182	Front Fork Oil Seal			
3013	991174	Front Fork Garnish			
3014	992376	Front Headlamp Rim			
3015	992328	Front Headlamp			
3016	992337	Front Headlamp Bracket			
3017	992345	Front Headlamp Pairing			
3018	992130	Front Windshield			
3019	992134	Front Wing Mirror			
3020	995245	Front LH Signal Lamp			
3021	995246	Front RH Signal Lamp			
3022	992556	Meter Casing			
3023	992553	Meter Assy			
3024	991019	ERP Bracket			
3025	991020	ERP Unit			
3026	992446	Ignition Switch			
3027	992442	Ignition Key Assy			
3028	990706	Cowling Stay			
3029	994470	Steering Stem			
3030	994427	Steering Cone			
3031	992299	Handle Bar			
3032	992312	Handle Bar Switch			
3033	992310	Handle Bar Grip L/H			
3034	995184	Handle Bar Balancer LH			
3035	992300	Handle Bar Balancer RH			
3036	992179	Fuel Tank			
3037	990438	Brake Reservoir			
3038	990621	Clutch Lever			
3039	992293	Hand Brake Lever			
3040	991119	Side Pairing			
3041	994220	Side Pairing Top Garnish			
3042	994219	Side Pairing Inner Garnish			
3043	991118	Pairing Shield			
3044	992047	Front Top Pairing Inner Garnish			
3045	991123	Pairing Top Garnish			
3046	990538	Center Pairing			
3047	993378	Rear Pairing			
3048	991121	Pairing Stopper			
3049	991117	Pairing Lower			

NAC	INC	Item	CON	AC	Qty
3050	995074	Radiator			
3051	992738	Radiator Cowling			
3052	994146	Seat Assy			
3053	990915	Engine Crash Bar			
3054	990928	Engine Case Housing 4/4			
3055	990219	Battery			
3056	990224	Battery Cover			
3057	990223	Battery Bracket			
3058	991144	Foot Brake			
3059	991154	Front Foot Rest 4/4			
3060	991779	Front Foot Rest Bracket			
3061	994269	Side Stand 4/4			
3062	992549	Main Stand			
3063	990615	Clutch Engine Cover			
3064	992478	Kick Starter Rubber			
3065	992477	Kick Starter Lever			
3066	991145	Foot Gear Shifter			
3067	993500	Rear Foot Rest 4/4			
3068	993501	Rear Foot Rest Bracket 4/4			
3069	992581	Exhaust Muffler Heat Shield			
3070	991058	Exhaust Muffler Assy			
3071	993719	Rear LH Shock Absorber			
3072	993720	Rear RH Shock Absorber			
3073	995065	Rear Tyre			
3074	991200	Rear Rim			
3075	994872	Rear Tyre Rim Spoke			
3076	993474	Rear Fender Wheel Guard			
3077	993443	Rear Fender Mudflap			
3078	992940	Rear Brake Disc			
3079	992936	Rear Brake Caliper			
3080	995236	Rear Spocket			
3081	990585	Chain			
3082	990580	Chain Guard			
3083	994530	Swing Arm			
3084	993819	Rear Sub frame			
3085	995245	Rear LH Signal Lamp			
3086	995246	Rear RH Signal Lamp			
3087	995251	Rear Taillamp			
3088	993626	Rear Number Plate			
3089	994192	Side Box 4/4			
3090	992927	Rear Box			
3091	992928	Rear Box Bracket			
3092	991328	Emblem			
3093	990247	Sticker			

Two of them

Assessor:

H-ANN

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Mar 2020 Edit Reg		11 Mar 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: WANG HONG , ID: S2739126E									
Main Claimant: SYAHRAIN BINTE MOHAMED RAMLAN , ID: S9641494C									
Vehicle Reg. No.:	FBQ6850K	Date of Loss:	05/03/2020 00:00 - :59 [3 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3819783447SG	Policy/Cover Note No.:	1900133273 (Comprehensive)						
Vehicle Reg. No. (Insured):	SMN718K	Policy No. (Claimant):							
		Excess:							
Repairer: Ong Motors (HQ) 464 Macpherson, 368182 Macpherson - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 20/03/2020]									
Claimant's Solicitor: CHIA S ARUL & LLC - Tel: 67334647									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBQ6850K (3819783447SG)
[SMN718K]
TP
SYAHRAIN BINTE MOHAMED RAMLAN
Mar 5 2020 12:00AM
[WANG HONG]
Ong Motors

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page		☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	11/03/20 17:20	Chassis Number														Load JPG ☒				
2	11/03/20 17:21	Odometer Reading														Load JPG ☒				
3	11/03/20 17:21	General View														Load JPG ☒				
4	11/03/20 17:21	General View														Load JPG ☒				
5	11/03/20 17:21	General View														Load JPG ☒				
6	11/03/20 17:21	General View														Load JPG ☒				
7	11/03/20 17:21	General View														Load JPG ☒				
8	11/03/20 17:21	General View														Load JPG ☒				
9	11/03/20 17:21	General View														Load JPG ☒				
10	11/03/20 17:21	General View														Load JPG ☒				
11	11/03/20 17:21	General View														Load JPG ☒				
12	11/03/20 17:21	General View														Load JPG ☒				
13	11/03/20 17:21	General View														Load JPG ☒				
14	11/03/20 17:21	General View														Load JPG ☒				
15	11/03/20 17:21	General View														Load JPG ☒				
16	11/03/20 17:21	General View														Load JPG ☒				
17	11/03/20 17:21	General View														Load JPG ☒				
18	11/03/20 17:21	General View														Load JPG ☒				
19	11/03/20 17:21	General View														Load JPG ☒				
20	11/03/20 17:21	General View														Load JPG ☒				
21	11/03/20 17:21	General View														Load JPG ☒				
22	11/03/20 17:21	General View														Load JPG ☒				
23	11/03/20 17:21	General View														Load JPG ☒				
24	11/03/20 17:21	General View														Load JPG ☒				
25	11/03/20 17:21	General View														Load JPG ☒				
26	11/03/20 17:21	General View														Load JPG ☒				
27	11/03/20 17:21	General View														Load JPG ☒				
28	11/03/20 17:21	General View														Load JPG ☒				
29	11/03/20 17:21	General View														Load JPG ☒				
30	11/03/20 17:21	General View														Load JPG ☒				
31	11/03/20 17:22	General View														Load JPG ☒				
32	11/03/20 17:22	General View														Load JPG ☒				
33	11/03/20 17:22	General View														Load JPG ☒				
34	11/03/20 17:22	General View														Load JPG ☒				
35	11/03/20 17:22	General View														Load JPG ☒				
36	11/03/20 17:22	General View														Load JPG ☒				
37	11/03/20 17:22	General View														Load JPG ☒				

Photos/Images			3 per page	☒	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
38	11/03/20 17:22	General View		Load JPG	☒
39	11/03/20 17:22	General View		Load JPG	☒
40	11/03/20 17:22	General View		Load JPG	☒
41	11/03/20 17:22	General View		Load JPG	☒
42	11/03/20 17:22	General View		Load JPG	☒
43	11/03/20 17:22	General View		Load JPG	☒
44	11/03/20 17:22	General View		Load JPG	☒
45	11/03/20 17:22	General View		Load JPG	☒
46	11/03/20 17:22	General View		Load JPG	☒
47	11/03/20 17:22	General View		Load JPG	☒
48	11/03/20 17:22	General View		Load JPG	☒
49	11/03/20 17:22	General View		Load JPG	☒
50	11/03/20 17:22	General View		Load JPG	☒
51	11/03/20 17:22	General View		Load JPG	☒
52	11/03/20 17:22	General View		Load JPG	☒
53	11/03/20 17:22	General View		Load JPG	☒
54	11/03/20 17:22	General View		Load JPG	☒
55	11/03/20 17:22	General View		Load JPG	☒
56	11/03/20 17:22	General View		Load JPG	☒
57	11/03/20 17:22	General View		Load JPG	☒
58	11/03/20 17:22	General View		Load JPG	☒
59	11/03/20 17:22	General View		Load JPG	☒
60	11/03/20 17:22	General View		Load JPG	☒
61	11/03/20 17:22	General View		Load JPG	☒
62	11/03/20 17:22	General View		Load JPG	☒
63	11/03/20 17:22	General View		Load JPG	☒
64	11/03/20 17:22	General View		Load JPG	☒
65	11/03/20 17:22	General View		Load JPG	☒
66	11/03/20 17:22	General View		Load JPG	☒
67	11/03/20 17:22	General View		Load JPG	☒
68	13/03/20 08:58	Reinspection Photo		Load JPG	☒
69	13/03/20 08:58	Reinspection Photo		Load JPG	☒
70	13/03/20 08:58	Reinspection Photo		Load JPG	☒
71	13/03/20 08:58	Reinspection Photo		Load JPG	☒
72	13/03/20 08:58	Reinspection Photo		Load JPG	☒
73	13/03/20 08:58	Reinspection Photo		Load JPG	☒
74	13/03/20 08:58	Reinspection Photo		Load JPG	☒
75	13/03/20 08:58	Reinspection Photo		Load JPG	☒
76	13/03/20 08:58	Reinspection Photo		Load JPG	☒
77	13/03/20 08:58	Reinspection Photo		Load JPG	☒
78	13/03/20 08:58	Reinspection Photo		Load JPG	☒
79	13/03/20 08:58	Reinspection Photo		Load JPG	☒
80	13/03/20 08:58	Reinspection Photo		Load JPG	☒
81	13/03/20 08:58	Reinspection Photo		Load JPG	☒
82	13/03/20 08:58	Reinspection Photo		Load JPG	☒
83	13/03/20 08:58	Reinspection Photo		Load JPG	☒
84	13/03/20 08:58	Reinspection Photo		Load JPG	☒
85	13/03/20 08:58	Reinspection Photo		Load JPG	☒
86	13/03/20 08:58	Reinspection Photo		Load JPG	☒
87	13/03/20 08:58	Reinspection Photo		Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	13/03/20 08:58	Reinspection Photo	 Load JPG	☒
89	13/03/20 08:58	Reinspection Photo	 Load JPG	☒
90	13/03/20 08:58	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	12/03/20 10:02	TP GIA report	 Load PDF	
2	12/03/20 15:13	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20003860/HTD3E2

Date: 20/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900133273
 Claimant Vehicle No: FBQ6850K Insured Vehicle No: SMN718K
 Date of Loss: 05/03/2020 Nature of Claim: TP Claim No: 3819783447SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBQ6850K
 Make & Model: KAWASAKI W175, 177cc SE Engine No: BJ175AEP21258
 Reg. Date: 20/11/2019 (Man. Year: 2019) Chassis No: MH4BJ175AJJP16805
 Colour: Blue Odometer: 2363 km
 Engine Capacity: 177 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 80/100/17 Rear Tyre Size: 100/90/17
 Front Left Side: IRC 9 mm Rear Left Side: IRC 9 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 11/03/2020
 Date Inspected: 11/03/2020 Inspected At: Ong Motors (HQ)
 464 Macpherson
 Singapore 368182
 Estimated Period of Repair: 3.0 days

Adjuster: LEE HOCK ANN

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER WHEEL GUARD	Cut	0.00 F	*- F
2	1		*FRONT FORK ASSY	Repair	0.00 F	*- F
3	1		*FRONT HEADLAMP	* Check	0.00 F	*- F
4	1		*FRONT HEADLAMP BRACKET	Scratched	0.00 F	*- F
5	1		*FRONT WING MIRROR	Scratched	0.00 F	*- F
6	1		*FRONT LH SIGNAL LAMP	Scratched	0.00 F	*- F
7	1		*COWLING STAY	Crumpled	0.00 F	*- F
8	1		*STEERING STEM	Repair	0.00 F	*- F
9	1		*STEERING CONE	Repair	0.00 F	*- F
10	1		*HANDLE BAR	Bent	0.00 F	*- F
11	1		*HANDLE BAR GRIP L/H	Scratched	0.00 F	*- F
12	1		*HANDLE BAR BALANCER LH	Crumpled	0.00 F	*- F
13	1		*FUEL TANK	Bent	0.00 F	*- F
14	1		*CLUTCH LEVER	Crumpled	0.00 F	*- F
15	1		*HAND BRAKE LEVER	Scratched	0.00 F	*- F
16	1		*ENGINE HOUSING L/H	Dented	0.00 F	*- F
17	1		*FRONT FOOT REST L/H	Scratched	0.00 F	*- F
18	1		*SIDE STAND L/H	Scratched	0.00 F	*- F
19	1		*FOOT GEAR SHIFTER	Bent	0.00 F	*- F
20	1		*REAR FOOT REST L/H	Cut	0.00 F	*- F
21	1		*REAR FOOT REST BRACKET L/H	Cut	0.00 F	*- F
22	1		*EXHAUST MUFFLER ASSY	Scratched	0.00 F	*- F
23	1		*SIDE BOX L/H	Scratched	0.00 F	*- F
Total Parts (\$\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >