

ASS. REC. BY:

REF: CS3 / CT120003872 / Grf3 / Special Instruction:

Surveyor: GA ASSIGNMENT (Office)From (Person): Ban Tam of CTI Date/Time: 11.3.2020 2:59p.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLX 3218B Insured: SKB 6282Yat Workshop m/s NIO Automotive Pte Ltd Tel: 909/4893
of 53 Ubi Ave 1 #05-44Policy No: _____ Claim No: SNM 2012012015 / SKB 6282Y / GCH4A

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 7.3.2020
(Client's Record)CA / REV / REP. / REV 24 HRS Wp H.O.D. Endorsement: _____Date/Time: 11.3.2020 3:30p.m Person Contacted: Mrs NIO Vehicle: IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SLX 3218B - NA / Time 2000-04/21/24 D.O.A. - 02/04/2020
	SKB 6282Y - NA / Time 2000-04/21/24 D.O.A. - 02/04/2020
13/3/20	Submit PRS, Est repair range \$7000 - \$8000

ASS. REC. BY:

REF: C11

ASSIGNMENT

From:

Date: 11.3.2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLX 3218B

at Workshop m/s N10 Automotive

of 53 UB Ave 1 #105-44

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SLX 3218B

Yr Regn:

23 Mar 2018

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius c.c 1797

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

167474

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

8VW 516062 412

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

NEXEN

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

D.O.I.

11-03-20

Survey held at

51 UB Ave 1 #105-44 3:45pm

Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$7000 - \$8000

12/3/2020

RECEIVED 16 MAR 2020

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2) 13/3 - typist

Rep. Format: Merimen

Lump Sum / L.B.J.:

Days Of Repair: 7

Resurvey No. of Trip:

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

T/TAL

190

190

Nivitha (LKK Auto)

From: Ben Tang <Ben.Tang@sg.cntaiping.com>
Sent: Wednesday, 11 March 2020 2:59 PM
To: 'Pamela Pamela'
Cc: Claims Dept of CTI; Cecilia Low; Winnie Phee; assignments
Subject: RE: OUR REF: SNM20D201205/SKB6282Y/CECILIA - PRI for Non Injury Motor Accident Cases Road Traffic Accident Involving Motor Vehicles SLX 3218B & SKB 6282Y on 07.03.2020 @ 15:05hrs along 1 Pasir Ris Central towards Pasir Ris Central Street 3

WITHOUT PREJUDICE

Dear Sirs

We refer to your email below.

We noted that you are not agreeable to our proposed list of surveyors. We will assign our panel surveyor M/s LKK Auto to conduct the Pre-repair survey.

Please contact our surveyor to conduct the pre repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please arrange for the survey.

Thank you.

Best Regards
Ben Tang
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Pamela Pamela <pamela@yoga-legal.com>
Sent: Tuesday, March 10, 2020 3:53 PM
To: Ben Tang <Ben.Tang@sg.cntaiping.com>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Cecilia Low <cecilia.low@sg.cntaiping.com>; Winnie Phee <winnie@yoga-legal.com>
Subject: Re: OUR REF: SNM20D201205/SKB6282Y/CECILIA - PRI for Non Injury Motor Accident Cases Road Traffic Accident Involving Motor Vehicles SLX 3218B & SKB 6282Y on 07.03.2020 @ 15:05hrs along 1 Pasir Ris Central towards Pasir Ris Central Street 3

Dear Sirs

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS
PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES
ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES SLX 3218B & SKB 6282Y ON
07.03.2020 @ 15:05HRS ALONG 1 PASIR RIS CENTRAL TOWARDS PASIR RIS CENTRAL
STREET 3**

Thank you for your reply and we refer to the matter above dated 10/03/2020.

Please be informed that we are not agreeable to your proposed motor surveyors. Instead we propose you choose a surveyor from our list of surveyors as appended below:-

1. Lee Kok Weng
2. Seah Kwang Boon
3. Amas Ong Poh Meng
4. Louis Ng

Please be informed that if we do not hear from you **within 2 working days** from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors you will be deemed to have agreed to the any of the above motor surveyors as a "single joint expert".

We will accordingly inform you who the "single joint expert" is to facilitate your conduct of a pre-repair survey.

Regards,

Pamela

M/s C. YOGARAJAH LLC

883 North Bridge Road

#11-03 Southbank

Singapore 198785

Tel : (65) 6292 5838

Fax : (65) 6292 5938

(UEN No. 201333127N) (GST Reg No. 201333127N)

Important Note: This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6292 5838, if you have received this message in error. Thank you.

On Tue, Mar 10, 2020 at 3:15 PM Ben Tang <Ben.Tang@sg.cntaiping.com> wrote:

Dear Sirs

We refer to your email dated 10 March 2020.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

LKK / LBS / STA

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

If we do not hear from you within two days of this letter, you shall have deemed to have agreed that the surveyor appointed by us shall be Single Joint Expert for this matter.

Thank you.

Best Regards

Ben Tang

Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #XX-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Tuesday, March 10, 2020 1:36 PM

To: Cecilia Low <cecilia.low@sg.cntaiping.com>; pamela@yoga-legal.com; Ben Tang <Ben.Tang@sg.cntaiping.com>

Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: OUR REF: SNM20D201205/SKB6282Y/CECILIA - PRI for Non Injury Motor Accident Cases Road Traffic Accident Involving Motor Vehicles SLX 3218B & SKB 6282Y on 07.03.2020 @ 15:05hrs along 1 Pasir Ris Central towards Pasir Ris Central Street 3

Dear Ben,

Please assist to conduct PRS for SLX3218B.

Note : officer in charge – Cecilia 63896530.

*** Kindly quote our reference number when replying.

Thank you,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Pamela Pamela <pamela@yoga-legal.com>

Sent: Tuesday, March 10, 2020 9:45 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: Winnie Phee <winnie@yoga-legal.com>

Subject: Pre-repair inspection for Non Injury Motor Accident Cases Road Traffic Accident Involving Motor Vehicles SLX 3218B & SKB 6282Y on 07.03.2020 @ 15:05hrs along 1 Pasir Ris Central towards Pasir Ris Central Street 3

Dear Sir/Mdm,

We enclosed herewith our letter and accident report (Pre-repair Inspection) dated 10 March 2020 for your attention.

Thank you.

Regards,

Pamela

M/s C. YOGARAJAH LLC

883 North Bridge Road

#11-03 Southbank

Singapore 198785

Tel : (65) 6292 5838

Fax : (65) 6292 5938

(UEN No. 201333127N) (GST Reg No. 201333127N)

Important Note: This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6292 5838, if you have received this message in error. Thank you.

Nivitha (LKK Auto)

From: Pamela Pamela <pamela@yoga-legal.com>
Sent: Wednesday, 11 March 2020 3:17 PM
To: Nivitha (LKK Auto)
Cc: Ben Tang; Claims Dept of CTI; Cecilia Low; Winnie Phee; assignments
Subject: Re: OUR REF: SNM20D201205/SKB6282Y/CECILIA - PRI for Non Injury Motor Accident Cases Road Traffic Accident Involving Motor Vehicles SLX 3218B & SKB 6282Y on 07.03.2020 @ 15:05hrs along 1 Pasir Ris Central towards Pasir Ris Central Street 3

Dear Nivitha

Please be informed that the said vehicle (SLX 3218B) can be inspected at:

Name of workshop : M/s. Neo Automotive Pte Ltd
Address : 53 Ubi Avenue 1
#05 - 44 Paya Ubi Industrial Park
Singapore 408934
Contact Person : Mrs Neo , 9091 4853

Regards,

Pamela

M/s C. YOGARAJAH LLC

883 North Bridge Road

#11-03 Southbank

Singapore 198785

Tel : (65) 6292 5838

Fax : (65) 6292 5938

(UEN No. 201333127N) (GST Reg No. 201333127N)

Important Note: This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6292 5838, if you have received this message in error. Thank you.

On Wed, Mar 11, 2020 at 3:09 PM Nivitha (LKK Auto) <admin-d@lkkauto.com> wrote:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Information	
Owner ID Type:	Company
Owner ID:	486C
Vehicle Information	
Vehicle No.:	SLX3218B
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Mar 2020
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8E CVT
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	2ZR8327932
Chassis No.:	ZVW516062412
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$23,902.00
Original Registration Date:	23 Mar 2018
First Registration Date:	23 Mar 2018
Transfer Count:	0
Actual ARF Paid:	\$15,463.00
PARF Eligibility Information	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Mar 2028
PARF Rebate Amount:	\$11,597.00
COE Information	
COE Expiry Date:	22 Mar 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$39,001.00
COE Rebate Amount:	\$31,316.00
Total Rebate Amount:	\$42,913.00

The information contained herein is correct as at 11 Mar 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/03/2020 17:37
Date Of Accident	07/03/2020 15:05
Exact Location Of Accident	1 PASIR RIS CENTRAL TWDS PASIR RIS CENTRAL ST 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLX3218B
Insured/Policyholder	
Name Of Registered Owner	FORTE AUTO LEASING PTE LTD
Co Reg No	2XXXXX486C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91449265
Alternative Phone No	OFFICE-91449265

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS HYBRID 1.8E CVT
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	19-MJ001253-R01
Cover Note Number	

Driver

Name of Driver	WONG SWEE CHIANG
NRIC No	SXXXX224D
Date Of Birth	08/11/1961
Occupation	OUTDOOR
Date Of Driving Pass	18/05/1990
Driving Experience	29 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91694391
Fax Number	
Contact Number	OFFICE-91694391
EMail Address	NOEMAIL

Address	BLK 117 PASIR RIS GROVE #12-53
Postcode	518173
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON STATED DATE AND TIME, I WAS QUEUEING TO ENTER TWDS PASIR RIS CENTRAL ST 3. WHILE I WAS FOLLOWING THE FRONT VEHICLE INTO 1ST LANE OF PASIR RIS CENTRAL ST 3 PASSING A PRIVATE CAR WHO IS STATIONARY QUEUEING ALONG THE TAXI QUEUE, WITHOUT TURNING ON HIS VEHICLE INDICATOR LIGHT HE SUDDENLY SWERVE ONTO MY LANE. HIS VEHICLE FRONT RIGHT PORTION HIT ONTO MY VEHICLE LEFT PORTION DOOR AREA.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	SKB6282Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MR TEO
NRIC/Passport Number	
Contact Number	93380549
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

2

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to statement.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name:
NRIC/PPN No.:

COMMITTEE/AGENCY/UNIT






































...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Mar 2020		11 Mar 2020 15:43 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	- Co. Reg. No.: -								
Main Claimant:	FORTE AUTO LEASING PTE LTD , Co. Reg. No.: 201631486C								
Vehicle Reg. No.:	SLX32188	Date of Loss:	07/03/2020 15:00 - :59 [23 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM20D201205	Policy/Cover Note No.:	DMPCSN30708119011						
Vehicle Reg. No. (Insured):	SKB6282Y	Policy No. (Claimant):	19-MJ001253-R01						
		Excess:	S\$0.00						
Repairer:	Neo Automotive (HQ) 53 UBI AVE 1 #05-44 PAYA UBI INDUSTRIAL PARK SINGAPORE, 408934 Ubi - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Cecilia Low - 63896530]								
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 20/03/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLX3218B (SNM20D201205)
[SKB6282Y]
TP
FORTE AUTO LEASING PTE LTD
Mar 7 2020 3:00PM
[-]
Neo Automotive


Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Photos/Images									3 per page					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print			
1	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
2	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
3	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
4	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
5	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
6	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
7	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
8	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
9	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
10	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
11	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
12	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
13	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
14	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
15	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
16	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
17	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
18	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
19	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
20	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
21	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
22	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
23	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
24	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
25	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
26	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
27	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
28	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
29	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
30	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
31	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
32	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
33	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
34	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
35	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
36	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			
37	11/03/20 17:31	General View								Load JPG	<input checked="" type="checkbox"/>			

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	11/03/20 17:31	General View	 Load JPG	<input checked="" type="checkbox"/>
39	11/03/20 17:31	General View	 Load JPG	<input checked="" type="checkbox"/>
40	11/03/20 17:31	General View	 Load JPG	<input checked="" type="checkbox"/>
41	11/03/20 17:31	General View	 Load JPG	<input checked="" type="checkbox"/>
42	11/03/20 17:31	General View	 Load JPG	<input checked="" type="checkbox"/>
43	11/03/20 17:31	General View	 Load JPG	<input checked="" type="checkbox"/>
44	11/03/20 17:31	General View	 Load JPG	<input checked="" type="checkbox"/>
45	11/03/20 17:31	General View	 Load JPG	<input checked="" type="checkbox"/>
46	11/03/20 17:31	General View	 Load JPG	<input checked="" type="checkbox"/>
47	11/03/20 17:31	General View	 Load JPG	<input checked="" type="checkbox"/>
48	11/03/20 17:31	General View	 Load JPG	<input checked="" type="checkbox"/>
49	11/03/20 17:31	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
50	11/03/20 17:31	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
51	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
68	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
69	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
70	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
71	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
72	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
73	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
74	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
75	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
76	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
77	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
78	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
79	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
80	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
81	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
82	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
83	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
84	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
85	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
86	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
87	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
89	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
90	13/03/20 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
91	18/03/20 17:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
92	18/03/20 17:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
93	18/03/20 17:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
94	18/03/20 17:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
95	18/03/20 17:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
96	18/03/20 17:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
97	18/03/20 17:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
98	18/03/20 17:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
99	18/03/20 17:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
100	18/03/20 17:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
101	18/03/20 17:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
102	18/03/20 17:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
103	18/03/20 17:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
104	18/03/20 17:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
105	18/03/20 17:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
106	18/03/20 17:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
107	18/03/20 17:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
108	18/03/20 17:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
109	18/03/20 17:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
110	18/03/20 17:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
111	18/03/20 17:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
112	18/03/20 17:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
113	18/03/20 17:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
114	18/03/20 17:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
115	18/03/20 17:58	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
116	18/03/20 17:58	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
117	18/03/20 17:58	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	09/03/20 18:00	Accident Statement	 Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	09/03/20 17:58	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	09/03/20 17:58	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	09/03/20 17:58	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	09/03/20 17:58	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	09/03/20 17:58	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	09/03/20 17:58	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	09/03/20 17:58	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	09/03/20 17:58	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	09/03/20 17:58	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	09/03/20 17:58	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
11	09/03/20 17:58	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	09/03/20 17:57	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	09/03/20 17:57	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div> Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div> <div></div> <div></div> </div> </div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI20003872/GVF3E2

Date: 19/03/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30708119011
Claimant Vehicle No:	SLX3218B	Insured Vehicle No:	SKB6282Y
Date of Loss:	07/03/2020	Nature of Claim:	TP
		Claim No:	SNM20D201205

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX3218B	Engine No:	2ZR8327932
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	ZVW516062412
Reg. Date:	23/03/2018 (Man. Year: 2017)	Odometer:	167474 km
Colour:	Black		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Nexen 5 mm	Rear Left Side:	Nexen 5 mm
Front Right Side:	Nexen 5 mm	Rear Right Side:	Nexen 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	11/03/2020	
Date Inspected:	11/03/2020 Inspected At:	Neo Automotive (HQ) 53 UBI AVE 1 #05-44 PAYA UBI INDUSTRIAL PARK SINGAPORE Singapore 408934
Estimated Period of Repair:	7.0 days	

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000.00 - \$8,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Mar 2020)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX3218B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >