

ASS. REC. BY:

REF: CS/C11 20003885/R1V-f3n2

Special Instruction: ✓

Surveyor: Rosa

ASSIGNMENT (Office)

From (Person): Tan Kah Leongof C11Date/Time: 11.3.20 12.49 p.m

Estimated Cost:

Bill to:

OD-TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

GBB 7548G

Insured:

GBD 911B

at Workshop m/s

Vah Hong Motors

Tel:

87783338of 38 Toh Guan Road East #01-57Policy No: DMCVSN 30762319 000

Claim No:

SNM20D 200978C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20.2.2020

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11/3/20 4.57 p.m

Person Contacted:

MelvinVehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

GBB 7548G - XGBD 911B - X26/3/20LS \$2500 confirmed by email (Red 2084, 457)

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

D.O.A.

20/04/2020

D.O.A.

12/07/2020

Survey held at

Wah HongDes. of Damages: Frt / Rear / DS / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 27 MAR 2020

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

6

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

220

1)

Date/Time, File Return to?

2)

26/3- typst

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Rep. Format:

merimen

Lump Sum / L.B.:

2500/2