在 并	ASS. REC. BY: REF: CS/C11 2006	38941 Rlyf3 Special Instruction:
	Surveyor ROSU ASSIGNME	
minm	From (Person); Adulin Chang of C71	Date/Time: 12.3.200 8.534.m
	Estimated Cost:	Bill to:
	OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS To inspect Vehicle No: SLU 8447 P	
	at Workshop m/s Promium PAC	Tel: 67689911 /6690093
	of 281 Durundra Road	
	Policy No: DMCVSNW 0000 85 22003	Claim No: SNM 20 D201204 / GV 51074 / ADELIM
	Sum Insured:	Excess:
	Make of Veh: (Client's Record)	D.O.A. 8.2.2020
	CA / REV / REP. / REV 24 HRS	Mr Chicag H.O.D. Endorsement:
<u>-</u>	Date/Time: 12.3.2000 10.(0.4.m Person Contacted:	(neovoja Vehicle IN/OUT)
	Date/Time Action/Instruction (/) Estimate	**************************************
	SL4 8447 P-X	
	GV 5107 U- CS/CTI 1801487	13/ Ded3n2 29-10103/2018

ASSIGNMENT			
ASSILTIVITIES	1001	- Thin/	
	4	I TIVIT	1 11 1 1
	PAUL	OT IT.	

From: Date: 13.3. 20 20	Veh No: SLU 8447 Yr Regn: 2017 / 06C
From: Date: Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
1	Make: Volksinger GOLF 1-2731 C.C 1197
	Colour GREY A/C: Insured / Std / NI / NA
	Sp.Reading 47/47 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: WV W222 A4 ZH W1.2034S
Claims No.	Gen. Cond: Good / Fair) Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Norder / Jammed / Leaked / Burnt or
Make of Veh: 1:30 am our waing	Modi: Nil / STRim / STD A/Rim or
	Tyre Size: F: 205 SSR16
(Policy Condition)	R: 2 ′
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU /FIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. R/Bal. 6 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. L/Bal. mm
Est. Repairs: days Res.: Yes or No	D.O.A. 08/03/2020 D.O.I. 13/03/2020
Lum Sum: % 3 Val.: Yes or No	Survey held at PREMIUM
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT	0 S FRT
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
218 Owner change to on claim 218 Withdraw Third Paty Cla	45
21/8 Withdraw Third Paty Cla	iM S
218 Submit Preli Report	
21/8 Submit l'reli Report	
Detective File Page 52	Days Of Repair:
Date/Time, File Pass to? : Preli. Report	Resurvey No. of Trip: Survey Fee:
1) : Final Report Date/Time, File Return to?	Transportation:
Add Fe	
2) 21/8/20 1//154	: Interview (\$) Photos
E word Francisco	: Tech. Invs (\$) Others
Report Formal :	: Weel end (\$
Lump Sum 11.8.1: (Submit Preli)	TOTAL
	TAKE I

...CLAIM SUBFOLDER...(New Assignment)

Case N	Votified	Est Submitted	Adj Assigned	Adj Rpt	Adj Sut	omitted -	Ins Auth'ed	Status	S	
Main 1	10 Mar 2020		12 Mar 2020 09:32 Assign					New Assignment Cancel Case		nt
М	ain	Re	eference		Claim Details		Document	ts		Show All
CLAIM SUB	FOLDER DE	TAILS			6 (00,000)	[Create	d by insurer1			
Insured:						1.				
Main Claimant:	LEW EE K	ENT, ID: S8834	701C							************
Vehicle Reg. No.:	SLU8447	7P		enonana ana ana ana ana ana ana ana ana a	Date of Loss:	08/03/20	020 09:00 - :59			
Claim Type:	TP / SNM	120D201204C0	2		Policy/Cover Note No.:	DMCVSN	W00008522003	The second		
Vehicle Reg. No. (Insured):	GV5107U				Policy No. (Claimant):	: P10282958R00				
			AVV.Z. SIII. SII. SIII.		Excess:	S\$0.00				
Repairer:	Premium	Automobiles Pte	Ltd - Alexandr	a (HQ) 281	L Alexandra Pte L	_td, Level B	32, 159938 Alexano	dra - Tel	: 6388223:	3
Handling Insurer:	China Tair	oing Insurance (Singapore) Pte	. Ltd. (HQ)) - Tel: 6389 611	11 [Hand	lled by Adeline Ch	ıng Pei	Wen]	
Claimant's Insurer:	Auto & Ge	eneral Insurance	(Singapore) P	te. Limited	. (HQ) - Tel: 65	40 2180	January Control of the Control of th			- 112.09
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	[Final Rpt	due 23/0	3/20201			
Adj Asg. Remarks:		ert, Third party re					*/			
ASSOCIATE	D MAIL REC	CEIVED					v	iew All	Compose	Case Mai
There are no	mail for this	case.		-					Compose	Cuscina
ALL ASSOC	IATED TASI	ks⊟				View All	Search Tasks	Create I	New Task 1	Complet
Due Date	Priority	Type Task	Group Subje	ect Han	dler Assign	ed By	Completed On		eated On	Done
No results.					-	,		-	cutca on	DOIL

Nivitha (LKK Auto)

From:

Adeline Chng <adeline.chng@sg.cntaiping.com>

Sent:

Thursday, 12 March 2020 8:58 AM

To:

assignments

Cc:

Claims; Claims Dept of CTI

Subject:

RE: OUR REF: SNM20D201204/GV5107U/ADELINE - FW: ACCIDENT INVOLVING SLU

8447 P AND YOUR INSURED GV 5107 U DATED 08/03/2020

Dear LKK

Please refer to below email and liaise with third party workshop.

Thank you.

Adeline Chng

Executive Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6155 | F: (65) 6225 5879

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims [mailto:claims@premiumauto.com.sg]

Sent: Thursday, 12 March 2020 8:37 AM

To: Adeline Chng <adeline.chng@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: OUR REF: SNM20D201204/GV5107U/ADELINE - FW: ACCIDENT INVOLVING SLU 8447 P AND YOUR INSURED

GV 5107 U DATED 08/03/2020

Dear Adeline.

We would like to choose Steve from LKK for pre-repair survey.

Thank you.

Best Regards,

George Wong

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

281 Alexandra Road Singapore 159938

p. +65 6366 2323, option 1

e. Claims@premiumauto.com.sg w. www.audi.com.sg



This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Adeline Chng <adeline.chng@sg.cntaiping.com>

Sent: Tuesday, March 10, 2020 1:10 PM

To: Claims Dept of CTI < claimsdept@sg.cntaiping.com >; Claims < claims@premiumauto.com.sg >

Subject: RE: OUR REF: SNM20D201204/GV5107U/ADELINE - FW: ACCIDENT INVOLVING SLU 8447 P AND YOUR

INSURED GV 5107 U DATED 08/03/2020

Without Prejudice

Our reference: SNM20D201204C02/ GV5107U/Chngpw

Your reference: SLU8447P

Dear Sirs

ACCIDENT INVOLVING GV5107U & SLU8447P ON 08/03/2020

We refer to your email of 10/03/2020.

We regret that we are unable to advice on liability as our insured has not file accident report yet.

Kindly note the following:-

- 1. We would like to conduct pre-repair survey of the vehicle at the appointed workshop.
- 2. We propose the following list of surveyors to be nominated as the Single Joint Expert to conduct survey of the claimant's vehicle:-

1. ADRIAN LING	6. KENNETH KONG
2. Kelvin Ang	7. SIMON HO
3. SEE CHEW SENG	8. CHUA WEIJIE
4. MOHD FADHILAH BIN OSMAN	9. MARCUS CHUA
5. XING QUO QIANG	10. HENRY NG

3. If we do not hear from you within two days of this letter, you shall have deemed to have agreed that the surveyor appointed by us shall be Single Joint Expert for this matter.

- 4. As per the NIMA Protocol, the survey by our appointed surveyor would include survey of your vehicle pre-repair, after it is dismantled, and post repairs. Hence, you need to provide us / our surveyors with the list of items that were damaged and required to be replaced or repaired to facilitate an effective survey.
- 5. As stated above, please inform us and our surveyor after the claimant's vehicle had been repaired so that our surveyor can carry out post repair inspection before the vehicle is returned to your client. Please co-ordinate with our surveyor immediately after the repair is completed.

If you have any queries, please contact Adeline Chng at 63896155 and email us at claimsdept@sg.cntaiping.com

Thank you.

Adeline Chng

Executive Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6155 | F: (65) 6225 5879

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Tuesday, 10 March 2020 12:17 PM

To: Claims < claims@premiumauto.com.sg>; Adeline Chng < adeline.chng@sg.cntaiping.com>

Cc: Claims Dept of CTI < claimsdept@sg.cntaiping.com>

Subject: OUR REF: SNM20D201204/GV5107U/ADELINE - FW: ACCIDENT INVOLVING SLU 8447 P AND YOUR INSURED

GV 5107 U DATED 08/03/2020

Dear Adeline,

Please conduct PRS for SLU8447P.

Note: officer in charge - Adeline 63896155.

*** Kindly quote our reference number when replying.

Thank you, Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or

partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims < claims@premiumauto.com.sg> Sent: Tuesday, March 10, 2020 8:51 AM

To: Claims Dept of CTI < claimsdept@sg.cntaiping.com>

Cc: 'Claims' < claims@premiumauto.com.sg>

Subject: ACCIDENT INVOLVING SLU 8447 P AND YOUR INSURED GV 5107 U DATED 08/03/2020

Dear all,

Kindly assist in the liability clearance for above mentioned case. We propose for a 100% direct settlement in our client's favour

Attached is the GIA report for your reference.

Kindly arrange survey on 13 of March @1130AM.

Address: 281 Alexandra Road Singapore 159938

Thank you.

Best Regards, George Wong Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

281 Alexandra Road Singapore 159938

p. +65 6366 2323, option 1

e. Claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom 281 Alexandra Road Singapore 159938 p. +65 68362223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

atoresaid.				
	ACCIDENT STATEMENT			
Date Of Report	09/03/2020 19:00			
Date Of Accident	08/03/2020 09:40			
Exact Location Of Accident	PUNGGOL PARK CAR PARK			
Country/State of Loss	SINGAPORE			
	DETAILS OF OWN VEHICLE			
Vehicle Registration Number	SLU8447P			
Insured/Policyholder				
Name Of Registered Owner	LEW EE KENT			
NRIC No	SXXXX701C			

LEWEEKENT@GMAIL.COM **Email Address** Mobile Phone No (LOCAL) +65-97120046 Alternative Phone No OFFICE-97120046

Vehicle Particulars

Manufacturer VOLKSWAGEN

GOLF 1.2 TSI AT 5G12BZ Model

Exact Purpose for which vehicle was being used at PRIVATE USE

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY PRIVATE CAR

Vehicle Category

Insurance Company

AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED. Name of Insurance Company

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

P10282958R00 Policy Number

Cover Note Number

Driver

LEW EE KENT Name of Driver NRIC No SXXXX701C Date Of Birth 24/09/1988 Occupation **INDOOR** Date Of Driving Pass 15/01/2009

Driving Experience 11 YEARS AND 1 MONTH

Gender MALE

Mobile Number (LOCAL) +65-97120046

Fax Number

OFFICE-97120046 Contact Number

EMail Address LEWEEKENT@GMAIL.COM Address

BLK 282B

SENG KANG EAST AVE # 15-57

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

OWNER

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD ON COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle)

involved in the accident

NO 2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged? I have been approached by unknown person(s) YES

soliciting/offering accident claims assistance.

NO 1

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO THE SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GV5107U

Details Of Properties

Vehicle Make/Model/Colour

TH HARDWARE & SCRAP METAL TRADING

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

CHAN BOON HEE

NRIC/Passport Number

GXXXXX286L

Contact Number

93202205

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders

Policyholder's Signature

Date & Time:

Driver's Signature

(If draver is not the policyholder)

Date & Time

Reporting Centre Personnel's Signature Name: Wash effects

NRIC/FIN No : 62987/434

SKETCH PLAN			NAME OF TAXABLE PARTY.
3 Mickup track of	he not signal his	Travel Path of B. O Crossed bold o opposing town	ck up track. white fine Tato
@ Mik up track crossed re	and dander	@ Collised into m	after I am to
This opposing touth	ankup truk	→	Solid
TIMETON	fination	Durana	to 11111 whate
8		L- 1	et line
Pirection St forel.	ME O	Troffic Road Directly	n Arrows
1 Pick up truck colli	ded toto me after	I came Toto on a	andete stop.
DESCRIBE CIRCUMSTANCES OF THE	ACCIDENT		1
A. the 8th	March at 9.40	lan That of	
On the 8th Pringgol Park Car as they were no the car park	Park 7 Ct- 1	H n 2 m	lane
Maggol Park Car	Lade Though	THE PAR IN MY	- avati
as there were no	meron people wa	iking and running) alross
the car park.			
When the pe	ople have cleared o	and a car park l	of 71
available available	on my left, I	proceeded to mart	forward
and ten to my	1eff. Here All	of a sudden	I
noticed a nik-u	in track veerin	a 7nto my lan	e without something
to do fact on	el from my	raht Tommed	ente/s
when the pe and tum to my noticed a pick-y at very fact sp	I can to a con	lete ston Afte	- (2007)20
Jammed broked an	of T 5 bl	hom to med	the
to a complete	stop, I bunded i	the costs of home	I'm Stoll
MICK-4n TMCK. 1	re pick-yp	ple reminister in	11.7
rute my path seconds later.	from my right i	and collided the r	4 12
seconds later.	After colling	the pick-up truck	- quickly
reverted out, asker	thing the evidence	on sune.	
Upon checking the	ndess, facts of the	case are O pick	up took
breached the rand on	older solld whole the	and went against	o take
That the opporting to			
That and love	without chaking	her Stand spot & mi	indi, and
DECLARATION O dad no		nd but my stationa	
I/We declare the foregoing particulars are	true in every respect. opponing	g lane.	0
Manne			(E)
Alle			1H.14
	Priver's Signature If driver is not the policyholder)	Name: Arush & Such	4 stany, GROUN
	late & Time:	NRIC/FIN No : GZ957	454 1
			4 sedertam
B) Pick up trick walking & running	reckless driving	The car park with	n proming
all o pond	na about op a	grows touthe dire	How & MILL
Walting &	Jestienty.		
Justin Tud. my	FICE WITT		



> Back to OneMotoring


Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	701C
Vehicle Details	
Vehicle No.:	SLU8447P
Vehicle to be Exported:	No
ntended Deregistration Date:	13 Mar 2020
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF 1.2 TSI AT 5G12BZ
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	CYV515044
Chassis No.:	WVWZZZAUZHW120345
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$15,773.00
Original Registration Date:	15 Dec 2017
First Registration Date:	15 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,773.00
निकालकी असी देवीका का मिलानी हैं	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Dec 2027
PARF Rebate Amount:	\$4,329.00
तिस्तरिक्तिस्टिशिः स्वकारिक् रि क्तारि	14.00.007
COE Expiry Date:	14 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period (Years):	10
QP Paid:	\$47,112.00
COE Rebate Amount:	\$36,524.00
Total Rebate Amount:	\$40,853.00

The information contained herein is correct as at 13 Mar 2020

62

ОК



55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sq / claims@premiumauto.com.sq

Telefax

Estimate

: Accident Repairs

WIP: 32415

Workshop Contact No : Ubi Road 1 : 6366 2323

Fax No

: 6841 1183

Reference

: PA/TP/0267/2020/NS

Date

: 11-Mar-20

Vehicle NOT IN workshop. Kindly arrange for survey.

Your Insured Veh No

: GV 5107 U

China Taiping Insurance (SG) Pte Ltd

105 Cecil Street #19-00 The Octagon Singapore 069534

Attn: Ms Angie - Motor Claims Dept/Windscreen

Tel: 6389 6541 - Fax: 6224 7175

Owner's Name

: Mr Lew Ee Kent

Address

Blk 282B Sengkang East Avenue

#15-571

Singapore 542282

Telephone

: HP +65 97120046: Third Party Claim

Type of Claim Policy No.

: P10282958R00

Vehicle No

: SLU 8447 P

Model Code

: Golf 1.2 TSI AT 5G12

Model / Year

Dec-17

E. M.

: CYV 515044

Engine No

: CYV 515044

Chassis No

: WVWZZZAUZHW120345

Mileage Date In

.

Estimated By

: Johnny Boo / Allan Wu

Accident Date

: 8-Mar-20

Place of Accident

: Punggol Park Car Park

55 Ubi Road 1, Singapore 408699

Telefax

Estimated Labour Charges for Accident Vehicle SLU 8447 P

<u>S/n</u>	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise crash management components. Reinstall all parts removed.		\$ 2,450.00	1750
3	To respray front bumper and rhs front fender.		\$ 2,000.00	1400
4	To renew rhs front rim and carry out wheel alignment.	S/N	\$ 280.00	×
5	To carry out diagnostic check.	S/N	\$ 192.00	
	TOTAL LABOUR CHARGES	: (\$ 5,282.00	

55 Ubi Road 1, Singapore 408699 Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLU 8447 P

		Damaged Parts & Pric		
S/N	Parts Description		S/Nett	Remarks
1	FRONT BUMPER de /	\$	1,394.00	
2	FRONT BUMPER FIXING PARTS AL	\$	102.00	
3	FRONT BUMPER SUPPORT ELEMENT - RH 🙎	\$	92.00	
4	SPOILER RETAINER ?	\$	315.00	
5	FRONT BUMPER SIDE REINFORCEMENT BEAM 🗶 🌈	\$	734.00	
6	FRONT BUMPER FOAM FILLER PIECE - CENTRE 🗶 🗥	\$	71.00	
7	FRONT BUMPER GUIDE PROFILE - RH ?	\$	35.00	
8	RADIATOR GRILLE .	\$	539.00	
9	VOLKSWAGEN EMBLEM - FRONT	\$	176.00	
10	RADIATOR VENT GRILLE - CENTRE 🗶 🗥	\$	217.00	
11	BUMPER COVER PART - RH ?	\$	47.00	
12	RADIATAIR GUIDE GRILLE - RH ?	\$	153.00	
13	FRONT FENDER - RH	\$	725.00	
14	UNDERBODY PROTECTION X nn	\$	77.00	
15	ANTI CORROSION WAX 💥 🟊 🦯	\$	44.00	
16	ADHESIVE SEALANT	\$	40.00	
17	FRONT FENDER BRACE - RH	\$	53.00	
18	FENDER SUPPORT - FRONT / BEAR ?	\$	70.00	Ipc Xnn
19	WHEEL HOUSING LINER - RH X MA	\$	197.00	£-
20	WHEEL HOUSING LINER - RH 🗶 🗥	\$	102.00	
	SUB TOTAL SPARE PARTS CHARGES :	\$	5,183.00	

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLU 8447 P

		Damaged Parts	& Prices	
S/N	Parts Description		S/Nett	Remarks
21	FRONT FENDER ATTACHMENT PARTS 🕰 🦟		\$ 50.00	
22	HEADLIGHTS BRACKET - RH FRONT ?		\$ 14.00	
23	HEADLIGHT RETAINING PLATE - RH FRONT 🕇		\$ 72.00	
24	HALOGEN TWIN HEADLIGHTS - RH 54		\$ 859.00	
25	SUNDRIES ?		\$ 300.00	
	TOTAL SPARE PARTS CHARGES		\$ 6,478.00	
	TOTAL LABOUR CHARGES	:	\$ 5,282.00	
	GRAND TOTAL	:	\$ 11,760.00	
	1 (1) [] [] [] [] [] [] [] [] [] [

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

Rean before point

Please Note

This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo Body Repair Manager Allan Wu Claims Consultant